79°21'W

43°39'30"N



Map : 0.25 Kilometer Radius

Order No: 20191015076

Address: 21 Broadview Ave, Toronto, ON, M4M 2E4

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership

79°21'W



Aerial (2017)

Address: 21 Broadview Ave, Toronto, ON, M4M 2E4

Source: ESRI World Imagery

Order No: 20191015076

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership

79°21'W



43°39'N

43°39'N

Topographic Map

Address: 21 Broadview Ave, Toronto, ON, M4M 2E4

Source: ESRI World Topographic Map

Order No: 20191015076

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	-/0.0	78.0 / -0.90	20 Sunlight Park Rd. Toronto ON	EHS

Order No:	20170918087	**Nearest Intersection:**	
Status:	C	**Municipality:**	Toronto
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	25-SEP-17	**Search Radius (km):**	.25
Date Received:	18-SEP-17	**X:**	-79.350155
Previous Site Name:	N/A	**Y:**	43.656111
Lot/Building Size:	N/A		
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
2	1 of 1	-/0.0	79.5 / 0.59	TORONTO ON	WWIS

Well ID:	7310390	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	4/17/2018
Sec. Water Use:	Monitoring	**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	6607
Casing Material:		**Form Version:**	7
Audit No:	Z278084	**Owner:**	
Tag:	A242168	**Street Name:**	GREEN SPACE BETWEEN EASTERN AVE ANF ON RAMP TO DVP
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1007035494	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632989
Code OB Desc:		**North83:**	4835034
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/29/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			

Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1007211925
Layer: 1
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3: 01
Other Materials: FILL
Formation Top Depth: 0
Formation End Depth: 0.9
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007211926
Layer: 2
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Other Materials: SAND
Mat3:
Other Materials:
Formation Top Depth: 0.9
Formation End Depth: 1.8
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007211929
Layer: 5
Color: 2
General Color: GREY
Mat1: 17
Most Common Material: SHALE
Mat2:
Other Materials:
Mat3: 92
Other Materials: WEATHERED
Formation Top Depth: 10.6
Formation End Depth: 11.88
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007211927
Layer: 3
Color: 6
General Color: BROWN
Mat1: 05

Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	1.8
Formation End Depth:	4.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007211930
Layer:	6
Color:	2
General Color:	GREY
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	
Mat3:	26
Other Materials:	ROCK
Formation Top Depth:	11.88
Formation End Depth:	22.86
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007211928
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	34
Other Materials:	TILL
Formation Top Depth:	4.5
Formation End Depth:	10.6
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007211938
Layer:	1
Plug From:	0
Plug To:	0.3
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007211941
Layer:	4
Plug From:	19.81
Plug To:	20.7
Plug Depth UOM:	m

Annular Space/Abandonment

Sealing Record

Plug ID:	1007211940
Layer:	3
Plug From:	6
Plug To:	19.81
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007211939
Layer:	2
Plug From:	0.3
Plug To:	6
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1007211924
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007211933
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	21.33
Casing Diameter:	5.1
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007211934
Layer:	1
Slot:	10
Screen Top Depth:	21.33
Screen End Depth:	22.86
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.4

Water Details

Water ID:	1007211932
Layer:	1
Kind Code:	

Kind:
Water Found Depth: 5.2
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1007211931
Diameter: 21
Depth From: 0
Depth To: 22.86
Hole Depth UOM: m
Hole Diameter UOM: cm

---

3 | **1 of 1** | **-/0.0** | **77.8 / -1.08** | **ON** | **WWIS**

Well ID: 7189068
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: C19031
Tag: A132936
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status: Yes
Data Src:
Date Received: 9/22/2012
Selected Flag: Yes
Abandonment Rec:
Contractor: 6607
Form Version: 8
Owner:
Street Name:
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004213989
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 8/1/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 78.719779
Elevrc:
Zone: 17
East83: 633058
North83: 4834983
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

---

4 | **1 of 1** | **-/0.0** | **77.9 / -0.99** | **ON** | **BORE**

Borehole ID: 644951
OGF ID: 215545334
Status:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No

Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	NOV-1962	***Municipality:***	
Static Water Level:	0.9	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.655803
Total Depth m:	12.2	***Longitude DD:***	-79.349824
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	633065
Drill Method:	Power auger	***Northing:***	4834968
Orig Ground Elev m:	78.3	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	78.6		

Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218509511	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.1	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Asphalt	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	

Gsc Material Description:
Stratum Description: ASPHALT.

Geology Stratum ID:	218509515	***Mat Consistency:***	
Top Depth:	8.9	***Material Moisture:***	
Bottom Depth:	12.2	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Shale	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	

Gsc Material Description:
Stratum Description: SHALE. GREY,AGE ORDOVICIAN. 018 017017028 016 0000403000145050001800800O **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218509513	***Mat Consistency:***	Stiff
Top Depth:	4.4	***Material Moisture:***	
Bottom Depth:	5.5	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial

Gsc Material Description:
Stratum Description: SILT,CLAY. GREY,GLACIAL,STIFF, AGE GLACIAL, WATER STABLE AT 253.9 FEET.

Geology Stratum ID:	218509512	***Mat Consistency:***	Stiff
Top Depth:	.1	***Material Moisture:***	
Bottom Depth:	4.4	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial

Gsc Material Description:
Stratum Description: SILT,CLAY. BROWN,GLACIAL,STIFF, AGE GLACIAL.

Geology Stratum ID:	218509514	**Mat Consistency:**	Stiff
Top Depth:	5.5	**Material Moisture:**	
Bottom Depth:	8.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial

Gsc Material Description:
Stratum Description: SILT,CLAY. GREY,GLACIAL,STIFF, AGE GLACIAL.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 129730 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

5 | ***1 of 1*** | ***-/0.0*** | ***78.8 / -0.05*** | ***Toronto ON*** | ***WWIS***

Well ID:	7310411	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	4/17/2018
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	7383
Casing Material:		**Form Version:**	7
Audit No:	Z275543	**Owner:**	
Tag:	A238959	**Street Name:**	11 SUNLIGHT PARK RD
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1007035626	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632957

Code OB Desc:		**North83:**	4835019
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/20/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Pipe Information

Pipe ID: 1007213900
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007213904
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007213905
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1007213902
Diameter:
Depth From: 0
Depth To: 32
Hole Depth UOM: ft
Hole Diameter UOM: inch

6	1 of 31	-/0.0	77.9 / -1.02	**LEVER BROTHERS LIMITED** **#1 SUNLIGHT PARK RD.** **TORONTO CITY ON**	CA

Certificate #: 8-3074-86-
Application Year: 86
Issue Date: 3/12/1987
Approval Type: Industrial air
Status: Approved in 1987

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: SODIUM CARBONATE BIN VENTS
Contaminants: Suspended Particulate Matter
Emission Control: Baghouse (Incl Vent Fil.)

6	2 of 31	-/0.0	77.9 / -1.02	1 Sunlight Park Road Toronto ON	EHS

Order No: 20020110004
Status: C
Report Type: Basic Report
Report Date: 1/16/02
Date Received: 1/10/02
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: Don Valley Parkway
Municipality:
Client Prov/State: ON
Search Radius (km): 0.35
X: -79.349948
Y: 43.655819

6	3 of 31	-/0.0	77.9 / -1.02	LEVER, DIVISION OF U.L. CANADA INC. 1 SUNLIGHT PARK ROAD TORONTO ON M4M 1B6	GEN

Generator No: ON0113800
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 3761
SIC Description: SOAP/CLEANING COMP.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 133
Waste Class Desc: BRINES, CHLOR-ALKALI WASTES

Waste Class: 123
Waste Class Desc: ALKALINE PHOSPHATES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

---

6 | ***4 of 31*** | ***-/0.0*** | ***77.9 / -1.02*** | ***LEVER BROTHERS LIMITED***
1 SUNLIGHT PARK ROAD
TORONTO ON M4M 1B6 | ***GEN***

Generator No: ON0113800
Status:
Approval Years: 86,87
Contam. Facility:
MHSW Facility:
SIC Code: 3761
SIC Description: SOAP/CLEANING COMP.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 242

Waste Class Desc: HALOGENATED PESTICIDES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	5 of 31	-/0.0	77.9 / -1.02	LEVER, A DIVISION OF U.L. CANADA INC. 1 SUNLIGHT PARK ROAD TORONTO ON M4M 1B6	GEN

Generator No: ON0113800
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 3761
SIC Description: SOAP/CLEANING COMP.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 123
Waste Class Desc: ALKALINE PHOSPHATES

Waste Class: 133
Waste Class Desc: BRINES, CHLOR-ALKALI WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	6 of 31	-/0.0	77.9 / -1.02	LEVER BROTHERS LIMITED 1 SUNLIGHT PARK ROAD TORONTO ON M4M 1B6	GEN

Generator No: ON0113800
Status:
Approval Years: 88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 3761
SIC Description: SOAP/CLEANING COMP.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 123
Waste Class Desc: ALKALINE PHOSPHATES

Waste Class: 133
Waste Class Desc: BRINES, CHLOR-ALKALI WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	7 of 31	-/0.0	77.9 / -1.02	LEVER, A(SEE & USE ON2489201)ADA INC. 1 SUNLIGHT PARK ROAD TORONTO ON M4M 1B6	GEN

Generator No: ON0113800
Status:
Approval Years: 99,00
Contam. Facility:
MHSW Facility:
SIC Code: 3761
SIC Description: SOAP/CLEANING COMP.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 123
Waste Class Desc: ALKALINE PHOSPHATES

Waste Class: 133
Waste Class Desc: BRINES, CHLOR-ALKALI WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

6 | ***8 of 31*** | ***-/0.0*** | ***77.9 / -1.02*** | ***LEVER P(OUT OF BUSINESS)***
1 SUNLIGHT PARK ROAD
TORONTO ON M4M 1B6 | ***GEN***

Generator No: ON2489201
Status:
Approval Years: 00
Contam. Facility:
MHSW Facility:
SIC Code: 3761
SIC Description: SOAP/CLEANING COMP.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 123
Waste Class Desc: ALKALINE PHOSPHATES

Waste Class: 133
Waste Class Desc: BRINES, CHLOR-ALKALI WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	9 of 31	-/0.0	77.9 / -1.02	LEVER PONDS 1 SUNLIGHT PARK ROAD TORONTO ON M4M 1B6	GEN

Generator No: ON2489201
Status:
Approval Years: 99
Contam. Facility:
MHSW Facility:
SIC Code: 3761
SIC Description: SOAP/CLEANING COMP.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 123
Waste Class Desc: ALKALINE PHOSPHATES

Waste Class: 133
Waste Class Desc: BRINES, CHLOR-ALKALI WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251

Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

---

6 | ***10 of 31*** | ***-/0.0*** | ***77.9 / -1.02*** | ***Talisker Corporation***
1 Sunlight Park Road
Toronto ON M4M 1B5 | ***GEN***

Generator No: ON4630819
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 243
Waste Class Desc: PCB'S

---

6 | ***11 of 31*** | ***-/0.0*** | ***77.9 / -1.02*** | ***LEVER BROTHERS***
1 SUNLIGHT PARK ROAD
TORONTO ON M4M 1B6 | ***NPCB***

Company Code: F0972
Industry:
Site Status:
Transaction Date:
Inspection Date:

---

6 | ***12 of 31*** | ***-/0.0*** | ***77.9 / -1.02*** | ***LEVER BROTHERS***
1 SUNLIGHT PARK ROAD
TORONTO ON | ***OPCB***

Year: 1995
Site Number: 30194A019
Name Owner:
Additional Site Information:

--Details--

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Quantity: 2.00
Address Site:
Description: Number of Drums of Ballasts with High Level PCBs (>1000 ppm)

Quantity: 400.00
Address Site:
Description: Weight of Drums of Ballasts with High Level PCBs (>1000 ppm) kg

---

6	13 of 31	-/0.0	77.9 / -1.02	LEVER PONDS 1 SUNLIGHT PARK RD TORONTO ON M4M 1B6	SCT

Established: 1910
Plant Size (ft²): 0
Employment: 500

--Details--
Description: SOAP AND OTHER DETERGENTS, EXCEPT SPECIALTY CLEANERS
SIC/NAICS Code: 2841

Description: SPECIALTY CLEANING, POLISHING, AND SANITATION PREPARATIONS
SIC/NAICS Code: 2842

Description: PERFUMES, COSMETICS, AND OTHER TOILET PREPARATIONS
SIC/NAICS Code: 2844

6	14 of 31	-/0.0	77.9 / -1.02	LEVER PONDS 1 SUNLIGHT PARK RD TORONTO ON M4M 1B6	SCT

Established: 0000
Plant Size (ft²): 0
Employment: 0

--Details--
Description: Soap and Cleaning Compound Manufacturing
SIC/NAICS Code: 325610

6	15 of 31	-/0.0	77.9 / -1.02	Unilever Canada Ltd. 1 Sunlight Park Rd Floor 3-4 Toronto ON M4M 1B6	SCT

Established: 1940
Plant Size (ft²):
Employment: 400

6	16 of 31	-/0.0	77.9 / -1.02	LEVER POND'S 1 Sunlight Park Rd Suite 300 Toronto ON M4M 1B6	SCT

Established: 1940
Plant Size (ft²): 0
Employment: 0

--Details--
Description: Soap and Cleaning Compound Manufacturing

SIC/NAICS Code: 325610

Description: Toilet Preparation Manufacturing
SIC/NAICS Code: 325620

---

6 | **17 of 31** | **-/0.0** | **77.9 / -1.02** | **LEVER BROTHERS LTD.**
1 SUNLIGHT PARK ROAD BETWEEN RAILWAY TRACK AND CHEMITHON BUILDING TORONTO
PLANT 1 SUNLIGHT PARK ROAD
TORONTO CITY ON | **SPL**

Ref No:	107265	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	11/10/1994	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	1106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	11/10/1994	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	

Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: LEVER BROS - APPROX 30 L MOLTEN SULPHUR TO GROUND FROM RAIL CAR.
Contaminant Qty:

---

6 | **18 of 31** | **-/0.0** | **77.9 / -1.02** | **LEVER BROTHERS LTD.**
TORONTO PLANT 1 SUNLIGHT PARK ROAD
TORONTO CITY ON | **SPL**

Ref No:	103261	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	7/27/1994	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PIPE/HOSE LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	1106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/27/1994	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	

Incident Reason:	EQUIPMENT FAILURE			**Source Type:**	
Site Name:					
Site County/District:					
Site Geo Ref Meth:					
Incident Summary:	LEVER BROTHERS - OLEUM TO AIR FOR 10 MINUTES FROM BROKEN LINE.				
Contaminant Qty:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	19 of 31	-/0.0	77.9 / -1.02	**LEVER BROTHERS LTD.** **1 SUNLIGHT PK. RD. TORONTO PLANT 1** **SUNLIGHT PARK ROAD** **TORONTO CITY ON**	SPL

Ref No:	46580	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	2/12/1991	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	01106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	F.D.
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2/12/1991	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER BROS. - 15 KG OF PROPANE RELEASED TO ATMOSPHERE FROM TANK.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	20 of 31	-/0.0	77.9 / -1.02	**LEVER BROTHERS LTD.** **TORONTO PLANT 1 SUNLIGHT PARK ROAD** **TORONTO CITY ON**	SPL

Ref No:	129837	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	7/30/1996	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PIPE/HOSE LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	01106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	WATER	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/30/1996	**Site Map Datum:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER BROS:35L WASTE WATER WITH 5% SOAP SOLN TO STORM SEWER.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	21 of 31	-/0.0	77.9 / -1.02	**LEVER PONDS** **TORONTO PLANT 1 SUNLIGHT PARK ROAD** **TORONTO CITY ON**	SPL

Ref No:	144988	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	8/12/1997	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PIPE/HOSE LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	01106
Nature of Impact:	Water course or lake	**Site Lot:**	
Receiving Medium:	LAND / WATER	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	WORKS
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/12/1997	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER PONDS:30L SOOTY WASTE WATER TO GROUND WITH 4L TO STORM SEWER.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	22 of 31	-/0.0	77.9 / -1.02	**LEVER PONDS** **1 SUNLIGHT PARK RD. TORONTO PLANT 1 SUNLIGHT PARK ROAD** **TORONTO CITY ON**	SPL

Ref No:	140564	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	5/9/1997	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	01106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MOE Reported Dt:	5/9/1997	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	EQUIPMENT FAILURE	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER PONDS-108 KG SOAP INGREDIENT ONTO ROOF THEN18 KG WENT ONTO DRIVEWAY.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	23 of 31	-/0.0	77.9 / -1.02	LEVER BROS. TORONTO PLANT 1 SUNLIGHT PARK ROAD TORONTO CITY ON	SPL

Ref No:	7677	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	8/6/1988	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CONTAINER LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	1106
Nature of Impact:		Site Lot:	
Receiving Medium:	WATER	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	METRO WORKS
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	8/6/1988	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	OTHER	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER BROTHERS - 150 L LATEX TO STORM SEWER		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	24 of 31	-/0.0	77.9 / -1.02	LEVER BROS. LEVER BROS. PROPERTY 1 SUNLIGHT PARK RD. TORONTO PLANT 1 SUNLIGHT PARK ROAD TORONTO CITY ON	SPL

Ref No:	164	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	1/5/1988	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	PIPE/HOSE LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	POSSIBLE	Site Municipality:	1106
Nature of Impact:	WATER COURSE OR LAKE	Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	METRO WORKS DEPT

Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	1/5/1988	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	9000 KG OF PROPYLENE GLYCOL TO GROUND AND STORM SEWER.		
Contaminant Qty:			

6	**25 of 31**	**-/0.0**	**77.9 / -1.02**	**LEVER BROTHERS LTD.** **TORONTO PLANT 1 SUNLIGHT PARK ROAD** **TORONTO CITY ON**	**SPL**

Ref No:	89976	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	8/18/1993	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PIPE/HOSE LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	01106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/18/1993	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER BROTHERS - SULFURICACID VAPOUR TO AIR FOR 20 SEC		
Contaminant Qty:			

6	**26 of 31**	**-/0.0**	**77.9 / -1.02**	**LEVER PONDS** **TORONTO PLANT 1 SUNLIGHT PARK ROAD** **TORONTO CITY ON**	**SPL**

Ref No:	142731	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	6/26/1997	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	01106
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/27/1997	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER PONDS- 50 KG DETERGENT ADDITIVE TO GRAVEL OUTSIDE BLDG.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	27 of 31	-/0.0	77.9 / -1.02	**LEVER BROTHERS LTD.** **1 SUNLIGHT PARK ROAD. TORONTO PLANT 1** **SUNLIGHT PARK ROAD** **TORONTO CITY ON**	SPL

Ref No:	149272		**Discharger Report:**		
Site No:			**Material Group:**		
Incident Dt:	11/15/1997		**Health/Env Conseq:**		
Year:			**Client Type:**		
Incident Cause:	UNKNOWN		**Sector Type:**		
Incident Event:			**Agency Involved:**		
Contaminant Code:			**Nearest Watercourse:**		
Contaminant Name:			**Site Address:**		
Contaminant Limit 1:			**Site District Office:**		
Contam Limit Freq 1:			**Site Postal Code:**		
Contaminant UN No 1:			**Site Region:**		
Environment Impact:	POSSIBLE		**Site Municipality:**	01106	
Nature of Impact:	Soil contamination		**Site Lot:**		
Receiving Medium:	LAND		**Site Conc:**		
Receiving Env:			**Northing:**		
MOE Response:			**Easting:**		
Dt MOE Arvl on Scn:			**Site Geo Ref Accu:**		
MOE Reported Dt:	11/15/1997		**Site Map Datum:**		
Dt Document Closed:			**SAC Action Class:**		
Incident Reason:	UNKNOWN		**Source Type:**		
Site Name:					
Site County/District:					
Site Geo Ref Meth:					
Incident Summary:	LEVER PONDS-450 LITERS SULPHURIC ACID TO ASPHALT,CLEAN-UP UNDERWAY.				
Contaminant Qty:					

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
6	28 of 31	-/0.0	77.9 / -1.02	**LEVER PONDS** **1 SUNLIGHT PARK TORONTO PLANT 1** **SUNLIGHT PARK ROAD** **TORONTO CITY ON**	SPL

Ref No:	132570		**Discharger Report:**		
Site No:			**Material Group:**		
Incident Dt:	10/1/1996		**Health/Env Conseq:**		
Year:			**Client Type:**		
Incident Cause:	PROCESS UPSET		**Sector Type:**		
Incident Event:			**Agency Involved:**		
Contaminant Code:			**Nearest Watercourse:**		
Contaminant Name:			**Site Address:**		
Contaminant Limit 1:			**Site District Office:**		
Contam Limit Freq 1:			**Site Postal Code:**		
Contaminant UN No 1:			**Site Region:**		
Environment Impact:	POSSIBLE		**Site Municipality:**	01106	
Nature of Impact:	Multi Media Pollution		**Site Lot:**		
Receiving Medium:	AIR		**Site Conc:**		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	10/1/1996	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	COMBUSTION PROBLEMS	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER PONDS-10 MINUTE RELEASE OF SULPHUR DIOXIDE DUE TO FIRE.		
Contaminant Qty:			

6	29 of 31	-/0.0	77.9 / -1.02	LEVER BROTHERS LTD. 1 SUNLIGHT PK RD TORONTO PLANT 1 SUNLIGHT PARK ROAD TORONTO CITY ON	SPL

Ref No:	75217	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	8/25/1992	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	CONTAINER OVERFLOW	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	01106
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	8/25/1992	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	ERROR	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER - UP TO 2000 LTR ALKYLATE SOL'N TO EARTH DYKE DURING TRUCK OFFLOAD		
Contaminant Qty:			

6	30 of 31	-/0.0	77.9 / -1.02	LEVER BROTHERS LTD. TORONTO PLANT 1 SUNLIGHT PARK ROAD TORONTO CITY ON	SPL

Ref No:	84589	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	4/26/1993	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	PIPE/HOSE LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	01106
Nature of Impact:		Site Lot:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	4/26/1993	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER BROTHERS-UNKNOWN QTY NITRILOTRIACETIC ACID TO ROOF & GROUND.		
Contaminant Qty:			

---

6 | ***31 of 31*** | ***-/0.0*** | ***77.9 / -1.02*** | ***LEVER BROTHERS LTD.***
1 SUNLIGHT PARK AV. TORONTO PLANT 1
SUNLIGHT PARK ROAD
TORONTO CITY ON | ***SPL***

Ref No:	86936	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	6/14/1993	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PROCESS UPSET	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	01106
Nature of Impact:	Human health	**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	FD,PD
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/14/1993	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER - 2 SEC. RELEASE OF SO2. CN WORKERS NOTICED IT AND CALLED FD TO SCENE		
Contaminant Qty:			

---

7 | ***1 of 1*** | ***-/0.0*** | ***77.8 / -1.03*** | ***1-9 Sunlight Park Rd.***
Toronto ON | ***EHS***

Order No:	20020212008	**Nearest Intersection:**	Broadview, and Eastern Ave.
Status:	C	**Municipality:**	
Report Type:	Basic Report	**Client Prov/State:**	ON
Report Date:	2/14/02	**Search Radius (km):**	0.35
Date Received:	2/12/02	**X:**	-79.349507
Previous Site Name:		**Y:**	43.655321
Lot/Building Size:			
Additional Info Ordered:			

---

8 | ***1 of 1*** | ***-/0.0*** | ***79.8 / 0.97*** | ***ON*** | ***BORE***

Borehole ID:	635259	**Inclin FLG:**	No
OGF ID:	215535656	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1962	**Municipality:**	
Static Water Level:	0.9	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657027
Total Depth m:	9.6	**Longitude DD:**	-79.350411
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633015
Drill Method:	Power auger	**Northing:**	4835103
Orig Ground Elev m:	79.9	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	80		

Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218472536	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill

Gsc Material Description:
Stratum Description: FILL,SILT,CLAY. BROWN.

Geology Stratum ID:	218472537	**Mat Consistency:**	Compact
Top Depth:	2.4	**Material Moisture:**	
Bottom Depth:	5.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine

Gsc Material Description:
Stratum Description: SILT,SAND,CLAY. GREY,BROWN,LACUSTRINE,COMPACT,AGE GLACIAL, WATER STABLE AT 258.9 FEET.

Geology Stratum ID:	218472538	**Mat Consistency:**	Firm
Top Depth:	5.8	**Material Moisture:**	
Bottom Depth:	9.5	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial

Gsc Material Description:
Stratum Description: TILL,CLAY,SILT,SAND.GREY,GLACIAL,FIRM, AGE NON-GLACIAL.

Geology Stratum ID:	218472539	**Mat Consistency:**	
Top Depth:	9.5	**Material Moisture:**	
Bottom Depth:	9.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Boulders	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:

Stratum Description: BOULDERS,SHALE. 0000001000080022001900100005 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 032150 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

9 ***1 of 1*** ***-/0.0*** ***77.9 / -0.97*** ***ON*** ***BORE***

Borehole ID:	635866	***Inclin FLG:***	No
OGF ID:	215536263	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:		***Primary Name:***	
Completion Date:	1923	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:		***Township:***	
Sec. Water Use:		***Latitude DD:***	43.655801
Total Depth m:	9.8	***Longitude DD:***	-79.3497
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	633075
Drill Method:		***Northing:***	4834968
Orig Ground Elev m:	77.7	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	78.5		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218474908	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	1.3	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill

Gsc Material Description:
Stratum Description: FILL.

Geology Stratum ID:	218474909	***Mat Consistency:***	
Top Depth:	1.3	***Material Moisture:***	

Bottom Depth:	2.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT. LACUSTRINE.		

Geology Stratum ID:	218474910	**Mat Consistency:**	
Top Depth:	2.8	**Material Moisture:**	
Bottom Depth:	9.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY. LACUSTRINE,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 038240 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

10	1 of 1	-/0.0	77.6 / -1.31	TORONTO ON	WWIS

Well ID:	7183716	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	7/6/2012
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z150818	**Owner:**	
Tag:	A130980	**Street Name:**	677 QUEEN ST E
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	WKQ-004975 A0-A02
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	1003965062	***Elevation:***	78.688438
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632973
Code OB Desc:		***North83:***	4834965
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/22/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1004345607
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	5
Formation End Depth:	10
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004345606
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Other Materials:	SAND
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0
Formation End Depth:	5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004345608
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05

Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	10
Formation End Depth:	15
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004345618
Layer:	3
Plug From:	4
Plug To:	15
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004345617
Layer:	2
Plug From:	1
Plug To:	4
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004345616
Layer:	1
Plug From:	0
Plug To:	1
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	DIRECT PUSH

Pipe Information

Pipe ID:	1004345605
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004345611
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	5
Casing Diameter:	2
Casing Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004345612
Layer: 1
Slot: 10
Screen Top Depth: 5
Screen End Depth: 15
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Hole Diameter

Hole ID: 1004345609
Diameter: 8
Depth From: 0
Depth To: 15
Hole Depth UOM: ft
Hole Diameter UOM: inch

11	*1 of 2*	*-/0.0*	*77.9 / -0.99*	***TWO HANDS REALTY INC.*** ***9 SUNLIGHT PARK RD*** ***Toronto ON***	***NPCB***

Company Code: O0152
Industry: Other
Site Status: In- Use
Transaction Date: 4/1/1989
Inspection Date: 8/28/1997

--Details--
Label:
Serial No.:
PCB Type/Code: Askarel/Askarel
Location: BUILDING #11
Item/State:
No. of Items:
Manufacturer:
Status: In-Use
Contents:

11	*2 of 2*	*-/0.0*	*77.9 / -0.99*	***TWO HANDS REALTY INC.*** ***9 SUNLIGHT PARK RD*** ***TORONTO ON M4M 1B5***	***NPCB***

Company Code: O0152
Industry: OTHER
Site Status: INSPECTED SITES (NON FEDERAL)
Transaction Date: 6/22/2000
Inspection Date: 8/28/1997

--Details--
Label: OR21792
Serial No.: 280607
PCB Type/Code: ASKAREL/ASKAREL
Location: BUILDING #11
Item/State: TRANSFORMER/FULL

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

No. of Items: 1
Manufacturer: CGE
Status: IN-USE
Contents: 1779 L

---

12 | 1 of 5 | -/0.0 | 77.7 / -1.19 | **BMW Canada Inc.**
11 Sunlight Park Road
Toronto ON M4M 1B5 | CA

Certificate #: 1774-5WPPV7
Application Year: 2004
Issue Date: 3/8/2004
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

12 | 2 of 5 | -/0.0 | 77.7 / -1.19 | **BMW Canada Inc.**
11 Sunlight Park Road
Toronto ON M4N 1B5 | ECA

Approval No: 1774-5WPPV7
Approval Date: 2004-03-08
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-AIR
Project Type: AIR
Address: 11 Sunlight Park Road
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7413-5RNK6F-14.pdf

MOE District: Metro Toronto
City:
Longitude: -79.34935999999999
Latitude: 43.65612
Geometry X:
Geometry Y:

---

12 | 3 of 5 | -/0.0 | 77.7 / -1.19 | **BMW CANADA**
11 SUNLIGHT PARK ROAD
TORONTO ON M4M 1B5 | GEN

Generator No: ON7547361
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

12 | 4 of 5 | -/0.0 | 77.7 / -1.19 | **BMW CANADA**
11 SUNLIGHT PARK ROAD | GEN

TORONTO ON M4M 1B5

Generator No:	ON7547361	**PO Box No:**	
Status:		**Country:**	Canada
Approval Years:	2016	**Choice of Contact:**	CO_ADMIN
Contam. Facility:	No	**Co Admin:**	GARNET SHAVER
MHSW Facility:	No	**Phone No Admin:**	5196473729 Ext.
SIC Code:	441110		
SIC Description:	NEW CAR DEALERS		

Detail(s)

Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES

---

12 | **5 of 5** | **-/0.0** | **77.7 / -1.19** | **BMW CANADA** | **GEN**

11 SUNLIGHT PARK ROAD
TORONTO ON M4M 1B5

Generator No:	ON7547361	**PO Box No:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Dec 2018	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class:	251 L
Waste Class Desc:	Waste oils/sludges (petroleum based)

---

13 | **1 of 1** | **-/0.0** | **77.0 / -1.92** | **BORE**

ON

Borehole ID:	644854	**Inclin FLG:**	No
OGF ID:	215545237	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	NOV-1962	**Municipality:**	
Static Water Level:	0.9	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655453
Total Depth m:	12.1	**Longitude DD:**	-79.350491
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633012
Drill Method:	Power auger	**Northing:**	4834928
Orig Ground Elev m:	78.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509131	**Mat Consistency:**	Stiff
Top Depth:	3.7	**Material Moisture:**	
Bottom Depth:	5.2	**Material Texture:**	

Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial

Gsc Material Description:
Stratum Description: TILL,CLAY. BROWN,GLACIAL,STIFF, AGE GLACIAL.

Geology Stratum ID:	218509133	**Mat Consistency:**	
Top Depth:	8.9	**Material Moisture:**	
Bottom Depth:	12.1	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: SHALE. GREY,AGE ORDOVICIAN. 018 000000040003510000007 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218509130	**Mat Consistency:**	Stiff
Top Depth:	1.1	**Material Moisture:**	
Bottom Depth:	3.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	organic

Gsc Material Description:
Stratum Description: SILT,CLAY,ORGANIC. BROWN,STIFF, WATER STABLE AT 254.4 FEET.

Geology Stratum ID:	218509129	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.1	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Asphalt	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	fill

Gsc Material Description:
Stratum Description: FILL,SAND,ASPHALT, GRAVEL. BROWN,LOOSE.

Geology Stratum ID:	218509132	**Mat Consistency:**	Stiff
Top Depth:	5.2	**Material Moisture:**	
Bottom Depth:	8.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial

Gsc Material Description:
Stratum Description: TILL,CLAY. GREY,GLACIAL,STIFF, AGE GLACIAL.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 128760 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

14	***1 of 1***	***-/0.0***	***79.8 / 0.97***	***ON***	***BORE***

Borehole ID:	635188	***Inclin FLG:***	No
OGF ID:	215535585	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	FEB-1962	***Municipality:***	
Static Water Level:	0.9	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.657038
Total Depth m:	9.7	***Longitude DD:***	-79.351154
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632955
Drill Method:	Power auger	***Northing:***	4835103
Orig Ground Elev m:	79.9	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	81.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472260	***Mat Consistency:***	Compact
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	1.2	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Granuls	***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,CINDERS. GREY,COMPACT.		

Geology Stratum ID:	218472261	***Mat Consistency:***	Dense
Top Depth:	1.2	***Material Moisture:***	
Bottom Depth:	5.8	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT(73),CLAY(19), SAND(8). GREY,BROWN,LACUSTRINE,DENSE, AGE GLACIAL, WATER STABLE AT 259.1 FEET.		

Geology Stratum ID:	218472263	***Mat Consistency:***	
Top Depth:	9.6	***Material Moisture:***	
Bottom Depth:	9.7	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Boulders	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	

Material 3: **Geologic Period:**
Material 4: **Depositional Gen:**
Gsc Material Description:
Stratum Description: BOULDERS,SHALE. WEATHERED. 015 0140170220000002000038037001900070007 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID: 218472262 **Mat Consistency:** Firm
Top Depth: 5.8 **Material Moisture:**
Bottom Depth: 9.6 **Material Texture:**
Material Color: Grey **Non Geo Mat Type:**
Material 1: Till **Geologic Formation:**
Material 2: Clay **Geologic Group:**
Material 3: Silt **Geologic Period:**
Material 4: Sand **Depositional Gen:** glacial
Gsc Material Description:
Stratum Description: TILL,CLAY,SILT,SAND.GREY,GLACIAL,FIRM, AGE NON-GLACIAL.

Source

Source Type: Data Survey **Source Appl:** Spatial/Tabular
Source Orig: Geological Survey of Canada **Source Iden:** 1
Source Date: 1956-1972 **Scale or Res:** Varies
Confidence: H **Horizontal:** NAD27
Observatio: **Verticalda:** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031440 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier: 1 **Horizontal Datum:** NAD27
Source Type: Data Survey **Vertical Datum:** Mean Average Sea Level
Source Date: 1956-1972 **Projection Name:** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

15 ***1 of 1*** ***-/0.0*** ***77.8 / -1.03*** ***ON*** ***BORE***

Borehole ID: 635865 **Inclin FLG:** No
OGF ID: 215536262 **SP Status:** Initial Entry
Status: **Surv Elev:** No
Type: Borehole **Piezometer:** No
Use: Geotechnical/Geological Investigation **Primary Name:**
Completion Date: FEB-1962 **Municipality:**
Static Water Level: **Lot:**
Primary Water Use: Not Used **Township:**
Sec. Water Use: **Latitude DD:** 43.655838
Total Depth m: 9.8 **Longitude DD:** -79.349141
Depth Ref: Ground Surface **UTM Zone:** 17
Depth Elev: **Easting:** 633120
Drill Method: Diamond Drill **Northing:** 4834973
Orig Ground Elev m: 77.7 **Location Accuracy:**
Elev Reliabil Note: **Accuracy:** Not Applicable
DEM Ground Elev m: 78.1
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218474905	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL,SAND.		

Geology Stratum ID:	218474906	**Mat Consistency:**	
Top Depth:	1.4	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT. LACUSTRINE.		

Geology Stratum ID:	218474907	**Mat Consistency:**	
Top Depth:	3	**Material Moisture:**	
Bottom Depth:	9.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY. LACUSTRINE,AGE GLACIAL. AY, SAND- **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 038230 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

16 ***1 of 1*** ***-/0.0*** ***76.9 / -1.94*** ***ON*** ***BORE***

Borehole ID:	644953	**Inclin FLG:**	No
OGF ID:	215545336	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	

Completion Date:	NOV-1962	**Municipality:**	
Static Water Level:	0.6	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655376
Total Depth m:	9.1	**Longitude DD:**	-79.350208
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633035
Drill Method:	Power auger	**Northing:**	4834920
Orig Ground Elev m:	76.5	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.5		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509520	**Mat Consistency:**	Firm
Top Depth:	2.4	**Material Moisture:**	
Bottom Depth:	6.2	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,FIRM,AGE GLACIAL,WATER STABLE AT 248.9 FEET.		

Geology Stratum ID:	218509521	**Mat Consistency:**	
Top Depth:	6.2	**Material Moisture:**	
Bottom Depth:	9.1	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SHALE. GREY,AGE ORDOVICIAN. 021 000000200007800800001 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218509519	**Mat Consistency:**	Stiff
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,CLAY. BROWN,GLACIAL,STIFF, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 129750 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

17	***1 of 1***	***-/0.0***	***76.8 / -2.08***	***ON***	***BORE***

Borehole ID:	644954	***Inclin FLG:***	No
OGF ID:	215545337	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	NOV-1962	***Municipality:***	
Static Water Level:	0.9	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.655362
Total Depth m:	12.2	***Longitude DD:***	-79.350456
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	633015
Drill Method:	Power auger	***Northing:***	4834918
Orig Ground Elev m:	78.4	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	78.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509522	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	1.4	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Asphalt	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND,ASPHALT, GRAVEL. BROWN,LOOSE.		

Geology Stratum ID:	218509526	***Mat Consistency:***	
Top Depth:	8.8	***Material Moisture:***	
Bottom Depth:	12.2	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Shale	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SHALE. GREY,AGE ORDOVICIAN. 00000002000450060014803000228100000004 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218509523	***Mat Consistency:***	Soft
Top Depth:	1.4	***Material Moisture:***	
Bottom Depth:	4.5	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	organic material	***Geologic Group:***	

Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	organic
Gsc Material Description:			
Stratum Description:	SILT,ORGANIC. BROWN,GREY,SOFT, WATER STABLE AT 254.4 FEET.		

Geology Stratum ID:	218509524	**Mat Consistency:**	Stiff
Top Depth:	4.5	**Material Moisture:**	
Bottom Depth:	6.9	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. BROWN,GLACIAL,STIFF, AGE GLACIAL.		

Geology Stratum ID:	218509525	**Mat Consistency:**	Stiff
Top Depth:	6.9	**Material Moisture:**	
Bottom Depth:	8.8	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,STIFF, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 129760 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

18 | ***1 of 1*** | ***-/0.0*** | ***79.8 / 0.97*** | ***Toronto ON*** | ***WWIS***

Well ID:	7293354	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	8/22/2017
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7360
Casing Material:		**Form Version:**	7
Audit No:	Z268911	**Owner:**	
Tag:	A226044	**Street Name:**	4041 EASTERN AVENUE
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	

Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1006713540	***Elevation:***	80.346458
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632922
Code OB Desc:		***North83:***	4835065
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	8/10/2017	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1006833009
Layer:	2
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	10
Formation End Depth:	20
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006833008
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	10
Formation End Depth UOM:	ft

Overburden and Bedrock

Materials Interval

Formation ID:	1006833010
Layer:	3
Color:	
General Color:	
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	34
Other Materials:	TILL
Formation Top Depth:	20
Formation End Depth:	32
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006833017
Layer:	1
Plug From:	25
Plug To:	0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	E
Method Construction:	Auger
Other Method Construction:	

Pipe Information

Pipe ID:	1006833007
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006833013
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	27
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006833014
Layer:	1
Slot:	.1
Screen Top Depth:	27
Screen End Depth:	32
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch

Screen Diameter: 2

Water Details

Water ID: 1006833012
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 20
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006833011
Diameter: 6
Depth From: 0
Depth To: 32
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

19 | ***1 of 1*** | ***-/0.0*** | ***78.8 / -0.03*** | ***Toronto Transit Commission***
Eastern Ave and Broadview
Toronto ON | ***SPL***

Ref No: 0088-ACC292
Site No: NA
Incident Dt: 2016/07/29
Year:
Incident Cause:
Incident Event: Leak/Break
Contaminant Code: 15
Contaminant Name: ENGINE OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Land
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 2016/07/29
Dt Document Closed:
Incident Reason: Equipment Failure
Site Name: TTC<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: TTC: engine oil to road and CB 21 L
Contaminant Qty: 21 L

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Miscellaneous Communal
Agency Involved:
Nearest Watercourse:
Site Address: Eastern Ave and Broadview
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Toronto
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

---

20 | ***1 of 1*** | ***-/0.0*** | ***78.8 / -0.03*** | ***TANK TRUCK***
EASTERN AVE. EAST OF BRAODVIEW, NEAR CARLAW AVE. TANK TRUCK (CARGO)
TORONTO CITY ON | ***SPL***

Ref No: 37977
Site No:
Incident Dt: 7/20/1990
Year:
Incident Cause: OTHER CONTAINER LEAK

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	01106
Nature of Impact:	Water course or lake	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/20/1990	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TANK TRUCK - DIESEL FUEL FROM PUNCTURED TANK ONTO ROAD AND CATCHBASINS.		
Contaminant Qty:			

---

21 **1 of 1** **-/0.0** **79.8 / 0.97** **ON** **BORE**

Borehole ID:	635187	**Inclin FLG:**	No
OGF ID:	215535584	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656865
Total Depth m:	12.8	**Longitude DD:**	-79.351655
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632915
Drill Method:	Power auger	**Northing:**	4835083
Orig Ground Elev m:	79.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	81.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472256	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	3.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,SAND. GREY,BROWN,LOOSE.		

Geology Stratum ID:	218472259	**Mat Consistency:**	
Top Depth:	9.3	**Material Moisture:**	
Bottom Depth:	12.8	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	

Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine

Gsc Material Description:
Stratum Description: BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. 0150170290000001300104010001400501AL.

Geology Stratum ID:	218472257	**Mat Consistency:**	Loose
Top Depth:	3.2	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine

Gsc Material Description:
Stratum Description: SILT,SAND. GREY,BROWN,LACUSTRINE,LOOSE, AGE GLACIAL.

Geology Stratum ID:	218472258	**Mat Consistency:**	Hard
Top Depth:	4.3	**Material Moisture:**	
Bottom Depth:	9.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial

Gsc Material Description:
Stratum Description: TILL,CLAY,SILT,SAND.BROWN,GLACIAL,HARD, AGE NON-GLACIAL.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031430 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

22 | ***1 of 1*** | ***-/0.0*** | ***79.8 / 0.98*** | ***ON*** | ***BORE***

Borehole ID:	633027	**Inclin FLG:**	No
OGF ID:	215533428	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAR-1957	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656508
Total Depth m:	3	**Longitude DD:**	-79.351913
Depth Ref:	Ground Surface	**UTM Zone:**	17

Depth Elev:		**Easting:**	632895
Drill Method:	Power auger	**Northing:**	4835043
Orig Ground Elev m:	77.8	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218464748	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218464749	**Mat Consistency:**	
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	2.4	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SILT,SAND MEDIUM. GREY,FLUVIO-GLACIAL, AGE GLACIAL.		

Geology Stratum ID:	218464750	**Mat Consistency:**	
Top Depth:	2.4	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SAND,SILT. BROWN,FLUVIO-GLACIAL, AGE GLACIAL. 01702302800001 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 009740 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

23 **1 of 1** **-/0.0** **79.8 / 0.97** **ON** **BORE**

Borehole ID: 635186
OGF ID: 215535583
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1962
Static Water Level: 0.8
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 7.7
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 77.5
Elev Reliabil Note:
DEM Ground Elev m: 81.8
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.65669
Longitude DD: -79.352032
UTM Zone: 17
Easting: 632885
Northing: 4835063
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218472255
Top Depth: 7.6
Bottom Depth: 7.7
Material Color: Red
Material 1: Boulders
Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: BOULDERS,SHALE. WEATHERED. 000000080004501200009 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218472253
Top Depth: 1.4
Bottom Depth: 5.2
Material Color: Brown
Material 1: Sand
Material 2: Silt
Material 3: Clay
Material 4: Organic
Gsc Material Description:
Stratum Description: SAND(43)-MEDIUM TO COARSE,SILT(42),CLAY(14),ORGANIC. BROWN,LACUSTRINE,LOOSE, AGE GLACIAL, WATER STABLE AT 251.9 FEET.

Mat Consistency: Loose
Material Moisture:
Material Texture: Coarse
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: lacustrine

Geology Stratum ID: 218472254
Top Depth: 5.2
Bottom Depth: 7.6
Material Color: Brown
Material 1: Till
Material 2: Sand
Material 3: Silt
Material 4: Clay
Gsc Material Description:
Stratum Description: TILL,SAND(33)-FINE TO MEDIUM,SILT(27), CLAY. BROWN,GLACIAL,HARD, AGE NON-GLACIAL.

Mat Consistency: Hard
Material Moisture:
Material Texture: Fine to Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID:	218472252	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	fill

Gsc Material Description:
Stratum Description: FILL,SAND,SILT, GRAVEL. BROWN,LOOSE.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031420 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

24	1 of 1	-/0.0	79.8 / 0.93	ON	BORE

Borehole ID:	635185	**Inclin FLG:**	No
OGF ID:	215535582	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1962	**Municipality:**	
Static Water Level:	1.1	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656872
Total Depth m:	11.1	**Longitude DD:**	-79.352151
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632875
Drill Method:	Power auger	**Northing:**	4835083
Orig Ground Elev m:	77.9	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	82.4		

Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218472249	**Mat Consistency:**	Dense
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	2.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	

Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SAND,SILT. BROWN,LACUSTRINE,DENSE, AGE GLACIAL, WATER STABLE AT 252.1 FEET.		

Geology Stratum ID:	218472251	**Mat Consistency:**	
Top Depth:	7.5	**Material Moisture:**	
Bottom Depth:	11.1	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. 00000030000380380009004300009 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472248	**Mat Consistency:**	Compact
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND,SILT, GRAVEL. BROWN,COMPACT.		

Geology Stratum ID:	218472250	**Mat Consistency:**	Hard
Top Depth:	2.7	**Material Moisture:**	
Bottom Depth:	7.5	**Material Texture:**	Coarse
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT(40), CLAY(30),SAND MEDIUM TO COARSE. GREY,BROWN,GLACIAL,HARD, AGE NON-GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031410 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

34	1 of 8	NE/20.1	78.8 / -0.03	21 Broadview Ave Toronto ON M4M 2E4	EHS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Order No:	20000414003	**Nearest Intersection:**	Broadview Ave / Eastern Ave
Status:	C	**Municipality:**	Toronto
Report Type:	Basic Report	**Client Prov/State:**	ON
Report Date:	4/24/00	**Search Radius (km):**	0.25
Date Received:	4/14/00	**X:**	-79.348969
Previous Site Name:		**Y:**	43.657112
Lot/Building Size:	1/4 acre		
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
34	2 of 8	NE/20.1	78.8 / -0.03	21 Broadview Avenue Toronto ON M4M 2E4	EHS

Order No:	20071203020	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	CAN - Complete Report	**Client Prov/State:**	
Report Date:	12/5/2007	**Search Radius (km):**	0.25
Date Received:	12/3/2007	**X:**	-79.348847
Previous Site Name:		**Y:**	43.656903
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps And /or Site Plans		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
34	3 of 8	NE/20.1	78.8 / -0.03	21 Broadview Ave Toronto ON M4M2E4	EHS

Order No:	20170206003	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	10-FEB-17	**Search Radius (km):**	.25
Date Received:	06-FEB-17	**X:**	-79.34876
Previous Site Name:		**Y:**	43.657113
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
34	4 of 8	NE/20.1	78.8 / -0.03	Rubidium Environmental Inc. 21 Broadview Avenue Toronto ON M4M 2E4	GEN

Generator No:	ON8403239	**PO Box No:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Dec 2017	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class:	221 L
Waste Class Desc:	Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
34	5 of 8	NE/20.1	78.8 / -0.03	SLR Consulting (Canada) Ltd. 21 Broadview Avenue Toronto ON M4M 2E4	GEN

Generator No:	ON8409347	**PO Box No:**	
Status:		**Country:**	
Approval Years:	07,08	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MHSW Facility: ***Phone No Admin:***
SIC Code: 441110
SIC Description: New Car Dealers

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

34 ***6 of 8*** ***NE/20.1*** ***78.8 / -0.03*** ***ONTARIO SALVAGE LIMITED*** ***GEN***
21 BROADVIEW AVENUE
TORONTO ON M4M 2E4

Generator No: ON0563600 ***PO Box No:***
Status: ***Country:***
Approval Years: 92,93,97,98,99,00,01 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 5619
SIC Description: COMB. METAL PROD.

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

---

34 ***7 of 8*** ***NE/20.1*** ***78.8 / -0.03*** ***ONTARIO SALVAGE LIMITED 29-141*** ***GEN***
21 BROADVIEW AVENUE
TORONTO ON M4M 2E4

Generator No: ON0563600 ***PO Box No:***
Status: ***Country:***
Approval Years: 94,95,96 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 5619
SIC Description: COMB. METAL PROD.

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

---

34 ***8 of 8*** ***NE/20.1*** ***78.8 / -0.03*** ***ONTARIO SALVAGE LIMITED*** ***GEN***
21 BROADVIEW AVENUE
TORONTO ON M4M 2E4

Generator No: ON0563600 ***PO Box No:***
Status: ***Country:***
Approval Years: 86,87,88,89,90 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 5619
SIC Description: COMB. METAL PROD.

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
25	1 of 1	SSE/3.3	77.2 / -1.65	ON	BORE

Borehole ID:	644952	**Inclin FLG:**	No
OGF ID:	215545335	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	NOV-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655486
Total Depth m:	8.7	**Longitude DD:**	-79.349709
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633075
Drill Method:	Power auger	**Northing:**	4834933
Orig Ground Elev m:	78.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509518	**Mat Consistency:**	Firm
Top Depth:	4	**Material Moisture:**	
Bottom Depth:	8.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			

Stratum Description: TILL,CLAY. GREY,GLACIAL,FIRM,AGE GLACIAL. 0160170240001302800130009 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218509516	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Wood Fragments	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			

Stratum Description: FILL,WOOD,SAND.

Geology Stratum ID:	218509517	**Mat Consistency:**	Stiff
Top Depth:	.4	**Material Moisture:**	
Bottom Depth:	4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			

Stratum Description: SILT,CLAY. BROWN,GLACIAL,STIFF, AGE GLACIAL.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular

Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 129740 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

26 ***1 of 1*** ***NNW/4.8*** ***79.8 / 0.97*** ***Toronto ON*** ***WWIS***

Well ID:	7310412	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	4/17/2018
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	7383
Casing Material:		**Form Version:**	7
Audit No:	Z275542	**Owner:**	
Tag:	A239167	**Street Name:**	11 SUNLIGHT PARK RD
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1007035675	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633004
Code OB Desc:		**North83:**	4835114
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/20/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Pipe Information

Pipe ID:	1007213907

Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007213911
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007213912
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1007213909
Diameter:
Depth From: 0
Depth To: 35
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

27 **1 of 1** **NE/5.7** **78.8 / -0.03** **Enbridge Gas Distribution Inc.**
45 Broadview Ave
Toronto ON M4M 2E4 **SPL**

Ref No: 2155-6K5H9S
Site No:
Incident Dt: 12/16/2005
Year:
Incident Cause: Discharge or Emission to Air
Incident Event:
Contaminant Code:
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Air Pollution; Human Health/Safety
Receiving Medium: Air
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 12/16/2005
Dt Document Closed:
Incident Reason: Other - Reason not otherwise defined
Site Name: Priv Res (unknown name) Natural Gas to ATM<UNOFFICIAL>

Discharger Report: 0
Material Group: Gases/Particulate
Health/Env Conseq:
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Toronto
Site Postal Code:
Site Region:
Site Municipality: Toronto
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: TSSA - Fuel Safety Branch
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site County/District:
Site Geo Ref Meth:
Incident Summary: TSSA: Broadview Ave-natural gas to ATM, safe @ 08:02
Contaminant Qty:

---

28 **1 of 1** **SSW/8.8** **76.9 / -1.95** **ON** **BORE**

Borehole ID:	633026	**Inclin FLG:**	No
OGF ID:	215533427	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:	FEB-1957	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655322
Total Depth m:	-999	**Longitude DD:**	-79.350805
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632987
Drill Method:		**Northing:**	4834913
Orig Ground Elev m:	78	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218464747	**Mat Consistency:**	
Top Depth:	2.8	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Granuls	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,CLAY,CINDERS. 019021033L. SAND **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218464746	**Mat Consistency:**	
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	2.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SILT(43),SAND(25), GRAVEL(20),CLAY. BROWN.		

Geology Stratum ID:	218464745	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Granuls	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			

Stratum Description: FILL,SAND,CINDERS.

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	0	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 009730 NTS_Sheet: 30M11C
Confiden 1: 00100

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

29 ***1 of 1*** ***W/9.7*** ***78.2 / -0.62*** ***ON*** ***BORE***

Borehole ID:	637126	***Inclin FLG:***	No
OGF ID:	215537523	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	FEB-1957	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.656375
Total Depth m:	9.6	***Longitude DD:***	-79.352003
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632888
Drill Method:	Diamond Drill	***Northing:***	4835028
Orig Ground Elev m:	78	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	77.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218479742	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	3.7	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Clay	***Geologic Period:***	
Material 4:	Granuls	***Depositional Gen:***	fill

Gsc Material Description:
Stratum Description: FILL,SAND,CLAY, CINDERS.

Geology Stratum ID:	218479745	***Mat Consistency:***	
Top Depth:	7.6	***Material Moisture:***	
Bottom Depth:	9.6	***Material Texture:***	

Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SHALE,CLAY,SAND. GLACIAL,LAYERED,AGE GLACIAL. 076 0000001100250050000011 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218479743	**Mat Consistency:**	
Top Depth:	3.7	**Material Moisture:**	
Bottom Depth:	6.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Peat	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,PEAT,CLAY,SAND.		

Geology Stratum ID:	218479744	**Mat Consistency:**	
Top Depth:	6.4	**Material Moisture:**	
Bottom Depth:	7.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	organic
Gsc Material Description:			
Stratum Description:	SAND,SILT,ORGANIC. FLUVIO-GLACIAL,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 050890 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

30 | ***1 of 1*** | ***ESE/10.9*** | ***78.3 / -0.59*** | ***11 Sunlight Park Road Toronto ON M4M 1B5*** | ***EHS***

Order No:	20180420136	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	18-MAY-18	**Search Radius (km):**	.25
Date Received:	20-APR-18	**X:**	-79.348625
Previous Site Name:		**Y:**	43.655835
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	1 of 1	NNW/14.3	79.8 / 0.97	Dominion Wheel & Foundry Co Ltd 131 Eastern Ave Toronto ON	TANK

Permit Date: 10/22/1920
Permit Type: BP 45881
User Type: Foundry
Installation Type: Gasoline tank
Installation Size:
Installation Config.: 1 x Gasoline tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 35
Capacity(gal):
Reference: CTA Building permits
Location Desc:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
32	1 of 6	SE/14.9	77.9 / -1.00	MINI TORONTO 20 SUNLIGHT PARK ROAD TORONTO ON M4M1B5	GEN

Generator No: ON6747824
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
32	2 of 6	SE/14.9	77.9 / -1.00	MINI TORONTO 20 SUNLIGHT PARK ROAD TORONTO ON M4M1B5	GEN

Generator No: ON6747824
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
32	3 of 6	SE/14.9	77.9 / -1.00	MINI TORONTO 20 SUNLIGHT PARK ROAD TORONTO ON M4M1B5	GEN

Generator No: ON6747824
Status:
Approval Years: 2016
Contam. Facility: No

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: GARNET SHAVER

MHSW Facility: No
Phone No Admin: 5196473729 Ext.
SIC Code: 441110
SIC Description: NEW CAR DEALERS

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

32 | ***4 of 6*** | ***SE/14.9*** | ***77.9 / -1.00*** | ***Domestic Storage & Forwarding Co Ltd*** | ***TANK***
20 Sunlight Park Rd
Toronto ON

Permit Date: 2/18/1928
Permit Type: BP A11387
User Type: Gasoline service station
Installation Type: Service station
Installation Size:
Installation Config.: Service station
No. Tanks Installed:
Units of Measure:
Value/Tank ($): 7500
Capacity(gal):
Reference: CTA Building permits
Location Desc: Eastern Ave cor Broadview

---

32 | ***5 of 6*** | ***SE/14.9*** | ***77.9 / -1.00*** | ***Domestic Storage & Forwarding Co Ltd*** | ***TANK***
20 Sunlight Park Rd
Toronto ON

Permit Date: 4/3/1928
Permit Type: BP A12201
User Type: Gasoline service station
Installation Type: Gasoline tanks
Installation Size:
Installation Config.: 2 x gasoline tanks
No. Tanks Installed: 2
Units of Measure:
Value/Tank ($): 1000
Capacity(gal):
Reference: CTA Building permits
Location Desc: Broadview Ave nw cor Eastern Ave

---

32 | ***6 of 6*** | ***SE/14.9*** | ***77.9 / -1.00*** | ***Dominion Storage & Warehouse Co*** | ***TANK***
20 Sunlight Park Rd
Toronto ON

Permit Date: 4/17/1928
Permit Type: BP A12563
User Type: Gasoline service station
Installation Type: Gasoline tanks
Installation Size:
Installation Config.: 4 x Gasoline tanks
No. Tanks Installed: 4
Units of Measure:
Value/Tank ($): 500
Capacity(gal):
Reference: CTA Building permits
Location Desc: Broadview Ave nw co Eastern Ave

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	1 of 3	NNE/15.5	79.8 / 0.97	78 Broadview Ave Toronto ON M4M2E6	EHS

Order No:	20140519026	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Site Report	**Client Prov/State:**	VA
Report Date:	20-MAY-14	**Search Radius (km):**	.001
Date Received:	19-MAY-14	**X:**	-79.349493
Previous Site Name:	Johnson Rose	**Y:**	43.657707
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	2 of 3	NNE/15.5	79.8 / 0.97	Generic Holdings Inc 68-78 Broadview Avenue Toronto ON	GEN

Generator No:	ON1844672	**PO Box No:**	
Status:		**Country:**	
Approval Years:	03,04,05,06	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
33	3 of 3	NNE/15.5	79.8 / 0.97	City Chemical & Consulting Inc. 68/78 Broadview Ave. Toronto ON M4M 2E6	GEN

Generator No:	ON8329837	**PO Box No:**	
Status:		**Country:**	
Approval Years:	04	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	325610		
SIC Description:	Soap and Cleaning Compound Manufacturing		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
35	1 of 1	WNW/21.7	79.7 / 0.83	ON	BORE

Borehole ID:	635183	**Inclin FLG:**	No
OGF ID:	215535580	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1962	**Municipality:**	
Static Water Level:	0.6	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656789
Total Depth m:	6.5	**Longitude DD:**	-79.352649
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632835
Drill Method:	Power auger	**Northing:**	4835073
Orig Ground Elev m:	76.5	**Location Accuracy:**	

Elev Reliabil Note: **Accuracy:** Not Applicable
DEM Ground Elev m: 81.7
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218472244 **Mat Consistency:** Loose
Top Depth: 0 **Material Moisture:**
Bottom Depth: 6.1 **Material Texture:** Medium
Material Color: Brown **Non Geo Mat Type:**
Material 1: Sand **Geologic Formation:**
Material 2: Silt **Geologic Group:**
Material 3: **Geologic Period:**
Material 4: **Depositional Gen:** lacustrine
Gsc Material Description:
Stratum Description: SAND(92)-MEDIUM,SILT(8). GREY,BROWN,LACUSTRINE,LOOSE, AGE GLACIAL.

Geology Stratum ID: 218472245 **Mat Consistency:**
Top Depth: 6.1 **Material Moisture:**
Bottom Depth: 6.5 **Material Texture:**
Material Color: Grey **Non Geo Mat Type:**
Material 1: Boulders **Geologic Formation:**
Material 2: Shale **Geologic Group:**
Material 3: **Geologic Period:**
Material 4: **Depositional Gen:**
Gsc Material Description:
Stratum Description: BOULDERS,SHALE. GREY,WEATHERED, WATER STABLE AT 248.9 FEET.0000000500005T.0 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Source Type: Data Survey **Source Appl:** Spatial/Tabular
Source Orig: Geological Survey of Canada **Source Iden:** 1
Source Date: 1956-1972 **Scale or Res:** Varies
Confidence: H **Horizontal:** NAD27
Observatio: **Verticalda:** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031390 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier: 1 **Horizontal Datum:** NAD27
Source Type: Data Survey **Vertical Datum:** Mean Average Sea Level
Source Date: 1956-1972 **Projection Name:** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

36 ***1 of 1*** ***SW/22.0*** ***76.7 / -2.14*** ***ON*** ***BORE***

Borehole ID: 635802 **Inclin FLG:** No
OGF ID: 215536199 **SP Status:** Initial Entry
Status: **Surv Elev:** No
Type: Borehole **Piezometer:** No
Use: Geotechnical/Geological Investigation **Primary Name:**
Completion Date: **Municipality:**
Static Water Level: **Lot:**

Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.655645
Total Depth m:	23.3	***Longitude DD:***	-79.351379
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632940
Drill Method:	Diamond Drill	***Northing:***	4834948
Orig Ground Elev m:	76.5	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	77.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218474660	***Mat Consistency:***	
Top Depth:	6.1	***Material Moisture:***	
Bottom Depth:	15.2	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474661	***Mat Consistency:***	
Top Depth:	15.2	***Material Moisture:***	
Bottom Depth:	17.4	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Shale	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SHALE,CLAY. GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474663	***Mat Consistency:***	
Top Depth:	21	***Material Moisture:***	
Bottom Depth:	23.3	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Shale	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine
Gsc Material Description:			
Stratum Description:	SHALE. MARINE,AGE ORDOVICIAN.		

Geology Stratum ID:	218474658	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2.9	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218474659	***Mat Consistency:***	
Top Depth:	2.9	***Material Moisture:***	
Bottom Depth:	6.1	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Muck	***Geologic Formation:***	

Material 2: ***Geologic Group:***
Material 3: ***Geologic Period:***
Material 4: ***Depositional Gen:***
Gsc Material Description:
Stratum Description: MUCK. LACUSTRINE,AGE POST-GLACIAL.

Geology Stratum ID: 218474662 ***Mat Consistency:***
Top Depth: 17.4 ***Material Moisture:***
Bottom Depth: 21 ***Material Texture:***
Material Color: ***Non Geo Mat Type:***
Material 1: Clay ***Geologic Formation:***
Material 2: ***Geologic Group:***
Material 3: ***Geologic Period:***
Material 4: ***Depositional Gen:*** lacustrine
Gsc Material Description:
Stratum Description: CLAY. LACUSTRINE,AGE GLACIAL.

Source

Source Type: Data Survey ***Source Appl:*** Spatial/Tabular
Source Orig: Geological Survey of Canada ***Source Iden:*** 1
Source Date: 1956-1972 ***Scale or Res:*** Varies
Confidence: M ***Horizontal:*** NAD27
Observatio: ***Verticalda:*** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 037600 NTS_Sheet: 30M11C
Confiden 1: Logs are approximately correct. Lack of information. Doubtful terminology.

Source List

Source Identifier: 1 ***Horizontal Datum:*** NAD27
Source Type: Data Survey ***Vertical Datum:*** Mean Average Sea Level
Source Date: 1956-1972 ***Projection Name:*** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

37 ***1 of 1*** ***SE/23.1*** ***77.9 / -1.02*** ***ON*** ***BORE***

Borehole ID: 635864 ***Inclin FLG:*** No
OGF ID: 215536261 ***SP Status:*** Initial Entry
Status: ***Surv Elev:*** No
Type: Borehole ***Piezometer:*** No
Use: Geotechnical/Geological Investigation ***Primary Name:***
Completion Date: FEB-1962 ***Municipality:***
Static Water Level: ***Lot:***
Primary Water Use: Not Used ***Township:***
Sec. Water Use: ***Latitude DD:*** 43.655479
Total Depth m: 9.8 ***Longitude DD:*** -79.349213
Depth Ref: Ground Surface ***UTM Zone:*** 17
Depth Elev: ***Easting:*** 633115
Drill Method: Diamond Drill ***Northing:*** 4834933
Orig Ground Elev m: 77.7 ***Location Accuracy:***
Elev Reliabil Note: ***Accuracy:*** Not Applicable
DEM Ground Elev m: 78.1
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218474903	**Mat Consistency:**	
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT. LACUSTRINE.		

Geology Stratum ID:	218474902	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL,SAND.		

Geology Stratum ID:	218474904	**Mat Consistency:**	
Top Depth:	3	**Material Moisture:**	
Bottom Depth:	9.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY. LACUSTRINE,AGE GLACIAL. AY, SAND- **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 038220 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

38 ***1 of 1*** ***SSW/25.0*** ***76.2 / -2.62*** ***Toronto ON*** ***WWIS***

Well ID:	7262475	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	5/3/2016
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	

Water Type:		**Contractor:**	7464
Casing Material:		**Form Version:**	7
Audit No:	Z202446	**Owner:**	
Tag:	A191959	**Street Name:**	DON VALLEY PKWY AND SUNLIGHT PK RD
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005958419	**Elevation:**	77.28514
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632961
Code OB Desc:		**North83:**	4834918
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/18/2015	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006067523
Layer:	2
Color:	
General Color:	
Mat1:	06
Most Common Material:	SILT
Mat2:	04
Other Materials:	PEAT
Mat3:	
Other Materials:	
Formation Top Depth:	4.6
Formation End Depth:	15.2
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006067524
Layer:	3
Color:	2
General Color:	GREY
Mat1:	34
Most Common Material:	TILL
Mat2:	05
Other Materials:	CLAY
Mat3:	42

Other Materials:	GREYWACKE
Formation Top Depth:	15.2
Formation End Depth:	22.9
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006067525
Layer:	4
Color:	2
General Color:	GREY
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	22.9
Formation End Depth:	25.9
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006067522
Layer:	1
Color:	
General Color:	
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	01
Other Materials:	FILL
Formation Top Depth:	0
Formation End Depth:	4.6
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006067532
Layer:	1
Plug From:	0
Plug To:	5.8
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1006067521
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006067528
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	9.1
Casing Diameter:	5
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1006067529
Layer:	1
Slot:	10
Screen Top Depth:	9.1
Screen End Depth:	12.1
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6

Hole Diameter

Hole ID:	1006067526
Diameter:	17.8
Depth From:	0
Depth To:	12.1
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

39 ***1 of 1*** ***W/29.3*** ***76.4 / -2.49*** ***ON*** ***BORE***

Borehole ID:	643272	***Inclin FLG:***	No
OGF ID:	215543661	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:		***Primary Name:***	
Completion Date:		***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:		***Township:***	
Sec. Water Use:		***Latitude DD:***	43.656242
Total Depth m:	9.6	***Longitude DD:***	-79.352168
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632875
Drill Method:		***Northing:***	4835013
Orig Ground Elev m:	78	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	76.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218503082	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	

Bottom Depth:	3.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Granuls	**Geologic Period:**	
Material 4:	Brick fragments	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND,CINDERS, BRICK.		

Geology Stratum ID:	218503083	**Mat Consistency:**	
Top Depth:	3.7	**Material Moisture:**	
Bottom Depth:	6.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Peat	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,PEAT,CLAY,SAND.		

Geology Stratum ID:	218503084	**Mat Consistency:**	
Top Depth:	6.7	**Material Moisture:**	
Bottom Depth:	7.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	organic
Gsc Material Description:			
Stratum Description:	SAND,SILT,ORGANIC. GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218503085	**Mat Consistency:**	
Top Depth:	7.6	**Material Moisture:**	
Bottom Depth:	9.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SHALE,GRAVEL,CLAY, SAND. BROWN,GLACIAL,LAYERED, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 112930 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	1 of 1	NNE/30.1	79.8 / 0.97	69 Broadview Ave Toronto ON M4M 2E4	TANK

Permit Date: 9/29/1932
Permit Type: BP A44665
User Type:
Installation Type: gasoline tank
Installation Size:
Installation Config.: gasoline tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 200
Capacity(gal):
Reference: CTA Building Permits
Location Desc: 69 Broadview Ave

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
41	1 of 1	WNW/30.6	79.0 / 0.17	Bayview Avenue Toronto ON	EHS

Order No: 20120507026
Status: C
Report Type: Custom Report
Report Date: 5/14/2012
Date Received: 5/7/2012 4:24:37 PM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.352468
Y: 43.657139

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	1 of 2	W/32.8	78.8 / -0.10	ON	BORE

Borehole ID: 635184
OGF ID: 215535581
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1962
Static Water Level: 0.9
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 9
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 75.3
Elev Reliabil Note:
DEM Ground Elev m: 78.2
Concession:
Location D:
Survey D:
Comments:
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.656517
Longitude DD: -79.352533
UTM Zone: 17
Easting: 632845
Northing: 4835043
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218472246
Top Depth: 0
Bottom Depth: 4.7
Material Color: Brown
Material 1: Silt
Material 2: Sand
Material 3: Clay
Material 4:
Mat Consistency: Loose
Material Moisture:
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: lacustrine

Gsc Material Description:
Stratum Description: SILT(49),SAND(28)MEDIUM,CLAY(23). GREY,BROWN,LACUSTRINE,LOOSE, AGE GLACIAL.

Geology Stratum ID: 218472247
Top Depth: 4.7
Bottom Depth: 9
Material Color: Grey
Material 1: Bedrock
Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN, WATER STABLE AT 244.0 FEET.0000000200001
**Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period: Ordovician
Depositional Gen: marine

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: H
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031400 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

42 **2 of 2** **W/32.8** **78.8 / -0.10** **ON** **BORE**

Borehole ID: 643273
OGF ID: 215543662
Status:
Type: Borehole
Use:
Completion Date:
Static Water Level:
Primary Water Use:
Sec. Water Use:
Total Depth m: 9
Depth Ref: Ground Surface
Depth Elev:
Drill Method:
Orig Ground Elev m: 75.3
Elev Reliabil Note:
DEM Ground Elev m: 78.2
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.656517
Longitude DD: -79.352533
UTM Zone: 17
Easting: 632845
Northing: 4835043
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218503086

Mat Consistency: Loose

Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND. GREY,BROWN,FLUVIO-GLACIAL, LOOSE,AGE GLACIAL.		

Geology Stratum ID:	218503087	**Mat Consistency:**	
Top Depth:	4.7	**Material Moisture:**	
Bottom Depth:	9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. AY, S **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 112940 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

43 ***1 of 2*** ***ENE/34.8*** ***78.8 / -0.03*** ***ON*** ***WWIS***

Well ID:	7287830	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	6/7/2017
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7464
Casing Material:		**Form Version:**	8
Audit No:	C37188	**Owner:**	
Tag:	A208212	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	

Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006513319	**Elevation:**	78.110679
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633173
Code OB Desc:		**North83:**	4835084
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/21/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

43 **2 of 2** **ENE/34.8** **78.8 / -0.03** **ON** **WWIS**

Well ID:	7289073	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	6/26/2017
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7464
Casing Material:		**Form Version:**	8
Audit No:	C37662	**Owner:**	
Tag:	A208212	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006575104	**Elevation:**	78.110679
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633173
Code OB Desc:		**North83:**	4835084
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/5/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
44	1 of 1	SW/35.5	76.2 / -2.63	ON	BORE

Borehole ID:	635805	**Inclin FLG:**	No
OGF ID:	215536202	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655511
Total Depth m:	24.2	**Longitude DD:**	-79.351444
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632935
Drill Method:	Diamond Drill	**Northing:**	4834933
Orig Ground Elev m:	76.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	76.6		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218474677	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218474680	**Mat Consistency:**	
Top Depth:	18.4	**Material Moisture:**	
Bottom Depth:	22.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,GRAVEL. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474681	**Mat Consistency:**	
Top Depth:	22.3	**Material Moisture:**	
Bottom Depth:	24.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	SHALE. MARINE,AGE ORDOVICIAN. GLACI **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218474679	**Mat Consistency:**	
Top Depth:	7.8	**Material Moisture:**	
Bottom Depth:	18.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	

Material 1:	Clay	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474678	**Mat Consistency:**	
Top Depth:	3	**Material Moisture:**	
Bottom Depth:	7.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY. LACUSTRINE,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 037630 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

45 | ***1 of 1*** | ***W/35.8*** | ***79.6 / 0.76*** | ***ON*** | ***BORE***

Borehole ID:	643274	**Inclin FLG:**	No
OGF ID:	215543663	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656582
Total Depth m:	-999	**Longitude DD:**	-79.352655
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632835
Drill Method:		**Northing:**	4835050
Orig Ground Elev m:	76.5	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Borehole Geology Stratum

Geology Stratum ID:	218503088	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:		***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SAND,SILT. GREY,BROWN,FLUVIO-GLACIAL, LOOSE,AGE GLACIAL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 112950 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
46	1 of 1	NNE/37.1	79.8 / 0.97	***Johnston [R A]*** ***88 Broadview Ave*** ***Toronto ON***	***TANK***

Permit Date:	8/16/1927
Permit Type:	BP A7445
User Type:	
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	500
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
47	1 of 2	WSW/38.9	76.0 / -2.84	***lot 15*** ***Toronto ON***	***WWIS***

Well ID:	7105285	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	5/20/2008
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	0	***Abandonment Rec:***	
Water Type:		***Contractor:***	6946
Casing Material:		***Form Version:***	7
Audit No:	Z86681	***Owner:***	
Tag:	A010069	***Street Name:***	77279 EAST DOON ROADWAY

Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	015
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1001597859	***Elevation:***	75.914222
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632896
Code OB Desc:		***North83:***	4834973
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	5/6/2008	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1001791076
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	84
Other Materials:	SILTY
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	3
Formation End Depth:	4.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1001791077
Layer:	3
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	4.5
Formation End Depth:	6.05
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1001791075
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	01
Other Materials:	FILL
Mat3:	11
Other Materials:	GRAVEL
Formation Top Depth:	0
Formation End Depth:	3
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1001791082
Layer:	3
Plug From:	0.3
Plug To:	0.1
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1001791080
Layer:	1
Plug From:	5.95
Plug To:	2.9
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1001791081
Layer:	2
Plug From:	2.9
Plug To:	0.3
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1001791074
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1001791084
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	5.95
Casing Diameter:	5.2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1001791085
Layer:	1
Slot:	10
Screen Top Depth:	2.95
Screen End Depth:	5.95
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	5.6

Water Details

Water ID:	1001791083
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	2.96
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1001791079
Diameter:	11.5
Depth From:	0.03
Depth To:	5.95
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1001791078
Diameter:	16.7
Depth From:	0
Depth To:	0.3
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

47 ***2 of 2*** ***WSW/38.9*** ***76.0 / -2.84*** ***ON*** ***WWIS***

Well ID:	7160900	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	3/29/2011
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	6946
Casing Material:		***Form Version:***	7
Audit No:	Z122578	***Owner:***	

Tag:	A094485	***Street Name:***	77275 EAST DONE RD WAY
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003491454	***Elevation:***	75.944221
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632896
Code OB Desc:		***North83:***	4834973
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	2/23/2011	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003842948
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	05
Other Materials:	CLAY
Formation Top Depth:	3.1
Formation End Depth:	3.8
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1003842947
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	81
Other Materials:	SANDY
Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	2.3
Formation End Depth:	3.1

Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003842946
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Other Materials: GRAVEL
Mat3: 77
Other Materials: LOOSE
Formation Top Depth: 1.5
Formation End Depth: 2.3
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003842949
Layer: 5
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 81
Other Materials: SANDY
Mat3: 66
Other Materials: DENSE
Formation Top Depth: 3.8
Formation End Depth: 5.3
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1003842945
Layer: 1
Color: 6
General Color: BROWN
Mat1:
Most Common Material:
Mat2:
Other Materials:
Mat3: 77
Other Materials: LOOSE
Formation Top Depth: 0
Formation End Depth: 1.5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1003842959
Layer: 2
Plug From: 2.8
Plug To: 0.3
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1003842958
Layer:	1
Plug From:	4.57
Plug To:	2.8
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1003842960
Layer:	3
Plug From:	0.3
Plug To:	0
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1003842944
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003842953
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	3
Casing Diameter:	5.2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003842954
Layer:	1
Slot:	10
Screen Top Depth:	3
Screen End Depth:	4.57
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03

Water Details

Water ID:	1003842952
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	3.15
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1003842951

Diameter: 11.4
Depth From: 0.3
Depth To: 4.57
Hole Depth UOM: m
Hole Diameter UOM: cm

Hole Diameter

Hole ID: 1003842950
Diameter: 15.2
Depth From: 0
Depth To: 3
Hole Depth UOM: m
Hole Diameter UOM: cm

---

48 | **1 of 11** | **N/39.3** | **79.8 / 0.97** | **859587 ONT. LTD., O/A. ATLANTIC INTL.**
68 BROADVIEW AVENUE
TORONTO CITY ON M4M 2E6 | **CA**

Certificate #: 8-3629-95-966
Application Year: 95
Issue Date: 4/1/96
Approval Type: Industrial air
Status: Received in 1995, Issued in 1996
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: PAINT SPRAY BOOTH FOR AUTO BODY SHOP
Contaminants: Xylene, Toluene(Pentyl Methane)(Methyl Benzene), N-Butyl Acetate, Methyl Ethyl Ketone (Butanone), Methyl Isobutyl Ketone, Ethyl Acetate, Other Organic Compounds
Emission Control: Panel Filter

---

48 | **2 of 11** | **N/39.3** | **79.8 / 0.97** | **859587 ONT. LTD., O/A. ATLANTIC INTL.**
68 BROADVIEW AVENUE
TORONTO CITY ON M4M 2E6 | **CA**

Certificate #: 8-3629-95-000
Application Year: 95
Issue Date: 2/21/96
Approval Type: Industrial air
Status: Application Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: SEE 1079645 ONT. LTD. PAIT SPRAY BOOTH
Contaminants: Xylene, Toluene(Pentyl Methane)(Methyl Benzene), N-Butyl Acetate, Methyl Ethyl Ketone (Butanone), Methyl Isobutyl Ketone, Ethyl Acetate, Other Organic Compounds
Emission Control: Panel Filter

---

48 | **3 of 11** | **N/39.3** | **79.8 / 0.97** | **859587 Ont. Ltd., O/A. Atlantic Intl.**
68 BROADVIEW AVENUE, TORONTO CITY
Toronto
ON | **EBR**

EBR Registry No: IA6E0141
Ministry Ref No: 8362995
Notice Type: Instrument Decision
Decision Posted:
Exception Posted:
Section:

Notice Stage: 800471131
Notice Date: August 02, 2001
Proposal Date: February 09, 1996
Year: 1996
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: 859587 Ont. Ltd., O/A. Atlantic Intl.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 221 N.Rivermede Rd.#7, Concord Ontario, L4K 3N7
Comment Period:
URL:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

68 BROADVIEW AVENUE, TORONTO CITY Toronto

---

48 | **4 of 11** | **N/39.3** | **79.8 / 0.97** | **68 Broadview Ave, Toronto ON M4M 2E6** | **EHS**

Order No: 20030325007
Status: C
Report Type: Custom Report
Report Date: 4/3/03
Date Received: 3/25/03
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 1.00
X: -79.349365
Y: 43.657475

---

48 | **5 of 11** | **N/39.3** | **79.8 / 0.97** | **68 Broadview Ave, Toronto ON M4M 2E6** | **EHS**

Order No: 20000316001
Status: C
Report Type: Complete Report
Report Date: 3/21/00
Date Received: 3/17/00
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection: Broadview and Eastern
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.349365
Y: 43.657475

---

48 | **6 of 11** | **N/39.3** | **79.8 / 0.97** | **METROPOLITAN SUPPLIES LTD., 68 BROADVIEW AVENUE, SUITE 511, TORONTO ON M4M 2E6** | **GEN**

Generator No: ON2315500
Status:
Approval Years: 97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 9999
SIC Description: OTHER SERVICES
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	7 of 11	N/39.3	79.8 / 0.97	Generic Holdings Inc. 68 BROADVIEW AVE, TORONTO, ON, M4M 2E6 Toronto ON M4M 2E6	RSC

RSC ID: 2089
RA No:
RSC Type:
Curr Property Use: Commercial
Ministry District: TORONTO
Filing Date: 12-Apr-06
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686: No

Cert Date: 11-Feb-04
Cert Prop Use No: No CPU
Intended Prop Use: Residential
Qual Person Name: Greg Tanzola
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N): Yes
Accuracy Estimate: 6 to 10 meters
Telephone: 905-8508508x260
Fax: 905-8506166
Email: gtanzola@sorbaragroup.com

Asmt Roll No: 1904-07-1-220-03200/03300
Prop ID No (PIN): 21077-0181 and 21077-0190
Property Municipal Address: 68 BROADVIEW AVE, TORONTO, ON, M4M 2E6
Mailing Address: Suite 800, 3700 STEELES AVE W, WOODBRIDGE, ON, L4L 8M9
Latitude & Latitude: 43.65750000N 79.35027780W
UTM Coordinates: NAD83 17-633024-4835156 (converted from Latitude & Longitude)
Consultant:
Filing Owner:
Legal Desc: Part of Lot 15, Broken Front Concession designated as Parts 1, 2, 3, 4, 5 and 6 on Plan 66R20522, City of Toronto, together with a right of way over parts 7 & 8 on Plan 66R20522 in favour of Parts 1, 2, 3, 4, and 5 on Plan 66R20522 as in CA706651, subject to a right of way over parts 3, 4, and 5 on Plan 66R20522 as in A924818, CA706651, 61506ES, CA778170 and CA 778171 and Part Lot 15, broken front concession, Township of York, part of Eastern Avenue Diversion closed by By-Law 56-2004 as in AT414318, designated as Part 1 on Plan 66R-21410 City of Toronto
Measurement Method: Global Positioning System
Applicable Standards: Full Depth Site Conditions Standard, with Nonpotable Ground Water, Coarse Textured Soil, for Residential/Parkland/Institutional property use
RSC PDF:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	8 of 11	N/39.3	79.8 / 0.97	GORD MILLER DISPLAY LTD. 68 BROADVIEW AVE FLOOR 3 TORONTO ON M4M 2E6	SCT

Established: 1961
Plant Size (ft²): 5000
Employment: 5

--Details--
Description: AUTOMOTIVE TRIMMINGS, APPAREL FINDINGS, AND RELATED PRODUCTS
SIC/NAICS Code: 2396

Description: COMMERCIAL PRINTING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2759

Description: Textile and Fabric Finishing
SIC/NAICS Code: 313310

Description: Commercial Screen Printing
SIC/NAICS Code: 323113

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
48	9 of 11	N/39.3	79.8 / 0.97	JINX SENIOR CREATIONS INC. 68 BROADVIEW AVE TORONTO ON M4M 2E6	SCT

Established: 1984
Plant Size (ft²): 4000
Employment: 12

--Details--
Description: KNIT OUTERWEAR MILLS
SIC/NAICS Code: 2253

Description: WOMEN'S, MISSES', AND JUNIORS' SUITS, SKIRTS, AND COATS
SIC/NAICS Code: 2337

Description: Other Clothing Knitting Mills
SIC/NAICS Code: 315190

Description: Women's and Girls' Cut and Sew Suit, Coat, Tailored Jacket and Skirt Manufacturing
SIC/NAICS Code: 315234

Description: Other Women's and Girls' Cut and Sew Clothing Manufacturing
SIC/NAICS Code: 315239

48	10 of 11	N/39.3	79.8 / 0.97	United Drug Co 68 Broadview Ave Toronto ON M4M 2E6	TANK

Permit Date: 7/13/1934
Permit Type: BP A52021
User Type: Drugs manufacturer?
Installation Type: gasoline tank
Installation Size:
Installation Config.: gasoline tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 300
Capacity(gal):
Reference: CTA Building Permits
Location Desc: 68 Broadview Ave

48	11 of 11	N/39.3	79.8 / 0.97	United Drug Co 68 Broadview Ave Toronto ON M4M 2E6	TANK

Permit Date: 9/14/1928
Permit Type: BP A16924
User Type: Drugs manufacturer?
Installation Type: Fuel oil tank
Installation Size:
Installation Config.: 1 x fuel oil tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 200
Capacity(gal):
Reference: CTA Building permits
Location Desc:

49	1 of 1	NW/46.3	79.8 / 0.97	ON	WWIS

Well ID: 7287668
Construction Date:
Primary Water Use:
Data Entry Status: Yes
Data Src:
Date Received: 6/5/2017

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	8
Audit No:	C37476	**Owner:**	
Tag:	A203037	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006505986	**Elevation:**	80.155281
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632894
Code OB Desc:		**North83:**	4835139
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	4/19/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

50 ***1 of 1*** ***NNW/46.9*** ***80.0 / 1.12*** ***TORONTO ON*** ***WWIS***

Well ID:	7183714	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	7/6/2012
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z150820	**Owner:**	
Tag:	A131030	**Street Name:**	677 QUEEN ST E
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	WKQ-004975 A0-A02
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003965056	**Elevation:**	80.038215

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632966.26
Code OB Desc:		**North83:**	4835154.46
Open Hole:		**Org CS:**	N27a
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/22/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004345537
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	5
Formation End Depth:	12
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004345538
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	12
Formation End Depth:	15
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004345536
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Other Materials:	SAND
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0

Formation End Depth: 5
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004345549
Layer: 3
Plug From: 4
Plug To: 15
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004345548
Layer: 2
Plug From: 1
Plug To: 4
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004345547
Layer: 1
Plug From: 0
Plug To: 1
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1004345535
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004345541
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 5
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Casing

Casing ID: 1004345542

Layer:	2
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004345543
Layer:	1
Slot:	10
Screen Top Depth:	5
Screen End Depth:	15
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Hole Diameter

Hole ID:	1004345539
Diameter:	8
Depth From:	0
Depth To:	15
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

51 | ***1 of 1*** | ***SE/47.0*** | ***78.5 / -0.40*** | ***1 to 11 Sunlight Park Road, 341, 353, 361 Eastern Avenue, 356 Eastern Avenue Toronto ON*** | ***EHS***

Order No:	20180307108	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	03-APR-18	**Search Radius (km):**	.25
Date Received:	07-MAR-18	**X:**	-79.348805
Previous Site Name:		**Y:**	43.655394
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

---

52 | ***1 of 1*** | ***WNW/47.3*** | ***79.4 / 0.51*** | ***Toronto ON*** | ***WWIS***

Well ID:	7281540	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	2/23/2017
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	6032
Casing Material:		**Form Version:**	7
Audit No:	Z229059	**Owner:**	
Tag:	A201454	**Street Name:**	EAST DON ROADWAY
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	

Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1006356045	***Elevation:***	78.693847
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632848
Code OB Desc:		***North83:***	4835129
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	8/24/2016	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006595516
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	12
Other Materials:	STONES
Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	0.6
Formation End Depth:	3
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006595519
Layer:	5
Color:	2
General Color:	GREY
Mat1:	17
Most Common Material:	SHALE
Mat2:	05
Other Materials:	CLAY
Mat3:	74
Other Materials:	LAYERED
Formation Top Depth:	25
Formation End Depth:	217
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006595517
Layer:	3

Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	3
Formation End Depth:	12.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006595515
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	12
Other Materials:	STONES
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	0
Formation End Depth:	0.6
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006595518
Layer:	4
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	85
Other Materials:	SOFT
Formation Top Depth:	12.5
Formation End Depth:	25
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006595529
Layer:	3
Plug From:	142
Plug To:	20
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006595527
Layer:	1
Plug From:	217
Plug To:	165

Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006595528
Layer: 2
Plug From: 161
Plug To: 159
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006595530
Layer: 4
Plug From: 53
Plug To: 1
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 6
Method Construction: Boring
Other Method Construction: DIAMOND

Pipe Information

Pipe ID: 1006595514
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006595523
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 149
Depth To: 0
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006595524
Layer: 1
Slot: 10
Screen Top Depth: 159
Screen End Depth: 149
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2

Hole Diameter

Hole ID: 1006595520
Diameter: 8
Depth From: 0
Depth To: 25
Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole Diameter

Hole ID: 1006595521
Diameter: 4
Depth From: 25
Depth To: 217
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

53 | ***1 of 2*** | ***WNW/54.1*** | ***79.7 / 0.80*** | ***77 & 79 EDR Inc.***
77 East Don Roadway (Western Retained Portion) Toronto, ON M4M 2A5 Canada
ON | ***CPU***

EBR Registry No: 019-0203
Ministry Ref No: 0344-AE3QJ3
Notice Type: Instrument
Notice Stage: Decision
Notice Date:
Proposal Date: June 18, 2019
Year: 2019
Instrument Type: Certificate of Property Use (EPA s. 168.6)
Off Instrument Name: Certificate of Property Use (EPA s. 168.6)
Posted By: Ministry of the Environment, Conservation and Parks
Company Name:
Site Address: 77 East Don Roadway (Western Retained Portion)
Toronto,
ON
M4M 2A5
Canada
Location Other:
Proponent Name: 77 & 79 EDR Inc.
Proponent Address: 1230 Dundas Street East
Toronto,
ON
M4M 1S3
Canada
Comment Period: June 18, 2019 - July 18, 2019 (30 days) Closed
URL: https://ero.ontario.ca/notice/019-0203

Site Location Details:

Decision Posted: September 12, 2019
Exception Posted:
Section: Section 168.6
Act 1: Environmental Protection Act, R.S.O. 1990
Act 2: Environmental Protection Act
Site Location Map: 43.657641,-79.353009

---

53 | ***2 of 2*** | ***WNW/54.1*** | ***79.7 / 0.80*** | ***77 East Don Roadway***
n/a ON M4M 2A5 | ***EHS***

Order No: 20070825011w
Status: C
Report Type: CAN - Online Mapless
Report Date: 8/25/2007
Date Received: 8/25/2007
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State:
Search Radius (km): 0.25
X:
Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

54 1 of 1 NW/54.9 79.8 / 0.91 ON WWIS

Well ID:	7267032	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	7/19/2016
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	8
Audit No:	C31965	**Owner:**	
Tag:	A197177	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006149682	**Elevation:**	80.271186
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632882
Code OB Desc:		**North83:**	4835145
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	1/28/2016	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

55 1 of 1 ENE/59.0 78.8 / -0.03 CARSTAR TORONTO EASTERN AVE INC.
344 EASTERN AVE
TORONTO ON M4M 3G5 EASR

Approval No:	R-001-6413256151	**SWP Area Name:**	Toronto
Status:	REGISTERED	**MOE District:**	Metro Toronto
Date:	2014-04-17	**Municipality:**	TORONTO
Record Type:	EASR	**Latitude:**	43.65666667
Link Source:	MOFA	**Longitude:**	-79.34777778
Project Type:	Automotive Refinishing Facility	**Geometry X:**	
Full Address:		**Geometry Y:**	
Approval Type:	EASR-Automotive Refinishing Facility		
Full PDF Link:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=6765		

56 1 of 1 W/59.2 75.8 / -3.03 ENBRIDGE GAS INC
ON EASR

Approval No:	R-009-1111465284	**SWP Area Name:**	Toronto

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	REGISTERED	**MOE District:**	Metro Toronto
Date:	2019-07-23	**Municipality:**	
Record Type:	EASR	**Latitude:**	43.65611111
Link Source:	MOFA	**Longitude:**	-79.3525
Project Type:	Water Taking - Construction Dewatering	**Geometry X:**	-8833479.8932
Full Address:		**Geometry Y:**	5412377.9011999965
Approval Type:	EASR-Water Taking - Construction Dewatering		
Full PDF Link:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2170061		

---

57 | ***1 of 1*** | ***WNW/60.2*** | ***79.2 / 0.29*** | ***ON*** | ***WWIS***

Well ID:	7221338	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	6/4/2014
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	8
Audit No:	C26040	**Owner:**	
Tag:	A159751	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004801232	**Elevation:**	78.170486
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632821
Code OB Desc:		**North83:**	4835132
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	4/17/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

58 | ***1 of 1*** | ***W/62.1*** | ***76.0 / -2.86*** | ***ON*** | ***BORE***

Borehole ID:	635189	**Inclin FLG:**	No
OGF ID:	215535586	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1962	**Municipality:**	
Static Water Level:	2.1	**Lot:**	
Primary Water Use:	Not Used	**Township:**	

Sec. Water Use:		***Latitude DD:***	43.656433
Total Depth m:	21.1	***Longitude DD:***	-79.352907
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632815
Drill Method:	Power auger	***Northing:***	4835033
Orig Ground Elev m:	76.9	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	78.8		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472267	***Mat Consistency:***	Soft
Top Depth:	12.2	***Material Moisture:***	
Bottom Depth:	15.8	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	organic material	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,ORGANIC. BROWN,LACUSTRINE,SOFT, AGE GLACIAL.		

Geology Stratum ID:	218472269	***Mat Consistency:***	
Top Depth:	18	***Material Moisture:***	
Bottom Depth:	21.1	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. 053 0000000200050004005200580006 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472264	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	1.5	***Material Texture:***	
Material Color:	Black	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Granuls	***Geologic Group:***	
Material 3:	Coal fragments	***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,CINDERS,COAL. BLACK,LOOSE.		

Geology Stratum ID:	218472266	***Mat Consistency:***	
Top Depth:	3	***Material Moisture:***	
Bottom Depth:	12.2	***Material Texture:***	Medium
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SAND(79)-MEDIUM,SILT(21). GREY,BROWN,LACUSTRINE,BEDDED, AGE GLACIAL, WATER STABLE AT 245.5 FEET.		

Geology Stratum ID:	218472268	***Mat Consistency:***	Stiff
Top Depth:	15.8	***Material Moisture:***	
Bottom Depth:	18	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	

Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT. GREY,GLACIAL,STIFF, AGE NON-GLACIAL.		

Geology Stratum ID:	218472265	**Mat Consistency:**	Soft
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,CLAY,SILT,SAND.VARI-COLOURED,SOFT.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031450 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

59 | ***1 of 1*** | ***NNW/65.2*** | ***80.5 / 1.63*** | ***TORONTO ON*** | ***WWIS***

Well ID:	7183715	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	7/6/2012
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z150819	**Owner:**	
Tag:	A131029	**Street Name:**	677 QUEEN ST E
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	WKQ-004975 A0-A02
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003965059	***Elevation:***	80.10144
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632944.26
Code OB Desc:		***North83:***	4835170.46
Open Hole:		***Org CS:***	N27a
Cluster Kind:		***UTMRC:***	3
Date Completed:	5/22/2012	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004345552
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	5
Formation End Depth:	13
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004345551
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Other Materials:	SAND
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0
Formation End Depth:	5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004345553
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT

Mat3: 91
Other Materials: WATER-BEARING
Formation Top Depth: 13
Formation End Depth: 17
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004345563
Layer: 3
Plug From: 6
Plug To: 17
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004345562
Layer: 2
Plug From: 1
Plug To: 6
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004345561
Layer: 1
Plug From: 0
Plug To: 1
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: B
Method Construction: Other Method
Other Method Construction: DIRECT PUSH

Pipe Information

Pipe ID: 1004345550
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004345556
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 7
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID:	1004345557
Layer:	1
Slot:	10
Screen Top Depth:	7
Screen End Depth:	17
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Hole Diameter

Hole ID:	1004345554
Diameter:	8
Depth From:	0
Depth To:	17
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

60 ***1 of 1*** ***W/66.4*** ***76.1 / -2.79*** ***ON*** ***BORE***

Borehole ID:	635190	***Inclin FLG:***	No
OGF ID:	215535587	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	FEB-1962	***Municipality:***	
Static Water Level:	1.9	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.656616
Total Depth m:	18.9	***Longitude DD:***	-79.35315
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632795
Drill Method:	Power auger	***Northing:***	4835053
Orig Ground Elev m:	76.7	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	80		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472273	***Mat Consistency:***	
Top Depth:	16.1	***Material Moisture:***	
Bottom Depth:	18.9	***Material Texture:***	
Material Color:	Green	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREEN,MARINE,AGE ORDOVICIAN. 0000000800080004004650230000 6LAC **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472270	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2.4	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	

Material 1:	Fill	**Geologic Formation:**	
Material 2:	Granuls	**Geologic Group:**	
Material 3:	Bedrock	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,CINDERS,BEDROCKLOOSE.		

Geology Stratum ID:	218472272	**Mat Consistency:**	Stiff
Top Depth:	14.2	**Material Moisture:**	
Bottom Depth:	16.1	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Shale	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SHALEGREY,GLACIAL,STIFF, AGE NON-GLACIAL.		

Geology Stratum ID:	218472271	**Mat Consistency:**	
Top Depth:	2.4	**Material Moisture:**	
Bottom Depth:	14.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. GREY,BROWN,LACUSTRINE,BEDDED, AGE GLACIAL, WATER STABLE AT 245.3 FEET.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031460 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

61 | ***1 of 1*** | ***ENE/68.4*** | ***78.8 / -0.03*** | ***12 Lewis Street Toronto ON M4M 2H3*** | ***EHS***

Order No:	20050408010	**Nearest Intersection:**	Eastern Ave. & Lewis St.
Status:	C	**Municipality:**	
Report Type:		**Client Prov/State:**	ON
Report Date:	4/18/2005	**Search Radius (km):**	0.25
Date Received:	4/8/2005	**X:**	-79.347813
Previous Site Name:		**Y:**	43.656946
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
62	1 of 1	W/70.3	76.1 / -2.75	ON	BORE

Borehole ID: 635176
OGF ID: 215535573
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: DEC-1961
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 6.6
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Orig Ground Elev m: 73.6
Elev Reliabil Note:
DEM Ground Elev m: 79
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.656798
Longitude DD: -79.353269
UTM Zone: 17
Easting: 632785
Northing: 4835073
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218472228
Top Depth: 2.5
Bottom Depth: 6.6
Material Color: Brown
Material 1: Bedrock
Material 2: Shale
Material 3: Limestone
Material 4:
Gsc Material Description:
Stratum Description: BEDROCK,SHALE, LIMESTONE. BROWN,GREY,MARINE, AGE ORDOVICIAN. 012 00000004 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period: Ordovician
Depositional Gen: marine

Geology Stratum ID: 218472227
Top Depth: 0
Bottom Depth: 2.5
Material Color: Grey
Material 1: Sand
Material 2: organic material
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SAND(99)-MEDIUM, ORGANIC(1). GREY,LACUSTRINE,LOOSE, AGE GLACIAL.

Mat Consistency: Loose
Material Moisture:
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: lacustrine

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: H
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031320 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Horizontal Datum: NAD27

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

63 | ***1 of 5*** | ***N/71.0*** | ***79.8 / 0.97*** | ***90 BROADVIEW INC.***
00090 BROADVIEW AVE, TORONTO, ON, M4P 1T4
ON | ***RSC***

RSC ID:	98117	**Cert Date:**	15-Dec-10
RA No:		**Cert Prop Use No:**	No CPU
RSC Type:		**Intended Prop Use:**	Residential
Curr Property Use:	Commercial	**Qual Person Name:**	CHRIS HARHAY
Ministry District:	TORONTO	**Stratified (Y/N):**	
Filing Date:	24-Feb-11	**Audit (Y/N):**	
Date Ack:		**Entire Leg Prop. (Y/N):**	Yes
Date Returned:		**Accuracy Estimate:**	21 to 100 meters
Restoration Type:		**Telephone:**	416-6267141
Soil Type:		**Fax:**	416-6207392
Criteria:		**Email:**	charhay@hcml.ca
CPU Issued Sect 1686:	No		

Asmt Roll No:	19 04 071 220 03100 0000
Prop ID No (PIN):	21077 - 0127 LT
Property Municipal Address:	00090 BROADVIEW AVE, TORONTO, ON, M4P 1T4
Mailing Address:	540 RICHMOND ST W, TORONTO, ON, M5V 1Y4
Latitude & Latitude:	43.65785250N 79.35007450W (converted from UTM)
UTM Coordinates:	NAD83 17-633040-4835195
Consultant:	
Filing Owner:	
Legal Desc:	PT LT 15 CON BROKEN FRONT TWP OF YORK AS IN ES59320 S/T ES59320 EXCEPT THE EASEMENT THEREIN; CITY OF TORONTO
Measurement Method:	Digitized from a map
Applicable Standards:	Full Depth Site Conditions Standard, with Nonpotable Ground Water, Medium/Fine Textured Soil, for Residential/Parkland/Institutional property use
RSC PDF:	

---

63 | ***2 of 5*** | ***N/71.0*** | ***79.8 / 0.97*** | ***Coca Cola Co of Canada Ltd***
90 Broadview Ave
Toronto ON | ***TANK***

Permit Date:	5/21/1936
Permit Type:	BP A59704
User Type:	Beverages
Installation Type:	gasoline tank
Installation Size:	
Installation Config.:	gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	25
Capacity(gal):	
Reference:	CTA Building Permits
Location Desc:	90 Broadview Ave

---

63 | ***3 of 5*** | ***N/71.0*** | ***79.8 / 0.97*** | ***Coca Cola Co of Canada Ltd***
90 Broadview Ave
Toronto ON | ***TANK***

Permit Date:	12/19/1923
Permit Type:	BP 76293
User Type:	Beverages

Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	450
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	

---

63 | ***4 of 5*** | ***N/71.0*** | ***79.8 / 0.97*** | ***Coca Cola Co of Canada Ltd*** | ***TANK***

90 Broadview Ave
Toronto ON

Permit Date:	7/18/1930
Permit Type:	BP A31563
User Type:	Beverages
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	200
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	

---

63 | ***5 of 5*** | ***N/71.0*** | ***79.8 / 0.97*** | ***Coca Cola Co of Canada Ltd*** | ***TANK***

90 Broadview Ave
Toronto ON

Permit Date:	7/7/1930
Permit Type:	BP A31263
User Type:	Beverages
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	1200
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	

---

64 | ***1 of 1*** | ***SW/72.5*** | ***75.8 / -3.03*** | ***ON*** | ***BORE***

Borehole ID:	635804	**Inclin FLG:**	No
OGF ID:	215536201	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655428
Total Depth m:	34.1	**Longitude DD:**	-79.351943
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632895
Drill Method:	Diamond Drill	**Northing:**	4834923

Orig Ground Elev m:	76.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	77.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218474669	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218474671	**Mat Consistency:**	
Top Depth:	6.9	**Material Moisture:**	
Bottom Depth:	9.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474675	**Mat Consistency:**	
Top Depth:	26.4	**Material Moisture:**	
Bottom Depth:	31.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474672	**Mat Consistency:**	
Top Depth:	9.6	**Material Moisture:**	
Bottom Depth:	21	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474674	**Mat Consistency:**	
Top Depth:	24.8	**Material Moisture:**	
Bottom Depth:	26.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474670	**Mat Consistency:**	
Top Depth:	4.9	**Material Moisture:**	
Bottom Depth:	6.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474673	**Mat Consistency:**	
Top Depth:	21	**Material Moisture:**	
Bottom Depth:	24.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474676	**Mat Consistency:**	
Top Depth:	31.1	**Material Moisture:**	
Bottom Depth:	34.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	SHALE. MARINE,AGE ORDOVICIAN.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 037620 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

65 ***1 of 1*** ***WNW/72.8*** ***79.3 / 0.39*** ***ON*** ***BORE***

Borehole ID:	635177	**Inclin FLG:**	No
OGF ID:	215535574	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1962	**Municipality:**	
Static Water Level:	0.8	**Lot:**	

Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657068
Total Depth m:	7.7	**Longitude DD:**	-79.353262
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632785
Drill Method:	Power auger	**Northing:**	4835103
Orig Ground Elev m:	75.6	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	76.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472229	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT(55),SAND(30)MEDIUM,CLAY(15). GREY,LACUSTRINE,LOOSE, AGE GLACIAL.		

Geology Stratum ID:	218472230	**Mat Consistency:**	
Top Depth:	4.3	**Material Moisture:**	
Bottom Depth:	7.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:	Limestone	**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE, LIMESTONE. BROWN,GREY,MARINE, AGE ORDOVICIAN, WATER STABLE AT 245.4 FEET.00000004 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031330 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

66	1 of 1	WNW/73.2	79.5 / 0.62	ON	BORE

Borehole ID:	643278	**Inclin FLG:**	No
OGF ID:	215543667	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657247
Total Depth m:	5.5	**Longitude DD:**	-79.353145
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632794
Drill Method:		**Northing:**	4835123
Orig Ground Elev m:	77.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.5		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218503101	**Mat Consistency:**	Firm
Top Depth:	2.4	**Material Moisture:**	
Bottom Depth:	5.5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SILT. GREY,BROWN,GLACIAL,FIRM, AGE GLACIAL.		

Geology Stratum ID:	218503102	**Mat Consistency:**	
Top Depth:	5.5	**Material Moisture:**	
Bottom Depth:	5.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. MARINE,AGE ORDOVICIAN.		

Geology Stratum ID:	218503100	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,ORGANIC. BROWN.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		

Source Details: File: TOR2.txt RecordID: 112990 NTS_Sheet: 30M11C
Confiden 1: Logs are approximately correct. Lack of information. Doubtful terminology.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

67 | **1 of 4** | **E/73.5** | **78.8 / -0.03** | **353 Eastern Avenue Toronto ON M4M 1B7** | **EHS**

Order No: 20180522193
Status: C
Report Type: Standard Report
Report Date: 29-MAY-18
Date Received: 22-MAY-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Aerial Photos
Nearest Intersection:
Municipality:
Client Prov/State: BC
Search Radius (km): .25
X: -79.347538
Y: 43.656218

---

67 | **2 of 4** | **E/73.5** | **78.8 / -0.03** | **WILD WALLS INC. 41-281 353 EASTERN AVE, UNIT 105 TORONTO ON M4M 1B7** | **GEN**

Generator No: ON1052400
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 2699
SIC Description: OTHER FURN. & FIXT.
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

67 | **3 of 4** | **E/73.5** | **78.8 / -0.03** | **WILD WALLS INC. 353 EASTERN AVE, UNIT 105 TORONTO ON M4M 1B7** | **GEN**

Generator No: ON1052400
Status:
Approval Years: 88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 2699
SIC Description: OTHER FURN. & FIXT.
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
67	4 of 4	E/73.5	78.8 / -0.03	Walter Klassen FX 353 Eastern Ave, un 107 Toronto ON M4M 1B7	GEN

Generator No: ON4292062
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

68	1 of 20	SE/75.1	78.8 / -0.03	LEVERBROS TORONTO ON	NEES

Incident Date: 5/27/87
Contaminant: sodium ethyl sulfate
Amount: 0.4
Units: Tonnes (Metric)
Quantity:
Cause: Overflow
Source: Other Storage Facilities
Reason: Equipment Failure
Sector: General Manufacturing

68	2 of 20	SE/75.1	78.8 / -0.03	LEVERDETERGENTS TORONTO ON	NEES

Incident Date: 9/28/83
Contaminant: animal fat
Amount: 1.8
Units: Tonnes (Metric)
Quantity:
Cause: Valve, Fitting Leak
Source: Other Industrial Plant
Reason: Material Failure
Sector: General Manufacturing

68	3 of 20	SE/75.1	78.8 / -0.03	LEVERBROS TORONTO ON	NEES

Incident Date: 5/29/87
Contaminant: coal
Amount:
Units:
Quantity:
Cause: Pipe Leak
Source: Other Industrial Plant
Reason: Material Failure
Sector: General Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	4 of 20	SE/75.1	78.8 / -0.03	LEVERDETERGENTS TORONTO ON	NEES

Incident Date:	9/27/84
Contaminant:	glycerol
Amount:	0.57
Units:	Tonnes (Metric)
Quantity:	
Cause:	Discharge
Source:	Tank Truck
Reason:	Error
Sector:	General Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	5 of 20	SE/75.1	78.8 / -0.03	LEVER BROS. TORONTO CITY (EAST OF YON ON	NEES

Incident Date:	1/5/88
Contaminant:	PROPYLENE GLYCOL
Amount:	9
Units:	Tonnes (Metric)
Quantity:	
Cause:	Pipe Leak
Source:	Other Industrial Plant
Reason:	Equipment Failure
Sector:	Chemical

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	6 of 20	SE/75.1	78.8 / -0.03	LEVERDETERGENT TORONTO ON	NEES

Incident Date:	11/25/83
Contaminant:	surfactant
Amount:	0.2
Units:	Tonnes (Metric)
Quantity:	
Cause:	Container Leak
Source:	Other Industrial Plant
Reason:	Damage by Equipment
Sector:	General Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	7 of 20	SE/75.1	78.8 / -0.03	LEVER TORONTO ON	NEES

Incident Date:	2/20/85
Contaminant:	sulfuric acid
Amount:	6.2
Units:	Tonnes (Metric)
Quantity:	
Cause:	Above Ground Tank Leak
Source:	Other Industrial Plant
Reason:	Material Failure
Sector:	General Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	8 of 20	SE/75.1	78.8 / -0.03	LEVERBROS TORONTO ON	NEES

Incident Date: 5/29/87
Contaminant: surfactant
Amount: 4
Units: Tonnes (Metric)
Quantity:
Cause: Pipe Leak
Source: Other Industrial Plant
Reason: Material Failure
Sector: General Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	9 of 20	SE/75.1	78.8 / -0.03	LEVERDETERGENTS TORONTO ON	NEES

Incident Date: 6/11/83
Contaminant: pcb
Amount:
Units:
Quantity:
Cause: Cooling System Leak
Source: Other Industrial Plant
Reason: Damage by Equipment
Sector: General Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	10 of 20	SE/75.1	78.8 / -0.03	LEVERDETERGENTSLTD TORONTO ON	NEES

Incident Date: 12/7/76
Contaminant: fuming sulfuric acid
Amount: 4.5
Units: Tonnes (Metric)
Quantity:
Cause: Pipe Leak
Source: Other Industrial Plant
Reason: Weld, Seam Failure
Sector: General Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	11 of 20	SE/75.1	78.8 / -0.03	LEVERBROTHERS TORONTO ON	NEES

Incident Date: 9/22/87
Contaminant: nitrilotriacetic acid
Amount: 0.454
Units: Tonnes (Metric)
Quantity:
Cause: Other
Source: Other Industrial Plant
Reason: Error
Sector: General Manufacturing

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	12 of 20	SE/75.1	78.8 / -0.03	LEVER BROS. TORONTO (EAST OF YONGE) ON	NEES

Incident Date:	8/6/88
Contaminant:	LATEX
Amount:	0
Units:	Container Leak
Quantity:	
Cause:	Other
Source:	Other Industrial Plant
Reason:	
Sector:	Chemical

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	13 of 20	SE/75.1	78.8 / -0.03	**Lever Bros Ltd** **299 Eastern Ave** **Toronto ON**	TANK

Permit Date:	10/8/1935
Permit Type:	BP A57292
User Type:	Chemical manufacture
Installation Type:	oil storage tank
Installation Size:	
Installation Config.:	oil storage tank
No. Tanks Installed:	4
Units of Measure:	
Value/Tank ($):	20000
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	299 Eastern Ave

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	14 of 20	SE/75.1	78.8 / -0.03	**British American Oil Co Ltd** **299 Eastern Ave** **Toronto ON**	TANK

Permit Date:	12/14/1935
Permit Type:	BP A58201
User Type:	Gasoline service station
Installation Type:	gas tanks
Installation Size:	
Installation Config.:	gas tanks
No. Tanks Installed:	4
Units of Measure:	
Value/Tank ($):	400
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	299 Eastern Ave

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	15 of 20	SE/75.1	78.8 / -0.03	**Hambleton & Co Ltd** **299 Eastern Ave** **Toronto ON**	TANK

Permit Date:	7/31/1930
Permit Type:	BP A31823
User Type:	Gasoline service station
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	2500
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	16 of 20	SE/75.1	78.8 / -0.03	Lever Bros Ltd 299 Eastern Ave Toronto ON	TANK

Permit Date: 1/10/1933
Permit Type: BP A45979
User Type: Chemical manufacture
Installation Type: storage tank
Installation Size:
Installation Config.: storage tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 600
Capacity(gal):
Reference: CTA Building Permits
Location Desc: 299 Eastern Ave

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	17 of 20	SE/75.1	78.8 / -0.03	Lever Bros Ltd 299 Eastern Ave Toronto ON	TANK

Permit Date: 12/10/1932
Permit Type: BP A45809
User Type: Chemical manufacture
Installation Type: oil storage tank
Installation Size:
Installation Config.: oil storage tank
No. Tanks Installed: 2
Units of Measure:
Value/Tank ($): 4500
Capacity(gal):
Reference: CTA Building Permits
Location Desc: 299 Eastern Ave

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	18 of 20	SE/75.1	78.8 / -0.03	Lever Bros Ltd 299 Eastern Ave Toronto ON	TANK

Permit Date: 5/8/1934
Permit Type: BP A50918
User Type: Chemical manufacture
Installation Type: vegetable oil tank
Installation Size:
Installation Config.: vegetable oil tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 500
Capacity(gal):
Reference: CTA Building Permits
Location Desc: 299 Eastern Ave

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
68	19 of 20	SE/75.1	78.8 / -0.03	Lever Bros Ltd 299 Eastern Ave Toronto ON	TANK

Permit Date: 5/22/1934
Permit Type: BP A51217
User Type: Chemical manufacture

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Installation Type: soap oil tank
Installation Size:
Installation Config.: soap oil tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 3000
Capacity(gal):
Reference: CTA Building Permits
Location Desc: 299 Eastern Ave

68	20 of 20	SE/75.1	78.8 / -0.03	**Hambleton & Co Ltd** **299 Eastern Ave** **Toronto ON**	TANK

Permit Date: 7/14/1930
Permit Type: BP A31418
User Type: Gasoline service station
Installation Type: Service station
Installation Size:
Installation Config.: Service station
No. Tanks Installed:
Units of Measure:
Value/Tank ($): 5700
Capacity(gal):
Reference: CTA Building permits
Location Desc:

69	1 of 23	WNW/76.3	79.8 / 0.95	**ALBERTO ACOSTA** **79 EAST DON ROADWAY (PRIVATE)** **TORONTO CITY ON M4M 2A5**	CA

Certificate #: 3-1179-90-
Application Year: 90
Issue Date: 7/6/1990
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

69	2 of 23	WNW/76.3	79.8 / 0.95	**ALBERTO ACOSTA** **79 EAST DON ROADWAY (PRIVATE)** **TORONTO CITY ON M4M 2A5**	CA

Certificate #: 7-0959-90-
Application Year: 90
Issue Date: 7/6/1990
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:

Contaminants:
Emission Control:

---

69 **3 of 23** **WNW/76.3** **79.8 / 0.95** **77 & 79 EDR INC.** **EASR**
77-79 EAST DON ROADWAY
TORONTO ON M4M 2A5

Approval No:	R-009-3110373459	**SWP Area Name:**	Toronto
Status:	REGISTERED	**MOE District:**	Metro Toronto
Date:	2018-03-01	**Municipality:**	TORONTO
Record Type:	EASR	**Latitude:**	43.65722222
Link Source:	MOFA	**Longitude:**	-79.3525
Project Type:	Water Taking - Construction Dewatering	**Geometry X:**	
Full Address:		**Geometry Y:**	

Approval Type: EASR-Water Taking - Construction Dewatering
Full PDF Link: http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2051651

---

69 **4 of 23** **WNW/76.3** **79.8 / 0.95** **TIPPET-RICHARDSON LTD.** **GEN**
79 EAST DON ROADWAY
TORONTO ON

Generator No:	ON0412501	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2013	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	811490		

SIC Description: OTHER PERSONAL AND HOUSEHOLD GOODS REPAIR AND MAINTENANCE

Detail(s)

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

---

69 **5 of 23** **WNW/76.3** **79.8 / 0.95** **MIJO Corporation** **GEN**
79 East Don Roadway
Toronto ON M4M 2A5

Generator No:	ON5226677	**PO Box No:**	
Status:		**Country:**	Canada
Approval Years:	2014	**Choice of Contact:**	CO_ADMIN
Contam. Facility:	No	**Co Admin:**	Althea Cupid
MHSW Facility:	No	**Phone No Admin:**	416 964-7539 Ext.3281
SIC Code:	323119		

SIC Description: OTHER PRINTING

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

69 **6 of 23** **WNW/76.3** **79.8 / 0.95** **TIPPET-RICHARDSON LTD. 37-218** **GEN**
79 EAST DON ROADWAY
TORONTO ON M4M 3J8

Generator No: ON0412501
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 4561
SIC Description: GEN. FREIGHT TRUCK.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

---

69 **7 of 23** **WNW/76.3** **79.8 / 0.95** **Progreen Demolition** **GEN**
77 - 79 East Don Roadway
Toronto ON M4M 2A5

Generator No: ON3618650
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 238910
SIC Description: SITE PREPARATION CONTRACTORS

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Akram Soliman
Phone No Admin: 416-779-7556 Ext.

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

69 **8 of 23** **WNW/76.3** **79.8 / 0.95** **Progreen Demolition** **GEN**
77 - 79 East Don Roadway
Toronto ON M4M 2A5

Generator No: ON3618650
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 238910
SIC Description: SITE PREPARATION CONTRACTORS

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Akram Soliman
Phone No Admin: 416-779-7556 Ext.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

69 ***9 of 23*** ***WNW/76.3*** ***79.8 / 0.95*** ***MIJO Corporation*** ***GEN***
79 East Don Roadway
Toronto ON

Generator No: ON5226677
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 323119
SIC Description: OTHER PRINTING

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

69 ***10 of 23*** ***WNW/76.3*** ***79.8 / 0.95*** ***TIPPET-RICHARDSON LTD.*** ***GEN***
79 EAST DON ROADWAY
TORONTO ON

Generator No: ON0412501
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 811490
SIC Description: Other Personal and Household Goods Repair and Maintenance

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

69 ***11 of 23*** ***WNW/76.3*** ***79.8 / 0.95*** ***WAREHOUSE PROPERTIES LTD.*** ***GEN***
79 EAST DON ROADWAY C/O 471 QUEEN ST. EAST
TORONTO ON M4M 2A5

Generator No: ON1249700
Status:
Approval Years: 89
Contam. Facility:
MHSW Facility:
SIC Code: 4799

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

SIC Description: OTHER STOR./WARE.

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

---

69 ***12 of 23*** ***WNW/76.3*** ***79.8 / 0.95*** ***TIPPET-RICHARDSON LTD.*** ***GEN***
79 EAST DON ROADWAY
TORONTO ON

Generator No: ON0412501 ***PO Box No:***
Status: ***Country:***
Approval Years: 2010 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 811490
SIC Description: Other Personal and Household Goods Repair and Maintenance

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

69 ***13 of 23*** ***WNW/76.3*** ***79.8 / 0.95*** ***TIPPET-RICHARDSON LTD.*** ***GEN***
79 EAST DON ROADWAY
TORONTO ON M4M 2A5

Generator No: ON0412501 ***PO Box No:***
Status: ***Country:***
Approval Years: 89,90,99,00,01,02,03,04,05,06,07,08 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 4561
SIC Description: GEN. FREIGHT TRUCK.

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

---

69 ***14 of 23*** ***WNW/76.3*** ***79.8 / 0.95*** ***MIJO Corporation*** ***GEN***
79 East Don Roadway
Toronto ON M4M 2A5

Generator No: ON5226677
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 323119
SIC Description: Other Printing
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

69 ***15 of 23*** ***WNW/76.3*** ***79.8 / 0.95*** ***WAREHOUSE PROPERTIES LTD. 41-336*** ***GEN***
79 EAST DON ROADWAY C/O 471 QUEEN ST. EAST
TORONTO ON M4M 2A5

Generator No: ON1249700
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 4799
SIC Description: OTHER STOR./WARE.
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

---

69 ***16 of 23*** ***WNW/76.3*** ***79.8 / 0.95*** ***TIPPET-RICHARDSON LTD.*** ***GEN***
79 EAST DON ROADWAY
TORONTO ON

Generator No: ON0412501
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 811490
SIC Description: Other Personal and Household Goods Repair and Maintenance
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

---

69 **17 of 23** **WNW/76.3** **79.8 / 0.95** **TIPPET-RICHARDSON LTD.** **GEN**
79 EAST DON ROADWAY
TORONTO ON M4M 3J8

Generator No: ON0412501
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 811490
SIC Description: Other Personal and Household Goods Repair and Maintenance

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

---

69 **18 of 23** **WNW/76.3** **79.8 / 0.95** **MIJO Corporation** **GEN**
79 East Don Roadway
Toronto ON M4M 2A5

Generator No: ON5226677
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 323119
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

69 **19 of 23** **WNW/76.3** **79.8 / 0.95** **TIPPET-RICHARDSON LTD.** **GEN**
79 EAST DON ROADWAY
TORONTO ON M4M 2A5

Generator No: ON0412501
Status:
Approval Years: 86,87,88
Contam. Facility:
MHSW Facility:
SIC Code: 4561
SIC Description: GEN. FREIGHT TRUCK.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212

Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

69 | **20 of 23** | **WNW/76.3** | **79.8 / 0.95** | **79 EAST DON ROADWAY, TORONTO, ON M4M 2A5**
Toronto ON | **RSC**

RSC ID: 225269
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Industrial
Ministry District: Toronto District Office
Filing Date: 2018/12/19
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:
Asmt Roll No: 19-04-07-1-220-02300-0000, 19-04-07-1-220-01200-0000, 19-04-07-1-220-01100-0000, 19-04-07-1-220-00200-0000
Prop ID No (PIN): 21077-0018 (LT), 21077-0382 (LT), 21077-0381 (LT), 21077-0019 (LT)
Property Municipal Address: 669 QUEEN STREET EAST, TORONTO, ON M4M 1G6, 661 QUEEN STREET EAST, TORONTO, ON M4M 1G6, 79 EAST DON ROADWAY, TORONTO, ON M4M 2A5, 677 QUEEN STREET EAST, TORONTO, ON M4M 1G6
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Filing Owner: 77 & 79 EDR INC.
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=106507&fileName=BROWNFIELDS-E.pdf

Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: CHRISTOPHER AKELAITIS
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:

Document(s) Detail

Document Heading: Supporting Documents
Document Name: 4 Survey.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=106509&fileName=4+Survey.pdf

Document Heading: Supporting Documents
Document Name: 2 Legal letter.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=106502&fileName=2+Legal+letter.pdf

Document Heading: Supporting Documents
Document Name: 6 Use TBL.pdf

Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=106508&fileName=6+Use+TBL.pdf

Document Heading: Supporting Documents
Document Name: 1 CofS.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=106505&fileName=1+CofS.pdf

Document Heading: Supporting Documents
Document Name: 5 APECs.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=106503&fileName=5+APECs.pdf

Document Heading: Supporting Documents
Document Name: 3 Deeds.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=106510&fileName=3+Deeds.pdf

Document Heading: Supporting Documents
Document Name: 7 P2 CSM.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=106500&fileName=7+P2+CSM.pdf

---

69	21 of 23	WNW/76.3	79.8 / 0.95	***BELDAM LASCAR PACKING LTD.*** ***79 East Don Roadway*** ***Toronto ON M4M 2A5***	SCT

Established: 1923
Plant Size (ft²): 10000
Employment: 5

--Details--
Description: Hardware Wholesaler-Distributors
SIC/NAICS Code: 416330

Description: Switchgear and Switchboard, and Relay and Industrial Control Apparatus Manufacturing
SIC/NAICS Code: 335315

Description: Industrial Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417230

Description: Professional Machinery, Equipment and Supplies Wholesaler-Distributors
SIC/NAICS Code: 417930

Description: Machinery, Equipment and Supplies Agents and Brokers
SIC/NAICS Code: 419170

Description: Adhesive Manufacturing
SIC/NAICS Code: 325520

Description: Plastic Pipe and Pipe Fitting Manufacturing
SIC/NAICS Code: 326122

Description: Clay Building Material and Refractory Manufacturing
SIC/NAICS Code: 327120

Description: Commercial and Service Industry Machinery Manufacturing
SIC/NAICS Code: 333310

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Measuring, Medical and Controlling Devices Manufacturing
SIC/NAICS Code: 334512

Description: All Other Miscellaneous Manufacturing
SIC/NAICS Code: 339990

---

69 | **22 of 23** | **WNW/76.3** | **79.8 / 0.95** | **MIJO**
79 East Don Roadway
Toronto ON M4M 2A5 | **SCT**

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Post-Production and Other Motion Picture and Video Industries
SIC/NAICS Code: 512190

---

69 | **23 of 23** | **WNW/76.3** | **79.8 / 0.95** | **BELDAM LASCAR PACKING LIMITED**
79 EAST DON ROADWAY
TORONTO ON M4M 2A5 | **SCT**

Established: 1923
Plant Size (ft²): 10000
Employment: 5

--Details--
Description: GASKETS, PACKING AND SEALING DEVICES
SIC/NAICS Code: 3053

Description: INDUSTRIAL MACHINERY AND EQUIPMENT
SIC/NAICS Code: 5084

Description: INDUSTRIAL SUPPLIES
SIC/NAICS Code: 5085

---

70 | **1 of 1** | **N/79.5** | **79.8 / 0.97** | **100 Broadview Ave**
Toronto ON M4M3H3 | **EHS**

Order No: 20131001045
Status: C
Report Type: Standard Select Report
Report Date: 10-OCT-13
Date Received: 01-OCT-13
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.350103
Y: 43.65809

---

71 | **1 of 1** | **WNW/79.8** | **77.0 / -1.90** | **ON** | **BORE**

Borehole ID: 635175
OGF ID: 215535572
Status:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No

Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	DEC-1961	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.65689
Total Depth m:	7	***Longitude DD:***	-79.353391
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632775
Drill Method:	Diamond Drill	***Northing:***	4835083
Orig Ground Elev m:	73.5	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	79.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472226	***Mat Consistency:***	
Top Depth:	3.2	***Material Moisture:***	
Bottom Depth:	7	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:	Limestone	***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE, LIMESTONE. BROWN,GREY,MARINE, AGE ORDOVICIAN. 012 00000003 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472225	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	3.2	***Material Texture:***	Medium
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	organic material	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SAND(99)-MEDIUM, ORGANIC(1). GREY,LACUSTRINE,LOOSE, AGE GLACIAL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031310 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
72	1 of 1	SW/80.6	75.8 / -3.03	ON	BORE

Borehole ID:	635803	**Inclin FLG:**	No
OGF ID:	215536200	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	1900	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655476
Total Depth m:	33.2	**Longitude DD:**	-79.352127
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632880
Drill Method:	Diamond Drill	**Northing:**	4834928
Orig Ground Elev m:	76.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	77.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218474665	**Mat Consistency:**	
Top Depth:	5	**Material Moisture:**	
Bottom Depth:	15.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474668	**Mat Consistency:**	
Top Depth:	30.8	**Material Moisture:**	
Bottom Depth:	33.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Gravel	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	GRAVEL. FLUVIO-GLACIAL,AGE GLACIAL. ,AGE **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218474664	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218474667	**Mat Consistency:**	
Top Depth:	16	**Material Moisture:**	
Bottom Depth:	30.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	

Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474666	**Mat Consistency:**	
Top Depth:	15.2	**Material Moisture:**	
Bottom Depth:	16	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND. FLUVIO-GLACIAL,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 037610 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

73 ***1 of 1*** ***WNW/80.8*** ***80.0 / 1.14*** ***ON*** ***BORE***

Borehole ID:	635179	**Inclin FLG:**	No
OGF ID:	215535576	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1962	**Municipality:**	
Static Water Level:	0.5	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657248
Total Depth m:	5.6	**Longitude DD:**	-79.353257
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632785
Drill Method:	Power auger	**Northing:**	4835123
Orig Ground Elev m:	77.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.6		
Concession:			
Location D:			
Survey D:			
Comments:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Borehole Geology Stratum

Geology Stratum ID:	218472235	***Mat Consistency:***	
Top Depth:	5.5	***Material Moisture:***	
Bottom Depth:	5.6	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Boulders	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. BROWN,WEATHERED. 0150120250000001300080025000006 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472233	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2.4	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Clay	***Geologic Period:***	
Material 4:	Organic	***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,CLAY, ORGANIC. BROWN,LOOSE.		

Geology Stratum ID:	218472234	***Mat Consistency:***	Stiff
Top Depth:	2.4	***Material Moisture:***	
Bottom Depth:	5.5	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY,SILT. GREY,BROWN,LACUSTRINE,STIFF, AGE GLACIAL, WATER STABLE AT 251.8 FEET.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031350 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

74	***1 of 2***	***NW/81.2***	***80.8 / 1.97***	***677 Queen Street East and 77 - 79 East Don Roadway Toronto ON M4M1G6***	***EHS***

Order No:	20140416045	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	RSC Report (Urban)	***Client Prov/State:***	ON

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Date:	28-APR-14			**Search Radius (km):**	.3
Date Received:	16-APR-14			**X:**	-79.35153
Previous Site Name:				**Y:**	43.657757
Lot/Building Size:					
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans				

74	2 of 2	NW/81.2	80.8 / 1.97	677 Queen St. East, 77 and 79 East Don Roadway Toronto ON	EHS

Order No:	20161213116	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report - Quote	**Client Prov/State:**	ON
Report Date:	07-APR-17	**Search Radius (km):**	.3
Date Received:	13-DEC-16	**X:**	-79.351538
Previous Site Name:		**Y:**	43.657751
Lot/Building Size:			
Additional Info Ordered:	City Directory		

75	1 of 1	WNW/82.4	79.3 / 0.46	ON	BORE

Borehole ID:	635178	**Inclin FLG:**	No
OGF ID:	215535575	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.65707
Total Depth m:	4.7	**Longitude DD:**	-79.353386
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632775
Drill Method:	Power auger	**Northing:**	4835103
Orig Ground Elev m:	75.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	75.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472231	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	Fine to Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SAND(95)-FINE TO MEDIUM,SILT(5). GREY,LACUSTRINE,LOOSE, AGE GLACIAL.		

Geology Stratum ID:	218472232	**Mat Consistency:**	
Top Depth:	4.3	**Material Moisture:**	
Bottom Depth:	4.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Boulders	**Geologic Formation:**	

Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. BROWN,WEATHERED. MA **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031340 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

76 | ***1 of 1*** | ***E/82.6*** | ***78.8 / -0.03*** | ***Diamond State Fibre Co***
350 Eastern Ave
Toronto ON | ***TANK***

Permit Date:	10/6/1931
Permit Type:	BP A39722
User Type:	
Installation Type:	FO tank
Installation Size:	
Installation Config.:	FO tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	200
Capacity(gal):	
Reference:	CTA Building Permits Index
Location Desc:	350 Eastern Ave

---

77 | ***1 of 1*** | ***SW/83.2*** | ***75.8 / -3.03*** | ***TORONTO ON*** | ***WWIS***

Well ID:	7051202	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	10/22/2007
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	4
Audit No:	Z63645	**Owner:**	
Tag:		**Street Name:**	225 EASERN DR.
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	

Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	23051202	***Elevation:***	77.979576
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632888
Code OB Desc:		***North83:***	4834914
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	9/7/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1000005444
Layer:	1
Color:	
General Color:	
Mat1:	
Most Common Material:	
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1000005446
Layer:	1
Plug From:	0
Plug To:	1.22
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1000005447
Layer:	2
Plug From:	1.22
Plug To:	6.1
Plug Depth UOM:	m

Pipe Information

Pipe ID: 1000005442

Casing No: 0
Comment:
Alt Name:

Construction Record - Screen

Screen ID: 1000005450
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1000005443
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

---

78 | ***1 of 1*** | ***NW/83.4*** | ***80.8 / 1.97*** | ***657, 661, 663, 669 and 677 Queen Street East, 77 and 79 East Don Roadway Toronto ON M4M 1G6*** | ***EHS***

Order No: 20181123063
Status: C
Report Type: RSC Report (Urban)
Report Date: 30-NOV-18
Date Received: 23-NOV-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.351572
Y: 43.657768

---

79 | ***1 of 1*** | ***N/83.6*** | ***79.8 / 0.97*** | ***100 Broadview Avenue Toronto ON*** | ***EHS***

Order No: 20160308027
Status: C
Report Type: Custom Report
Report Date: 11-MAR-16
Date Received: 08-MAR-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.350139
Y: 43.658116

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
80	1 of 1	N/84.8	79.8 / 0.97	100 Broadview Avenue Toronto ON M4M 3H3	EHS

Order No:	20180925165	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	02-OCT-18	**Search Radius (km):**	.25
Date Received:	25-SEP-18	**X:**	-79.350157
Previous Site Name:		**Y:**	43.658119
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
81	1 of 1	WNW/86.8	79.9 / 1.04	ON	BORE

Borehole ID:	633028	**Inclin FLG:**	No
OGF ID:	215533429	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1957	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657453
Total Depth m:	9.1	**Longitude DD:**	-79.353115
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632796
Drill Method:	Diamond Drill	**Northing:**	4835146
Orig Ground Elev m:	76	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218464758	**Mat Consistency:**	Soft
Top Depth:	6.7	**Material Moisture:**	
Bottom Depth:	9.1	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,SOFT,LAYERED, AGE ORDOVICIAN. 000000080003000700003 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218464755	**Mat Consistency:**	Soft
Top Depth:	5	**Material Moisture:**	
Bottom Depth:	5.3	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY. GREY,SOFT,AGE GLACIAL.		

Geology Stratum ID:	218464752	**Mat Consistency:**	
Top Depth:	.9	**Material Moisture:**	

Bottom Depth:	4	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND(75)-MEDIUM,SILT(21),CLAY(04). GREY,FLUVIO-GLACIAL, AGE GLACIAL.		

Geology Stratum ID:	218464751	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.9	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND. BROWN.		

Geology Stratum ID:	218464753	**Mat Consistency:**	
Top Depth:	4	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SILT,GRAVEL. GREY,FLUVIO-GLACIAL, AGE GLACIAL.		

Geology Stratum ID:	218464757	**Mat Consistency:**	Soft
Top Depth:	6.4	**Material Moisture:**	
Bottom Depth:	6.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,SOFT,LAYERED, AGE ORDOVICIAN.		

Geology Stratum ID:	218464754	**Mat Consistency:**	Soft
Top Depth:	4.6	**Material Moisture:**	
Bottom Depth:	5	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SHALE,SILT,CLAY. GREY,SOFT,LAYERED,AGE GLACIAL.		

Geology Stratum ID:	218464756	**Mat Consistency:**	Soft
Top Depth:	5.3	**Material Moisture:**	
Bottom Depth:	6.4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,SOFT,LAYERED, AGE ORDOVICIAN.		

Source

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: H
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 009750 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.
Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

82 | **1 of 5** | **N/88.1** | **79.8 / 0.97** | **100 Broadview Ave**
Toronto ON M4M 3H3 | **EHS**

Order No: 20070509010
Status: C
Report Type: CAN - Basic Report
Report Date: 5/17/2007
Date Received: 5/9/2007
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State:
Search Radius (km): 0.25
X: -79.349655
Y: 43.658143

---

82 | **2 of 5** | **N/88.1** | **79.8 / 0.97** | **Tanurb Developments Inc**
100 Broadview Avenue
Toronto ON M4M 3H3 | **GEN**

Generator No: ON2242289
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

82 | **3 of 5** | **N/88.1** | **79.8 / 0.97** | **ATKIN & ASSOCIATES**
100 Broadview Ave Suite 302
Toronto ON M4M 3H3 | **SCT**

Established: 1986
Plant Size (ft²): 0
Employment: 9

--Details--
Description: Software Publishers
SIC/NAICS Code: 511210

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	4 of 5	N/88.1	79.8 / 0.97	AGRICULTURAL PUBLISHING CO LTD 100 BROADVIEW AVE SUITE 402 TORONTO ON M4M 3H3	SCT

Established: 1969
Plant Size (ft²):
Employment: 10

--Details--
Description: NEWSPAPERS: PUBLISHING, OR PUBLISHING & PRINTING
SIC/NAICS Code: 2711

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
82	5 of 5	N/88.1	79.8 / 0.97	Small Winemakers Collection 100 Broadview Ave Unit 404 Toronto ON M4M 3H3	SCT

Established: 01-SEP-91
Plant Size (ft²):
Employment:

--Details--
Description: Wholesale Trade Agents and Brokers
SIC/NAICS Code: 419120

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
83	1 of 1	WNW/89.6	80.1 / 1.19	ON	BORE

Borehole ID: 635180
OGF ID: 215535577
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1962
Static Water Level: 0.8
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 8.3
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 76.3
Elev Reliabil Note:
DEM Ground Elev m: 78.9
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.65725
Longitude DD: -79.353381
UTM Zone: 17
Easting: 632775
Northing: 4835123
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218472237
Top Depth: 4.6
Bottom Depth: 8.3
Material Color: Grey
Material 1: Bedrock
Material 2: Shale
Material 3:
Material 4:

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period: Ordovician
Depositional Gen: marine

Gsc Material Description:
Stratum Description: BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN, WATER STABLE AT 247.5 FEET.0000515012025
**Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218472236	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	Coarse
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine

Gsc Material Description:
Stratum Description: SAND(68)-MEDIUM TO COARSE,SILT(27),CLAY(5). GREY,LACUSTRINE,LOOSE, AGE GLACIAL.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031360 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

84 | ***1 of 1*** | ***W/90.2*** | ***76.2 / -2.64*** | ***ON*** | ***BORE***

Borehole ID:	635160	**Inclin FLG:**	No
OGF ID:	215535557	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1962	**Municipality:**	
Static Water Level:	1.7	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656802
Total Depth m:	16.7	**Longitude DD:**	-79.353517
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632765
Drill Method:	Power auger	**Northing:**	4835073
Orig Ground Elev m:	77.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	80.8		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472175	**Mat Consistency:**	

Top Depth:	13.7	**Material Moisture:**	
Bottom Depth:	16.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine

Gsc Material Description:
Stratum Description: BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. 00000002000800020018001000009 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218472174	**Mat Consistency:**	Stiff
Top Depth:	12.6	**Material Moisture:**	
Bottom Depth:	13.7	**Material Texture:**	
Material Color:	Green	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine

Gsc Material Description:
Stratum Description: CLAY,SILT,ORGANIC. GREEN,LACUSTRINE,STIFF, AGE GLACIAL.

Geology Stratum ID:	218472171	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Granuls	**Depositional Gen:**	fill

Gsc Material Description:
Stratum Description: FILL,SAND,SILT, CINDERS. LOOSE.

Geology Stratum ID:	218472173	**Mat Consistency:**	Loose
Top Depth:	5.5	**Material Moisture:**	
Bottom Depth:	12.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine

Gsc Material Description:
Stratum Description: SILT,SAND. GREY,BROWN,LACUSTRINE,LOOSE, BEDDED,AGE GLACIAL.

Geology Stratum ID:	218472172	**Mat Consistency:**	Loose
Top Depth:	2.4	**Material Moisture:**	
Bottom Depth:	5.5	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine

Gsc Material Description:
Stratum Description: SAND,SILT,ORGANIC. GREY,LACUSTRINE,LOOSE, AGE GLACIAL, WATER STABLE AT 248.6 FEET.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031160 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

85 ***1 of 1*** ***W/90.3*** ***79.1 / 0.22*** ***ON*** ***BORE***

Borehole ID:	635154	***Inclin FLG:***	No
OGF ID:	215535551	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	MAR-1962	***Municipality:***	
Static Water Level:	3.0	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.656256
Total Depth m:	30.5	***Longitude DD:***	-79.35316
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632795
Drill Method:	Power auger	***Northing:***	4835013
Orig Ground Elev m:	77.9	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	80		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472147	***Mat Consistency:***	Dense
Top Depth:	28.7	***Material Moisture:***	
Bottom Depth:	30	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SAND,SILT, GRAVEL. GREY,GLACIAL,VERY DENSE, AGE NON-GLACIAL, WATER STABLE AT 245.5 FEET.		

Geology Stratum ID:	218472148	***Mat Consistency:***	
Top Depth:	30	***Material Moisture:***	
Bottom Depth:	30.5	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Boulders	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. GREY,MARINE,AGE ORDOVICIAN. 00000001000900090094006900010 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472145	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2.7	***Material Texture:***	

Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Granuls	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,CINDERS. BROWN,LOOSE.		

Geology Stratum ID:	218472146	**Mat Consistency:**	
Top Depth:	2.7	**Material Moisture:**	
Bottom Depth:	28.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. GREY,BROWN,LACUSTRINE,BEDDED, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031100 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

86 ***1 of 1*** ***WNW/90.6*** ***80.1 / 1.19*** ***ON*** ***BORE***

Borehole ID:	643279	**Inclin FLG:**	No
OGF ID:	215543668	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657286
Total Depth m:	9.1	**Longitude DD:**	-79.353367
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632776
Drill Method:		**Northing:**	4835127
Orig Ground Elev m:	76	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.5		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218503106	***Mat Consistency:***	
Top Depth:	4.6	***Material Moisture:***	
Bottom Depth:	9.1	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN.		

Geology Stratum ID:	218503103	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.9	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND. BROWN.		

Geology Stratum ID:	218503104	***Mat Consistency:***	
Top Depth:	.9	***Material Moisture:***	
Bottom Depth:	4	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	SAND,SILT. GREY,FLUVIO-GLACIAL, AGE GLACIAL.		

Geology Stratum ID:	218503105	***Mat Consistency:***	
Top Depth:	4	***Material Moisture:***	
Bottom Depth:	4.6	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SILT,GRAVEL. GREY,GLACIAL,AGE GLACIAL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 113000 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

87 *1 of 1* *SSW/94.7* *75.8 / -3.03* *ON* *WWIS*

Well ID:	7269525	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/18/2016
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	8
Audit No:	C29341	**Owner:**	
Tag:	A173219	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006224009	**Elevation:**	77.82241
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632969
Code OB Desc:		**North83:**	4834814
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/1/2015	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

88 *1 of 2* *SSW/94.7* *75.8 / -3.03* *TORONTO ON* *WWIS*

Well ID:	7185078	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127722	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	

Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004101415	***Elevation:***	78.013359
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632932
Code OB Desc:		***North83:***	4834844
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/17/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395198
Layer:	1
Plug From:	35.75
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395191
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395195
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395196
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch

Screen Diameter:

Hole Diameter

Hole ID: 1004395193
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

88 ***2 of 2*** ***SSW/94.7*** ***75.8 / -3.03*** ***TORONTO ON*** ***WWIS***

Well ID: 7185080
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127723
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004101421
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/17/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 78.014144
Elevrc:
Zone: 17
East83: 632932
North83: 4834845
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004395214
Layer: 1
Plug From: 17.667
Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004395207
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395211
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395212
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395209
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

89 | ***1 of 1*** | ***NW/97.3*** | ***80.0 / 1.16*** | ***TORONTO ON*** | ***WWIS***

Well ID: 7216131
Construction Date:
Primary Water Use: Monitoring and Test Hole
Sec. Water Use: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z184758
Tag: A159306
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:

Data Entry Status:
Data Src:
Date Received: 2/10/2014
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 635 QUEEN STREET EAST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	1004707051	***Elevation:***	81.127182
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632842
Code OB Desc:		***North83:***	4835179
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	1/3/2014	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005075811
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	01
Other Materials:	FILL
Formation Top Depth:	0
Formation End Depth:	4
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005075812
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	4
Formation End Depth:	10
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005075813
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06

Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	
Other Materials:	
Formation Top Depth:	10
Formation End Depth:	16
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005075821
Layer:	1
Plug From:	16
Plug To:	5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005075822
Layer:	2
Plug From:	5
Plug To:	0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005075810
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005075816
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	6
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005075817
Layer:	1
Slot:	.10
Screen Top Depth:	6
Screen End Depth:	16

Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.25

Hole Diameter

Hole ID:	1005075814
Diameter:	2.25
Depth From:	0
Depth To:	16
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

90 ***1 of 1*** ***SW/97.8*** ***75.8 / -3.03*** ***ON*** ***WWIS***

Well ID:	7291886	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	8/2/2017
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	6607
Casing Material:		**Form Version:**	7
Audit No:	Z240177	**Owner:**	
Tag:	A224456	**Street Name:**	LOWER DON TRAIL
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006695234	**Elevation:**	77.9626
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632874
Code OB Desc:		**North83:**	4834908
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/29/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006798068
Layer:	2
Color:	2

General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	2.7
Formation End Depth:	7
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006798067
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	0
Formation End Depth:	2.7
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006798077
Layer:	3
Plug From:	2.5
Plug To:	4.7
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006798078
Layer:	4
Plug From:	4.7
Plug To:	7
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006798076
Layer:	2
Plug From:	0.3
Plug To:	2.5
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006798075
Layer:	1
Plug From:	0
Plug To:	0.3

Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1006798066
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006798071
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 3
Casing Diameter: 5.1
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006798072
Layer: 1
Slot: 10
Screen Top Depth: 3
Screen End Depth: 4.6
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.4

Water Details

Water ID: 1006798070
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 3.3
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006798069
Diameter: 21
Depth From: 0
Depth To: 7
Hole Depth UOM: m
Hole Diameter UOM: cm

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
91	1 of 1	WNW/97.8	79.9 / 1.02	ON	BORE

Borehole ID:	633029	**Inclin FLG:**	No
OGF ID:	215533430	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAR-1957	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657649
Total Depth m:	9.1	**Longitude DD:**	-79.352961
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632808
Drill Method:	Diamond Drill	**Northing:**	4835168
Orig Ground Elev m:	78.1	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	80.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218464761	**Mat Consistency:**	
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	6.2	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SAND,SILT, GRAVEL. GREY,GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218464760	**Mat Consistency:**	
Top Depth:	.9	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SILT,SAND, GRAVEL. GREY,GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218464762	**Mat Consistency:**	
Top Depth:	6.2	**Material Moisture:**	
Bottom Depth:	6.4	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Silt	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SHALE,CLAY,SAND,SILTGLACIAL,LAYERED,AGE GLACIAL.		

Geology Stratum ID:	218464763	**Mat Consistency:**	
Top Depth:	6.4	**Material Moisture:**	
Bottom Depth:	9.1	**Material Texture:**	
Material Color:	Red	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	

Material 3: ***Geologic Period:***
Material 4: ***Depositional Gen:*** glacial
Gsc Material Description:
Stratum Description: SHALE,CLAY. GLACIAL,LAYERED,AGE GLACIAL. 012015020 012015020000000220003001000050013002O
**Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID: 218464759 ***Mat Consistency:***
Top Depth: 0 ***Material Moisture:***
Bottom Depth: .9 ***Material Texture:*** Fine to Medium
Material Color: ***Non Geo Mat Type:***
Material 1: Sand ***Geologic Formation:***
Material 2: Gravel ***Geologic Group:***
Material 3: ***Geologic Period:***
Material 4: ***Depositional Gen:*** glacial
Gsc Material Description:
Stratum Description: SAND-FINE TO MEDIUM,GRAVEL. FLUVIO-GLACIAL,AGE GLACIAL.

Source

Source Type: Data Survey ***Source Appl:*** Spatial/Tabular
Source Orig: Geological Survey of Canada ***Source Iden:*** 1
Source Date: 1956-1972 ***Scale or Res:*** Varies
Confidence: H ***Horizontal:*** NAD27
Observatio: ***Verticalda:*** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 009760 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier: 1 ***Horizontal Datum:*** NAD27
Source Type: Data Survey ***Vertical Datum:*** Mean Average Sea Level
Source Date: 1956-1972 ***Projection Name:*** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

92 ***1 of 1*** ***W/97.9*** ***79.3 / 0.44*** ***ON*** ***BORE***

Borehole ID: 635164 ***Inclin FLG:*** No
OGF ID: 215535561 ***SP Status:*** Initial Entry
Status: ***Surv Elev:*** No
Type: Borehole ***Piezometer:*** No
Use: Geotechnical/Geological Investigation ***Primary Name:***
Completion Date: MAR-1962 ***Municipality:***
Static Water Level: ***Lot:***
Primary Water Use: Not Used ***Township:***
Sec. Water Use: ***Latitude DD:*** 43.656532
Total Depth m: 31 ***Longitude DD:*** -79.353525
Depth Ref: Ground Surface ***UTM Zone:*** 17
Depth Elev: ***Easting:*** 632765
Drill Method: Power auger ***Northing:*** 4835043
Orig Ground Elev m: 77.4 ***Location Accuracy:***
Elev Reliabil Note: ***Accuracy:*** Not Applicable
DEM Ground Elev m: 85.1
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218472186	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	28	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. LACUSTRINE,AGE GLACIAL.		

Geology Stratum ID:	218472187	**Mat Consistency:**	Stiff
Top Depth:	28	**Material Moisture:**	
Bottom Depth:	30.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SAND.GREY,GLACIAL,STIFF, AGE NON-GLACIAL.		

Geology Stratum ID:	218472188	**Mat Consistency:**	
Top Depth:	30.9	**Material Moisture:**	
Bottom Depth:	31	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Boulders	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031200 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

93 ***1 of 1*** ***SW/98.6*** ***75.8 / -3.03*** ***TORONTO ON*** ***WWIS***

Well ID:	7185087	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102

Casing Material:		**Form Version:**	7
Audit No:	Z127717	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101480	**Elevation:**	77.940826
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632867
Code OB Desc:		**North83:**	4834915
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/16/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395275
Layer:	1
Plug From:	20
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395268
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395272
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395273
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395270
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

94 **1 of 2** **WSW/99.3** **76.1 / -2.75** **lot 64 ON** **WWIS**

Well ID:	7053004	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Dewatering	**Date Received:**	11/30/2007
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Dewatering	**Abandonment Rec:**	
Water Type:		**Contractor:**	6926
Casing Material:		**Form Version:**	4
Audit No:	Z62262	**Owner:**	
Tag:	A058471	**Street Name:**	BAYVIEW AVE & FRONT ST. EAST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	064
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	23053004	**Elevation:**	77.78469
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632849
Code OB Desc:		**North83:**	4834935
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	11/7/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1000053059
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	84
Other Materials:	SILTY
Mat3:	
Other Materials:	
Formation Top Depth:	1
Formation End Depth:	3
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1000053058
Layer:	1
Color:	2
General Color:	GREY
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	1
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1000053060
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	61
Other Materials:	CLAYEY
Mat3:	
Other Materials:	
Formation Top Depth:	3
Formation End Depth:	6
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1000053063
Layer:	2
Plug From:	1
Plug To:	3.5
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID: 1000053064
Layer: 3
Plug From: 3.5
Plug To: 6
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1000053062
Layer: 1
Plug From: 0
Plug To: 1
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: E
Method Construction: Auger
Other Method Construction:

Pipe Information

Pipe ID: 1000053056
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1000053066
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 6
Casing Diameter: 0.056
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1000053067
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM:
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1000053057
Pump Set At:
Static Level:
Final Level After Pumping:

Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM: m
Rate UOM: LPM
Water State After Test Code: 0
Water State After Test:
Pumping Test Method: 0
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Water Details

Water ID: 1000053065
Layer: 1
Kind Code:
Kind:
Water Found Depth: 2
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1000053061
Diameter: 23.32
Depth From:
Depth To: 6
Hole Depth UOM: m
Hole Diameter UOM: cm

---

94 **2 of 2** **WSW/99.3** **76.1 / -2.75** **lot 64 ON** **WWIS**

Well ID: 7115423
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z76096
Tag: A058471
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 11/21/2008
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 6926
Form Version: 4
Owner:
Street Name: BAVIEW AVE AND FRONT ST E
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot: 064
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1001886781
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:

Elevation: 77.78469
Elevrc:
Zone: 17
East83: 632849
North83: 4834935

Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/2/2008	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1002562297
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	1
Formation End Depth:	3
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1002562296
Layer:	1
Color:	2
General Color:	GREY
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	1
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1002562298
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	3
Formation End Depth:	6
Formation End Depth UOM:	m

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Annular Space/Abandonment Sealing Record

Plug ID:	1002562299
Layer:	1
Plug From:	0
Plug To:	1
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002562301
Layer:	3
Plug From:	3.5
Plug To:	6
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002562300
Layer:	2
Plug From:	1
Plug To:	3.5
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1002562295
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002562303
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	
Casing Diameter:	0.056
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002562304
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	
Screen Diameter UOM:	
Screen Diameter:	

95	***1 of 1***	***W/99.9***	***79.4 / 0.52***	***City of Toronto*** ***East side of Bayview Ave, south of Eastern parkway***	***GEN***

Toronto ON

Generator No: ON3840506
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 913910
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

96 | **1 of 1** | **NNE/100.0** | **79.8 / 0.97** | **80 LEWIS STREET, TORONTO ON** | **INC**

Incident No: 1325702
Incident ID:
Attribute Category: FS-Perform L1 Incident Insp
Status Code:
Incident Location: 80 LEWIS STREET, TORONTO - CO RELEASE
Drainage System:
Sub Surface Contam.:
Aff. Prop. Use Water:
Contam. Migrated:
Contact Natural Env.:
Near Body of Water:
Approx. Quant. Rel.:
Equipment Model:
Serial No:
Residential App. Type:
Commercial App. Type:
Industrial App. Type:
Institutional App. Type:
Venting Type:
Vent Connector Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Depth Ground Cover:
Regulator Location:
Regulator Type:
Operation Pressure:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Equipment Type:
Cylinder Capacity:
Cylinder Capac. Units:
Cylinder Material Type:
Tank Capacity:
Fuels Occurence Type: CO Release
Fuel Type Involved: Natural Gas
Date of Occurence: 2014/01/25 00:00:00
Time of Occurence: 10:42:00
Occur Insp Start Date: 2014/01/27 00:00:00
Any Health Impact: No
Any Environmental Impact: No
Was Service Interrupted: No
Was Property Damaged: No

Operation Type Involved:	Multi-unit Residential
Enforcement Policy:	NULL
Prc Escalation Required:	NULL
Task No:	4787717
Notes:	
Occurence Narrative:	40 PPM IN BOILER ROOM
Tank Material Type:	
Tank Storage Type:	
Tank Location Type:	
Pump Flow Rate Capac:	
Liquid Prop Notes:	

---

97 **1 of 2** **WNW/100.3** **79.9 / 1.03** **ON** **BORE**

Borehole ID:	635181	**Inclin FLG:**	No
OGF ID:	215535578	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1962	**Municipality:**	
Static Water Level:	0.9	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.65743
Total Depth m:	9.2	**Longitude DD:**	-79.353376
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632775
Drill Method:	Power auger	**Northing:**	4835143
Orig Ground Elev m:	77.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.8		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472239	**Mat Consistency:**	Firm
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY,SILT,ORGANIC. BROWN,LACUSTRINE,FIRM, AGE GLACIAL.		

Geology Stratum ID:	218472240	**Mat Consistency:**	Hard
Top Depth:	4.3	**Material Moisture:**	
Bottom Depth:	6.1	**Material Texture:**	Fine
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT(47), CLAY(26),SAND-FINE. GREY,BROWN,GLACIAL,HARD, AGE NON-GLACIAL, WATER STABLE AT 250.2 FEET.		

Geology Stratum ID:	218472241	**Mat Consistency:**	
Top Depth:	6.1	**Material Moisture:**	

Bottom Depth:	9.2	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			

Stratum Description: BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. 0150220310001001100140050000004 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218472238	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			

Stratum Description: FILL.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031370 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

97 ***2 of 2*** ***WNW/100.3*** ***79.9 / 1.03*** ***ON*** ***BORE***

Borehole ID:	643277	**Inclin FLG:**	No
OGF ID:	215543666	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	43.65743
Total Depth m:	10.1	**Longitude DD:**	-79.353376
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632775
Drill Method:		**Northing:**	4835143
Orig Ground Elev m:	77.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.8		
Concession:			
Location D:			
Survey D:			

Comments:

Borehole Geology Stratum

Geology Stratum ID:	218503096	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.3	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218503097	***Mat Consistency:***	Firm
Top Depth:	.3	***Material Moisture:***	
Bottom Depth:	4.3	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Organic	***Geologic Period:***	
Material 4:		***Depositional Gen:***	organic
Gsc Material Description:			
Stratum Description:	CLAY,SILT,ORGANIC. BROWN,GLACIAL,FIRM, AGE GLACIAL.		

Geology Stratum ID:	218503098	***Mat Consistency:***	Hard
Top Depth:	4.3	***Material Moisture:***	
Bottom Depth:	6.1	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SILT,GRAVEL. GREY,BROWN,GLACIAL,HARD, AGE GLACIAL.		

Geology Stratum ID:	218503099	***Mat Consistency:***	
Top Depth:	6.1	***Material Moisture:***	
Bottom Depth:	10.1	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. L.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 112980 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level

Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

98 **1 of 1** **WSW/100.6** **77.1 / -1.79** **Toronto ON** **WWIS**

Well ID:	7281534	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	2/23/2017
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	6032
Casing Material:		**Form Version:**	7
Audit No:	Z229073	**Owner:**	
Tag:	A201446	**Street Name:**	BAYVIEW EASTERN AVE
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006356027	**Elevation:**	76.019363
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632815
Code OB Desc:		**North83:**	4834973
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/20/2016	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006595314
Layer:	4
Color:	2
General Color:	GREY
Mat1:	17
Most Common Material:	SHALE
Mat2:	05
Other Materials:	CLAY
Mat3:	73
Other Materials:	HARD
Formation Top Depth:	105
Formation End Depth:	213
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006595313
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	28
Other Materials:	SAND
Mat3:	85
Other Materials:	SOFT
Formation Top Depth:	20
Formation End Depth:	105
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006595311
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	12
Other Materials:	STONES
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0
Formation End Depth:	11
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006595312
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	85
Other Materials:	SOFT
Formation Top Depth:	11
Formation End Depth:	20
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006595323
Layer:	2
Plug From:	156
Plug To:	155
Plug Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1006595324
Layer:	3
Plug From:	142
Plug To:	139
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006595325
Layer:	4
Plug From:	139
Plug To:	1
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1006595322
Layer:	1
Plug From:	213
Plug To:	156
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	DIAMOND

Pipe Information

Pipe ID:	1006595310
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006595318
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	144
Depth To:	0
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006595319
Layer:	1
Slot:	10
Screen Top Depth:	154
Screen End Depth:	144
Screen Material:	5

Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2

Hole Diameter

Hole ID: 1006595315
Diameter: 8
Depth From: 0
Depth To: 105
Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole Diameter

Hole ID: 1006595316
Diameter: 4
Depth From: 105
Depth To: 213
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

99 | **1 of 1** | **NNE/100.6** | **79.8 / 0.97** | **Cruise Roofing Co**
95 Broadview Ave
Toronto ON | **TANK**

Permit Date: 5/13/1930
Permit Type: BP A29781
User Type: Roofing firm
Installation Type: Gasoline tank
Installation Size:
Installation Config.: 1 x Gasoline tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 200
Capacity(gal):
Reference: CTA Building permits
Location Desc:

---

100 | **1 of 1** | **SSW/100.9** | **75.8 / -3.03** | **TORONTO ON** | **WWIS**

Well ID: 7185099
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127737
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004101554	***Elevation:***	77.995605
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632956
Code OB Desc:		***North83:***	4834814
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/18/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395375
Layer:	1
Plug From:	25.333
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395368
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395372
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395373
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Hole ID: 1004395370
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

101 | **1 of 1** | **S/101.5** | **75.9 / -2.97** | **Old Don Reclamation** | **ANDR**

Toronto ON M5A

Legal Description: York
Location Description: swale of Old Don channel at N side of front st nr D
Municipality: Toronto City
Current Municipality: Toronto City
RM: Toronto City
Facility: Dump
Date Active: 1881-84
Date Begun:
Date Complete:
Area (Ha):
Landfill Type: open dump reclamation
Group Name: Don River
Operated By: Toronto SC
Serial: TOR183
NTS: 30M11
Diameter (m):

Historical Summary:

Dump, Old Don Channel, foot of Front Street In 1881 ashes mud and scrapings were being deposited here (TCM 1881 Appendix: Committee on Markets & Health 35th report 11.1.82). In 1884 ashes, refuse, mud and scrapings were being deposited here (TCM 1884: Appendix #26 14.1.85). The old course of the Don River at the foot of Front Street was used as a dump for mixed MSW in the 1880s (CTA Proposed Crematories RG8 Box 68 File 8: Letter, Emerson Coatsworth, City Commissioner to Property Committee, October 6, 1898). The Don River was one of only 4 dumps in the city in 1887 (TCM 1887 Appendix Committee for Markets and Health Final Report #27 6.1.88). 1885 Map The Don is shown in its natural course and ravine, with marshes south of the GTR tracks. 1903 Map The Don is shown in its "improved" course north of the GTR tracks, and the marshes have been reduced south of the tracks, but its course here has not been altered much 1885-1903. Take a centroid @ UTM 632970--4834580 on the segment of the old channel of the Don which vanished 1885-1903, just north of the GTR tracks near the end of Front St W. Goad's Atlas 1923 I: 29 This site apparently occupied by Don Esplanade West, the site of modern Bayview Ave.

Waste Type: garbage, street sweepings, ashes & rubbish
UTM X Nad 27: 632970
UTM Y Nad 27: 4834580
UTM Zone: 17

---

102 | **1 of 1** | **W/101.6** | **77.8 / -1.09** | **ON** | **BORE**

Borehole ID: 635163
OGF ID: 215535560
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: MAR-1962
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 28.8
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 77.6
Elev Reliabil Note:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.656714
Longitude DD: -79.353644
UTM Zone: 17
Easting: 632755
Northing: 4835063
Location Accuracy:
Accuracy: Not Applicable

DEM Ground Elev m: 80.9
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218472183
Top Depth: 0
Bottom Depth: 27.1
Material Color:
Material 1: Silt
Material 2: Sand
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SILT,SAND. LACUSTRINE,BEDDED,AGE GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: lacustrine

Geology Stratum ID: 218472185
Top Depth: 28.8
Bottom Depth: 28.8
Material Color:
Material 1: Boulders
Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: BOULDERS,SHALE.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218472184
Top Depth: 27.1
Bottom Depth: 28.8
Material Color: Grey
Material 1: Till
Material 2: Clay
Material 3: Silt
Material 4: Sand
Gsc Material Description:
Stratum Description: TILL,CLAY,SILT,SAND.GREY,GLACIAL,STIFF, AGE NON-GLACIAL.

Mat Consistency: Stiff
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031190 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
103	1 of 1	NW/101.8	80.4 / 1.53	TORONTO ON	WWIS

Well ID: 7216132
Construction Date:
Primary Water Use: Monitoring and Test Hole
Sec. Water Use: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z184756
Tag: A154838
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 2/10/2014
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 635 QUEEN STREET EAST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004707054
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 1/3/2014
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 81.206481
Elevrc:
Zone: 17
East83: 632856
North83: 4835187
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005075873
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 28
Other Materials: SAND
Mat3:
Other Materials:
Formation Top Depth: 10
Formation End Depth: 13.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005075871

Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Other Materials: GRAVEL
Mat3: 01
Other Materials: FILL
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005075872
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 4
Formation End Depth: 10
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005075881
Layer: 1
Plug From: 13.5
Plug To: 2.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005075882
Layer: 2
Plug From: 2.5
Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1005075870
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1005075876
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	3.5
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005075877
Layer:	1
Slot:	.10
Screen Top Depth:	3.5
Screen End Depth:	13.5
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.25

Hole Diameter

Hole ID:	1005075874
Diameter:	2.25
Depth From:	0
Depth To:	13.5
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

104	***1 of 3***	***W/103.2***	***79.3 / 0.47***	***City of Toronto*** ***West Don Lands, Group 2 Near the intersections of Bayview Avenue and Eastern Avenue. CITY OF TORONTO*** ***ON***	***CPU***

EBR Registry No:	011-5334	***Decision Posted:***	
Ministry Ref No:	7582-8GHK88-TOR	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:		***Act 1:***	
Notice Date:	March 19, 2012	***Act 2:***	
Proposal Date:	December 08, 2011	***Site Location Map:***	
Year:	2011		
Instrument Type:	(EPA s. 168.6) - Certificate of Property Use		
Off Instrument Name:			
Posted By:			
Company Name:	City of Toronto		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	100 Queen Street West, Toronto Ontario, Canada M5H 2N2		
Comment Period:			
URL:			

Site Location Details:

West Don Lands, Group 2 Near the intersections of Bayview Avenue and Eastern Avenue. CITY OF TORONTO

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	2 of 3	W/103.2	79.3 / 0.47	Her Majesty the Queen In Right of Ontario As Represented by the Minister of Infrastructure ON	CPU

EBR Registry No: 011-5333
Ministry Ref No: 7582-8GHK88-MOI
Notice Type: Instrument Decision
Notice Stage:
Notice Date: March 19, 2012
Proposal Date: December 08, 2011
Year: 2011
Instrument Type: (EPA s. 168.6) - Certificate of Property Use
Off Instrument Name:
Posted By:
Company Name: Her Majesty the Queen In Right of Ontario As Represented by the Minister of Infrastructure
Site Address:
Location Other:
Proponent Name:
Proponent Address: c/o Ontario Infrastructure and Lands Corporation, 2000 -1 Dundas Street West, Toronto Ontario, Canada M5G 2L5
Comment Period:
URL:

Site Location Details:

West Don Lands, Group 2 Near the intersections of Bayview Avenue and Eastern Avenue CITY OF TORONTO

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
104	3 of 3	W/103.2	79.3 / 0.47	CANADIAN NATIONAL RAILWAY BAYVIEW AVE. AND EASTERN AVE. TRAIN TORONTO CITY ON	SPL

Ref No: 52351
Site No:
Incident Dt: 6/14/1991
Year:
Incident Cause: PIPE/HOSE LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/14/1991
Dt Document Closed:
Incident Reason: EQUIPMENT FAILURE
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: CN RAIL - 500 L HYDRAULICOIL TO GROUND WHEN HOSE BLEW ON MOBILE HOIST.
Contaminant Qty:
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 01106
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
105	1 of 1	SW/103.7	75.8 / -3.03	TORONTO ON	WWIS

Well ID: 7185100
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127726
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004101557
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/17/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 78.01567
Elevrc:
Zone: 17
East83: 632907
North83: 4834860
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004395383
Layer: 1
Plug From: 16.167
Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004395376
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395380
Layer:
Material:

Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395381
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395378
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

106 | ***1 of 1*** | ***S/105.2*** | ***75.8 / -3.03*** | ***ONTARIO HYDRO OPPOSITE FRONT ST DEAD END ACROSS RAILWAY TRACKS BESIDE DON RIVER HIGH VOLTAGE CABLE TORONTO CITY ON*** | ***SPL***

Ref No: 92053
Site No:
Incident Dt: //
Year:
Incident Cause: CONTAINER OVERFLOW
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Soil contamination
Receiving Medium: LAND
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/6/1993
Dt Document Closed:
Incident Reason: ERROR
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: ONTARIO HYDRO: 30L CABLE OIL OVERFLOW FROM STORAGE TANK
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 01106
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

107 | ***1 of 1*** | ***NNE/106.5*** | ***79.8 / 0.97*** | | ***WWIS***

TORONTO ON

Well ID:	7046644	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	7/17/2007
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	3
Audit No:	Z74019	***Owner:***	
Tag:	A061566	***Street Name:***	717 QUEEN STREET EAST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	23046644	***Elevation:***	80.094116
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633101
Code OB Desc:		***North83:***	4835276
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	6/25/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	30246644
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	0.61
Formation End Depth:	3.1
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	30346644
Layer:	3

Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	3.1
Formation End Depth:	6.1
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	30146644
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Other Materials:	SAND
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0
Formation End Depth:	0.61
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	44001324
Layer:	1
Plug From:	0
Plug To:	0.3
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	44001323
Layer:	3
Plug From:	2.44
Plug To:	6.1
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	44001325
Layer:	2
Plug From:	0.3
Plug To:	2.44
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	B
Method Construction:	Other Method

Other Method Construction:

Pipe Information

Pipe ID: 29046644
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 42146644
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 3.1
Casing Diameter: 3.81
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 43146644
Layer: 1
Slot: 10
Screen Top Depth: 3.1
Screen End Depth: 6.1
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 3.67

Hole Diameter

Hole ID: 46000811
Diameter: 8.89
Depth From: 0
Depth To: 6.1
Hole Depth UOM: m
Hole Diameter UOM: cm

---

108 ***1 of 1*** ***ENE/106.9*** ***79.8 / 0.97*** ***Between 19 and 23 Lewis Street Toronto ON*** ***SPL***

Ref No: 7127-878JRQ
Site No:
Incident Dt:
Year:
Incident Cause: Unknown
Incident Event:
Contaminant Code: 15
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Confirmed
Nature of Impact: Human Health/Safety; Other Impact(s)
Receiving Medium:
Receiving Env:
MOE Response: Planned Field Response
Dt MOE Arvl on Scn: 7/12/2010

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MOE Reported Dt:	7/10/2010	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:		**Source Type:**	
Site Name:	Roadway on Lewis Street<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TO Works: unkn source of diesel to grnd, clng		
Contaminant Qty:	0 other - see incident description		

---

109 *1 of 1* *ENE/107.6* *79.8 / 0.97* *ON* **WWIS**

Well ID:	7315920	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2018
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	7
Audit No:	Z285572	**Owner:**	
Tag:	A247013	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1007237998	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633253
Code OB Desc:		**North83:**	4835073
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	6/26/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

110 *1 of 1* *WNW/108.3* *79.8 / 0.94* *ON* **BORE**

Borehole ID:	635170	**Inclin FLG:**	No
OGF ID:	215535567	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JUN-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	

Sec. Water Use:		**Latitude DD:**	43.657626
Total Depth m:	10.4	**Longitude DD:**	-79.353247
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632785
Drill Method:	Power auger	**Northing:**	4835165
Orig Ground Elev m:	81.9	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.2		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472209	**Mat Consistency:**	Firm
Top Depth:	5.9	**Material Moisture:**	
Bottom Depth:	8.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,FIRM,AGE GLACIAL.		

Geology Stratum ID:	218472211	**Mat Consistency:**	
Top Depth:	9.9	**Material Moisture:**	
Bottom Depth:	10.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. AGE ORDOVICIAN. 018 00000009000950120019500500285095 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472210	**Mat Consistency:**	Hard
Top Depth:	8.7	**Material Moisture:**	
Bottom Depth:	9.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,HARD,AGE GLACIAL.		

Geology Stratum ID:	218472208	**Mat Consistency:**	Compact
Top Depth:	2.9	**Material Moisture:**	
Bottom Depth:	5.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND. GREY,FLUVIO-GLACIAL,COMPACT, AGE GLACIAL.		

Geology Stratum ID:	218472207	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.9	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	

Material 2:	Granuls	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,CINDERS. BROWN,LOOSE.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031260 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

111 ***1 of 1*** ***WNW/111.4*** ***80.0 / 1.09*** ***ON*** ***BORE***

Borehole ID:	635172	**Inclin FLG:**	No
OGF ID:	215535569	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JUN-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657477
Total Depth m:	5	**Longitude DD:**	-79.353499
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632765
Drill Method:	Power auger	**Northing:**	4835148
Orig Ground Elev m:	77.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	80.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472217	**Mat Consistency:**	Loose
Top Depth:	.9	**Material Moisture:**	
Bottom Depth:	2.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT. GREY,BROWN,LACUSTRINE,LOOSE, AGE GLACIAL.		

Geology Stratum ID: 218472216
Top Depth: 0
Bottom Depth: .9
Material Color: Brown
Material 1: Fill
Material 2: Sand
Material 3: Clay
Material 4:
Gsc Material Description:
Stratum Description: FILL,SAND,CLAY. BROWN,LOOSE.

Mat Consistency: Loose
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Geology Stratum ID: 218472219
Top Depth: 4
Bottom Depth: 5
Material Color: Grey
Material 1: Till
Material 2: Clay
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: TILL,CLAY. GREY,GLACIAL,HARD,AGE GLACIAL. 026 0003000800090016001300340007 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Hard
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218472218
Top Depth: 2.7
Bottom Depth: 4
Material Color: Grey
Material 1: Till
Material 2: Clay
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: TILL,CLAY. GREY,GLACIAL,FIRM,AGE GLACIAL.

Mat Consistency: Firm
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031280 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

112	1 of 1	SW/111.4	75.8 / -3.03	1095542 Ontario Ltd 102 Bayview Ave Toronto ON M6R 2K3	GEN

Generator No: ON2715405
Status:
Approval Years: 05
Contam. Facility:

PO Box No:
Country:
Choice of Contact:
Co Admin:

MHSW Facility: **Phone No Admin:**
SIC Code: 485510
SIC Description: Charter Bus Industry

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

113 **1 of 2** **SW/111.5** **75.8 / -3.03** **TORONTO ON** **WWIS**

Well ID: 7185075
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127716
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004100974
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/16/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.894805
Elevrc:
Zone: 17
East83: 632884
North83: 4834875
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004395174
Layer: 1
Plug From: 17.5
Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004395167
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395171
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395172
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395169
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

113 **2 of 2** **SW/111.5** **75.8 / -3.03** **TORONTO ON** **WWIS**

Well ID: 7185073
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127715
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004100968	***Elevation:***	77.894805
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632884
Code OB Desc:		***North83:***	4834875
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/16/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395155
Layer:	1
Plug From:	37.667
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395148
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395152
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395153
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395150
Diameter:	

Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

114 **1 of 1** **NW/113.5** **80.8 / 1.89** **TORONTO ON** **WWIS**

Well ID:	7216130	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	2/10/2014
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Monitoring and Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z184757	**Owner:**	
Tag:	A159305	**Street Name:**	635 QUEEN STREET EAST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004707048	**Elevation:**	81.642173
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632835
Code OB Desc:		**North83:**	4835194
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	1/3/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005075776
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	01
Other Materials:	FILL
Formation Top Depth:	0
Formation End Depth:	4
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005075778
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	
Other Materials:	
Formation Top Depth:	8
Formation End Depth:	13
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005075777
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	4
Formation End Depth:	8
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005075786
Layer:	1
Plug From:	13
Plug To:	2.5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005075787
Layer:	2
Plug From:	2.5
Plug To:	0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005075775
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005075781
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	3
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005075782
Layer:	1
Slot:	.10
Screen Top Depth:	3
Screen End Depth:	13
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.25

Hole Diameter

Hole ID:	1005075779
Diameter:	2.25
Depth From:	0
Depth To:	13
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

115 ***1 of 1*** ***SSW/114.6*** ***75.8 / -3.03*** ***TORONTO ON*** ***WWIS***

Well ID:	7185066	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127720	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	1004100909	***Elevation:***	77.96936
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632938
Code OB Desc:		***North83:***	4834810
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/17/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395026
Layer:	1
Plug From:	17.5
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395019
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395023
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395024
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID: 1004395021
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

116 **1 of 1** **SW/114.7** **75.8 / -3.03** **TORONTO ON** **WWIS**

Well ID: 7185067
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127721
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004100912
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/17/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.909934
Elevrc:
Zone: 17
East83: 632890
North83: 4834863
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004395034
Layer: 1
Plug From: 17.5
Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004395027

Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395031
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395032
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395029
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

117 **1 of 1** **ENE/116.2** **79.8 / 0.97** **ON** **WWIS**

Well ID: 7315921
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: Z285573
Tag: A247018
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status: Yes
Data Src:
Date Received: 8/9/2018
Selected Flag: Yes
Abandonment Rec:
Contractor: 7215
Form Version: 7
Owner:
Street Name:
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Bore Hole ID:	1007238001	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633255
Code OB Desc:		**North83:**	4835095
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	6/26/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

118 **1 of 1** **WNW/116.9** **79.9 / 0.99** **ON** **BORE**

Borehole ID:	635182	**Inclin FLG:**	No
OGF ID:	215535579	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1962	**Municipality:**	
Static Water Level:	0.5	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657434
Total Depth m:	4.8	**Longitude DD:**	-79.353624
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632755
Drill Method:	Power auger	**Northing:**	4835143
Orig Ground Elev m:	76.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.1		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472243	**Mat Consistency:**	
Top Depth:	4.7	**Material Moisture:**	
Bottom Depth:	4.8	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Boulders	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. GREY,WEATHERED, WATER STABLE AT 248.6 FEET.0000000500005FEET.B **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472242	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.7	**Material Texture:**	Coarse
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			

Stratum Description: SILT(55),SAND(33)MEDIUM TO COARSE, CLAY(12). GREY,BROWN,LACUSTRINE,LOOSE, AGE GLACIAL.

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031380 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

119 ***1 of 1*** ***SE/117.2*** ***79.8 / 0.97*** ***Sunlight Park Road Toronto ON*** ***EHS***

Order No:	20160725142	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Custom Report	***Client Prov/State:***	ON
Report Date:	02-AUG-16	***Search Radius (km):***	.03
Date Received:	25-JUL-16	***X:***	-79.348111
Previous Site Name:		***Y:***	43.654948
Lot/Building Size:			
Additional Info Ordered:			

---

120 ***1 of 1*** ***WSW/117.9*** ***77.4 / -1.47*** ***TORONTO ON*** ***WWIS***

Well ID:	7310391	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Test Hole	***Date Received:***	4/17/2018
Sec. Water Use:	Monitoring	***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	6607
Casing Material:		***Form Version:***	7
Audit No:	Z267047	***Owner:***	
Tag:	A243558	***Street Name:***	CORKTOWN COMMONS PARK
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1007035510	***Elevation:***	

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632811
Code OB Desc:		**North83:**	4834951
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/27/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1007211948
Layer:	6
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	25.9
Formation End Depth:	27.4
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007211946
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	2.7
Formation End Depth:	7.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1007211947
Layer:	5
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	7.5

Formation End Depth: 25.9
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007211943
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Other Materials: SILT
Mat3: 05
Other Materials: CLAY
Formation Top Depth: 0
Formation End Depth: 1.5
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007211945
Layer: 3
Color: 8
General Color: BLACK
Mat1: 04
Most Common Material: PEAT
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 2.1
Formation End Depth: 2.7
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1007211944
Layer: 2
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Other Materials: CLAY
Mat3:
Other Materials:
Formation Top Depth: 1.5
Formation End Depth: 2.1
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1007211957
Layer: 1
Plug From: 0
Plug To: 0.3
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID:	1007211958
Layer:	2
Plug From:	0.3
Plug To:	4.5
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007211960
Layer:	4
Plug From:	23.7
Plug To:	25.2
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1007211959
Layer:	3
Plug From:	4.5
Plug To:	23.7
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1007211942
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007211952
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	25.9
Casing Diameter:	5.1
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1007211953
Layer:	1
Slot:	10

Screen Top Depth:	25.9
Screen End Depth:	27.4
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.4

Water Details

Water ID:	1007211950
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	5.4
Water Found Depth UOM:	m

Water Details

Water ID:	1007211951
Layer:	2
Kind Code:	
Kind:	
Water Found Depth:	26.3
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1007211949
Diameter:	21
Depth From:	0
Depth To:	27.4
Hole Depth UOM:	m
Hole Diameter UOM:	cm

121 ***1 of 1*** ***WSW/118.7*** ***76.8 / -2.10*** ***ON*** ***BORE***

Borehole ID:	639907	**Inclin FLG:**	No
OGF ID:	215540303	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1963	**Municipality:**	
Static Water Level:	0.5	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655485
Total Depth m:	29.6	**Longitude DD:**	-79.352747
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632830
Drill Method:	Power auger	**Northing:**	4834928
Orig Ground Elev m:	78.6	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	77.1		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218490221	**Mat Consistency:**	
Top Depth:	4.6	**Material Moisture:**	

Bottom Depth:	13.2	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Shells	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	organic
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM,SHELLS, ORGANIC. GREY,GLACIAL,AGE GLACIAL, WATER STABLE AT 256.5 FEET.		

Geology Stratum ID:	218490220	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL. LOOSE.		

Geology Stratum ID:	218490222	**Mat Consistency:**	
Top Depth:	13.2	**Material Moisture:**	
Bottom Depth:	29.6	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM,SILT. GREY,GLACIAL,AGE GLACIAL. 00000003001500300043405500010 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 078720 NTS_Sheet: 30M11F		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

122	***1 of 1***	***S/119.3***	***76.1 / -2.79***	***ON***	***WWIS***

Well ID:	7179628	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	4/10/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7464
Casing Material:		**Form Version:**	8
Audit No:	C17249	**Owner:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Tag:	A124572	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003755707	**Elevation:**	77.70655
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632989
Code OB Desc:		**North83:**	4834782
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	11/24/2011	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

123 **1 of 1** **W/119.7** **79.3 / 0.42** **ON** **BORE**

Borehole ID:	639908	**Inclin FLG:**	No
OGF ID:	215540304	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1963	**Municipality:**	
Static Water Level:	0.4	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656581
Total Depth m:	28.4	**Longitude DD:**	-79.353833
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632740
Drill Method:	Power auger	**Northing:**	4835048
Orig Ground Elev m:	78.9	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	80.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218490225	**Mat Consistency:**	
Top Depth:	12.2	**Material Moisture:**	
Bottom Depth:	28.4	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	

Material 3: **Geologic Period:**
Material 4: **Depositional Gen:** glacial
Gsc Material Description:
Stratum Description: SAND-MEDIUM,SILT. GREY,AGE GLACIAL. 00000002001400400040002500009 50 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID: 218490223 **Mat Consistency:** Loose
Top Depth: 0 **Material Moisture:**
Bottom Depth: 4.3 **Material Texture:**
Material Color: **Non Geo Mat Type:**
Material 1: Fill **Geologic Formation:**
Material 2: **Geologic Group:**
Material 3: **Geologic Period:**
Material 4: **Depositional Gen:** fill
Gsc Material Description:
Stratum Description: FILL. LOOSE.

Geology Stratum ID: 218490224 **Mat Consistency:**
Top Depth: 4.3 **Material Moisture:**
Bottom Depth: 12.2 **Material Texture:** Medium
Material Color: Grey **Non Geo Mat Type:**
Material 1: Sand **Geologic Formation:**
Material 2: Shells **Geologic Group:**
Material 3: Organic **Geologic Period:**
Material 4: **Depositional Gen:** organic
Gsc Material Description:
Stratum Description: SAND-MEDIUM,SHELLS, ORGANIC. GREY,GLACIAL,AGE GLACIAL, WATER STABLE AT 257.6 FEET.

Source

Source Type: Data Survey **Source Appl:** Spatial/Tabular
Source Orig: Geological Survey of Canada **Source Iden:** 1
Source Date: 1956-1972 **Scale or Res:** Varies
Confidence: M **Horizontal:** NAD27
Observatio: **Verticalda:** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1B.txt RecordID: 078730 NTS_Sheet: 30M11F
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1 **Horizontal Datum:** NAD27
Source Type: Data Survey **Vertical Datum:** Mean Average Sea Level
Source Date: 1956-1972 **Projection Name:** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

124 **1 of 1** **W/120.2** **79.8 / 0.97** **ON** **BORE**

Borehole ID: 635157 **Inclin FLG:** No
OGF ID: 215535554 **SP Status:** Initial Entry
Status: **Surv Elev:** No
Type: Borehole **Piezometer:** No
Use: Geotechnical/Geological Investigation **Primary Name:**
Completion Date: MAR-1962 **Municipality:**
Static Water Level: 3.2 **Lot:**
Primary Water Use: Not Used **Township:**
Sec. Water Use: **Latitude DD:** 43.656445
Total Depth m: 32 **Longitude DD:** -79.353775
Depth Ref: Ground Surface **UTM Zone:** 17
Depth Elev: **Easting:** 632745

Drill Method:	Diamond Drill	**Northing:**	4835033
Orig Ground Elev m:	77.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	83.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472157	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	5.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Wood Fragments	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,CLAY,SILT,WOOD.BROWN,LOOSE.		

Geology Stratum ID:	218472158	**Mat Consistency:**	
Top Depth:	5.8	**Material Moisture:**	
Bottom Depth:	28	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. GREY,BROWN,LACUSTRINE,BEDDED, AGE GLACIAL, WATER STABLE AT 243.5 FEET.		

Geology Stratum ID:	218472159	**Mat Consistency:**	Dense
Top Depth:	28	**Material Moisture:**	
Bottom Depth:	32	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. GREY,GLACIAL,VERY DENSE, AGE NON-GLACIAL.		

Geology Stratum ID:	218472160	**Mat Consistency:**	
Top Depth:	32	**Material Moisture:**	
Bottom Depth:	32	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Boulders	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. 00000008001900090000070004 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Details: File: TOR1A.txt RecordID: 031130 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

125 | **1 of 2** | **W/120.6** | **79.8 / 0.97** | **Infrastructure Ontario (IO)**
124 Bayview Avenue
Toronto ON M5A 3C4 | **GEN**

Generator No: ON8890095
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 221 I
Waste Class Desc: Light fuels

---

125 | **2 of 2** | **W/120.6** | **79.8 / 0.97** | **Infrastructure Ontario (IO)**
124 Bayview Avenue
Toronto ON M5A 3C4 | **GEN**

Generator No: ON8890095
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221 I
Waste Class Desc: Light fuels

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

126 | **1 of 2** | **SW/120.7** | **75.8 / -3.03** | **Eastern Crematory Fill**

Toronto ON M5A | **ANDR**

Legal Description: York
Location Description: Cypress St
Municipality: Toronto City
Current Municipality: Toronto City
RM: Toronto City

Facility:	Dump
Date Active:	1881-91
Date Begun:	
Date Complete:	
Area (Ha):	
Landfill Type:	
Group Name:	
Operated By:	Toronto CC
Serial:	TOR140
NTS:	30M11
Diameter (m):	

Historical Summary:

Fills, Cypress Street In 1881 and 1884 ashes, refuse, mud and scrapings were being deposited here (TCM 1881 Appendix: Committee on Markets & Health 35th report January 11 1882; TCM 1884: Appendix #26 January 14 1885). Eastern Crematory Fill In 1891 the City constructed the Eastern crematory on filled land beside the new Don improvement on eastern Avenue on a new street (later known as Cypress) The lot had a frontage of 22'6" on eastern Avenue, 480' on Cypress and 169'3" on Front Streeet east (TCM: 1891 Appendix 43: Markets & Licences Annual Report). 1885 Map The Don River and ravine area shown in their "unimproved" configuration. The Eastern Crematory site is part of the ravine area. 1903 Map Cypress St is marked, and the Eastern Crematory is also marked at the rear of the lot on an area previously part of the Don ravine. The Don has now been straightened and improved. Take a centroid @ UTM 632880--4834630. 1923 Goad's Atlas I: 29 A [Toronto City] Corporation Yard is marked where, on the 1903 map, the Eastern Crematory was shown, fronting Don Esplanade West. Working conclusion This section of the Don Ravine was at least partially filled 1881-1891, and may have been topped up subsequently.

Waste Type:	street sweepings, street mud and street scrapings, ashes & rubbish
UTM X Nad 27:	632880
UTM Y Nad 27:	4834630
UTM Zone:	17

---

126 **2 of 2** **SW/120.7** **75.8 / -3.03** **Eastern Crematory** **ANDR**

Toronto ON M5A

Legal Description:	York
Location Description:	
Municipality:	Toronto City
Current Municipality:	Toronto City
RM:	Toronto City
Facility:	Incinerator
Date Active:	1881-84
Date Begun:	
Date Complete:	
Area (Ha):	
Landfill Type:	
Group Name:	
Operated By:	Toronto CC
Serial:	TOR141
NTS:	30M11
Diameter (m):	

Historical Summary:

Eastern Crematory In 1891 the City constructed the Eastern crematory on filled land beside the new Don improvement on eastern Avenue on a new street (later known as Cypress) The lot had a frontage of 22'6" on eastern Avenue, 480' on Cypress and 169'3" on Front Streeet east (TCM: 1891 Appendix 43: Markets & Licences Annual Report). Eastern Crematory The Eastern Crematory was constructed under the supervision of City Commissioner Emerson Coatsworth in 1890-1 as a modified version of the Mann system. The building was clad in corrugated metal. It was located at Eastern Crematory, south side of Eastern Avenue, one street west of Don at the Don Bridge, next to the Belt Line Crossing. Its rated capacity (in 1899) was 100 cubic yards daily (TCER 1899: 60). The building was constructed on filled land, over the original course of the Don. The fill proved to be poor for load bearing, and as early as October 1893 one furnace cell was unoperational due to the effects of settlement. Eventually, the entire facility would have to be abandoned due to settlement and other structural defects. In 1891, the eastern stables were removed from Eastern Avenue to the Eastern Crematory lot. The Eastern Crematory was built on filled land on the banks of the Don Improvement. The lot measured 22'6" on Eastern Avenue and 480' on the new street and 169'3" on Front Street. there was a crematory building, stables, caretakers house, sheds, fencing and it was valued at $27,000 in 1891. It had a double furnace, a single 100' smokestack. Its capacity was supposed to be 100 cubic yards a day for ten hours or 200 cubic yards in 24 hours. It began operations six weeks before the City Engineer's Annual Report for 1891. The average consumption of coal in this winter period was 1 ton daily, and it burned 80 to 100 cubic yards daily of combustible refuse. Its operations were seen as satisfactory: consuming less coal

and doing its job. In 1898 the city decided to shut down the Eastern Crematory feeling that it would be cheaper to dump the garbage unburned directly into Ashbridges Bay. The Medical Officer of Health agreed with the idea, although he suggested that some of the garbage might need to be burned. Commissioner Coatsworth tried to oppose the move, but was defeated. By October 1898 the facility was closed, although it continued to see some service in order to assist the overloaded Western crematory. In the 1901 City Engineer's Report the Eastern Crematory was theoretically operational though in need of considerable renovation. Settlement was the worst problem and threatened both furnaces. The Engineer recommended its replacement with a new facility on filled land at Ashbridge's Bay. "No possible complaint of odor" could be expected from a crematory at this location (TCER 1901: 51). Although it continued to operate into 1902, by the end of the year the it had become impossible to use. It was in such a bad state that the engineer feared the building would collapse soon, in a heavy wind storm. The smoke stack had already collapsed. The facility was dead from 1903 onwards, and renovation efforts went into the Western Crematory site. In 1913 the Eastern Crematory site was a City stable and pound. 1885 Map The Don River and ravine area shown in their "unimproved" configuration. The Eastern Crematory site is part of the ravine area. 1903 Map Cypress St is marked, and the Eastern Crematory is also marked at the rear of the lot on an area previously part of the Don ravine. The Don has now been straightened and improved. Take a centroid @ UTM 632880--4834630. 1923 Goad's Atlas I: 29 A [Toronto City] Corporation Yard is marked where, on the 1903 map, the Eastern Crematory was shown, fronting Don Esplanade West.

Waste Type:	garbage, street sweepings, ashes & rubbish, low temperature incinerator ash
UTM X Nad 27:	632880
UTM Y Nad 27:	4834630
UTM Zone:	17

---

127 ***1 of 1*** ***W/121.4*** ***79.8 / 0.97*** ***ON*** ***BORE***

Borehole ID:	635153	***Inclin FLG:***	No
OGF ID:	215535550	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	FEB-1962	***Municipality:***	
Static Water Level:	3.3	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.656263
Total Depth m:	32.9	***Longitude DD:***	-79.353656
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632755
Drill Method:	Power auger	***Northing:***	4835013
Orig Ground Elev m:	77.5	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	84.6		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472141	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	27.4	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. LACUSTRINE,BEDDED,AGE GLACIAL.		

Geology Stratum ID:	218472142	***Mat Consistency:***	
Top Depth:	27.4	***Material Moisture:***	
Bottom Depth:	30.5	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Gravel	***Geologic Group:***	
Material 3:	Boulders	***Geologic Period:***	

Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND,GRAVEL,BOULDERSGLACIAL,AGE GLACIAL, WATER STABLE AT 243.4 FEET.		

Geology Stratum ID:	218472143	**Mat Consistency:**	Stiff
Top Depth:	30.5	**Material Moisture:**	
Bottom Depth:	32.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SAND.GREY,GLACIAL,STIFF, AGE NON-GLACIAL.		

Geology Stratum ID:	218472144	**Mat Consistency:**	
Top Depth:	32.9	**Material Moisture:**	
Bottom Depth:	32.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Boulders	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. 00007 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031090 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
128	1 of 1	NNE/122.5	79.8 / 0.97	715 Queen St E Toronto ON M4M1H1	EHS

Order No:	20171222012	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	02-JAN-18	**Search Radius (km):**	.25
Date Received:	22-DEC-17	**X:**	-79.349346
Previous Site Name:		**Y:**	43.658712
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
129	1 of 3	E/123.2	79.8 / 0.97	APPLEBEE AUTO WRECKERS 361 EASTERN AVE	AUWR

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				TORONTO ON M4M 1B7	

Headcode: 98600
Headcode Desc: Automobile Wrecking & Recycling
Phone: 4164699632
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
129	2 of 3	E/123.2	79.8 / 0.97	361 Eastern Ave. Toronto ON M4M 1B7	EHS

Order No: 20040216006
Status: C
Report Type: Complete Report
Report Date: 2/18/04
Date Received: 2/16/04
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.347012
Y: 43.656495

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
129	3 of 3	E/123.2	79.8 / 0.97	City of Toronto 361 Eastern Ave, Toronto Toronto ON M4M 1B7	SPL

Ref No: 7114-82DSB4
Site No:
Incident Dt:
Year:
Incident Cause: Other Discharges
Incident Event:
Contaminant Code: 15
Contaminant Name: PETROLEUM OIL (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact: Surface Water Pollution
Receiving Medium:
Receiving Env:
MOE Response: Deferred Field Response
Dt MOE Arvl on Scn: 2/11/2010
MOE Reported Dt: 2/5/2010
Dt Document Closed:
Incident Reason: Other - Reason not otherwise defined
Site Name: 361 Eastern Ave, Toronto<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Toronto: ukn amt oil/grease/diesel contam. to cb
Contaminant Qty: 0 other - see incident description

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Watercourse Spills
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
130	1 of 5	SW/123.2	75.8 / -3.03	Infrastructure Ontario (IO) 100 Bayview Avenue Toronto ON M5A 3C4	GEN

Generator No: ON7601588
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

130 ***2 of 5*** ***SW/123.2*** ***75.8 / -3.03*** ***WICKETT AND CRAIG LTD.*** ***GEN***
100 BAYVIEW AVE.
TORONTO ON M5A 3R6

Generator No: ON0187900
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 1711
SIC Description: LEATHER TANNERIES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

130 ***3 of 5*** ***SW/123.2*** ***75.8 / -3.03*** ***WICKETT AND CRAIG LTD. 42-092*** ***GEN***
100 BAYVIEW AVE.
TORONTO ON M5A 3R6

Generator No: ON0187900
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 1711
SIC Description: LEATHER TANNERIES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 243
Waste Class Desc: PCB'S

---

130 ***4 of 5*** ***SW/123.2*** ***75.8 / -3.03*** ***TORONTO,CITY OF PROPERTY DEPT. 37-791*** ***GEN***
100 BAYVIEW AVENUE,C/O 100 QUEEN ST. W.
EAST TOWER, 9TH FLOOR
TORONTO ON M5H 2N2

Generator No: ON0173854
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 8375
SIC Description: REGION. PLAN./ DEV.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 243

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class Desc: PCB'S

---

130 | **5 of 5** | **SW/123.2** | **75.8 / -3.03** | **Infrastructure Ontario (IO)**
100 Bayview Avenue
Toronto ON M5A 3C4 | **GEN**

Generator No:	ON7601588	**PO Box No:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Dec 2018	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

131 | **1 of 1** | **NW/123.8** | **80.8 / 1.97** | **645 Queen St E**
Toronto ON M4M 1G4 | **EHS**

Order No:	20190611212	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	18-JUN-19	**Search Radius (km):**	.25
Date Received:	11-JUN-19	**X:**	-79.35211
Previous Site Name:		**Y:**	43.658055
Lot/Building Size:			

Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos

---

132 | **1 of 1** | **SW/123.9** | **75.8 / -3.03** | **ON** | **WWIS**

Well ID:	7306995	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	3/8/2018
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	0	**Abandonment Rec:**	
Water Type:		**Contractor:**	6607
Casing Material:		**Form Version:**	7
Audit No:	Z255420	**Owner:**	
Tag:	A224248	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006996338	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632883

Code OB Desc:		**North83:**	4834857
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	8/16/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Pipe Information

Pipe ID:	1007201193
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1007201197
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1007201198
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1007201195
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

133 ***1 of 1*** ***NNW/126.6*** ***80.8 / 1.97*** ***TORONTO ON*** ***WWIS***

Well ID:	7190680	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Not Used	**Date Received:**	10/31/2012
Sec. Water Use:	Monitoring	**Selected Flag:**	Yes
Final Well Status:	0	**Abandonment Rec:**	
Water Type:		**Contractor:**	7314
Casing Material:		**Form Version:**	7

Audit No:	Z100820	**Owner:**	
Tag:	A066232	**Street Name:**	677 QUEEN ST E
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004191495	**Elevation:**	80.445121
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632961
Code OB Desc:		**North83:**	4835234
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	8/1/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004531958
Layer:	1
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	
Other Materials:	
Mat3:	81
Other Materials:	SANDY
Formation Top Depth:	0
Formation End Depth:	3.6
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004531959
Layer:	2
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	84
Other Materials:	SILTY
Formation Top Depth:	3.6

Formation End Depth: 5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004531968
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004531967
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1004531957
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004531962
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 3.51
Casing Diameter: 15
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1004531963
Layer: 1
Slot: 10
Screen Top Depth: 3.51
Screen End Depth: 5
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 15

Water Details

Water ID:	1004531961
Layer:	1
Kind Code:	
Kind:	
Water Found Depth:	2.39
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1004531960
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

134 ***1 of 1*** ***WNW/127.2*** ***80.0 / 1.16*** ***ON*** ***BORE***

Borehole ID:	643275	***Inclin FLG:***	No
OGF ID:	215543664	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:		***Primary Name:***	
Completion Date:		***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:		***Township:***	
Sec. Water Use:		***Latitude DD:***	43.657596
Total Depth m:	5	***Longitude DD:***	-79.353619
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632755
Drill Method:		***Northing:***	4835161
Orig Ground Elev m:	77.3	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	78.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218503091	***Mat Consistency:***	
Top Depth:	2.7	***Material Moisture:***	
Bottom Depth:	5	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218503090	***Mat Consistency:***	Loose
Top Depth:	.9	***Material Moisture:***	
Bottom Depth:	2.7	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial

Gsc Material Description:
Stratum Description: SILT. GREY,BROWN,FLUVIO-GLACIAL, LOOSE,AGE GLACIAL.

Geology Stratum ID: 218503089
Top Depth: 0
Bottom Depth: .9
Material Color: Brown
Material 1: Fill
Material 2: Sand
Material 3: Clay
Material 4:
Mat Consistency: Loose
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill
Gsc Material Description:
Stratum Description: FILL,SAND,CLAY. BROWN,LOOSE.

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 112960 NTS_Sheet: 30M11C
Confiden 1: Logs are approximately correct. Lack of information. Doubtful terminology.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

135 | ***1 of 2*** | ***SW/127.5*** | ***75.8 / -3.03*** | ***TORONTO ON*** | ***WWIS***

Well ID: 7185081
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127725
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004101424
DP2BR:
Elevation: 77.498092
Elevrc:

Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632852
Code OB Desc:		**North83:**	4834888
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/17/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395223
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004395222
Layer:	1
Plug From:	29
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395215
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395219
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395220
Layer:	1
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395217
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

135 ***2 of 2*** ***SW/127.5*** ***75.8 / -3.03*** ***TORONTO ON*** ***WWIS***

Well ID:	7185072	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127714	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004100965	***Elevation:***	77.498092
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632852
Code OB Desc:		***North83:***	4834888
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	5
Date Completed:	5/17/2012	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395147
Layer:	1
Plug From:	16.583
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID: 1004395140
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395144
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395145
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395142
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

136 ***1 of 7*** ***NW/128.1*** ***80.8 / 1.97*** ***635 Queen Street East Toronto ON M4M 1G4*** ***EHS***

Order No: 20190816085
Status: C
Report Type: Standard Report
Report Date: 22-AUG-19
Date Received: 16-AUG-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.352579
Y: 43.65802

---

136 ***2 of 7*** ***NW/128.1*** ***80.8 / 1.97*** ***635 Queen St E Toronto On Toronto ON M4M1G4*** ***EHS***

Order No: 20131115002
Status: C
Report Type: Custom Report
Report Date: 21-NOV-13
Date Received: 15-NOV-13
Previous Site Name:
Lot/Building Size:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.352579
Y: 43.65802

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Additional Info Ordered:

---

136 ***3 of 7*** ***NW/128.1*** ***80.8 / 1.97*** ***MIJO CORPORATION*** ***GEN***
635 Queen Street East
Toronto ON M4M 1G4

Generator No:	ON6887244	***PO Box No:***	
Status:		***Country:***	
Approval Years:	03,04	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:			
SIC Description:			

---

136 ***4 of 7*** ***NW/128.1*** ***80.8 / 1.97*** ***MIJO CORPORATION*** ***GEN***
635 QUEEN STREET EAST
TORONTO ON M4M 1G4

Generator No:	ON3467148	***PO Box No:***	
Status:		***Country:***	
Approval Years:	03,04,05,06	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	541430		
SIC Description:	Graphic Design Services		

Detail(s)

Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	264
Waste Class Desc:	PHOTOPROCESSING WASTES

---

136 ***5 of 7*** ***NW/128.1*** ***80.8 / 1.97*** ***Artistat Premedia*** ***SCT***
635 Queen St E
Toronto ON M4M 1G4

Established:	
Plant Size (ft²):	
Employment:	

--Details--

Description:	All Other Support Services
SIC/NAICS Code:	561990
Description:	Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code:	332810
Description:	Graphic Design Services
SIC/NAICS Code:	541430
Description:	Digital Printing
SIC/NAICS Code:	323115
Description:	Other Printing
SIC/NAICS Code:	323119
Description:	Motion Picture and Video Production
SIC/NAICS Code:	512110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Sound Recording Studios
SIC/NAICS Code: 512240

Description: Support Activities for Printing
SIC/NAICS Code: 323120

---

136 **6 of 7** **NW/128.1** **80.8 / 1.97** **Artistat Premedia - Div. of**
635 Queen St E
Toronto ON M4M 1G4 **SCT**

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Digital Printing
SIC/NAICS Code: 323115

Description: Other Printing
SIC/NAICS Code: 323119

Description: Support Activities for Printing
SIC/NAICS Code: 323120

Description: Coating, Engraving, Heat Treating and Allied Activities
SIC/NAICS Code: 332810

Description: Graphic Design Services
SIC/NAICS Code: 541430

---

136 **7 of 7** **NW/128.1** **80.8 / 1.97** **Comprehensive Distributors**
635 Queen St E Floor 1
Toronto ON M4M 1G4 **SCT**

Established: 1980
Plant Size (ft²): 3000
Employment: 35

--Details--
Description: Motion Picture and Video Distribution
SIC/NAICS Code: 512120

---

137 **1 of 9** **SSE/128.3** **79.5 / 0.60** **LEVERBROS**

TORONTO ON **NATE**

File No.: 44622T
Reported By: Province
Material Reaction:
Spill Date: 870527
Lead Agency:
Basin: St. Lawrence River Drainage
Air:
DOE on Scene:
Land:
Fresh Water:
Ground Water:
Salt Water:
Other Environment:

Waterbody:	DON RIVER
Cause:	Overflow
Reason:	Equipment Failure
Source:	Other Storage Facilities
Sector:	General Manufacturing
Ship No.:	
Ship Name:	
Clean Up By:	polluter
Disposal Method:	landfill
Recovery %:	50.00
Act Invoked:	None
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	0.00
No. of Dead:	
Cleanup Cost:	0.00
Material:	sodium ethyl sulfate
Amount (ton):	0.40
Volume (L):	0.00
Concentration:	0.00
Phase:	
Additional Info:	

137	2 of 9	SSE/128.3	79.5 / 0.60	LEVERBROS TORONTO ON	NATE

File No.:	44622T
Reported By:	Province
Material Reaction:	
Spill Date:	870529
Lead Agency:	
Basin:	St. Lawrence River Drainage
Air:	
DOE on Scene:	
Land:	Y
Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	
Cause:	Pipe Leak
Reason:	Material Failure
Source:	Other Industrial Plant
Sector:	General Manufacturing
Ship No.:	
Ship Name:	
Clean Up By:	none
Disposal Method:	none
Recovery %:	0.00
Act Invoked:	None
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N

Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	0.00
No. of Dead:	
Cleanup Cost:	0.00
Material:	surfactant
Amount (ton):	4.00
Volume (L):	0.00
Concentration:	0.00A
Phase:	
Additional Info:	

---

137 | ***3 of 9*** | ***SSE/128.3*** | ***79.5 / 0.60*** | ***LEVERDETERGENTS***

TORONTO ON

NATE

File No.:	MOE83482
Reported By:	Province
Material Reaction:	
Spill Date:	830928
Lead Agency:	
Basin:	St. Lawrence River Drainage
Air:	
DOE on Scene:	
Land:	
Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	DON RIVER
Cause:	Valve, Fitting Leak
Reason:	Material Failure
Source:	Other Industrial Plant
Sector:	General Manufacturing
Ship No.:	
Ship Name:	
Clean Up By:	other
Disposal Method:	unknown
Recovery %:	80.00
Act Invoked:	Unknown
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	0.00
No. of Dead:	
Cleanup Cost:	
Material:	animal fat
Amount (ton):	1.80
Volume (L):	2270.00
Concentration:	
Phase:	

Additional Info:

---

137 ***4 of 9*** ***SSE/128.3*** ***79.5 / 0.60*** ***LEVERBROTHERS*** ***NATE***

TORONTO ON

File No.:	44622T
Reported By:	Province
Material Reaction:	
Spill Date:	870922
Lead Agency:	
Basin:	St. Lawrence River Drainage
Air:	
DOE on Scene:	
Land:	Y
Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	
Cause:	Other
Reason:	Error
Source:	Other Industrial Plant
Sector:	General Manufacturing
Ship No.:	
Ship Name:	
Clean Up By:	polluter
Disposal Method:	recycle
Recovery %:	100.00
Act Invoked:	None
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	0.00
No. of Dead:	
Cleanup Cost:	0.00
Material:	nitrilotriacetic acid
Amount (ton):	0.45
Volume (L):	0.00
Concentration:	0.00
Phase:	
Additional Info:	

---

137 ***5 of 9*** ***SSE/128.3*** ***79.5 / 0.60*** ***LEVERDETERGENTSLTD*** ***NATE***

TORONTO ON

File No.:	MOE76598
Reported By:	Province
Material Reaction:	
Spill Date:	761207
Lead Agency:	
Basin:	St. Lawrence River Drainage
Air:	

DOE on Scene:	
Land:	Y
Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	
Cause:	Pipe Leak
Reason:	Weld, Seam Failure
Source:	Other Industrial Plant
Sector:	General Manufacturing
Ship No.:	
Ship Name:	
Clean Up By:	polluter
Disposal Method:	landfill
Recovery %:	80.00
Act Invoked:	Unknown
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	
No. of Dead:	
Cleanup Cost:	
Material:	fuming sulfuric acid
Amount (ton):	4.50
Volume (L):	2350.00
Concentration:	
Phase:	
Additional Info:	

---

137 | ***6 of 9*** | ***SSE/128.3*** | ***79.5 / 0.60*** | ***LEVER TORONTO ON*** | ***NATE***

File No.:	MOE85089
Reported By:	Province
Material Reaction:	
Spill Date:	850220
Lead Agency:	
Basin:	St. Lawrence River Drainage
Air:	
DOE on Scene:	
Land:	Y
Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	
Cause:	Above Ground Tank Leak
Reason:	Material Failure
Source:	Other Industrial Plant
Sector:	General Manufacturing
Ship No.:	
Ship Name:	
Clean Up By:	polluter
Disposal Method:	recycle

Recovery %:	100.00
Act Invoked:	Unknown
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	
No. of Dead:	
Cleanup Cost:	
Material:	sulfuric acid
Amount (ton):	6.20
Volume (L):	
Concentration:	
Phase:	
Additional Info:	

137	7 of 9	SSE/128.3	79.5 / 0.60	LEVERDETERGENTS TORONTO ON	NATE

File No.:	MOE84445
Reported By:	Province
Material Reaction:	
Spill Date:	840927
Lead Agency:	
Basin:	St. Lawrence River Drainage
Air:	
DOE on Scene:	
Land:	
Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	DON RIVER
Cause:	Discharge
Reason:	Error
Source:	Tank Truck
Sector:	General Manufacturing
Ship No.:	
Ship Name:	
Clean Up By:	polluter
Disposal Method:	unknown
Recovery %:	80.00
Act Invoked:	Unknown
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	
No. of Dead:	

Cleanup Cost:	
Material:	glycerol
Amount (ton):	0.57
Volume (L):	455.00
Concentration:	
Phase:	
Additional Info:	

137 **8 of 9** **SSE/128.3** **79.5 / 0.60** **LEVERDETERGENTS** **NATE**

TORONTO ON

File No.:	MOE83301
Reported By:	Province
Material Reaction:	
Spill Date:	830611
Lead Agency:	
Basin:	St. Lawrence River Drainage
Air:	
DOE on Scene:	
Land:	Y
Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	
Cause:	Cooling System Leak
Reason:	Damage by Equipment
Source:	Other Industrial Plant
Sector:	General Manufacturing
Ship No.:	
Ship Name:	
Clean Up By:	other
Disposal Method:	other
Recovery %:	80.00
Act Invoked:	Unknown
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	0.00
No. of Dead:	
Cleanup Cost:	
Material:	pcb
Amount (ton):	
Volume (L):	
Concentration:	
Phase:	
Additional Info:	

137 **9 of 9** **SSE/128.3** **79.5 / 0.60** **LEVERDETERGENT** **NATE**

TORONTO ON

File No.:	MOE83569

Reported By:	Province
Material Reaction:	
Spill Date:	831125
Lead Agency:	
Basin:	St. Lawrence River Drainage
Air:	
DOE on Scene:	
Land:	
Fresh Water:	
Ground Water:	
Salt Water:	
Other Environment:	
Waterbody:	DON RIVER
Cause:	Container Leak
Reason:	Damage by Equipment
Source:	Other Industrial Plant
Sector:	General Manufacturing
Ship No.:	
Ship Name:	
Clean Up By:	none
Disposal Method:	none
Recovery %:	0.00
Act Invoked:	Unknown
Enforcement Resp:	
Fish Kill:	N
Oiled Birds:	N
Other Kill:	N
Vegetation Damage:	N
Property Damage:	N
Drinking Water:	N
Income Loss:	N
Other Consequences:	N
No. of Injuries:	
No. of Evacuations:	
Fine:	0.00
No. of Dead:	
Cleanup Cost:	
Material:	surfactant
Amount (ton):	0.20
Volume (L):	214.00
Concentration:	
Phase:	
Additional Info:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
138	1 of 1	N/128.7	80.5 / 1.65	**Ancient Excavation** **697 Queen St E** **Toronto ON M4M 1G6**	SCT

Established:	1997
Plant Size (ft²):	
Employment:	

--Details--

Description:	All Other Non-Metallic Mineral Product Manufacturing
SIC/NAICS Code:	327990

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
139	1 of 2	ENE/129.1	79.8 / 0.97	**SWEDISH MOTORS** **356 EASTERN AVE** **TORONTO ON M4M 1B8**	AUWR

Headcode:	98600

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Headcode Desc: Automobile Wrecking & Recycling
Phone: 4168686586
List Name:
Description: Automobile Wrecking

---

139 **2 of 2** **ENE/129.1** **79.8 / 0.97** **356 Eastern Avenue Toronto ON** **EHS**

Order No: 20170109041
Status: C
Report Type: Standard Report
Report Date: 12-JAN-17
Date Received: 09-JAN-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.347217
Y: 43.65679

---

140 **1 of 1** **SSE/129.1** **79.6 / 0.77** **Toronto ON** **WWIS**

Well ID: 7310413
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z275541
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 4/17/2018
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 7383
Form Version: 7
Owner:
Street Name: 11 SUNLIGHT PARK RD
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1007035689
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 3/21/2018
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 633145
North83: 4834828
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Pipe Information

Pipe ID: 1007213930
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1007213935
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1007213936
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1007213933
Diameter:
Depth From: 0
Depth To: 22
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

141 **1 of 1** **WNW/129.7** **80.0 / 1.16** **ON** **BORE**

Borehole ID: 635171
OGF ID: 215535568
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JUN-1962
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 4.8
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 77.4
Elev Reliabil Note:
DEM Ground Elev m: 78.9
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.657632
Longitude DD: -79.353618
UTM Zone: 17
Easting: 632755
Northing: 4835165
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID:	218472213	***Mat Consistency:***	Compact
Top Depth:	1.2	***Material Moisture:***	
Bottom Depth:	2.4	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT. BROWN,LACUSTRINE,COMPACT, AGE GLACIAL.		

Geology Stratum ID:	218472214	***Mat Consistency:***	Stiff
Top Depth:	2.4	***Material Moisture:***	
Bottom Depth:	4	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,STIFF, AGE GLACIAL.		

Geology Stratum ID:	218472212	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	1.2	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Clay	***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND,CLAY. BROWN,LOOSE.		

Geology Stratum ID:	218472215	***Mat Consistency:***	Hard
Top Depth:	4	***Material Moisture:***	
Bottom Depth:	4.8	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,HARD,AGE GLACIAL. 014 000400090008001100130036000070 18 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031270 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

142 **1 of 1** **NW/130.0** **79.8 / 0.91** **TORONTO ON** **WWIS**

Well ID:	6928986	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	6/8/2005
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	3
Audit No:	Z25308	**Owner:**	
Tag:	A024928	**Street Name:**	625 QUEEN STREET WEST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	UNIT 2
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	11327955	**Elevation:**	82.321273
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:	o	**East83:**	632795.9
Code OB Desc:	Overburden	**North83:**	4835198
Open Hole:		**Org CS:**	G83a
Cluster Kind:		**UTMRC:**	4
Date Completed:	4/14/2005	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933037847
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	85
Other Materials:	SOFT
Formation Top Depth:	3.1
Formation End Depth:	5.49
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933037846
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	84
Other Materials:	SILTY
Mat3:	01
Other Materials:	FILL
Formation Top Depth:	0.3
Formation End Depth:	3.1
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933037845
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	77
Other Materials:	LOOSE
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	0.3
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933270335
Layer:	1
Plug From:	0
Plug To:	0.3
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933270336
Layer:	2
Plug From:	0.3
Plug To:	2.13
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933270337
Layer:	3
Plug From:	2.13
Plug To:	5.49
Plug Depth UOM:	m

Method of Construction & Well

Use

Method Construction ID:
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11342810
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930872944
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 2.44
Casing Diameter: 3.17
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933413051
Layer: 1
Slot: 10
Screen Top Depth: 2.44
Screen End Depth: 5.49
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 3.67

Hole Diameter

Hole ID: 11549099
Diameter: 8.255
Depth From: 0
Depth To: 5.49
Hole Depth UOM: m
Hole Diameter UOM: cm

---

143 ***1 of 1*** ***SSW/130.9*** ***76.2 / -2.68*** ***TORONTO ON*** ***WWIS***

Well ID: 7185097
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127735
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:

Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004101548	***Elevation:***	77.852485
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632927
Code OB Desc:		***North83:***	4834798
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/18/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395359
Layer:	1
Plug From:	28.917
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395352
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395356
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395357
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	

Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395354
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

144 | **1 of 1** | **NNE/131.4** | **79.8 / 0.97** | **711 Queen St E**
Toronto ON M4M1H1 | **EHS**

Order No: 20170731096
Status: C
Report Type: Standard Report
Report Date: 08-AUG-17
Date Received: 31-JUL-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.349482
Y: 43.658781

---

145 | **1 of 6** | **NNE/131.8** | **79.8 / 0.97** | **Remembrance Services Inc.**
717 Queen St. E.
TORONTO ON M4M 1H1 | **GEN**

Generator No: ONF029500
Status:
Approval Years: 02,03,04,05,06
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

145 | **2 of 6** | **NNE/131.8** | **79.8 / 0.97** | **BROWN BROS. FUNERAL HOMES**
717 QUEEN STREET EAST
TORONTO ON M4M 1H1 | **GEN**

Generator No: ONF029500
Status:
Approval Years: 00,01
Contam. Facility:
MHSW Facility:
SIC Code: 9731
SIC Description: FUNERAL HOMES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	3 of 6	NNE/131.8	79.8 / 0.97	BROWN BROS FUNERAL HOMES 44-295 WASHINGTON & JOHNSTON FUNERAL HOME 717 QUEEN STREET EAST TORONTO ON M4M 1H1	GEN

Generator No: ONF029500
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 9731
SIC Description: FUNERAL HOMES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	4 of 6	NNE/131.8	79.8 / 0.97	BROWN BROS FUNERAL HOMES 717 QUEEN STREET EAST TORONTO ON M4M 1H1	GEN

Generator No: ONF029500
Status:
Approval Years: 92,93,97,98,99
Contam. Facility:
MHSW Facility:
SIC Code: 9731
SIC Description: FUNERAL HOMES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	5 of 6	NNE/131.8	79.8 / 0.97	BROWN BROS FUNERAL HOMES WASHINGTON & JOHNSTON FUNERAL HOME 717 QUEEN STREET EAST TORONTO ON M4M 1H1	GEN

Generator No: ONF029500
Status:
Approval Years: 88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 9731
SIC Description: FUNERAL HOMES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
145	6 of 6	NNE/131.8	79.8 / 0.97	Johnston B 717 Queen St E Toronto ON M4M 1H1	TANK

Permit Date: 1/27/1920
Permit Type: BP 39916
User Type:

Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	200
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	

146 **1 of 1** **SW/132.5** **75.8 / -3.03** **TORONTO ON** **WWIS**

Well ID:	7157751	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Other	**Date Received:**	1/14/2011
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	7
Audit No:	Z122207	**Owner:**	
Tag:		**Street Name:**	100 MILL ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003456236	**Elevation:**	77.748657
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632882
Code OB Desc:		**North83:**	4834845
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	11/4/2010	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1003781585
Layer:	1
Plug From:	0
Plug To:	20
Plug Depth UOM:	ft

Pipe Information

Pipe ID: 1003781576
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1003781580
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1003781581
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1003781578
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

147 | ***1 of 1*** | ***S/132.7*** | ***76.7 / -2.16*** | ***ON*** | ***WWIS***

Well ID: 6905489
Construction Date:
Primary Water Use: Not Used
Sec. Water Use: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No:
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:

Data Entry Status:
Data Src: 1
Date Received: 2/19/1952
Selected Flag: Yes
Abandonment Rec:
Contractor: 2801
Form Version: 1
Owner:
Street Name:
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	10496194	***Elevation:***	78.093544
DP2BR:	94	***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:	r	***East83:***	632976.8
Code OB Desc:	Bedrock	***North83:***	4834771
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	1/15/1952	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	p9
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932728689
Layer:	3
Color:	3
General Color:	BLUE
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	37
Formation End Depth:	51
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932728690
Layer:	4
Color:	3
General Color:	BLUE
Mat1:	05
Most Common Material:	CLAY
Mat2:	11
Other Materials:	GRAVEL
Mat3:	
Other Materials:	
Formation Top Depth:	51
Formation End Depth:	94
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932728688
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	03

Most Common Material:	MUCK
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	18
Formation End Depth:	37
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932728687
Layer:	1
Color:	
General Color:	
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	18
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932728691
Layer:	5
Color:	3
General Color:	BLUE
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	94
Formation End Depth:	110
Formation End Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	11044764
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930808530
Layer:	1

Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

---

148 ***1 of 1*** ***W/133.5*** ***79.8 / 0.97*** ***ON*** ***BORE***

Borehole ID:	635197	***Inclin FLG:***	No
OGF ID:	215535594	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	JAN-1962	***Municipality:***	
Static Water Level:	3.3	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.656357
Total Depth m:	33.4	***Longitude DD:***	-79.353901
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632735
Drill Method:	Power auger	***Northing:***	4835023
Orig Ground Elev m:	77.4	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	83.3		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472298	***Mat Consistency:***	
Top Depth:	4.3	***Material Moisture:***	
Bottom Depth:	27.1	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. GREY,BROWN,LACUSTRINE,BEDDED, AGE GLACIAL, WATER STABLE AT 243.1 FEET.		

Geology Stratum ID:	218472301	***Mat Consistency:***	
Top Depth:	33.3	***Material Moisture:***	
Bottom Depth:	33.4	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Boulders	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. 000000080014000600008 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472299	***Mat Consistency:***	Dense
Top Depth:	27.1	***Material Moisture:***	
Bottom Depth:	31.1	***Material Texture:***	Fine
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Gravel	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	

Material 4:	Boulders	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	GRAVEL(67),SAND(23)FINE,SILT(09), BOULDERS. GREY,GLACIAL,VERY DENSE, AGE GLACIAL.		

Geology Stratum ID:	218472300	**Mat Consistency:**	Hard
Top Depth:	31.1	**Material Moisture:**	
Bottom Depth:	33.3	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SAND.GREY,GLACIAL,HARD, AGE NON-GLACIAL.		

Geology Stratum ID:	218472297	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.3	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Organic	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,CLAY,SILT, ORGANIC. BROWN,LOOSE,VARVED.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031530 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

149 | ***1 of 1*** | ***WSW/133.9*** | ***79.1 / 0.22*** | ***ON*** | ***WWIS***

Well ID:	7215540	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	1/27/2014
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	8
Audit No:	C23563	**Owner:**	
Tag:	A155108	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004700048	**Elevation:**	76.66365
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632779
Code OB Desc:		**North83:**	4834964
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	12/11/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

150 | ***1 of 5*** | ***NW/135.4*** | ***80.0 / 1.14*** | ***Streetcar Riverside (625) Developments Ltd.***
625 Queen Street East, Toronto, Ontario, M4M 1G4
Toronto ON M4M 1G4 | ***RSC***

RSC ID:	13106	**Cert Date:**	2-Feb-07
RA No:		**Cert Prop Use No:**	No CPU
RSC Type:		**Intended Prop Use:**	Residential
Curr Property Use:	Commercial	**Qual Person Name:**	Les Mallins
Ministry District:	TORONTO	**Stratified (Y/N):**	
Filing Date:	27-Feb-07	**Audit (Y/N):**	
Date Ack:		**Entire Leg Prop. (Y/N):**	Yes
Date Returned:		**Accuracy Estimate:**	21 to 100 meters
Restoration Type:		**Telephone:**	416-6869199
Soil Type:		**Fax:**	416-6154181
Criteria:		**Email:**	lmallins@streetcar.ca
CPU Issued Sect 1686:	No		

Asmt Roll No: 1904071-220003000000
Prop ID No (PIN): 21077-0191 LT
Property Municipal Address: 625 Queen Street East, Toronto, Ontario, M4M 1G4
Mailing Address: 569 King Street East, Toronto, Ontario, M5A 1M5
Latitude & Latitude: 43.65569030N 79.35311000W (converted from UTM)
UTM Coordinates: NAD83 17-632800-4834950
Consultant:
Filing Owner:
Legal Desc: PART OF LOT 15, CONCESSION BROKEN FRONT DESIGNATED AS PART 1 ON PLAN 66R-22056. CITY OF TORONTO
Measurement Method: Interpolation from a map
Applicable Standards: Full Depth Site Conditions Standard, with Nonpotable Ground Water, Medium/Fine Textured Soil, for Residential/Parkland/Institutional property use
RSC PDF:

---

150 | ***2 of 5*** | ***NW/135.4*** | ***80.0 / 1.14*** | ***Imperial Oil Co Ltd***
625 Queen St E
Toronto ON M4M 1G4 | ***TANK***

Permit Date: 10/15/1923

Permit Type:	BP 74532
User Type:	Gasoline service station
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	200
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	Queen St E cor davies

---

150 | ***3 of 5*** | ***NW/135.4*** | ***80.0 / 1.14*** | ***Imperial Oil Co Ltd***
625 Queen St E
Toronto ON M4M 1G4 | ***TANK***

Permit Date:	12/12/1934
Permit Type:	BP A54038
User Type:	Gasoline service station
Installation Type:	gasoline service station alteration & addition
Installation Size:	
Installation Config.:	gasoline service station alteration & addition
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	1500
Capacity(gal):	
Reference:	CTA Building Permits
Location Desc:	Queen SE cor Don Roadway

---

150 | ***4 of 5*** | ***NW/135.4*** | ***80.0 / 1.14*** | ***Imperial Oil Co Ltd***
625 Queen St E
Toronto ON M4M 1G4 | ***TANK***

Permit Date:	11/29/1934
Permit Type:	BP A53922
User Type:	Gasoline service station
Installation Type:	gasoline service station
Installation Size:	
Installation Config.:	gasoline service station
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	7600
Capacity(gal):	
Reference:	CTA Building Permits
Location Desc:	SE cor Queen & Don Roadway

---

150 | ***5 of 5*** | ***NW/135.4*** | ***80.0 / 1.14*** | ***Imperial Oil Co Ltd***
625 Queen St E
Toronto ON M4M 1G4 | ***TANK***

Permit Date:	1/23/1935
Permit Type:	BP A54306
User Type:	Gasoline service station
Installation Type:	gasoline tanks
Installation Size:	
Installation Config.:	gasoline tanks
No. Tanks Installed:	2
Units of Measure:	
Value/Tank ($):	900
Capacity(gal):	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Reference:		CTA Building Permits			
Location Desc:		Queen St E & Don Roadway			

151	1 of 1	NW/136.0	80.8 / 1.97	**Mary Macleod's Shortbread** **639 Queen St E** **Toronto ON M4M 1G4**	SCT

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Retail Bakeries
SIC/NAICS Code: 311811

152	1 of 2	NW/137.8	80.8 / 1.97	**Markplan Inc. - The Magazine** **643 Queen St E** **Toronto ON M4M 1G4**	SCT

Established: 01-JUL-91
Plant Size (ft²):
Employment:

--Details--
Description: Periodical Publishers
SIC/NAICS Code: 511120

152	2 of 2	NW/137.8	80.8 / 1.97	**The Magazine - Div. of Markpla** **643 Queen St E** **Toronto ON M4M 1G4**	SCT

Established:
Plant Size (ft²):
Employment: 20

--Details--
Description: Periodical Publishers
SIC/NAICS Code: 511120

153	1 of 1	N/138.7	80.7 / 1.88	**Toronto ON**	WWIS

Well ID:	7298322	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	11/1/2017
Sec. Water Use:	Monitoring	**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7383
Casing Material:		**Form Version:**	7
Audit No:	Z264510	**Owner:**	
Tag:	A235339	**Street Name:**	911 QUEEN ST E
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1006787800
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 9/15/2017
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 80.479454
Elevrc:
Zone: 17
East83: 633055
North83: 4835299
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1006906911
Layer: 2
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3: 28
Other Materials: SAND
Formation Top Depth: 1
Formation End Depth: 14
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006906910
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2: 11
Other Materials: GRAVEL
Mat3: 28
Other Materials: SAND
Formation Top Depth: 0
Formation End Depth: 1
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006906919
Layer: 1
Plug From: 0
Plug To: 1
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006906921
Layer: 3
Plug From: 3
Plug To: 14
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006906920
Layer: 2
Plug From: 1
Plug To: 3
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1006906909
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006906914
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 4
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006906915
Layer: 1
Slot: .10
Screen Top Depth: 4
Screen End Depth: 14
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Screen Diameter: 2.375

Water Details

Water ID: 1006906913
Layer: 1
Kind Code: 8
Kind: Untested
Water Found Depth: 13
Water Found Depth UOM: ft

Hole Diameter

Hole ID: 1006906912
Diameter: 4
Depth From: 0
Depth To: 14
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

154 | ***1 of 3*** | ***NW/139.1*** | ***80.8 / 1.97*** | ***Printopolis Inc.***
651 Queen St E
Toronto ON M4M 1G4 | ***SCT***

Established: 01-AUG-07
Plant Size (ft²):
Employment:

--Details--
Description: Digital Printing
SIC/NAICS Code: 323115

Description: Sound Recording Studios
SIC/NAICS Code: 512240

Description: Digital Printing
SIC/NAICS Code: 323115

---

154 | ***2 of 3*** | ***NW/139.1*** | ***80.8 / 1.97*** | ***Longboat Alliance Graphics Group Inc.***
651 Queen St E
Toronto ON M4M 1G4 | ***SCT***

Established: 1997
Plant Size (ft²):
Employment: 6

--Details--
Description: Other Printing
SIC/NAICS Code: 323119

Description: Support Activities for Printing
SIC/NAICS Code: 323120

---

154 | ***3 of 3*** | ***NW/139.1*** | ***80.8 / 1.97*** | ***Longboat Alliance Graphics Gro***
651 Queen St E
Toronto ON M4M 1G4 | ***SCT***

Established: 1997

Plant Size (ft²):
Employment:

--Details--
Description: Digital Printing
SIC/NAICS Code: 323115

Description: Support Activities for Printing
SIC/NAICS Code: 323120

---

155 | 1 of 1 | SSW/139.2 | 76.8 / -2.03 | TORONTO ON | WWIS

Well ID: 7185098
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127738
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004101551
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/19/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 78.024833
Elevrc:
Zone: 17
East83: 632967
North83: 4834767
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004395367
Layer: 1
Plug From:
Plug To:
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004395360
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395364
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395365
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395362
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

156 | ***1 of 1*** | ***SSE/139.8*** | ***79.8 / 0.93*** | ***Eastern Avenue And Sunlight Park Road Toronto ON*** | ***EHS***

Order No: 20160314238
Status: C
Report Type: Custom Report
Report Date: 21-MAR-16
Date Received: 14-MAR-16
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .03
X: -79.348817
Y: 43.65444

---

157 | ***1 of 1*** | ***NNW/140.4*** | ***80.8 / 1.97*** | ***Cdn Inst of Cultural Affairs 655 Queen St E Toronto ON M4M 1G4*** | ***SCT***

Established: 01-OCT-76
Plant Size (ft²):
Employment:

--Details--
Description: Business Associations
SIC/NAICS Code: 813910

---

158 ***1 of 2*** ***SSW/141.3*** ***76.8 / -2.07*** ***TORONTO ON*** ***WWIS***

Well ID:	7185095	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127733	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101542	***Elevation:***	77.773162
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632941
Code OB Desc:		***North83:***	4834776
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/18/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395343
Layer:	1
Plug From:	37
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395336
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395340
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395341
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395338
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

158 ***2 of 2*** ***SSW/141.3*** ***76.8 / -2.07*** ***TORONTO ON*** ***WWIS***

Well ID:	7185065	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127728	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004100906	***Elevation:***	77.773162
DP2BR:		***Elevrc:***	

Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632941
Code OB Desc:		**North83:**	4834776
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/18/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395015
Layer:	1
Plug From:	34.5
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395008
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395012
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395013
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395010
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
159	1 of 1	W/141.4	79.8 / 0.97	ON	BORE

Borehole ID:	635151	**Inclin FLG:**	No
OGF ID:	215535548	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656085
Total Depth m:	31.4	**Longitude DD:**	-79.353785
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632745
Drill Method:	Power auger	**Northing:**	4834993
Orig Ground Elev m:	77.5	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	82.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472133	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	27.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. LACUSTRINE,BEDDED,AGE GLACIAL.		

Geology Stratum ID:	218472135	**Mat Consistency:**	Stiff
Top Depth:	31.1	**Material Moisture:**	
Bottom Depth:	31.4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SAND.GREY,GLACIAL,STIFF, AGE NON-GLACIAL.		

Geology Stratum ID:	218472136	**Mat Consistency:**	
Top Depth:	31.4	**Material Moisture:**	
Bottom Depth:	31.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Boulders	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. I **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472134	**Mat Consistency:**	
Top Depth:	27.1	**Material Moisture:**	
Bottom Depth:	31.1	**Material Texture:**	

Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:	Boulders	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND,GRAVEL,BOULDERSGREY,GLACIAL,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031070 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

160 | ***1 of 1*** | ***NNE/141.9*** | ***79.9 / 0.99*** | ***709 - 717 1/2 Queen Street East, Toronto ON M4M 1H1*** | ***EHS***

Order No:	20101202031	**Nearest Intersection:**	Queen Street East and Broadview Avenue
Status:	C	**Municipality:**	Toronto
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	12/8/2010	**Search Radius (km):**	0.25
Date Received:	12/2/2010 12:35:19 PM	**X:**	-79.349365
Previous Site Name:		**Y:**	43.658886
Lot/Building Size:			
Additional Info Ordered:			

---

161 | ***1 of 1*** | ***N/142.6*** | ***80.8 / 1.97*** | ***Fish W A, 685 Queen St E, Toronto ON M4M 1G6*** | ***TANK***

Permit Date:	7/7/1924
Permit Type:	BP 80715
User Type:	
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	20
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	

---

162 | ***1 of 6*** | ***NNW/142.7*** | ***80.8 / 1.97*** | ***77 & 79 EDR INC., 677 Queen ST E, Toronto ON M4M 1G6*** | ***EASR***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval No:	R-009-4111223508	**SWP Area Name:**	Toronto
Status:	REGISTERED	**MOE District:**	Metro Toronto
Date:	2019-04-18	**Municipality:**	Toronto
Record Type:	EASR	**Latitude:**	43.65805556
Link Source:	MOFA	**Longitude:**	-79.35083333
Project Type:	Water Taking - Construction Dewatering	**Geometry X:**	
Full Address:		**Geometry Y:**	
Approval Type:	EASR-Water Taking - Construction Dewatering		
Full PDF Link:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2145812		

---

162 **2 of 6** **NNW/142.7** **80.8 / 1.97** **677 Queen Street East**
Toronto ON **EHS**

Order No:	20140911059	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	QC
Report Date:	15-SEP-14	**Search Radius (km):**	.25
Date Received:	11-SEP-14	**X:**	-79.351002
Previous Site Name:		**Y:**	43.658364
Lot/Building Size:			
Additional Info Ordered:			

---

162 **3 of 6** **NNW/142.7** **80.8 / 1.97** **677 Queen Street East**
Toronto ON M4M 1G6 **EHS**

Order No:	20050520014	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:		**Client Prov/State:**	ON
Report Date:	5/31/2005	**Search Radius (km):**	0.25
Date Received:	5/20/2005	**X:**	-79.351189
Previous Site Name:		**Y:**	43.658519
Lot/Building Size:			
Additional Info Ordered:			

---

162 **4 of 6** **NNW/142.7** **80.8 / 1.97** **677 Queen Street East**
Toronto ON M4M 1G6 **EHS**

Order No:	20120705021	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	16-JUL-12	**Search Radius (km):**	.25
Date Received:	05-JUL-12	**X:**	-79.350928
Previous Site Name:		**Y:**	43.658512
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans		

---

162 **5 of 6** **NNW/142.7** **80.8 / 1.97** **Clean Harbors Canada Inc.**
alley behind 677 Queen St East
Toronto ON **SPL**

Ref No:	4807-B8BL7Q	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	2019/01/11	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	Corporation
Incident Cause:		**Sector Type:**	Miscellaneous Industrial
Incident Event:	Overflow/Surcharge	**Agency Involved:**	
Contaminant Code:	46	**Nearest Watercourse:**	
Contaminant Name:	WASTE OIL	**Site Address:**	alley behind 677 Queen St East

Contaminant Limit 1:		**Site District Office:**	Toronto - District
Contam Limit Freq 1:	n/a	**Site Postal Code:**	
Contaminant UN No 1:	1993	**Site Region:**	Central
Environment Impact:		**Site Municipality:**	Toronto
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Land; Source Water Zone	**Northing:**	4835274
MOE Response:	No	**Easting:**	632970
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2019/01/11	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:	Operator/Human Error	**Source Type:**	Tank - Above Ground

Site Name: customer site behind Toyota<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Clean Harbors: waste oil to grd, ctnd,clng 30 L
Contaminant Qty: 30 L

---

162 | ***6 of 6*** | ***NNW/142.7*** | ***80.8 / 1.97*** | ***Riverdale Lumber Co***
677 Queen St E
Toronto ON M4M 1G6 | ***TANK***

Permit Date: 3/19/1920
Permit Type: BP 40418
User Type: Lumber dealer
Installation Type: Gasoline tank
Installation Size:
Installation Config.: 1 x Gasoline tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 325
Capacity(gal):
Reference: CTA Building permits
Location Desc:

---

163 | ***1 of 1*** | ***SW/143.1*** | ***75.8 / -3.03*** | ***TORONTO ON*** | ***WWIS***

Well ID:	7185079	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127724	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101418	**Elevation:**	77.585212
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632874
Code OB Desc:		**North83:**	4834838
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/17/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395206
Layer:	1
Plug From:	31.5
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395199
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395203
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395204
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395201
Diameter:	
Depth From:	
Depth To:	

Hole Depth UOM: ft
Hole Diameter UOM: inch

---

164 **1 of 1** **WNW/143.3** **79.9 / 1.05** **ON** **BORE**

Borehole ID:	643276	**Inclin FLG:**	No
OGF ID:	215543665	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:		**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:		**Township:**	
Sec. Water Use:		**Latitude DD:**	43.657706
Total Depth m:	4.8	**Longitude DD:**	-79.353753
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632744
Drill Method:		**Northing:**	4835173
Orig Ground Elev m:	77.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218503092	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SAND,CLAY. BROWN,LOOSE.		

Geology Stratum ID:	218503094	**Mat Consistency:**	Stiff
Top Depth:	2.4	**Material Moisture:**	
Bottom Depth:	4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,STIFF, AGE GLACIAL.		

Geology Stratum ID:	218503093	**Mat Consistency:**	Compact
Top Depth:	1.2	**Material Moisture:**	
Bottom Depth:	2.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT. BROWN,FLUVIO-GLACIAL,COMPACT, AGE GLACIAL.		

Geology Stratum ID:	218503095	**Mat Consistency:**	Hard
Top Depth:	4	**Material Moisture:**	

Bottom Depth:	4.8	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,HARD,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 112970 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

165 | ***1 of 1*** | ***NNE/144.6*** | ***79.8 / 0.97*** | ***85 Lewis Street in Toronto Toronto ON*** | ***SPL***

Ref No:	1114-ARCPUJ	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	9/19/2017	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Industrial
Incident Event:	Leak/Break	**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	NATURAL GAS (METHANE)	**Site Address:**	85 Lewis Street in Toronto
Contaminant Limit 1:		**Site District Office:**	Toronto - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:	1075	**Site Region:**	Central
Environment Impact:		**Site Municipality:**	Toronto
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:	Air	**Northing:**	
MOE Response:	No	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/19/2017	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Incident Reason:	Operator/Human Error	**Source Type:**	Valve/Fitting/Piping
Site Name:	85 Lewis Street in Toronto<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TSSA FSB: 1/2" pl IP service damage, made safe		
Contaminant Qty:	0 other - see incident description		

---

166 | ***1 of 1*** | ***SW/144.6*** | ***75.8 / -3.03*** | ***TORONTO ON*** | ***WWIS***

Well ID:	7185101	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127713	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101560	**Elevation:**	77.200805
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632844
Code OB Desc:		**North83:**	4834871
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/17/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395394
Layer:	1
Plug From:	23
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395387
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395391
Layer:	
Material:	
Open Hole or Material:	
Depth From:	

Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395392
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395389
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

167 **1 of 1** **W/144.8** **79.7 / 0.87** **ON** **WWIS**

Well ID: 7260214
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: C27831
Tag: A178786
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status: Yes
Data Src:
Date Received: 3/30/2016
Selected Flag: Yes
Abandonment Rec:
Contractor: 7215
Form Version: 8
Owner:
Street Name:
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1005916957
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 3/6/2015
Remarks:
Elevrc Desc:

Elevation: 81.946815
Elevrc:
Zone: 17
East83: 632724
North83: 4835019
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

168 ***1 of 1*** ***WNW/145.9*** ***79.7 / 0.84*** ***ON*** ***BORE***

Borehole ID:	635196	***Inclin FLG:***	No
OGF ID:	215535593	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	JUN-1962	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.657883
Total Depth m:	11.9	***Longitude DD:***	-79.35355
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632760
Drill Method:	Power auger	***Northing:***	4835193
Orig Ground Elev m:	84.1	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	80.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472294	***Mat Consistency:***	Dense
Top Depth:	2.4	***Material Moisture:***	
Bottom Depth:	7.6	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND. BROWN,LACUSTRINE,DENSE, AGE GLACIAL.		

Geology Stratum ID:	218472293	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2.4	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Granuls	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,CINDERS. BROWN,LOOSE.		

Geology Stratum ID:	218472295	***Mat Consistency:***	Stiff
Top Depth:	7.6	***Material Moisture:***	
Bottom Depth:	10.1	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,STIFF, AGE GLACIAL.		

Geology Stratum ID:	218472296	**Mat Consistency:**	Hard
Top Depth:	10.1	**Material Moisture:**	
Bottom Depth:	11.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			

Stratum Description: TILL,CLAY. GREY,GLACIAL,HARD,AGE GLACIAL. 006015019 0150130110000000500080023002500 18 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031520 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

169 | ***1 of 1*** | ***NNE/146.1*** | ***79.8 / 0.97*** | ***711-717.5 Queen Street East, Toronto ON M4M 1H1*** | ***EHS***

Order No:	20080812021	**Nearest Intersection:**	Broadview Avenue
Status:	C	**Municipality:**	Toronto
Report Type:	Complete Report	**Client Prov/State:**	ON
Report Date:	8/21/2008	**Search Radius (km):**	0.25
Date Received:	8/12/2008	**X:**	-79.349129
Previous Site Name:		**Y:**	43.658678
Lot/Building Size:	Approximately 0.09 ha		
Additional Info Ordered:	Fire Insur. Maps And /or Site Plans		

---

170 | ***1 of 4*** | ***SW/146.5*** | ***75.8 / -3.03*** | ***Infrastructure Ontario (IO), 155 Bayview Avenue, Toronto ON M5A 3C4*** | ***GEN***

Generator No:	ON7521288	**PO Box No:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Jul 2019	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class:	251 L
Waste Class Desc:	Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
170	2 of 4	SW/146.5	75.8 / -3.03	Toronto Transit Commission 155 Bayview Avenue Toronto ON M5A 0G4	GEN

Generator No: ON2570064
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 146 L
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 221 L
Waste Class Desc: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
170	3 of 4	SW/146.5	75.8 / -3.03	Infrastructure Ontario (IO) 155 Bayview Avenue Toronto ON M5A 3C4	GEN

Generator No: ON7521288
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
170	4 of 4	SW/146.5	75.8 / -3.03	Toronto Transit Commission 155 Bayview Avenue Toronto ON M5A 0G4	GEN

Generator No: ON2570064
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146 L
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 221 L
Waste Class Desc: Light fuels

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

171 *1 of 2* *N/147.7* *80.8 / 1.97* ***Queen Street E & Broadview Ave Don Valley Pky & Eastern Ave Toronto ON*** **EHS**

Order No: 20040113013
Status: C
Report Type: Custom Report
Report Date: 1/15/04
Date Received: 1/12/04
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality: Toronto
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.386
Y: 43.667245

---

171 *2 of 2* *N/147.7* *80.8 / 1.97* ***Broadview at Queen St E. Toronto ON*** **SPL**

Ref No: 3132-74MLR5
Site No:
Incident Dt:
Year:
Incident Cause: Unknown
Incident Event:
Contaminant Code: 15
Contaminant Name: GREASE (N.O.S.)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact: Other Impact(s)
Receiving Medium: Land & Water
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 6/29/2007
Dt Document Closed:
Incident Reason: Unknown - Reason not determined
Site Name: Grease/Cooking Lard on sidewalk and CB<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: Broadview/Queen St E:cooking lard/grease to sidewalk/CB
Contaminant Qty: unknown unknown
Discharger Report:
Material Group: Oil
Health/Env Conseq:
Client Type:
Sector Type: Unknown
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Toronto
Site Lot:
Site Conc:
Northing:
Easting:
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

172 *1 of 1* *S/148.2* *76.0 / -2.86* ***ON*** **BORE**

Borehole ID: 640167
OGF ID: 215540563
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: SEP-1950
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 15.1
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.653874
Longitude DD: -79.350311
UTM Zone: 17
Easting: 633030
Northing: 4834753

Orig Ground Elev m:	79.6	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	76.2		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218491213	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL. AGE POST-GLACIAL.		

Geology Stratum ID:	218491218	**Mat Consistency:**	Dense
Top Depth:	11	**Material Moisture:**	
Bottom Depth:	12.8	**Material Texture:**	Fine to Medium
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-FINE TO MEDIUM,GRAVEL. FLUVIO-GLACIAL,DENSE, AGE GLACIAL.		

Geology Stratum ID:	218491220	**Mat Consistency:**	Dense
Top Depth:	13.5	**Material Moisture:**	
Bottom Depth:	15.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND,GRAVEL. FLUVIO-GLACIAL,DENSE, AGE GLACIAL. 00000003000450060015002200165004002700150036003800 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218491216	**Mat Consistency:**	Loose
Top Depth:	5	**Material Moisture:**	
Bottom Depth:	8.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	alluvial
Gsc Material Description:			
Stratum Description:	SAND,SILT. ALLUVIAL,LOOSE, AGE POST-GLACIAL.		

Geology Stratum ID:	218491219	**Mat Consistency:**	
Top Depth:	12.8	**Material Moisture:**	
Bottom Depth:	13.5	**Material Texture:**	Fine to Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			

Stratum Description: SAND-FINE TO MEDIUM.GREY,FLUVIO-GLACIAL, AGE GLACIAL.

Geology Stratum ID:	218491215	**Mat Consistency:**	Dense
Top Depth:	4.6	**Material Moisture:**	
Bottom Depth:	5	**Material Texture:**	Medium
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	alluvial
Gsc Material Description:			

Stratum Description: SAND-MEDIUM. ALLUVIAL,DENSE, AGE POST-GLACIAL.

Geology Stratum ID:	218491214	**Mat Consistency:**	Loose
Top Depth:	1.4	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	Medium
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	alluvial
Gsc Material Description:			

Stratum Description: SAND-MEDIUM. ALLUVIAL,LOOSE, AGE POST-GLACIAL.

Geology Stratum ID:	218491217	**Mat Consistency:**	Dense
Top Depth:	8.2	**Material Moisture:**	
Bottom Depth:	11	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			

Stratum Description: SAND,SILT. FLUVIO-GLACIAL,DENSE, AGE GLACIAL.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1B.txt RecordID: 081320 NTS_Sheet: 30M11F
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

173 ***1 of 1*** ***SSW/149.3*** ***76.6 / -2.25*** ***TORONTO ON*** ***WWIS***

Well ID:	7185057	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes

Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127727	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004100488	**Elevation:**	77.678001
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632915
Code OB Desc:		**North83:**	4834784
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/18/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004394866
Layer:	1
Plug From:	36.75
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004394859
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004394863
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004394864
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004394861
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

174 ***1 of 1*** ***WSW/152.6*** ***79.8 / 0.97*** ***TORONTO ON*** ***WWIS***

Well ID:	7185088	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127718	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101483	***Elevation:***	78.304626
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632751
Code OB Desc:		***North83:***	4834968
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/15/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395283
Layer:	1
Plug From:	30
Plug To:	
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395276
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395280
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395281
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395278
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

175	*1 of 1*	*NW/153.7*	*80.8 / 1.97*	***TIPPET-RICHARDSON*** ***QUEEN AT CARROLL TRANSPORT TRUCK (CARGO)*** ***TORONTO CITY ON***	*SPL*

Ref No:	46246	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/2/1991	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	01106
Nature of Impact:	Water course or lake	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	WORKS F.D.
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2/2/1991	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TIPPET-RICHARDSON TRUCK- DIESEL FUEL TO ROAD, SIDEWALK AND CATCHBASIN		
Contaminant Qty:			

176 **1 of 1** **W/155.9** **79.8 / 0.97** **ON** **BORE**

Borehole ID:	635148	**Inclin FLG:**	No
OGF ID:	215535545	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1962	**Municipality:**	
Static Water Level:	3.4	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656271
Total Depth m:	34.3	**Longitude DD:**	-79.354152
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632715
Drill Method:	Power auger	**Northing:**	4835013
Orig Ground Elev m:	77.8	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	81.2		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472120	**Mat Consistency:**	Dense
Top Depth:	27.4	**Material Moisture:**	
Bottom Depth:	29	**Material Texture:**	Fine
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Gravel	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Boulders	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	GRAVEL(56),SAND(25)FINE,SILT(18), BOULDERS. GREY,GLACIAL,DENSE,GRADED, AGE GLACIAL, WATER STABLE AT 243.9 FEET.		

Geology Stratum ID:	218472118	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	

Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,CLAY,SAND.GREY,LOOSE.		

Geology Stratum ID:	218472121	**Mat Consistency:**	
Top Depth:	29	**Material Moisture:**	
Bottom Depth:	30.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SAND.GREY,GLACIAL,AGE NON-GLACIAL.		

Geology Stratum ID:	218472122	**Mat Consistency:**	
Top Depth:	30.9	**Material Moisture:**	
Bottom Depth:	34.3	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. 00000008000800050090004500004 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472119	**Mat Consistency:**	
Top Depth:	2.4	**Material Moisture:**	
Bottom Depth:	27.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. GREY,BROWN,LACUSTRINE,BEDDED, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031040 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

177 ***1 of 2*** ***WSW/156.3*** ***78.9 / 0.00*** ***TORONTO ON*** ***WWIS***

Well ID:	7185058	**Data Entry Status:**	

Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127704	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004100529	***Elevation:***	76.122222
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632770
Code OB Desc:		***North83:***	4834940
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/15/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004394874
Layer:	1
Plug From:	30.25
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004394867
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004394871
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	

Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004394872
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004394869
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

177 ***2 of 2*** ***WSW/156.3*** ***78.9 / 0.00*** ***TORONTO ON*** ***WWIS***

Well ID:	7185052	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127696	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004100435	***Elevation:***	76.122222
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632770
Code OB Desc:		***North83:***	4834940
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/15/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			

Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1004394744
Layer: 1
Plug From: 30.25
Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004394737
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004394741
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004394742
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004394739
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

178 | ***1 of 1*** | ***ESE/156.4*** | ***79.8 / 0.97*** | ***375-385 Eastern Avenue Toronto ON*** | ***EHS***

Order No: 20180307111
Status: C
Report Type: Custom Report
Report Date: 03-APR-18
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25

Date Received:	07-MAR-18	**X:**	-79.34682
Previous Site Name:		**Y:**	43.655341
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

179 **1 of 1** **N/157.2** **80.8 / 1.97** **ON** **WWIS**

Well ID:	7221339	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	6/4/2014
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	8
Audit No:	C26046	**Owner:**	
Tag:	A162706	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004801504	**Elevation:**	80.602043
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632981
Code OB Desc:		**North83:**	4835275
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	4/16/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

180 **1 of 1** **NW/158.5** **80.8 / 1.97** **Hoodward & Lengas**
644 Queen St E
Toronto ON **TANK**

Permit Date:	4/4/1919
Permit Type:	BP 33456
User Type:	
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	40
Capacity(gal):	
Reference:	CTA Building permits

Location Desc:

---

181 ***1 of 1*** ***NNE/159.1*** ***79.8 / 0.97*** ***TORONTO ON*** ***WWIS***

Well ID:	6928022	***Data Entry Status:***	
Construction Date:		***Data Src:***	1
Primary Water Use:		***Date Received:***	7/2/2004
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	6607
Casing Material:		***Form Version:***	3
Audit No:	Z14468	***Owner:***	
Tag:	A011839	***Street Name:***	747 QUEEN STREET EAST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	PLAN D135/P.I21076
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	11180547	***Elevation:***	79.566162
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:	o	***East83:***	633176
Code OB Desc:	Overburden	***North83:***	4835314
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	6/9/2004	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932991801
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	
Other Materials:	
Formation Top Depth:	5
Formation End Depth:	6.2
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932991800
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	
Other Materials:	
Formation Top Depth:	3.1
Formation End Depth:	5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932991802
Layer:	4
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	05
Other Materials:	CLAY
Mat3:	
Other Materials:	
Formation Top Depth:	6.2
Formation End Depth:	7
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932991799
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	28
Other Materials:	SAND
Formation Top Depth:	0
Formation End Depth:	3.1
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933263470
Layer:	3
Plug From:	3.4
Plug To:	7
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID: 933263469
Layer: 2
Plug From: 0.3
Plug To: 3.4
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933263468
Layer: 1
Plug From: 0
Plug To: 0.3
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 11189066
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930853430
Layer: 1
Material:
Open Hole or Material:
Depth From: 0
Depth To: 3.8
Casing Diameter: 5
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933411201
Layer: 1
Slot: 020
Screen Top Depth: 3.8
Screen End Depth: 7
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.4

Water Details

Water ID: 934057490
Layer: 1
Kind Code: 1
Kind: FRESH

Water Found Depth: 5
Water Found Depth UOM: m

Hole Diameter

Hole ID: 11314653
Diameter: 15
Depth From: 0
Depth To: 7
Hole Depth UOM: m
Hole Diameter UOM: cm

---

182 | 1 of 1 | W/160.4 | 79.8 / 0.97 | ON | WWIS

Well ID: 7185089
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127719
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004101486
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/15/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 80.726455
Elevrc:
Zone: 17
East83: 632734
North83: 4834976
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: digit

Annular Space/Abandonment Sealing Record

Plug ID: 1004395291
Layer: 1
Plug From: 31.75
Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID:	1004395284
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395288
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395289
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395286
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

183 ***1 of 1*** ***NNE/162.2*** ***79.8 / 0.97*** ***ON*** ***WWIS***

Well ID:	7315552	***Data Entry Status:***	Yes
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	7/30/2018
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:		***Abandonment Rec:***	
Water Type:		***Contractor:***	7147
Casing Material:		***Form Version:***	8
Audit No:	C43005	***Owner:***	
Tag:	A243756	***Street Name:***	
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	

Flow Rate:
Clear/Cloudy:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1007229406	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633170
Code OB Desc:		**North83:**	4835320
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	6/29/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

184 **1 of 1** **W/163.2** **79.8 / 0.97** **ON** **BORE**

Borehole ID:	635152	**Inclin FLG:**	No
OGF ID:	215535549	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1962	**Municipality:**	
Static Water Level:	3.3	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655999
Total Depth m:	33.3	**Longitude DD:**	-79.354035
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632725
Drill Method:	Power auger	**Northing:**	4834983
Orig Ground Elev m:	77.8	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	82.6		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472139	**Mat Consistency:**	Stiff
Top Depth:	29.9	**Material Moisture:**	
Bottom Depth:	33.2	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SAND.GREY,GLACIAL,STIFF, AGE NON-GLACIAL.		

Geology Stratum ID:	218472138	**Mat Consistency:**	
Top Depth:	28.7	**Material Moisture:**	
Bottom Depth:	29.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	

Material 2:	Gravel	**Geologic Group:**	
Material 3:	Boulders	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND,GRAVEL,BOULDERSGLACIAL,AGE GLACIAL, WATER STABLE AT 244.3 FEET.		

Geology Stratum ID:	218472137	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	28.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. LACUSTRINE,BEDDED,AGE GLACIAL.		

Geology Stratum ID:	218472140	**Mat Consistency:**	
Top Depth:	33.2	**Material Moisture:**	
Bottom Depth:	33.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Boulders	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. 00009 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031080 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

185 ***1 of 1*** ***SSW/164.1*** ***77.0 / -1.84*** ***ON*** ***WWIS***

Well ID:	6905488	**Data Entry Status:**	
Construction Date:		**Data Src:**	1
Primary Water Use:	Not Used	**Date Received:**	2/19/1952
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	2801
Casing Material:		**Form Version:**	1
Audit No:		**Owner:**	
Tag:		**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY

Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	10496193	***Elevation:***	77.635993
DP2BR:	105	***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:	r	***East83:***	632931.8
Code OB Desc:	Bedrock	***North83:***	4834755
Open Hole:		***Org CS:***	
Cluster Kind:		***UTMRC:***	9
Date Completed:	1/9/1952	***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	p9
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	932728683
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	09
Other Materials:	MEDIUM SAND
Mat3:	
Other Materials:	
Formation Top Depth:	55
Formation End Depth:	91
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932728681
Layer:	1
Color:	
General Color:	
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	19
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932728682
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	03
Most Common Material:	MUCK
Mat2:	09
Other Materials:	MEDIUM SAND
Mat3:	
Other Materials:	
Formation Top Depth:	19
Formation End Depth:	55
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932728686
Layer:	6
Color:	3
General Color:	BLUE
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	105
Formation End Depth:	115
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932728684
Layer:	4
Color:	
General Color:	
Mat1:	05
Most Common Material:	CLAY
Mat2:	11
Other Materials:	GRAVEL
Mat3:	
Other Materials:	
Formation Top Depth:	91
Formation End Depth:	96
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	932728685
Layer:	5
Color:	
General Color:	
Mat1:	05
Most Common Material:	CLAY
Mat2:	11
Other Materials:	GRAVEL
Mat3:	

Other Materials:
Formation Top Depth: 96
Formation End Depth: 105
Formation End Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 11044763
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930808529
Layer: 1
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter: 6
Casing Diameter UOM: inch
Casing Depth UOM: ft

Water Details

Water ID: 933989002
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 96
Water Found Depth UOM: ft

---

186 ***1 of 1*** ***SSW/164.8*** ***77.3 / -1.54*** ***ON*** ***WWIS***

Well ID: 7291887
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z240176
Tag: A224172
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):

Data Entry Status:
Data Src:
Date Received: 8/2/2017
Selected Flag: Yes
Abandonment Rec:
Contractor: 6607
Form Version: 7
Owner:
Street Name: LOWER DON TRAIL
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:

Flow Rate:
Clear/Cloudy:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1006695246	**Elevation:**	77.909217
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632958
Code OB Desc:		**North83:**	4834743
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/29/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006798131
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	2.7
Formation End Depth:	7
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006798130
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	0
Formation End Depth:	2.7
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006798141
Layer:	4
Plug From:	6.4
Plug To:	7

Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006798139
Layer: 2
Plug From: 0.3
Plug To: 2.5
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006798138
Layer: 1
Plug From: 0
Plug To: 0.3
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1006798140
Layer: 3
Plug From: 2.5
Plug To: 0.9
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1006798129
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006798134
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 3
Casing Diameter: 6.1
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1006798135
Layer: 1

Slot:	10
Screen Top Depth:	3
Screen End Depth:	6.1
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.4

Water Details

Water ID:	1006798133
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	2.6
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1006798132
Diameter:	21
Depth From:	0
Depth To:	7
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

187 **1 of 1** **W/165.0** **79.8 / 0.97** **ON** **BORE**

Borehole ID:	635149	**Inclin FLG:**	No
OGF ID:	215535546	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	FEB-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.656272
Total Depth m:	26.5	**Longitude DD:**	-79.354276
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632705
Drill Method:	Power auger	**Northing:**	4835013
Orig Ground Elev m:	78.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	80.7		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472123	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	3.4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Wood Fragments	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,WOOD. BROWN,LOOSE.		

Geology Stratum ID: 218472124
Top Depth: 3.4
Bottom Depth: 22.6
Material Color: Brown
Material 1: Silt
Material 2: Sand
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SILT,SAND. GREY,BROWN,LACUSTRINE,BEDDED, AGE GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: lacustrine

Geology Stratum ID: 218472125
Top Depth: 22.6
Bottom Depth: 23.9
Material Color: Grey
Material 1: Till
Material 2: Clay
Material 3: Silt
Material 4: Sand
Gsc Material Description:
Stratum Description: TILL,CLAY,SILT,SAND.GREY,GLACIAL,VERY DENSE, AGE NON-GLACIAL.

Mat Consistency: Dense
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218472126
Top Depth: 23.9
Bottom Depth: 26.5
Material Color: Grey
Material 1: Bedrock
Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. 0000000400112028LT,SAND **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period: Ordovician
Depositional Gen: marine

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: H
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031050 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

188 | ***1 of 1*** | ***NNE/165.1*** | ***79.8 / 0.97*** | ***LMB GRAPHICS 24-824 93 LEWIS STREET TORONTO ON M4M 2H2*** | ***GEN***

Generator No: ON1416800
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:

PO Box No:
Country:
Choice of Contact:
Co Admin:

MHSW Facility: **Phone No Admin:**
SIC Code: 2821
SIC Description: PLATEMAKING, ETC.

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

---

189 **1 of 1** **S/165.8** **76.4 / -2.49** **TORONTO ON** **WWIS**

Well ID: 6928569
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z19512
Tag: A016933
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src: 1
Date Received: 12/13/2004
Selected Flag: Yes
Abandonment Rec:
Contractor: 6607
Form Version: 3
Owner:
Street Name: 470 LAKESHORE BLVD. EAST (DON YARD)
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11180410
DP2BR:
Spatial Status:
Code OB: o
Code OB Desc: Overburden
Open Hole:
Cluster Kind:
Date Completed: 10/13/2004
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 76.778884
Elevrc:
Zone: 17
East83: 633030
North83: 4834735
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 932993523
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Other Materials: SILT

Mat3: 91
Other Materials: WATER-BEARING
Formation Top Depth: 2.3
Formation End Depth: 8
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 932993522
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 68
Other Materials: DRY
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 2.3
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933264611
Layer: 3
Plug From: 1.3
Plug To: 8
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933264610
Layer: 2
Plug From: 0.3
Plug To: 1.3
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933264609
Layer: 1
Plug From: 0
Plug To: 0.3
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 11188929

Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930853993
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 1.5
Casing Diameter: 5
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933411548
Layer: 1
Slot: 10
Screen Top Depth: 1.5
Screen End Depth: 8
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 6.4

Water Details

Water ID: 934057730
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 2.3
Water Found Depth UOM: m

Hole Diameter

Hole ID: 11315204
Diameter: 21
Depth From: 0
Depth To: 8
Hole Depth UOM: m
Hole Diameter UOM: cm

---

190 ***1 of 1*** ***WNW/166.6*** ***79.3 / 0.42*** ***City of Toronto***
Queen Street Viaduct over Don Valley
Toronto ON M6B4J3 ***GEN***

Generator No: ON3558917
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146

Waste Class Desc: OTHER SPECIFIED INORGANICS

---

191 **1 of 1** **WSW/167.3** **79.3 / 0.40** **TORONTO ON** **WWIS**

Well ID:	7185082	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127689	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101465	**Elevation:**	77.132858
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632747
Code OB Desc:		**North83:**	4834950
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/15/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395231
Layer:	1
Plug From:	34.583
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395224
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID: 1004395228
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395229
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395226
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

192 **1 of 1** **WNW/170.1** **79.2 / 0.34** **ON** **BORE**

Borehole ID: 635800
OGF ID: 215536197
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date:
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 6.4
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Orig Ground Elev m: 77.7
Elev Reliabil Note:
DEM Ground Elev m: 82.2
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.657977
Longitude DD: -79.353857
UTM Zone: 17
Easting: 632735
Northing: 4835203
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218474654
Top Depth: 3
Bottom Depth: 6.4
Material Color:
Material 1: Clay

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:

Material 2: **Geologic Group:**
Material 3: **Geologic Period:**
Material 4: **Depositional Gen:** lacustrine
Gsc Material Description:
Stratum Description: CLAY. LACUSTRINE,AGE GLACIAL.

Geology Stratum ID: 218474653 **Mat Consistency:**
Top Depth: 0 **Material Moisture:**
Bottom Depth: 3 **Material Texture:**
Material Color: **Non Geo Mat Type:**
Material 1: Clay **Geologic Formation:**
Material 2: Sand **Geologic Group:**
Material 3: **Geologic Period:**
Material 4: **Depositional Gen:** glacial
Gsc Material Description:
Stratum Description: CLAY,SAND. FLUVIO-GLACIAL,AGE GLACIAL.

Source

Source Type: Data Survey **Source Appl:** Spatial/Tabular
Source Orig: Geological Survey of Canada **Source Iden:** 1
Source Date: 1956-1972 **Scale or Res:** Varies
Confidence: M **Horizontal:** NAD27
Observatio: **Verticalda:** Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 037580 NTS_Sheet: 30M11C
Confiden 1: Logs are approximately correct. Lack of information. Doubtful terminology.

Source List

Source Identifier: 1 **Horizontal Datum:** NAD27
Source Type: Data Survey **Vertical Datum:** Mean Average Sea Level
Source Date: 1956-1972 **Projection Name:** Universal Transverse Mercator
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

193 | ***1 of 1*** | ***N/170.7*** | ***80.8 / 1.97*** | ***716 Queen St E Toronto ON M4M1H2*** | ***EHS***

Order No: 20141126101 **Nearest Intersection:**
Status: C **Municipality:**
Report Type: Standard Report **Client Prov/State:** ON
Report Date: 03-DEC-14 **Search Radius (km):** .25
Date Received: 26-NOV-14 **X:** -79.349714
Previous Site Name: **Y:** 43.659108
Lot/Building Size:
Additional Info Ordered:

---

194 | ***1 of 1*** | ***WSW/171.3*** | ***76.9 / -2.00*** | ***Toronto ON*** | ***WWIS***

Well ID: 7101168 **Data Entry Status:**
Construction Date: **Data Src:**
Primary Water Use: Monitoring **Date Received:** 10/22/2007
Sec. Water Use: **Selected Flag:** Yes
Final Well Status: Other Status **Abandonment Rec:** Yes
Water Type: **Contractor:** 7241
Casing Material: **Form Version:** 5
Audit No: M00182 **Owner:**
Tag: **Street Name:** 100 MILL ST.
Construction Method: **County:** YORK

Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1001480667	**Elevation:**	76.293678
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632803
Code OB Desc:		**North83:**	4834878
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	8/17/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002524277
Layer:	1
Plug From:	0
Plug To:	0.3
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002524278
Layer:	2
Plug From:	0.3
Plug To:	2.13
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002524279
Layer:	3
Plug From:	2.13
Plug To:	9.14
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring

Other Method Construction:

Pipe Information

Pipe ID: 1002524276
Casing No: 0
Comment:
Alt Name:

Construction Record - Screen

Screen ID: 1002524280
Layer: 1
Slot: 10
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5.08

Bore Hole Information

Bore Hole ID: 1002524267
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 76.285369
Elevrc:
Zone: 17
East83: 632803
North83: 4834874
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002524271
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID:
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002524272
Casing No: 0
Comment:

Alt Name:

Construction Record - Casing

Casing ID:	1002524274
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.5
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002524273
Layer:	
Slot:	
Screen Top Depth:	1.5
Screen End Depth:	4.57
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1002524275
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002524269
Diameter:	5.08
Depth From:	
Depth To:	4.57
Hole Depth UOM:	m
Hole Diameter UOM:	cm

195	*1 of 1*	*WSW/172.3*	*79.0 / 0.12*		*WWIS*

TORONTO ON

Well ID:	7185083	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes

Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127703	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101468	***Elevation:***	76.614356
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632749
Code OB Desc:		***North83:***	4834940
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/15/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395239
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395232
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395236
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID: 1004395237
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395234
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

196 | ***1 of 1*** | ***NW/172.4*** | ***80.8 / 1.97*** | ***630-640 Queen Street East Toronto ON M4M 1G3*** | ***EHS***

Order No: 20110526035
Status: C
Report Type: Standard Select Report
Report Date: 6/6/2011
Date Received: 5/26/2011 2:50:40 PM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.352591
Y: 43.658426

---

197 | ***1 of 1*** | ***N/173.2*** | ***80.8 / 1.97*** | ***704 QUEEN STREET EAST, TORONTO, ON M4M 1G9 Toronto ON*** | ***RSC***

RSC ID: 219546
RA No:
RSC Type: Phase 1 and 2 RSC
Curr Property Use: Commercial
Ministry District: Toronto District Office
Filing Date: 2015/10/28
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Criteria:
CPU Issued Sect 1686:

Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: CHRISTOPHER AKELAITIS
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:
Email:

Asmt Roll No: 19040730620050000001
Prop ID No (PIN): 21073-0194 (LT)
Property Municipal Address: 704 QUEEN STREET EAST, TORONTO, ON M4M 1G9
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Filing Owner: 704 QUEEN STREET EAST INC.
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=55163&fileName=BRO

WNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: Cert.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=55172&fileName=Cert.pdf

Document Heading: Supporting Documents
Document Name: 702126 - Current and Past Use.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=55165&fileName=702126+-+Current+and+Past+Use.pdf

Document Heading: Supporting Documents
Document Name: Plan of Survey.PDF
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=55162&fileName=Plan+of+Survey.PDF

Document Heading: Supporting Documents
Document Name: AT3610614.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=55168&fileName=AT3610614.pdf

Document Heading: Supporting Documents
Document Name: 702126 - APEC Table.pdf
Document Type: Area(s) of Potential Environmental Concern
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=55164&fileName=702126+-+APEC+Table.pdf

Document Heading: Supporting Documents
Document Name: Lawyer LTR.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=55169&fileName=Lawyer+LTR.pdf

Document Heading: Supporting Documents
Document Name: 702126 Phase Two CSM.pdf
Document Type: Phase 2 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=55166&fileName=702126+Phase+Two+CSM.pdf

---

198 | ***1 of 1*** | ***N/173.5*** | ***80.8 / 1.97*** | ***704 Queen St E Toronto On Toronto ON*** | ***EHS***

Order No: 20150316056
Status: C
Report Type: RSC Report (Urban)
Report Date: 23-MAR-15
Date Received: 16-MAR-15
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: City Directory

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.350217
Y: 43.659029

---

199 | ***1 of 1*** | ***SSW/173.5*** | ***77.8 / -1.02*** | ***TORONTO ON*** | ***WWIS***

Well ID: 7185094
Construction Date:

Data Entry Status:
Data Src:

Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127732	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101539	**Elevation:**	77.940551
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632961
Code OB Desc:		**North83:**	4834733
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/18/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395335
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004395334
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395327
Casing No:	0
Comment:	
Alt Name:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Construction Record - Casing

Casing ID: 1004395331
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395332
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395329
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

200 | ***1 of 1*** | ***N/173.8*** | ***80.8 / 1.97*** | ***704 Queen Street East Inc.***
106 Broadview Avenue
Toronto ON M4M 2G1 | ***GEN***

Generator No: ON5197362
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

---

201 | ***1 of 1*** | ***NNE/174.5*** | ***79.8 / 0.97*** | ***Streetcar Riverside (747) Developments Ltd.***
747 QUEEN ST E, TORONTO, ON, M4M 1H3
Toronto ON M4M 1H3 | ***RSC***

RSC ID: 2979
RA No:
RSC Type:
Curr Property Use: Commercial
Ministry District: TORONTO
Filing Date: 24-Mar-06
Date Ack:
Date Returned:

Cert Date: 9-Jul-04
Cert Prop Use No: No CPU
Intended Prop Use: Residential
Qual Person Name: Les Mallins
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N): Yes
Accuracy Estimate: 0 to 1 meters

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Restoration Type:		***Telephone:***	416-6869199x105
Soil Type:		***Fax:***	416-6862245
Criteria:		***Email:***	lmallins@streetcar.ca
CPU Issued Sect 1686:	No		
Asmt Roll No:	1904071-20004500		
Prop ID No (PIN):	21076-0315 (LT)		
Property Municipal Address:	747 QUEEN ST E, TORONTO, ON, M4M 1H3		
Mailing Address:	Suite 2ND FLOOR, 569 KING ST E, TORONTO, ON, M5A 1M5		
Latitude & Latitude:	43.65694440N 79.34833330W		
UTM Coordinates:	NAD83 17-633182-4835097 (converted from Latitude & Longitude)		
Consultant:			
Filing Owner:			
Legal Desc:	Part of Lots 100 & 101 Registered Plan D-135		
Measurement Method:	Surveyed		
Applicable Standards:	Full Depth Site Conditions Standard, with Nonpotable Ground Water, Coarse Textured Soil, for Residential/Parkland/Institutional property use		
RSC PDF:			

202	***1 of 15***	***NNE/175.3***	***80.8 / 1.97***	***Betterway Dry Cleaners*** ***724 Queen St E*** ***Toronto ON M4M1H2***	***CDRY***

Legal Name of Company:

Contact Info (2016)

Postal Address:	724 Queen St E
Postal City:	Toronto
Postal Province:	ON
Postal Postal Code:	M4M1H2
Telephone No:	
Fax No:	
Email Address:	

Waste Quantity by Year

Reporting Year:	2016
Quantity of PERC (kg):	773
Total Waste Water (kg):	342
Total Waste Water (L):	0
Total Residue (kg):	320
Total Residue (L):	0
Total Mix (kg):	0
Total Mix (L):	0
Request for Confidentiality:	No
Reason for Confidentiality:	

Reporting Year:	2015
Quantity of PERC (kg):	110
Total Waste Water (kg):	570
Total Waste Water (L):	-
Total Residue (kg):	0
Total Residue (L):	0
Total Mix (kg):	0
Total Mix (L):	-
Request for Confidentiality:	No
Reason for Confidentiality:	

Reporting Year:	2014
Quantity of PERC (kg):	221
Total Waste Water (kg):	456
Total Waste Water (L):	-

Total Residue (kg): 0
Total Residue (L): -
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality:

Reporting Year: 2013
Quantity of PERC (kg): 148
Total Waste Water (kg): 0
Total Waste Water (L): -
Total Residue (kg): 0
Total Residue (L): -
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality:

Reporting Year: 2012
Quantity of PERC (kg): 177
Total Waste Water (kg): 0
Total Waste Water (L): -
Total Residue (kg): 0
Total Residue (L): -
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality:

Reporting Year: 2011
Quantity of PERC (kg): 516
Total Waste Water (kg): 114
Total Waste Water (L): 456
Total Residue (kg): -
Total Residue (L): 0
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality:

Reporting Year: 2010
Quantity of PERC (kg): 110
Total Waste Water (kg): 570
Total Waste Water (L): -
Total Residue (kg): 0
Total Residue (L): -
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality:

Reporting Year: 2009
Quantity of PERC (kg): 330
Total Waste Water (kg): 0
Total Waste Water (L): -
Total Residue (kg): 0
Total Residue (L): -
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality:

Reporting Year: 2008
Quantity of PERC (kg): 110
Total Waste Water (kg): 0
Total Waste Water (L): -

Total Residue (kg): 0
Total Residue (L): -
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality:

Reporting Year: 2006
Quantity of PERC (kg): 184
Total Waste Water (kg): 0
Total Waste Water (L): -
Total Residue (kg): 0
Total Residue (L): -
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality: N/A

Reporting Year: 2005
Quantity of PERC (kg): 184
Total Waste Water (kg): 0
Total Waste Water (L): -
Total Residue (kg): 0
Total Residue (L): -
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality: N/A

Reporting Year: 2004
Quantity of PERC (kg): 194.4
Total Waste Water (kg): -
Total Waste Water (L): 0
Total Residue (kg): -
Total Residue (L): 0
Total Mix (kg): 0
Total Mix (L): -
Request for Confidentiality: No
Reason for Confidentiality: N/A

202	*2 of 15*	*NNE/175.3*	*80.8 / 1.97*	***Betterway Drycleaners*** ***724 Queen Street East*** ***Toronto ON M4M 1H2***	***GEN***

Generator No: ON3376028
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213 H
Waste Class Desc: Petroleum distillates

Waste Class: 213 L
Waste Class Desc: Petroleum distillates

202	*3 of 15*	*NNE/175.3*	*80.8 / 1.97*	***BETTERWAY CLEANERS*** ***724 QUEEN STREET EAST*** ***TORONTO ON M4M 1H2***	***GEN***

Generator No:	ON0542900	**PO Box No:**	
Status:		**Country:**	
Approval Years:	86,87,88,89	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	9721		
SIC Description:	POWER LAUND./CLEANERS		

Detail(s)

Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS

---

202 ***4 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***GEN***

BETTERWAY CLEANERS & LAUNDERERS
724 QUEEN STREET EAST
TORONTO ON M4M 1H2

Generator No:	ON0542900	**PO Box No:**	
Status:		**Country:**	Canada
Approval Years:	2014	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	
MHSW Facility:	No	**Phone No Admin:**	
SIC Code:	812320		
SIC Description:	DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)		

Detail(s)

Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS

---

202 ***5 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***GEN***

BETTERWAY CLEANERS & LAUNDERERS
724 QUEEN STREET EAST
TORONTO ON M4M 1H2

Generator No:	ON0542900	**PO Box No:**	
Status:		**Country:**	Canada
Approval Years:	2016	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	
MHSW Facility:	No	**Phone No Admin:**	
SIC Code:	812320		
SIC Description:	DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)		

Detail(s)

Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS

---

202 ***6 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***GEN***

BETTERWAY CLEANERS & LAUNDERERS
724 QUEEN STREET EAST
TORONTO ON M4M 1H2

Generator No:	ON0542900	**PO Box No:**	
Status:		**Country:**	Canada
Approval Years:	2015	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	
MHSW Facility:	No	**Phone No Admin:**	
SIC Code:	812320		
SIC Description:	DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

202 ***7 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***BETTERWAY CLEANERS & LAUNDERERS*** ***GEN***
724 QUEEN STREET EAST
TORONTO ON

Generator No: ON0542900 ***PO Box No:***
Status: ***Country:***
Approval Years: 2009 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

202 ***8 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***BETTERWAY CLEANERS & LAUNDERERS*** ***GEN***
724 QUEEN STREET EAST
TORONTO ON

Generator No: ON0542900 ***PO Box No:***
Status: ***Country:***
Approval Years: 2011 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

202 ***9 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***BETTERWAY CLEANERS & LAUNDERERS*** ***GEN***
724 QUEEN STREET EAST
TORONTO ON

Generator No: ON0542900 ***PO Box No:***
Status: ***Country:***
Approval Years: 2013 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 812320
SIC Description: DRY CLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

202 ***10 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***BETTERWAY CLEANERS & LAUNDERERS*** ***GEN***
724 QUEEN STREET EAST
TORONTO ON

Generator No: ON0542900
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

202 ***11 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***BETTERWAY CLEANERS & LAUNDERERS*** ***GEN***
724 QUEEN STREET EAST
TORONTO ON M4M 1H2

Generator No: ON0542900
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 812320
SIC Description: Dry Cleaning and Laundry Services (except Coin-Operated)

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

202 ***12 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***BETTERWAY CLEANERS & LAUNDERERS 05-109*** ***GEN***
724 QUEEN STREET EAST
TORONTO ON M4M 1H2

Generator No: ON0542900
Status:
Approval Years: 92,93,94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 9721
SIC Description: POWER LAUND./CLEANER

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

202 ***13 of 15*** ***NNE/175.3*** ***80.8 / 1.97*** ***Betterway Drycleaners*** ***GEN***
724 Queen Street East
Toronto ON M4M 1H2

Generator No: ON3376028
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 213 H
Waste Class Desc: Petroleum distillates

Waste Class: 213 L
Waste Class Desc: Petroleum distillates

---

202 | ***14 of 15*** | ***NNE/175.3*** | ***80.8 / 1.97*** | ***BETTERWAY CLEANERS & LAUNDERERS***
724 QUEEN STREET EAST
TORONTO ON M4M 1H2 | ***GEN***

Generator No: ON0542900
Status:
Approval Years: 97,98,99,00,01,02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 9721
SIC Description: POWER LAUND./CLEANERS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

---

202 | ***15 of 15*** | ***NNE/175.3*** | ***80.8 / 1.97*** | ***BETTERWAY CLEANERS & LAUNDERERS***
724 QUEEN STREET EAST
TORONTO ON M4M 1H2 | ***GEN***

Generator No: ON0542900
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 241 H
Waste Class Desc: Halogenated solvents and residues

---

203 | ***1 of 1*** | ***SSE/176.0*** | ***79.8 / 0.97*** | ***n/a***
Toronto ON | ***EHS***

Order No: 20170816018
Status: C
Report Type: Custom Report
Report Date: 22-AUG-17
Date Received: 16-AUG-17
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory; Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.348818
Y: 43.654069

---

204 | ***1 of 1*** | ***WSW/176.0*** | ***79.8 / 0.97*** | ***ON*** | ***BORE***

Borehole ID: 635156
OGF ID: 215535553
Status:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No

Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	MAR-1962	***Municipality:***	
Static Water Level:	1.5	***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.655819
Total Depth m:	15.4	***Longitude DD:***	-79.35404
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632725
Drill Method:	Power auger	***Northing:***	4834963
Orig Ground Elev m:	78.6	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	80.2		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472153	***Mat Consistency:***	Firm
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2.4	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Clay	***Geologic Period:***	
Material 4:	Organic	***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,CLAY, ORGANIC. GREY,BROWN,FIRM.		

Geology Stratum ID:	218472155	***Mat Consistency:***	Stiff
Top Depth:	13.7	***Material Moisture:***	
Bottom Depth:	15.2	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	
Material 4:	Sand	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SAND.BROWN,GLACIAL,STIFF, AGE NON-GLACIAL.		

Geology Stratum ID:	218472154	***Mat Consistency:***	Loose
Top Depth:	2.4	***Material Moisture:***	
Bottom Depth:	13.7	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND. GREY,LACUSTRINE,LOOSE,BEDDED, AGE GLACIAL, WATER STABLE AT 252.9 FEET.		

Geology Stratum ID:	218472156	***Mat Consistency:***	
Top Depth:	15.2	***Material Moisture:***	
Bottom Depth:	15.4	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Boulders	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. YELLOW,WEATHERED. 0008000400005000 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031120 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

205 ***1 of 1*** ***NW/176.7*** ***80.8 / 1.97*** ***630 Queen Street East Inc.*** ***RSC***
630 and 642 Queen Street East, Toronto, Ontario M4M 1G3,
ON

RSC ID:	110110	***Cert Date:***	27-May-11
RA No:		***Cert Prop Use No:***	No CPU
RSC Type:		***Intended Prop Use:***	Residential
Curr Property Use:	Commercial	***Qual Person Name:***	Les Mallins
Ministry District:	TORONTO	***Stratified (Y/N):***	
Filing Date:	9-Jun-11	***Audit (Y/N):***	
Date Ack:		***Entire Leg Prop. (Y/N):***	Yes
Date Returned:		***Accuracy Estimate:***	6 to 10 meters
Restoration Type:		***Telephone:***	416-6869199
Soil Type:		***Fax:***	416-6862245
Criteria:		***Email:***	
CPU Issued Sect 1686:	No		
Asmt Roll No:	1904073-050004000000; 1904073-050003000000		
Prop ID No (PIN):	21073 - 0156 LT; 21073 - 0157 LT		
Property Municipal Address:	630 and 642 Queen Street East, Toronto, Ontario M4M 1G3,		
Mailing Address:	43 DAVIES AVE, TORONTO, ON, M5H 2Y2		
Latitude & Latitude:	43.65845690N 79.35264990W (converted from UTM)		
UTM Coordinates:	NAD83 17-632831-4835258		
Consultant:			
Filing Owner:			
Legal Desc:	LT 8-10 PL 347 RIVERDALE; PT LT 7 PL 347 RIVERDALE PT 1 63R3212; CITY OF TORONTO; PT LT 6-7 PL 347 RIVERDALE AS IN CA235123, T/W CA235123; CITY OF TORONTO		
Measurement Method:	Digitized from a satellite image		
Applicable Standards:	Full Depth Site Conditions Standard, with Nonpotable Ground Water, Medium/Fine Textured Soil, for Residential/Parkland/Institutional property use		
RSC PDF:			

---

206 ***1 of 1*** ***W/177.0*** ***78.4 / -0.47*** ***TORONTO ON*** ***WWIS***

Well ID:	7199371	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Not Used	***Date Received:***	3/25/2013
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	7341
Casing Material:		***Form Version:***	7

Audit No:	Z150245	**Owner:**	
Tag:	A083901	**Street Name:**	SOUTH WOONERF
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004268238	**Elevation:**	78.116516
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632684
Code OB Desc:		**North83:**	4835034
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/18/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004954456
Layer:	2
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004954455
Layer:	1
Plug From:	1.5
Plug To:	8
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004954457
Layer:	1
Plug From:	2
Plug To:	8
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004954447

Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004954451
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 8
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004954452
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004954449
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

207 **1 of 1** **NNE/177.8** **80.3 / 1.42** **BAKERY (N.0.S.)**
728 QUEEN STREET EAST
TORONTO CITY ON M4M 1H2 **SPL**

Ref No: 106687
Site No:
Incident Dt: 10/25/1994
Year:
Incident Cause: PIPE/HOSE LEAK
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: NOT ANTICIPATED
Nature of Impact:
Receiving Medium: AIR
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/25/1994
Dt Document Closed:
Incident Reason: FIRE/EXPLOSION
Site Name:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 1106
Site Lot:
Site Conc:
Northing:
Easting: MCCR
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site County/District:
Site Geo Ref Meth:
Incident Summary: BROADVIEW/QUEEN BAKERY: FIRE :SUSPECTED CAUSE IS NATURAL GAS OVEN
Contaminant Qty:

---

208 **1 of 1** **NW/177.8** **80.0 / 1.13** **Motorcade Auto Parts Ltd.** **SCT**
600 Queen St E
Toronto ON M4M 1G3

Established: 01-OCT-58
Plant Size (ft²):
Employment:

--Details--
Description: Automotive Parts and Accessories Stores
SIC/NAICS Code: 441310

---

209 **1 of 1** **SE/177.9** **79.8 / 0.97** **ON** **BORE**

Borehole ID: 644979
OGF ID: 215545362
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: 1946
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 10.8
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Orig Ground Elev m: 77.7
Elev Reliabil Note:
DEM Ground Elev m: 80.9
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.654468
Longitude DD: -79.347753
UTM Zone: 17
Easting: 633235
Northing: 4834823
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218509618
Top Depth: 0
Bottom Depth: 3
Material Color:
Material 1: Fill
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: FILL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Geology Stratum ID: 218509622
Top Depth: 9.3
Bottom Depth: 10.8
Material Color:
Material 1: Clay
Material 2: Sand
Material 3: Gravel

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:

Material 4: **Depositional Gen:** beach
Gsc Material Description:
Stratum Description: CLAY,SAND,GRAVEL. BEACH,AGE POST-GLACIAL. CLAY **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID: 218509621
Top Depth: 6.1
Bottom Depth: 9.3
Material Color:
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: CLAY. BEACH,AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: beach

Geology Stratum ID: 218509620
Top Depth: 4.4
Bottom Depth: 6.1
Material Color:
Material 1: Silt
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SILT.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218509619
Top Depth: 3
Bottom Depth: 4.4
Material Color:
Material 1: Clay
Material 2: Silt
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: CLAY,SILT.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 130010 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

210	1 of 2	NNW/178.0	81.7 / 2.86	650 Queen Street East Toronto ON M4M 1G5	EHS

Order No: 20071127004
Status: C

Nearest Intersection:
Municipality:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report Type:	CAN - Complete Report	**Client Prov/State:**	
Report Date:	12/5/2007	**Search Radius (km):**	0.25
Date Received:	11/27/2007	**X:**	-79.352096
Previous Site Name:		**Y:**	43.658497
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps And /or Site Plans		

---

210 | **2 of 2** | **NNW/178.0** | **81.7 / 2.86** | **Edwin Hotel**
650 Queen St E
Toronto ON M4M 1G5 | **TANK**

Permit Date:	4/21/1927
Permit Type:	BP A4044
User Type:	Hotel
Installation Type:	Fuel oil tank
Installation Size:	
Installation Config.:	1 x fuel oil tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	150
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	

---

211 | **1 of 1** | **NW/178.7** | **80.8 / 1.97** | **Laser Heating & A/C Inc.**
630 Queen St. E.
TORONTO ON M4M 1G3 | **GEN**

Generator No:	ON6013794	**PO Box No:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Jul 2019	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class:	212 L
Waste Class Desc:	Aliphatic solvents and residues

---

212 | **1 of 1** | **NW/179.2** | **79.1 / 0.26** | **ON** | **BORE**

Borehole ID:	640670	**Inclin FLG:**	No
OGF ID:	215541066	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JUN-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.658226
Total Depth m:	11.1	**Longitude DD:**	-79.353602
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632755
Drill Method:	Power auger	**Northing:**	4835231
Orig Ground Elev m:	84.4	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	81.6		
Concession:			

Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218493100	***Mat Consistency:***	Stiff
Top Depth:	6.7	***Material Moisture:***	
Bottom Depth:	10.1	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL,STIFF, AGE GLACIAL.		

Geology Stratum ID:	218493099	***Mat Consistency:***	Compact
Top Depth:	4	***Material Moisture:***	
Bottom Depth:	6.7	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND. BROWN,GREY,LACUSTRINE,COMPACT,AGE GLACIAL.		

Geology Stratum ID:	218493101	***Mat Consistency:***	Hard
Top Depth:	10.1	***Material Moisture:***	
Bottom Depth:	11.1	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,HARD. 018 016 0000000900130016C **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218493098	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	4	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Granuls	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,CINDERS. BROWN.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 086360 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

213 | **1 of 1** | **SE/180.1** | **79.8 / 0.97** | **Toronto ON** | **WWIS**

Well ID:	7295928	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	9/29/2017
Sec. Water Use:	Monitoring	**Selected Flag:**	Yes
Final Well Status:	Monitoring and Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z267968	**Owner:**	
Tag:	A208893	**Street Name:**	21 DONWAY ROADWAY
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	WKQ-010280 A0-A04
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006741483	**Elevation:**	78.635261
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633262
Code OB Desc:		**North83:**	4834836
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	8/11/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006907610
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	

Formation Top Depth: 4
Formation End Depth: 24
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006907609
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Other Materials: GRAVEL
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006907618
Layer: 1
Plug From: 24
Plug To: 13
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006907619
Layer: 2
Plug From: 13
Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1006907608
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006907613
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0

Depth To:	14
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006907614
Layer:	1
Slot:	.1
Screen Top Depth:	14
Screen End Depth:	24
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Hole Diameter

Hole ID:	1006907611
Diameter:	6
Depth From:	0
Depth To:	24
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

214 ***1 of 1*** ***W/181.5*** ***79.3 / 0.41*** ***WWIS***

Toronto ON

Well ID:	7173967	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	12/23/2011
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	7
Audit No:	Z143094	**Owner:**	
Tag:	A100050	**Street Name:**	FRONT ST. AND CHERRY ST.
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003625613	**Elevation:**	81.954399
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632690
Code OB Desc:		**North83:**	4835005
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	2
Date Completed:	9/12/2011	**UTMRC Desc:**	margin of error : 3 - 10 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1004095959
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 6
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004095960
Layer: 2
Color: 6
General Color: BROWN
Mat1: 34
Most Common Material: TILL
Mat2: 06
Other Materials: SILT
Mat3: 68
Other Materials: DRY
Formation Top Depth: 6
Formation End Depth: 20
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004095961
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3: 91
Other Materials: WATER-BEARING
Formation Top Depth: 20
Formation End Depth: 28
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004095971
Layer: 4

Plug From: 2
Plug To: 0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004095968
Layer: 1
Plug From: 28
Plug To: 17
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004095969
Layer: 2
Plug From: 17
Plug To: 14
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004095970
Layer: 3
Plug From: 14
Plug To: 2
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1004095958
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004095964
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 18
Depth To: 0
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID:	1004095965
Layer:	1
Slot:	10
Screen Top Depth:	28
Screen End Depth:	18
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2

Hole Diameter

Hole ID:	1004095962
Diameter:	8
Depth From:	0
Depth To:	28
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

215 ***1 of 1*** ***W/181.6*** ***78.5 / -0.38*** ***TORONTO ON*** ***WWIS***

Well ID:	7199374	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	3/25/2013
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	7341
Casing Material:		**Form Version:**	7
Audit No:	Z150242	**Owner:**	
Tag:	A083901	**Street Name:**	SOUTH WOONERF
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004268247	**Elevation:**	78.92797
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632682
Code OB Desc:		**North83:**	4835025
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/18/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment

Sealing Record

Plug ID:	1004957497
Layer:	2
Plug From:	
Plug To:	
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004957496
Layer:	1
Plug From:	0.5
Plug To:	8
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004957498
Layer:	1
Plug From:	0.5
Plug To:	8
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1004957488
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004957492
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	8
Casing Diameter:	2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004957493
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	

Hole Diameter

Hole ID:	1004957490
Diameter:	

Depth From:
Depth To:
Hole Depth UOM: m
Hole Diameter UOM: cm

---

216 *1 of 2* *NNE/183.2* *79.9 / 1.00* ***734 Queen St E*** ***Toronto ON M4M1H2*** ***EHS***

Order No:	20170503035	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	08-MAY-17	**Search Radius (km):**	.25
Date Received:	03-MAY-17	**X:**	-79.349016
Previous Site Name:		**Y:**	43.659255
Lot/Building Size:			
Additional Info Ordered:			

---

216 *2 of 2* *NNE/183.2* *79.9 / 1.00* ***Mathewson Hardware Co*** ***734 Queen St E*** ***Toronto ON M4M 1H2*** ***TANK***

Permit Date:	8/18/1928
Permit Type:	BP A16303
User Type:	Hardware
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	125
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	734 Queen St E

---

217 *1 of 1* *W/184.8* *78.0 / -0.85* ***TORONTO ON*** ***WWIS***

Well ID:	7199372	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Not Used	**Date Received:**	3/25/2013
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	7341
Casing Material:		**Form Version:**	7
Audit No:	Z150244	**Owner:**	
Tag:	A100050	**Street Name:**	SOUTH WOONERF
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004268241	**Elevation:**	78.905349

DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632678
Code OB Desc:		**North83:**	4835027
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/18/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004955867
Layer:	1
Plug From:	1.5
Plug To:	8
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004955865
Layer:	1
Plug From:	1.5
Plug To:	8
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004955866
Layer:	2
Plug From:	
Plug To:	
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1004955857
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004955861
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	8
Casing Diameter:	2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Construction Record - Screen

Screen ID: 1004955862
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Hole Diameter

Hole ID: 1004955859
Diameter:
Depth From:
Depth To:
Hole Depth UOM: m
Hole Diameter UOM: cm

---

218 | ***1 of 1*** | ***WSW/185.3*** | ***78.8 / -0.10*** | ***LENSCAPE INC. (OUT OF BUSINESS) 24-728 222 EASTERN AVE. TORONTO ON M5A 1J1*** | ***GEN***

Generator No: ON1299000
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 9931
SIC Description: PHOTOGRAPHERS
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

---

219 | ***1 of 1*** | ***NNE/186.1*** | ***79.8 / 0.97*** | ***751 Queen Street East Toronto ON M4M 1H3*** | ***EHS***

Order No: 20190711041
Status: C
Report Type: RSC Report (Urban)
Report Date: 17-JUL-19
Date Received: 11-JUL-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; City Directory
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.347955
Y: 43.659011

---

220 | ***1 of 1*** | ***E/187.2*** | ***79.8 / 0.97*** | ***Toronto ON*** | ***WWIS***

Well ID: 7295930
Construction Date:
Primary Water Use: Test Hole
Sec. Water Use: Monitoring
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z267969
Data Entry Status:
Data Src:
Date Received: 9/29/2017
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:

Tag:	A208892	***Street Name:***	21 DONWAY ROADWAY
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	WKQ-010280 A0-A04
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006741519	***Elevation:***	79.193183
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633354
Code OB Desc:		***North83:***	4834997
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	5
Date Completed:	8/11/2017	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006907656
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	4
Formation End Depth:	35
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1006907655
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	4

Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006907664
Layer: 1
Plug From: 35
Plug To: 24
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006907665
Layer: 2
Plug From: 24
Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1006907654
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006907659
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 25
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006907660
Layer: 1
Slot: .1
Screen Top Depth: 25
Screen End Depth: 35
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Hole Diameter

Hole ID: 1006907657
Diameter: 6
Depth From: 0
Depth To: 35
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

221 *1 of 2* *NNW/188.5* *81.9 / 3.02* ***660 QUEEN STREET EAST, TORONTO ON*** ***INC***

Incident No: 1286950
Incident ID:
Attribute Category: FS-Perform L1 Incident Insp
Status Code:
Incident Location: 660 QUEEN STREET EAST, TORONTO - VAPOUR RELEASE
Drainage System:
Sub Surface Contam.:
Aff. Prop. Use Water:
Contam. Migrated:
Contact Natural Env.:
Near Body of Water:
Approx. Quant. Rel.:
Equipment Model:
Serial No:
Residential App. Type:
Commercial App. Type:
Industrial App. Type:
Institutional App. Type:
Venting Type:
Vent Connector Mater:
Vent Chimney Mater:
Pipeline Type:
Pipeline Involved:
Pipe Material:
Depth Ground Cover:
Regulator Location:
Regulator Type:
Operation Pressure:
Liquid Prop Make:
Liquid Prop Model:
Liquid Prop Serial No:
Equipment Type:
Cylinder Capacity:
Cylinder Capac. Units:
Cylinder Material Type:
Tank Capacity:
Fuels Occurence Type: Vapour Release
Fuel Type Involved: Natural Gas
Date of Occurence: 2013/11/20 00:00:00
Time of Occurence: 08:23:00
Occur Insp Start Date: 2013/11/20 00:00:00
Any Health Impact: No
Any Environmental Impact: No
Was Service Interrupted: Yes
Was Property Damaged: No
Operation Type Involved: Commercial (e.g. restaurant, business unit, etc)
Enforcement Policy: NULL
Prc Escalation Required: NULL
Task No: 4719459
Notes:
Occurence Narrative: A garbage truck hit a meter
Tank Material Type:
Tank Storage Type:
Tank Location Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Pump Flow Rate Capac:
Liquid Prop Notes:

---

221 **2 of 2** **NNW/188.5** **81.9 / 3.02** **660 Queen Street East Toronto ON** **SPL**

Ref No:	4858-9DMJP5	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	2013/11/20	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Leak/Break	**Sector Type:**	Pipeline/Components
Incident Event:		**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	NATURAL GAS (METHANE)	**Site Address:**	660 Queen Street East
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Toronto
Nature of Impact:	Air Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	Referral to others	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2013/11/20	**Site Map Datum:**	
Dt Document Closed:	2014/01/15	**SAC Action Class:**	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Incident Reason:	Operator/Human Error	**Source Type:**	
Site Name:	Multi-unit building<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TSSA; gas meter hit by truck.		
Contaminant Qty:	0 other - see incident description		

---

222 **1 of 2** **SSW/188.6** **76.8 / -2.05** **lot L Toronto ON** **WWIS**

Well ID:	7102283	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	2/21/2008
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	0	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	5
Audit No:	M00911	**Owner:**	
Tag:	_NO_TAG	**Street Name:**	100 MILL ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	L
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1001524532	**Elevation:**	77.249389
DP2BR:		**Elevrc:**	

Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632886
Code OB Desc:		***North83:***	4834757
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	8/23/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002650568
Layer:	2
Plug From:	0.3
Plug To:	2.13
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002650569
Layer:	3
Plug From:	2.13
Plug To:	21.1
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002650567
Layer:	1
Plug From:	0
Plug To:	0.3
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1002650566
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Screen

Screen ID:	1002650570
Layer:	1
Slot:	10
Screen Top Depth:	
Screen End Depth:	
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	5.08

Bore Hole Information

Bore Hole ID:	1002650553	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	50632561
Code OB Desc:		**North83:**	4834927
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	9
Date Completed:	9/7/2007	**UTMRC Desc:**	unknown UTM
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002650557
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Pipe Information

Pipe ID:	1002650558
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002650560
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	4.57
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002650559
Layer:	
Slot:	
Screen Top Depth:	4.57
Screen End Depth:	6.1
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1002650561
Pump Set At:	
Static Level:	

Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002650555
Diameter: 5.08
Depth From:
Depth To: 6.1
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002650544
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone: 17
East83: 50632624
North83: 4834951
Org CS: UTM83
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002650548
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Pipe Information

Pipe ID: 1002650549
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002650551
Layer:
Material: 5

Open Hole or Material: PLASTIC
Depth From:
Depth To: 4.57
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002650550
Layer:
Slot:
Screen Top Depth: 4.57
Screen End Depth: 7.62
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002650552
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002650546
Diameter: 15.24
Depth From:
Depth To: 7.62
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002650535
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:

Elevation:
Elevrc:
Zone: 17
East83: 50632579
North83: 4834939
Org CS: UTM83
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: wwr

Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002650539
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Pipe Information

Pipe ID: 1002650540
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002650542
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 7.01
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002650541
Layer:
Slot:
Screen Top Depth: 7.01
Screen End Depth: 10.1
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002650543
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1002650537
Diameter:	5.08
Depth From:	
Depth To:	10.1
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002650562	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	9
Date Completed:		***UTMRC Desc:***	unknown UTM
Remarks:		***Location Method:***	na
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Hole Diameter

Hole ID:	1002650564
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

222 ***2 of 2*** ***SSW/188.6*** ***76.8 / -2.05*** ***WWIS***

Toronto ON

Well ID:	7101167	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	10/22/2007
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Other Status	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	5
Audit No:	M00185	***Owner:***	
Tag:		***Street Name:***	100 MILL ST.
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1002524248	**Elevation:**	79.401527
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632579
Code OB Desc:		**North83:**	4834939
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	8/17/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002524252
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1002524253
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002524255
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	7.01
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002524254
Layer:	
Slot:	
Screen Top Depth:	7.01
Screen End Depth:	10.1
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	

Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002524256
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002524250
Diameter: 5.08
Depth From:
Depth To: 10.1
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1001480664
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.249389
Elevrc:
Zone: 17
East83: 632886
North83: 4834757
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002524260
Layer: 3
Plug From: 2.13
Plug To: 21.1
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002524259
Layer: 2

Plug From: 0.3
Plug To: 2.13
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002524258
Layer: 1
Plug From: 0
Plug To: 0.3
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1002524257
Casing No: 0
Comment:
Alt Name:

Construction Record - Screen

Screen ID: 1002524261
Layer: 1
Slot: 10
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5.08

---

223 **1 of 1** **N/190.4** **80.8 / 1.97** **Toronto ON** **WWIS**

Well ID: 7208868
Construction Date:
Primary Water Use: Monitoring and Test Hole
Sec. Water Use: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z176326
Tag: A152595
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:

Data Entry Status:
Data Src:
Date Received: 10/2/2013
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 714 QUEEN STREET EAST
County: YORK
Municipality: TORONTO CITY
Site Info: WKQ-006265 A0-A04
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	1004591506	***Elevation:***	80.682327
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633057
Code OB Desc:		***North83:***	4835353
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:		***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004627459
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	0.51
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004627462
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	6
Formation End Depth:	12
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004627461
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	28

Most Common Material: SAND
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 3
Formation End Depth: 6
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004627460
Layer: 2
Color: 6
General Color: BROWN
Mat1:
Most Common Material:
Mat2: 01
Other Materials: FILL
Mat3:
Other Materials:
Formation Top Depth: 0.51
Formation End Depth: 3
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004627470
Layer: 1
Plug From: 0
Plug To: 0.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004627471
Layer: 2
Plug From: 0.5
Plug To: 5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004627472
Layer: 3
Plug From: 5
Plug To: 11.75
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID:	1004627458
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004627465
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	6.75
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004627466
Layer:	1
Slot:	10
Screen Top Depth:	6.75
Screen End Depth:	11.75
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.5

Hole Diameter

Hole ID:	1004627463
Diameter:	2.5
Depth From:	0
Depth To:	11.75
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

224 ***1 of 2*** ***N/190.8*** ***81.0 / 2.11*** ***ON*** ***WWIS***

Well ID:	7284559	***Data Entry Status:***	Yes
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	4/7/2017
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:		***Abandonment Rec:***	
Water Type:		***Contractor:***	7215
Casing Material:		***Form Version:***	8
Audit No:	C36017	***Owner:***	
Tag:		***Street Name:***	
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	1006377176	***Elevation:***	80.858146
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633031
Code OB Desc:		***North83:***	4835346
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	1/12/2017	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

224 ***2 of 2*** ***N/190.8*** ***81.0 / 2.11*** ***ON*** ***WWIS***

Well ID:	7244594	***Data Entry Status:***	Yes
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	7/14/2015
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:		***Abandonment Rec:***	
Water Type:		***Contractor:***	6988
Casing Material:		***Form Version:***	8
Audit No:	C27465	***Owner:***	
Tag:	A174902	***Street Name:***	
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005482791	***Elevation:***	80.857215
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633031
Code OB Desc:		***North83:***	4835346
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	4/16/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
225	1 of 1	WSW/190.9	78.8 / -0.04	TORONTO ON	WWIS

Well ID: 7185085
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127706
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004101474
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/14/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 76.627769
Elevrc:
Zone: 17
East83: 632739
North83: 4834923
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004395256
Layer: 1
Plug From: 24.833
Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004395249
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395253
Layer:
Material:

Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395254
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395251
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

226 ***1 of 1*** ***E/191.1*** ***79.8 / 0.97*** ***Toronto ON*** ***WWIS***

Well ID:	7295927	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	9/29/2017
Sec. Water Use:	Test Hole	***Selected Flag:***	Yes
Final Well Status:	Monitoring and Test Hole	***Abandonment Rec:***	
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	7
Audit No:	Z267972	***Owner:***	
Tag:	A208894	***Street Name:***	21 DONWAY ROADWAY
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	WKQ-010280 A0-A04
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006741480	***Elevation:***	80.244949
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633354
Code OB Desc:		***North83:***	4835028
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	5
Date Completed:	8/11/2017	***UTMRC Desc:***	margin of error : 100 m - 300 m

Remarks: ***Location Method:*** wwr
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1006907588
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3:
Other Materials:
Formation Top Depth: 4
Formation End Depth: 24
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006907587
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 11
Other Materials: GRAVEL
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 4
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006907596
Layer: 1
Plug From: 24
Plug To: 13
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006907597
Layer: 2
Plug From: 13
Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1006907586
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006907591
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 14
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006907592
Layer: 1
Slot: .7
Screen Top Depth: 14
Screen End Depth: 24
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Hole Diameter

Hole ID: 1006907589
Diameter: 6
Depth From: 0
Depth To: 24
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

227 ***1 of 1*** ***WSW/191.4*** ***78.8 / -0.04*** ***ON*** ***BORE***

Borehole ID: 635167
OGF ID: 215535564
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JUN-1962
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 7.4
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.655411
Longitude DD: -79.353828
UTM Zone: 17
Easting: 632743
Northing: 4834918

Orig Ground Elev m:	77.1	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	76.6		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472200	**Mat Consistency:**	
Top Depth:	5.8	**Material Moisture:**	
Bottom Depth:	7.4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. 014 0002503900006 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472198	**Mat Consistency:**	Compact
Top Depth:	.8	**Material Moisture:**	
Bottom Depth:	5.5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,BROWN,GLACIAL, LOOSE TO VERY COMPACT, AGE GLACIAL.		

Geology Stratum ID:	218472197	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Granuls	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,CINDERS. BROWN,LOOSE.		

Geology Stratum ID:	218472199	**Mat Consistency:**	
Top Depth:	5.5	**Material Moisture:**	
Bottom Depth:	5.8	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SHALE. GREY,WEATHERED,AGE ORDOVICIAN.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031230 NTS_Sheet: 30M11C		

Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

228 **1 of 1** **W/191.4** **78.3 / -0.53** **TORONTO ON** **WWIS**

Well ID: 7199373
Construction Date:
Primary Water Use: Not Used
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z150243
Tag: A083401
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Data Entry Status:
Data Src:
Date Received: 3/25/2013
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 7341
Form Version: 7
Owner:
Street Name: SOUTH WOONERF
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004268244
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 3/18/2013
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 80.151557
Elevrc:
Zone: 17
East83: 632674
North83: 4835018
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004955931
Layer: 2
Plug From:
Plug To:
Plug Depth UOM: m

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Annular Space/Abandonment Sealing Record

Plug ID:	1004955932
Layer:	1
Plug From:	1.5
Plug To:	8
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004955930
Layer:	1
Plug From:	1.5
Plug To:	8
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1004955922
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004955926
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	8
Casing Diameter:	2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004955927
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	

Hole Diameter

Hole ID:	1004955924
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	m
Hole Diameter UOM:	cm

229	***1 of 1***	***WNW/191.5***	***78.2 / -0.68***	***ON***	***BORE***

Borehole ID:	635168	**Inclin FLG:**	No
OGF ID:	215535565	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JUN-1962	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.658159
Total Depth m:	6	**Longitude DD:**	-79.353976
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632725
Drill Method:	Power auger	**Northing:**	4835223
Orig Ground Elev m:	77.1	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.1		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472201	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.8	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Granuls	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,CINDERS. BROWN,LOOSE.		

Geology Stratum ID:	218472203	**Mat Consistency:**	
Top Depth:	4.6	**Material Moisture:**	
Bottom Depth:	6	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN. 00025048BEDROCK **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472202	**Mat Consistency:**	Hard
Top Depth:	.8	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,BROWN,GLACIAL,HARD, AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR1A.txt RecordID: 031240 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

230 **1 of 1** **W/191.7** **79.8 / 0.91** **ON** **BORE**

Borehole ID: 635143
OGF ID: 215535540
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1962
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 11.6
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 78.4
Elev Reliabil Note:
DEM Ground Elev m: 82.9
Concession:
Location D:
Survey D:
Comments:
Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.656096
Longitude DD: -79.354529
UTM Zone: 17
Easting: 632685
Northing: 4834993
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218472100
Top Depth: 3.7
Bottom Depth: 10.7
Material Color: Brown
Material 1: Silt
Material 2: Sand
Material 3: Clay
Material 4:
Gsc Material Description:
Stratum Description: SILT(65),SAND(19)MEDIUM,CLAY(16). GREY,BROWN,LACUSTRINE,BEDDED, AGE GLACIAL.
Mat Consistency:
Material Moisture:
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: lacustrine

Geology Stratum ID: 218472102
Top Depth: 11.6
Bottom Depth: 11.6
Material Color:
Material 1: Boulders
Material 2: Shale
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: BOULDERS,SHALE. 0000000800120004 **Note: Many records provided by the department have a truncated [Stratum Description] field.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218472099
Mat Consistency: Loose

Top Depth:	0	**Material Moisture:**	
Bottom Depth:	3.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,CLAY,SAND.GREY,LOOSE.		

Geology Stratum ID:	218472101	**Mat Consistency:**	Hard
Top Depth:	10.7	**Material Moisture:**	
Bottom Depth:	11.6	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Shale	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT,SHALEGREY,GLACIAL,HARD, AGE NON-GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 030990 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

231 | ***1 of 1*** | ***N/192.3*** | ***80.8 / 1.97*** | ***Toronto ON*** | ***WWIS***

Well ID:	7208877	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	10/2/2013
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Monitoring and Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z176322	**Owner:**	
Tag:	A150068	**Street Name:**	714 QUEEN STREET EAST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	WKQ-006265 A0-A04
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	1004591533	***Elevation:***	80.663948
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633061
Code OB Desc:		***North83:***	4835356
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	8/28/2013	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004627889
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	0.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004627891
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	3
Formation End Depth:	6
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1004627890
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	01

Most Common Material: FILL
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0.5
Formation End Depth: 3
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004627892
Layer: 4
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 6
Formation End Depth: 12
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004627900
Layer: 1
Plug From: 0
Plug To: 0.5
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004627902
Layer: 3
Plug From: 5
Plug To: 12
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004627901
Layer: 2
Plug From: 0.5
Plug To: 5
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID:	1004627888
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004627895
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	7
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004627896
Layer:	1
Slot:	10
Screen Top Depth:	7
Screen End Depth:	12
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.5

Hole Diameter

Hole ID:	1004627893
Diameter:	25
Depth From:	0
Depth To:	12
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

232 ***1 of 1*** ***W/192.5*** ***79.8 / 0.91*** ***ON*** ***BORE***

Borehole ID:	633031	***Inclin FLG:***	No
OGF ID:	215533432	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	AUG-1962	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.656032
Total Depth m:	15.2	***Longitude DD:***	-79.354493
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632688
Drill Method:	Diamond Drill	***Northing:***	4834986
Orig Ground Elev m:	78.6	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	82.8		
Concession:			
Location D:			
Survey D:			

Comments:

Borehole Geology Stratum

Geology Stratum ID:	218464767	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	3.7	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Coal fragments	***Geologic Period:***	
Material 4:	Wood Fragments	***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,COAL,WOOD.BROWN.		

Geology Stratum ID:	218464768	***Mat Consistency:***	Loose
Top Depth:	3.7	***Material Moisture:***	
Bottom Depth:	12.8	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Organic	***Geologic Period:***	
Material 4:		***Depositional Gen:***	organic
Gsc Material Description:			
Stratum Description:	SILT,SAND,ORGANIC. BROWN,GREY,GLACIAL,LOOSE, AGE GLACIAL.		

Geology Stratum ID:	218464770	***Mat Consistency:***	
Top Depth:	15.2	***Material Moisture:***	
Bottom Depth:	15.2	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine
Gsc Material Description:			
Stratum Description:	BEDROCK,SHALE. GREY,MARINE,AGE ORDOVICIAN.		

Geology Stratum ID:	218464769	***Mat Consistency:***	Dense
Top Depth:	12.8	***Material Moisture:***	
Bottom Depth:	15.2	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Silt	***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY,SILT. GLACIAL,VERY DENSE, AGE GLACIAL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 009780 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level

Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

233 **1 of 1** **WSW/193.2** **78.9 / 0.03** **TORONTO ON** **WWIS**

Well ID:	7185084	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127705	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101471	**Elevation:**	76.753395
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632736
Code OB Desc:		**North83:**	4834923
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/15/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395248
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004395247
Layer:	1
Plug From:	40.833

Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004395240
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395244
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395245
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395242
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

234 | ***1 of 1*** | ***NNW/193.8*** | ***81.9 / 3.06*** | ***672 and 678 Queen Street East Toronto ON M4M 1G8*** | ***EHS***

Order No: 20190816084
Status: C
Report Type: Standard Report
Report Date: 22-AUG-19
Date Received: 16-AUG-19
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.351281
Y: 43.658816

---

235 | ***1 of 2*** | ***NNW/194.0*** | ***82.0 / 3.09*** | ***ALRON PHOTO REPRODUCTION 678 QUEEN STREET EAST TORONTO ON M4M 1G8*** | ***GEN***

Generator No: ON1593900

PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: **Country:**
Approval Years: 99,00,01 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No Admin:**
SIC Code: 6571
SIC Description: CAMERA/PHOTO. SUPPLY

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

---

235 ***2 of 2*** ***NNW/194.0*** ***82.0 / 3.09*** ***ALRON PHOTO REPRODUCTION 02-648*** ***GEN***
678 QUEEN ST. EAST
TORONTO ON M4M 1G8

Generator No: ON1593900 **PO Box No:**
Status: **Country:**
Approval Years: 92,93,94,95,96,97,98 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No Admin:**
SIC Code: 6571
SIC Description: CAMERA/PHOTO. SUPPLY

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

---

236 ***1 of 2*** ***NNW/194.2*** ***81.9 / 3.02*** ***D & S Vending Machine Co. Ltd.*** ***SCT***
672 Queen St E
Toronto ON M4M 1G8

Established: 1960
Plant Size (ft²):
Employment: 3

--Details--
Description: Other Major Appliance Manufacturing
SIC/NAICS Code: 335229

Description: Non-Alcoholic Beverage Wholesaler-Distributors
SIC/NAICS Code: 413210

Description: Office and Store Machinery and Equipment Wholesaler-Distributors
SIC/NAICS Code: 417910

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

---

236 ***2 of 2*** ***NNW/194.2*** ***81.9 / 3.02*** ***D. & S. Vending Machine Co. Ltd.*** ***SCT***
672 Queen St E
Toronto ON M4M 1G8

Established: 1960
Plant Size (ft²):
Employment: 3

--Details--

Description: Non-Alcoholic Beverage Wholesaler-Distributors
SIC/NAICS Code: 413210

Description: Office and Store Machinery and Equipment Wholesaler-Distributors
SIC/NAICS Code: 417910

Description: Chemical (except Agricultural) and Allied Product Wholesaler-Distributors
SIC/NAICS Code: 418410

Description: Other Major Appliance Manufacturing
SIC/NAICS Code: 335229

---

237 **1 of 1** **W/196.2** **79.7 / 0.85** **Toronto ON** **WWIS**

Well ID: 7218566
Construction Date:
Primary Water Use: Test Hole
Sec. Water Use:
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z167270
Tag: A159742
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 3/28/2014
Selected Flag: Yes
Abandonment Rec:
Contractor: 7215
Form Version: 7
Owner:
Street Name: NEAR TROLLEY CRESCENT
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004726709
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 2/20/2014
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 82.872116
Elevrc:
Zone: 17
East83: 632679
North83: 4834994
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005120261
Layer: 6
Color: 2
General Color: GREY
Mat1: 17

Most Common Material:	SHALE
Mat2:	92
Other Materials:	WEATHERED
Mat3:	
Other Materials:	
Formation Top Depth:	48.5
Formation End Depth:	60
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005120259
Layer:	4
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	28
Formation End Depth:	39
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005120260
Layer:	5
Color:	2
General Color:	GREY
Mat1:	34
Most Common Material:	TILL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	39
Formation End Depth:	48.5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005120258
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	34
Most Common Material:	TILL
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	1.5
Formation End Depth:	28
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID: 1005120257
Layer: 2
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0.417
Formation End Depth: 1.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005120256
Layer: 1
Color:
General Color:
Mat1:
Most Common Material:
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 0.417
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005120268
Layer: 1
Plug From: 0
Plug To: 2
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005120269
Layer: 2
Plug From: 2
Plug To: 48
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005120270
Layer: 3
Plug From: 48
Plug To: 60
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005120255
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005120264
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 50
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005120265
Layer: 1
Slot: 10
Screen Top Depth: 50
Screen End Depth: 60
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2

Hole Diameter

Hole ID: 1005120262
Diameter: 9
Depth From: 0
Depth To: 60
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

238 **1 of 1** **WSW/196.3** **78.9 / 0.03** **TORONTO ON** **WWIS**

Well ID: 7185086
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127707
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004101477	***Elevation:***	76.595298
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632737
Code OB Desc:		***North83:***	4834917
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/14/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395264
Layer:	1
Plug From:	21
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395257
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395261
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395262
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft

Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395259
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

239 | ***1 of 2*** | ***W/196.6*** | ***79.8 / 0.97*** | ***METROPOLITAN TORONTO, MUNICIPALITY OF RICHMOND-ADELAIDE INTERCHANGE AT DON VALLEY PARKWAY TORONTO ON*** | ***GEN***

Generator No: ON0605934
Status:
Approval Years: 95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 4591
SIC Description: HIGHWAY, ETC. IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

---

239 | ***2 of 2*** | ***W/196.6*** | ***79.8 / 0.97*** | ***TORONTO, MUNICIPALITY OF METROPOLITAN RICHMOND-ADELAIDE INTERCHANGE AT DON VALLEY PARKWAY TORONTO ON*** | ***GEN***

Generator No: ON0605934
Status:
Approval Years: 99,00,01,03,04
Contam. Facility:
MHSW Facility:
SIC Code: 4591
SIC Description: HIGHWAY, ETC. IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

---

240 | ***1 of 1*** | ***NNW/196.8*** | ***81.9 / 2.99*** | ***Similas Graphics Limited 670 Queen St E Toronto ON M4M 1G8*** | ***SCT***

Established: 1981
Plant Size (ft²):
Employment: 4

--Details--
Description: Commercial Screen Printing
SIC/NAICS Code: 323113

Description: Quick Printing
SIC/NAICS Code: 323114

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Other Printing
SIC/NAICS Code: 323119

---

241 **1 of 1** **S/197.4** **78.9 / 0.00** **TORONTO ON** **WWIS**

Well ID: 7185096
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127734
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004101545
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/19/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 78.002677
Elevrc:
Zone: 17
East83: 632966
North83: 4834707
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004395351
Layer: 1
Plug From: 33.5
Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004395344
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395348
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395349
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395346
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

242 **1 of 1** **WSW/197.7** **79.8 / 0.97** **ON** **BORE**

Borehole ID: 635155
OGF ID: 215535552
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: MAR-1962
Static Water Level: 0.9
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 8.9
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 78.9
Elev Reliabil Note:
DEM Ground Elev m: 81.5
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.655732
Longitude DD: -79.35429
UTM Zone: 17
Easting: 632705
Northing: 4834953
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID:	218472149	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	2.4	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Clay	***Geologic Period:***	
Material 4:	Granuls	***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,SILT,CLAY, CINDERS. LOOSE.		

Geology Stratum ID:	218472151	***Mat Consistency:***	Dense
Top Depth:	5.8	***Material Moisture:***	
Bottom Depth:	8.8	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Till	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:	Gravel	***Depositional Gen:***	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND, GRAVEL. GREY,BROWN,GLACIAL,VERY DENSE,AGE NON-GLACIAL.		

Geology Stratum ID:	218472152	***Mat Consistency:***	
Top Depth:	8.8	***Material Moisture:***	
Bottom Depth:	8.9	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Boulders	***Geologic Formation:***	
Material 2:	Shale	***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine
Gsc Material Description:			
Stratum Description:	BOULDERS,SHALE. GREY,MARINE,AGE ORDOVICIAN. 00000005000800040019006000012 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218472150	***Mat Consistency:***	Soft
Top Depth:	2.4	***Material Moisture:***	
Bottom Depth:	5.8	***Material Texture:***	
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Organic	***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY,ORGANIC. GREY,LACUSTRINE,SOFT, AGE GLACIAL, WATER STABLE AT 256.1 FEET.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031110 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level

Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

243 **1 of 1** **E/197.8** **79.8 / 0.97** **ON** **BORE**

Borehole ID:	644980	**Inclin FLG:**	No
OGF ID:	215545363	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	1946	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655974
Total Depth m:	10.5	**Longitude DD:**	-79.346099
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633365
Drill Method:	Diamond Drill	**Northing:**	4834993
Orig Ground Elev m:	78.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.5		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509624	**Mat Consistency:**	
Top Depth:	2.7	**Material Moisture:**	
Bottom Depth:	5.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SILT.		

Geology Stratum ID:	218509623	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218509625	**Mat Consistency:**	
Top Depth:	5.9	**Material Moisture:**	
Bottom Depth:	10.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Gravel	**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach
Gsc Material Description:			
Stratum Description:	CLAY,SAND,GRAVEL. BEACH,AGE POST-GLACIAL. AY,SAND,G **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 130020 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

244 ***1 of 1*** ***NW/198.9*** ***80.1 / 1.21*** ***ON*** ***BORE***

Borehole ID:	635169	***Inclin FLG:***	No
OGF ID:	215535566	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	JUN-1962	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.65838
Total Depth m:	6	***Longitude DD:***	-79.353722
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	632745
Drill Method:	Power auger	***Northing:***	4835248
Orig Ground Elev m:	78.3	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	79.5		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472204	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.3	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:	Granuls	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL,CINDERS. BROWN,LOOSE.		

Geology Stratum ID:	218472205	***Mat Consistency:***	Stiff
Top Depth:	.3	***Material Moisture:***	
Bottom Depth:	3.4	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	

Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,BROWN,GLACIAL,STIFF, AGE GLACIAL.		

Geology Stratum ID:	218472206	**Mat Consistency:**	
Top Depth:	3.4	**Material Moisture:**	
Bottom Depth:	6	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,CLAY. GREY,GLACIAL, SENSITIVE TO VERY SENSITIVE, AGE GLACIAL. 014 0001001400110068 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031250 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

245 ***1 of 1*** ***NNW/198.9*** ***81.9 / 3.04*** ***TORONTO ON*** ***WWIS***

Well ID:	7043154	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Not Used	**Date Received:**	4/30/2007
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7147
Casing Material:		**Form Version:**	3
Audit No:	Z64349	**Owner:**	
Tag:	A041543	**Street Name:**	678 QUEEN ST EAST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	11765614	***Elevation:***	80.923835
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:	o	***East83:***	632955
Code OB Desc:	Overburden	***North83:***	4835308
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	4/13/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	933099183
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	
Most Common Material:	
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	0.2
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933099184
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0.2
Formation End Depth:	0.46
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933099186
Layer:	4
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	84

Other Materials:	SILTY
Mat3:	
Other Materials:	
Formation Top Depth:	3.8
Formation End Depth:	5.2
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	933099185
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	0.46
Formation End Depth:	3.8
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933317940
Layer:	1
Plug From:	0
Plug To:	0.2
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933317941
Layer:	2
Plug From:	0.2
Plug To:	1.8
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933317942
Layer:	3
Plug From:	1.8
Plug To:	5.2
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	933317943
Layer:	4
Plug From:	
Plug To:	5.2
Plug Depth UOM:	m

Method of Construction & Well

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Use

Method Construction ID:
Method Construction Code: B
Method Construction: Other Method
Other Method Construction:

Pipe Information

Pipe ID: 11773304
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930898659
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 2.1
Casing Diameter: 3.2
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933424254
Layer: 1
Slot:
Screen Top Depth: 2.1
Screen End Depth: 5.2
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 4.3

Hole Diameter

Hole ID: 11851972
Diameter: 5
Depth From: 0
Depth To: 5.2
Hole Depth UOM: m
Hole Diameter UOM: cm

246	*1 of 4*	*N/198.9*	*81.9 / 3.04*	***CROSS TOWN AUTO RADIATORS SERVICE CO*** ***3 HAMILTON ST*** ***TORONTO ON M4M 2C4***	***AUWR***

Headcode: 96400
Headcode Desc: Automobile Parts & Supplies-Used & Rebuilt
Phone: 4164691615
List Name:
Description:

246	*2 of 4*	*N/198.9*	*81.9 / 3.04*	***CROSSTOWN RADIATOR SERVICE & MFG.*** ***3 HAMILTON STREET, PT.LOTS 1&2*** ***TORONTO CITY ON M4M 2C4***	***CA***

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Certificate #: 8-3602-95-966
Application Year: 95
Issue Date: 4/22/96
Approval Type: Industrial air
Status: Received in 1995, Issued in 1996
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: FUME CABINET HOOD, PAINT SPRAY BOOTH
Contaminants: Suspended Particulate Matter, Ammonium Chloride, Ammonia, Hydrogen Chloride, Chlorine
Emission Control: No Controls

---

246 | **3 of 4** | **N/198.9** | **81.9 / 3.04** | **3 Hamilton Street**
Toronto ON M4M 2C4 | **EHS**

Order No: 20060403005
Status: C
Report Type: Complete Report
Report Date: 4/11/2006
Date Received: 4/3/2006
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans; Title Search; Aerials Photos

Nearest Intersection: Broadview Ave. & Queen St. E.
Municipality: Toronto
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.35077
Y: 43.658979

---

246 | **4 of 4** | **N/198.9** | **81.9 / 3.04** | **Streetcar Develomemts Inc.**
3 Hamilton Street
Toronto ON | **GEN**

Generator No: ON4248920
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 236220
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

247 | **1 of 1** | **WNW/200.1** | **76.7 / -2.16** | **ON** | **BORE**

Borehole ID: 635799
OGF ID: 215536196
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date:
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 22.9
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Orig Ground Elev m: 76.2
Elev Reliabil Note:
DEM Ground Elev m: 81.2
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.657851
Longitude DD: -79.354481
UTM Zone: 17
Easting: 632685
Northing: 4835188
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID:	218474652	***Mat Consistency:***	
Top Depth:	18.9	***Material Moisture:***	
Bottom Depth:	22.9	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY. LACUSTRINE,AGE GLACIAL. C **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218474650	***Mat Consistency:***	
Top Depth:	5.5	***Material Moisture:***	
Bottom Depth:	9.1	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Clay	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY. LACUSTRINE.		

Geology Stratum ID:	218474649	***Mat Consistency:***	
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	5.5	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Fill	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218474651	***Mat Consistency:***	
Top Depth:	9.1	***Material Moisture:***	
Bottom Depth:	18.9	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Soil	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SOIL.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	M	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 037570 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level

Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

248 **1 of 1** **WSW/200.7** **77.6 / -1.23** **ON** **WWIS**

Well ID:	7309140	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	4/10/2018
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	6032
Casing Material:		**Form Version:**	8
Audit No:	C41419	**Owner:**	
Tag:	A244536	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1007015090	**Elevation:**	
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632755
Code OB Desc:		**North83:**	4834889
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	3/6/2018	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

249 **1 of 1** **NNE/201.9** **79.8 / 0.97** **macFAB Ltd.**
755 Queen St E
Toronto ON M4M 1H3 **SCT**

Established:	01-AUG-58
Plant Size (ft²):	6000
Employment:	

--Details--

Description:	Piece Goods, Notions and Other Dry Goods Wholesaler-Distributors
SIC/NAICS Code:	414130
Description:	Curtain and Linen Mills
SIC/NAICS Code:	314120
Description:	Piece Goods, Notions and Other Dry Goods Wholesaler-Distributors

SIC/NAICS Code: 414130

---

250 *1 of 1* *NNW/202.2* *81.9 / 3.05* ***7 East Hampton St. Toronto ON*** ***SPL***

Ref No:	1432-9AUNY2	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	2013/08/23	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Dumping	**Sector Type:**	Unknown / N/A
Incident Event:		**Agency Involved:**	
Contaminant Code:	n/a	**Nearest Watercourse:**	
Contaminant Name:	ORGANIC MATERIAL	**Site Address:**	7 East Hampton St.
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Toronto
Nature of Impact:	Other Impact(s)	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2013/08/23	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:	Unknown / N/A	**Source Type:**	
Site Name:	7 East Hampton St.<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Toronto Water: Unknown qty of tomato pulp/seeds to cb		
Contaminant Qty:	0 other - see incident description		

---

251 *1 of 1* *SSW/205.7* *76.0 / -2.89* ***TOROTNO ON*** ***WWIS***

Well ID:	6929808	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	1/23/2006
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	3
Audit No:	Z43625	**Owner:**	
Tag:	A031393	**Street Name:**	FROTN & OVEREND
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	11558608	**Elevation:**	76.855896
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:	_	**East83:**	632853

Code OB Desc:	No formation data	***North83:***	4834766
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	3
Date Completed:	1/11/2006	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	933286269
Layer:	1
Plug From:	9
Plug To:	0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	B
Method Construction:	Other Method
Other Method Construction:	

Pipe Information

Pipe ID:	11568215
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930873786
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	5
Depth To:	0
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	933416721
Layer:	1
Slot:	
Screen Top Depth:	5
Screen End Depth:	20
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2

Hole Diameter

Hole ID:	11690740
Diameter:	8
Depth From:	20
Depth To:	0
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

252 **1 of 1** **WNW/206.2** **79.9 / 1.01** **TORONTO ON** **WWIS**

Well ID:	7255561	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	1/11/2016
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7360
Casing Material:		**Form Version:**	7
Audit No:	Z208190	**Owner:**	
Tag:	A194033	**Street Name:**	185 BAYVIEW AVE
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005862206	**Elevation:**	80.702919
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632664
Code OB Desc:		**North83:**	4835161
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	12/7/2015	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005905561
Layer:	5
Color:	
General Color:	
Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	91
Other Materials:	WATER-BEARING

Formation Top Depth: 20
Formation End Depth: 70
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005905558
Layer: 2
Color:
General Color:
Mat1: 28
Most Common Material: SAND
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 5
Formation End Depth: 10
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005905557
Layer: 1
Color:
General Color:
Mat1: 01
Most Common Material: FILL
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005905562
Layer: 6
Color:
General Color:
Mat1: 01
Most Common Material: FILL
Mat2:
Other Materials:
Mat3: 73
Other Materials: HARD
Formation Top Depth: 70
Formation End Depth: 100
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005905560
Layer: 4
Color:
General Color:

Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	15
Formation End Depth:	20
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005905559
Layer:	3
Color:	
General Color:	
Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	10
Formation End Depth:	15
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005905569
Layer:	1
Plug From:	0
Plug To:	87
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1005905556
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005905565
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	90
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005905566
Layer:	1
Slot:	10
Screen Top Depth:	90
Screen End Depth:	100
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Water Details

Water ID:	1005905564
Layer:	1
Kind Code:	8
Kind:	Untested
Water Found Depth:	
Water Found Depth UOM:	ft

Hole Diameter

Hole ID:	1005905563
Diameter:	6
Depth From:	0
Depth To:	100
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

253 ***1 of 1*** ***SSW/206.6*** ***78.9 / 0.04*** ***TORONTO ON*** ***WWIS***

Well ID:	7185056	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127730	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004100485	***Elevation:***	77.955078
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632960
Code OB Desc:		***North83:***	4834699

Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/19/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004394858
Layer:	1
Plug From:	17.333
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004394851
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004394855
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004394856
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004394853
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
254	1 of 1	W/207.1	76.9 / -1.97	Her Majesty the Queen in right of Ontario as represented by MOI No Municipal Address TORONTO ON	RSC

RSC ID:	109539	**Cert Date:**	12-May-11
RA No:		**Cert Prop Use No:**	3010-8ELR9H-MOI
RSC Type:		**Intended Prop Use:**	Residential
Curr Property Use:	Industrial	**Qual Person Name:**	Daniel Horowitz
Ministry District:	TORONTO	**Stratified (Y/N):**	
Filing Date:	25-May-11	**Audit (Y/N):**	
Date Ack:		**Entire Leg Prop. (Y/N):**	Yes
Date Returned:		**Accuracy Estimate:**	0 to 1 meters
Restoration Type:		**Telephone:**	416-3273937
Soil Type:		**Fax:**	416-3271906
Criteria:		**Email:**	daniel.horowitz@ontariorealty.ca
CPU Issued Sect 1686:	Yes		
Asmt Roll No:			

Prop ID No (PIN): 21078-0188 (LT); 21078-0189 (LT); 21078-0190 (LT); 21078-0191 (LT); 21078-0197 (LT); 21078-0198 (LT); 21078-0199 (LT); 21078-0200 (LT); 21078-0201 (LT); 21078-0202 (LT)

Property Municipal Address: No Municipal Address

Mailing Address: Suite 2000, 1 DUNDAS ST W, TORONTO, ON, M5G 2L5

Latitude & Latitude: 43.65667130N 79.35495580W (converted from UTM)

UTM Coordinates: NAD83 17-632649-4835056

Consultant:

Filing Owner:

Legal Desc: BLOCK 2, PLAN 66M2473 CITY OF TORONTO; BLOCK 3, PLAN 66M2473 SUBJECT TO AN EASEMENT AS IN AT2310791 SUBJECT TO AN EASEMENT OVER BLOCK 3 PL 66M2473 IN FAVOUR OF PTS 1 TO 7 INCLUSIVE PL 66R22377 AS IN AT2311416 CITY OF TORONTO; BLOCK 4, PLAN 66M2473 SUBJECT TO AN EASEMENT AS IN AT2310791 SUBJECT TO AN EASEMENT OVER BLOCK 4 PL 66M2473 IN FAVOUR OF PTS 1 TO 7 INCLUSIVE PL 66R22377 AS IN AT2311416 CITY OF TORONTO; BLOCK 7, PLAN 66M2473;S/T CT53885 AS TRANSFERRED BY CT174850 SUBJECT TO AN EASEMENT AS IN CT466801 SUBJECT TO AN EASEMENT AS IN AT2310791 CITY OF TORONTO; BLOCK 15, PLAN 66M2473;S/T CT53885 AS TRANSFERRED BY CT174850 SUBJECT TO AN EASEMENT AS IN CT466801 CITY OF TORONTO; BLOCK 21, 22, 23, 24, and 25, PLAN 66M2473 CITY OF TORONTO

Measurement Method: Digitized from a map

Applicable Standards: Background Site Conditions Standard, with Nonpotable Ground Water, Coarse Textured Soil, for Residential/Parkland/Institutional property use with Risk

RSC PDF:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
255	1 of 1	S/207.8	78.9 / 0.04	TORONTO ON	WWIS

Well ID:	7185054	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127688	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004100441	***Elevation:***	77.983741
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632963
Code OB Desc:		***North83:***	4834697
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/19/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004394800
Layer:	1
Plug From:	24.667
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004394799
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004394792
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004394796
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004394797
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	

Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004394794
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

256 ***1 of 2*** ***NE/208.3*** ***79.8 / 0.97*** ***Palmer [E J]*** ***82 Saulter St*** ***Toronto ON*** ***TANK***

Permit Date: 11/12/1927
Permit Type: BP A9835
User Type: Trucking?
Installation Type: Gasoline tank
Installation Size:
Installation Config.: 1 x Gasoline tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 200
Capacity(gal):
Reference: CTA Building permits
Location Desc:

---

256 ***2 of 2*** ***NE/208.3*** ***79.8 / 0.97*** ***Riverdale Cartage Co*** ***82 Saulter St*** ***Toronto ON*** ***TANK***

Permit Date: 1930
Permit Type: BP A34763
User Type: Trucking
Installation Type: Gasoline pump
Installation Size:
Installation Config.: 1 x gasoline pump
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 100
Capacity(gal):
Reference: CTA Building permits
Location Desc:

---

257 ***1 of 1*** ***NNE/208.8*** ***79.8 / 0.97*** ***754 Queen St E*** ***Toronto ON M4M 1H4*** ***EHS***

Order No: 20121115003
Status: C
Report Type: Custom Report
Report Date: 23-NOV-12
Date Received: 15-NOV-12
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality: Toronto
Client Prov/State: ON
Search Radius (km): .25
X: -79.348229
Y: 43.659347

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
258	1 of 1	SSE/209.3	79.8 / 0.97	Eastern Avenue Toronto ON	EHS

Order No:	20151021064	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	27-OCT-15	**Search Radius (km):**	.03
Date Received:	21-OCT-15	**X:**	-79.348357
Previous Site Name:		**Y:**	43.653909
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
259	1 of 1	WSW/209.4	79.5 / 0.59	Toronto ON	WWIS

Well ID:	7263275	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	5/20/2016
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7147
Casing Material:		**Form Version:**	7
Audit No:	Z228041	**Owner:**	
Tag:	A198738	**Street Name:**	WEST DON LANDS AREA
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006002669	**Elevation:**	78.227455
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632713
Code OB Desc:		**North83:**	4834925
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	4/29/2016	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006083385
Layer:	2
Color:	6
General Color:	BROWN

Mat1:	06
Most Common Material:	SILT
Mat2:	01
Other Materials:	FILL
Mat3:	81
Other Materials:	SANDY
Formation Top Depth:	0.6
Formation End Depth:	3.7
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006083386
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	
Other Materials:	
Formation Top Depth:	3.7
Formation End Depth:	7.3
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1006083384
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	
Most Common Material:	
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	0.6
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006083394
Layer:	2
Plug From:	0.3
Plug To:	3.8
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006083395
Layer:	3
Plug From:	3.8
Plug To:	7.3
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006083393
Layer:	1
Plug From:	0
Plug To:	0.3
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006083396
Layer:	4
Plug From:	
Plug To:	7.3
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1006083383
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006083389
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0.9
Depth To:	4.2
Casing Diameter:	5
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1006083390
Layer:	1
Slot:	.01
Screen Top Depth:	4.2
Screen End Depth:	7.3
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.3

Water Details

Water ID:	1006083388
Layer:	1

Kind Code: 1
Kind: FRESH
Water Found Depth: 4.9
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006083387
Diameter: 11.4
Depth From: 0
Depth To: 7.3
Hole Depth UOM: m
Hole Diameter UOM: cm

---

260 **1 of 1** **NE/209.4** **79.8 / 0.97** **Broadview Ave./Queen Street East Toronto ON** **EHS**

Order No: 20120126024
Status: C
Report Type: Custom Report
Report Date: 1/30/2012
Date Received: 1/26/2012 2:34:11 PM
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.347574
Y: 43.659067

---

261 **1 of 1** **E/210.1** **79.8 / 0.97** **Toronto ON** **WWIS**

Well ID: 7275173
Construction Date:
Primary Water Use: Monitoring and Test Hole
Sec. Water Use: 0
Final Well Status: Monitoring and Test Hole
Water Type:
Casing Material:
Audit No: Z209897
Tag: A181932
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 11/22/2016
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 400 EASTERN AVE
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1006294104
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/18/2016
Remarks:
Elevrc Desc:

Elevation: 80.784034
Elevrc:
Zone: 17
East83: 633360
North83: 4835075
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID: 1006422617
Layer: 2
Color: 6
General Color: BROWN
Mat1: 08
Most Common Material: FINE SAND
Mat2: 06
Other Materials: SILT
Mat3: 85
Other Materials: SOFT
Formation Top Depth: 0.5
Formation End Depth: 9
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006422616
Layer: 1
Color: 8
General Color: BLACK
Mat1:
Most Common Material:
Mat2:
Other Materials:
Mat3: 85
Other Materials: SOFT
Formation Top Depth: 0
Formation End Depth: 0.5
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006422618
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3: 85
Other Materials: SOFT
Formation Top Depth: 9
Formation End Depth: 18
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006422631
Layer: 3

Plug From: 7
Plug To: 18
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006422629
Layer: 1
Plug From: 0
Plug To: 1
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006422630
Layer: 2
Plug From: 1
Plug To: 7
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1006422615
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006422621
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 8
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1006422622
Layer: 1
Slot: 10
Screen Top Depth: 8
Screen End Depth: 18
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Hole Diameter

Hole ID: 1006422619
Diameter: 6
Depth From: 0
Depth To: 18
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

262 ***1 of 1*** ***SSW/211.6*** ***76.2 / -2.70*** ***n/a*** ***Toronto ON*** ***EHS***

Order No: 20180426252
Status: C
Report Type: Standard Report
Report Date: 04-MAY-18
Date Received: 26-APR-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.352435
Y: 43.653893

---

263 ***1 of 2*** ***NNE/211.7*** ***79.8 / 0.97*** ***744 Queen St. E*** ***Toronto ON*** ***EHS***

Order No: 20010517001
Status: C
Report Type: Site Report
Report Date: 5/22/01
Date Received: 5/17/01
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection: at Grant St. see map
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.348322
Y: 43.659313

---

263 ***2 of 2*** ***NNE/211.7*** ***79.8 / 0.97*** ***Stephan Caras Design Inc.*** ***744 Queen St E*** ***Toronto ON M4M 1H4*** ***SCT***

Established: 01-JUL-84
Plant Size (ft²): 5000
Employment:

--Details--
Description: Women's and Girls' Cut and Sew Blouse and Shirt Manufacturing
SIC/NAICS Code: 315232

Description: Cut and Sew Clothing Contracting
SIC/NAICS Code: 315210

---

264 ***1 of 1*** ***SSW/212.2*** ***78.9 / -0.01*** ***TORONTO ON*** ***WWIS***

Well ID: 7185063
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7

Audit No:	Z127744	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004100544	**Elevation:**	77.931007
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632957
Code OB Desc:		**North83:**	4834694
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/19/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004394999
Layer:	1
Plug From:	10.417
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004394992
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004394996
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004394997
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004394994
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

265 | ***1 of 1*** | ***N/212.8*** | ***81.8 / 2.92*** | ***120 Broadview Toronto ON*** | ***EHS***

Order No:	20050506010	**Nearest Intersection:**	Broadview and Thompson
Status:	C	**Municipality:**	Toronto
Report Type:		**Client Prov/State:**	ON
Report Date:	5/12/2005	**Search Radius (km):**	0.25
Date Received:	5/6/2005	**X:**	-79.350206
Previous Site Name:		**Y:**	43.659408
Lot/Building Size:			
Additional Info Ordered:	Aerials Photos and/or Topographical Maps		

---

266 | ***1 of 1*** | ***WNW/212.9*** | ***79.8 / 0.89*** | ***ON*** | ***WWIS***

Well ID:	7189253	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	10/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	6926
Casing Material:		**Form Version:**	8
Audit No:	C18659	**Owner:**	
Tag:	A127787	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004175116	**Elevation:**	78.236351
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632648
Code OB Desc:		**North83:**	4835134

Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	7/4/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

267 **1 of 1** **NNE/213.4** **79.8 / 0.97** **ON** **BORE**

Borehole ID:	635885	**Inclin FLG:**	No
OGF ID:	215536282	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:		**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.659428
Total Depth m:	7.9	**Longitude DD:**	-79.348361
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633175
Drill Method:	Diamond Drill	**Northing:**	4835373
Orig Ground Elev m:	80.8	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	80.1		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218474993	**Mat Consistency:**	
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	1.8	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND. GREY,FLUVIO-GLACIAL, AGE GLACIAL.		

Geology Stratum ID:	218474994	**Mat Consistency:**	
Top Depth:	1.8	**Material Moisture:**	
Bottom Depth:	4	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND,SILT. BROWN,GLACIAL,AGE GLACIAL.		

Geology Stratum ID:	218474998	**Mat Consistency:**	
Top Depth:	6.7	**Material Moisture:**	
Bottom Depth:	7.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	

Material 2:	Silt	**Geologic Group:**	
Material 3:	Stones	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	CLAY,SILT,STONES. GREY,GLACIAL,AGE GLACIAL. 000600360013004000180025002200l0 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218474992	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218474997	**Mat Consistency:**	
Top Depth:	6.4	**Material Moisture:**	
Bottom Depth:	6.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND. GREY,FLUVIO-GLACIAL, AGE GLACIAL.		

Geology Stratum ID:	218474996	**Mat Consistency:**	
Top Depth:	5.5	**Material Moisture:**	
Bottom Depth:	6.4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY. GREY,LACUSTRINE,VARVED, AGE GLACIAL.		

Geology Stratum ID:	218474995	**Mat Consistency:**	
Top Depth:	4	**Material Moisture:**	
Bottom Depth:	5.5	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND,SILT. GREY,GLACIAL,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 038430 NTS_Sheet: 30M11C		
Confiden 1:	Logs are approximately correct. Lack of information. Doubtful terminology.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

268 **1 of 1** **SSE/213.6** **80.0 / 1.08** **Toronto ON** **WWIS**

Well ID:	7295929	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	9/29/2017
Sec. Water Use:	Monitoring	**Selected Flag:**	Yes
Final Well Status:	Monitoring and Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z267971	**Owner:**	
Tag:	A208890	**Street Name:**	21 DONWAY ROADWAY
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	WKQ-010280 A0-A04
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1006741486	**Elevation:**	78.242156
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633191
Code OB Desc:		**North83:**	4834757
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	8/11/2017	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1006907631
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	11
Other Materials:	GRAVEL
Mat3:	
Other Materials:	
Formation Top Depth:	0

Formation End Depth: 4
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1006907632
Layer: 2
Color: 6
General Color: BROWN
Mat1: 05
Most Common Material: CLAY
Mat2: 06
Other Materials: SILT
Mat3:
Other Materials:
Formation Top Depth: 4
Formation End Depth: 24
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006907640
Layer: 1
Plug From: 24
Plug To: 13
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1006907641
Layer: 2
Plug From: 13
Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: A
Method Construction: Digging
Other Method Construction:

Pipe Information

Pipe ID: 1006907630
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1006907635
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 14

Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1006907636
Layer:	1
Slot:	.1
Screen Top Depth:	14
Screen End Depth:	24
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Hole Diameter

Hole ID:	1006907633
Diameter:	6
Depth From:	0
Depth To:	24
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

269 ***1 of 1*** ***WNW/213.6*** ***79.9 / 1.03*** ***635 King Street East Toronto ON*** ***SPL***

Ref No:	5574-8NETAK	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	11/8/2011	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Transport Truck
Incident Event:		**Agency Involved:**	
Contaminant Code:	15	**Nearest Watercourse:**	
Contaminant Name:	HYDRAULIC OIL	**Site Address:**	635 King Street East
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Toronto
Nature of Impact:		**Site Lot:**	
Receiving Medium:	Sewage - Municipal/Private and Commercial	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	11/8/2011	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:		**Source Type:**	
Site Name:	site<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Lafarge: truck leaked 10 L hydraulic oil on gravel		
Contaminant Qty:	10 L		

---

270 ***1 of 1*** ***WNW/215.0*** ***79.9 / 1.03*** ***TORONTO ON*** ***WWIS***

Well ID:	7185104	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes

Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127698	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101645	**Elevation:**	78.933685
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632648
Code OB Desc:		**North83:**	4835142
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/23/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395459
Layer:	1
Plug From:	31.667
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395452
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395456
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395457
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395454
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

271 ***1 of 1*** ***WSW/215.1*** ***78.9 / -0.02*** ***TORONTO ON*** ***WWIS***

Well ID:	7185090	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	8/9/2012
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Abandoned-Other	***Abandonment Rec:***	Yes
Water Type:		***Contractor:***	4102
Casing Material:		***Form Version:***	7
Audit No:	Z127712	***Owner:***	
Tag:		***Street Name:***	WEST DON LANDS KING/RIVER ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101527	***Elevation:***	77.115379
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632720
Code OB Desc:		***North83:***	4834908
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/14/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395299
Layer:	1
Plug From:	31.833
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395292
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395296
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395297
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395294
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

272	***1 of 1***	***WNW/215.1***	***79.5 / 0.64***	***Enbridge Gas Distribution Inc.*** ***West-side of Bayview Extension approximately 20 meters north of Queen Street Bridge*** ***Toronto ON***	***SPL***

Ref No:	1518-9BHKJJ	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2013/09/13	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Leak/Break	***Sector Type:***	Other
Incident Event:		***Agency Involved:***	
Contaminant Code:	13	***Nearest Watercourse:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Contaminant Name:	DIESEL FUEL	**Site Address:**	West-side of Bayview Extension approximately 20 meters north of Queen Street Bridge
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Toronto
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2013/09/13	**Site Map Datum:**	
Dt Document Closed:	2013/09/20	**SAC Action Class:**	Land Spills
Incident Reason:	Material Failure - Poor Design/Substandard Material	**Source Type:**	
Site Name:	Bayview Extension<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Enbridge: 2L dsl to grass, Cleaned		
Contaminant Qty:	2 L		

---

273 | ***1 of 1*** | ***NNE/215.3*** | ***79.8 / 0.97*** | ***759, 761 763 Queen St. E. Toronto ON*** | ***EHS***

Order No:	20110428023	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	5/9/2011	**Search Radius (km):**	0.25
Date Received:	4/28/2011 1:57:24 PM	**X:**	-79.347755
Previous Site Name:		**Y:**	43.659132
Lot/Building Size:			
Additional Info Ordered:			

---

274 | ***1 of 2*** | ***ENE/215.7*** | ***79.8 / 0.97*** | ***Dibble [Robert] 378 Eastern Ave Toronto ON*** | ***TANK***

Permit Date:	1930
Permit Type:	BP A34837
User Type:	
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x gasoline tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	800
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	

---

274 | ***2 of 2*** | ***ENE/215.7*** | ***79.8 / 0.97*** | ***Dibble [Robert G] 378 Eastern Ave Toronto ON*** | ***TANK***

Permit Date:	8/29/1927
Permit Type:	BP A7771
User Type:	
Installation Type:	Gasoline tank
Installation Size:	
Installation Config.:	1 x Gasoline tank
No. Tanks Installed:	1

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Units of Measure:
Value/Tank ($): 500
Capacity(gal):
Reference: CTA Building permits
Location Desc: Eastern Ave nr Strange

---

275 | **1 of 1** | **NE/216.3** | **79.8 / 0.97** | **63, 65, 67 Saulter St Toronto ON** | **EHS**

Order No: 20100713008
Status: C
Report Type: Standard Select Report
Report Date: 7/21/2010
Date Received: 7/13/2010
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Aerial Photos

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.346951
Y: 43.658611

---

276 | **1 of 5** | **NW/216.4** | **80.8 / 1.97** | **BURRY SIGN STUDIO INC. 1 DAVIES AVE TORONTO ON M4M 2A6** | **SCT**

Established: 1965
Plant Size (ft²): 4000
Employment: 3

--Details--
Description: SIGNS AND ADVERTISING SPECIALTIES
SIC/NAICS Code: 3993

---

276 | **2 of 5** | **NW/216.4** | **80.8 / 1.97** | **Burry Sign Studio Inc. 1 Davies Ave Toronto ON M4M 2A6** | **SCT**

Established: 01-AUG-70
Plant Size (ft²): 4000
Employment:

--Details--
Description: Support Activities for Printing
SIC/NAICS Code: 323120

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Sign Manufacturing
SIC/NAICS Code: 339950

Description: Sign Manufacturing
SIC/NAICS Code: 339950

---

276 | **3 of 5** | **NW/216.4** | **80.8 / 1.97** | **Carter Service Station 1 Davies Ave Toronto ON M4M 2A6** | **TANK**

Permit Date: 10/19/1926
Permit Type: BP A611

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
User Type:		Auto service garage			
Installation Type:		Fuel oil tank			
Installation Size:					
Installation Config.:		1 x fuel oil tank			
No. Tanks Installed:		1			
Units of Measure:					
Value/Tank ($):		100			
Capacity(gal):					
Reference:		CTA Building permits			
Location Desc:		1 Davis Ave			
276	4 of 5	NW/216.4	80.8 / 1.97	**Coleman Lamp Co** **1 Davies Ave** **Toronto ON M4M 2A6**	TANK
Permit Date:		12/14/1925			
Permit Type:		BP 93714			
User Type:		Lamps and stoves			
Installation Type:		Water tank			
Installation Size:					
Installation Config.:		1 x water tank			
No. Tanks Installed:		1			
Units of Measure:					
Value/Tank ($):		1000			
Capacity(gal):					
Reference:		CTA Building permits			
Location Desc:		es Davies n Queen			
276	5 of 5	NW/216.4	80.8 / 1.97	**Mandell M** **1 Davies Ave** **Toronto ON M4M 2A6**	TANK
Permit Date:		2/15/1926			
Permit Type:		BP 94359			
User Type:		Gasoline service station			
Installation Type:		Gasoline tank			
Installation Size:					
Installation Config.:		1 x Gasoline tank			
No. Tanks Installed:		1			
Units of Measure:					
Value/Tank ($):		50			
Capacity(gal):					
Reference:		CTA Building permits			
Location Desc:		Davies cor Queen			
277	1 of 3	NE/217.1	79.8 / 0.97	**Maydwell Manufacturing Co. Ltd.** **65 Saulter St** **Toronto ON M4M 2H8**	SCT
Established:		1966			
Plant Size (ft²):		43560			
Employment:		12			
277	2 of 3	NE/217.1	79.8 / 0.97	**DOMINION BRASS PRODUCTS LTD.** **65 SAULTER ST** **TORONTO ON M4M 2H8**	SCT
Established:		1920			
Plant Size (ft²):		5000			

Employment: 4

--Details--

Description: FABRICATED METAL PRODUCTS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3499

Description: Other Ornamental and Architectural Metal Products Manufacturing
SIC/NAICS Code: 332329

Description: Hardware Manufacturing
SIC/NAICS Code: 332510

Description: Metal Valve Manufacturing
SIC/NAICS Code: 332910

Description: All Other Miscellaneous Fabricated Metal Product Manufacturing
SIC/NAICS Code: 332999

Description: HARDWARE, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3429

Description: PLUMBING FIXTURE FITTINGS AND TRIM
SIC/NAICS Code: 3432

Description: ARCHITECTURAL AND ORNAMENTAL METAL WORK
SIC/NAICS Code: 3446

Description: VALVES AND PIPE FITTINGS, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 3494

277	3 of 3	NE/217.1	79.8 / 0.97	MAYDWELL MANUFACTURING CO. 65 SAULTER ST TORONTO ON M4M 2H8	SCT

Established: 1904
Plant Size (ft²): 43560
Employment: 12

--Details--

Description: Other Wood Household Furniture Manufacturing
SIC/NAICS Code: 337123

Description: MILLWORK
SIC/NAICS Code: 2431

Description: WOOD HOUSEHOLD FURNITURE, EXCEPT UPHOLSTERED
SIC/NAICS Code: 2511

Description: Other Millwork
SIC/NAICS Code: 321919

278	1 of 2	WNW/218.2	79.9 / 1.03	ON	WWIS

Well ID: 7203404
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:

Data Entry Status: Yes
Data Src:
Date Received: 6/19/2013
Selected Flag: Yes
Abandonment Rec:
Contractor: 7201
Form Version: 8

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Audit No:	C19949	**Owner:**	
Tag:	A107933	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004358860	**Elevation:**	79.119842
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632645
Code OB Desc:		**North83:**	4835143
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	12/17/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

278 **2 of 2** **WNW/218.2** **79.9 / 1.03** **ON** **WWIS**

Well ID:	7203402	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	6/19/2013
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	7201
Casing Material:		**Form Version:**	8
Audit No:	C19989	**Owner:**	
Tag:	A107934	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004358854	**Elevation:**	79.119842
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632645
Code OB Desc:		**North83:**	4835143

Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	2/15/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

279 **1 of 1** **WSW/218.6** **79.8 / 0.97** **WWIS**

TORONTO ON

Well ID:	7185077	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127708	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101374	**Elevation:**	80.897529
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632695
Code OB Desc:		**North83:**	4834932
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	4/14/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395190
Layer:	1
Plug From:	22.25
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID: 1004395183
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395187
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395188
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395185
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

280 ***1 of 1*** ***SSW/218.7*** ***79.0 / 0.10*** ***TORONTO ON*** ***WWIS***

Well ID: 7185103
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127690
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS RIVER/KING ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	1004101642	***Elevation:***	77.82566
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632947
Code OB Desc:		***North83:***	4834690
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/22/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395451
Layer:	1
Plug From:	24
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395444
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395448
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395449
Layer:	1
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395446
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

281 **1 of 1** **NE/220.0** **79.8 / 0.97** **Toronto ON** **WWIS**

Well ID:	7190994	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	11/9/2012
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z158370	**Owner:**	
Tag:	A138505	**Street Name:**	53 SAULTER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	WKQ-005332
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004199762	**Elevation:**	79.710823
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633295
Code OB Desc:		**North83:**	4835287
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/3/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004487050
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	

Formation Top Depth: 20
Formation End Depth: 30
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004487049
Layer: 2
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Other Materials: CLAY
Mat3:
Other Materials:
Formation Top Depth: 12
Formation End Depth: 20
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1004487048
Layer: 1
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 12
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004487058
Layer: 1
Plug From: 30
Plug To: 9
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004487059
Layer: 2
Plug From: 19
Plug To: 1
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1004487060
Layer: 3
Plug From: 1

Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: D
Method Construction: Direct Push
Other Method Construction:

Pipe Information

Pipe ID: 1004487047
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004487053
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 20
Casing Diameter: 1.25
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004487054
Layer: 1
Slot: 10
Screen Top Depth: 20
Screen End Depth: 30
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 1.5

Hole Diameter

Hole ID: 1004487051
Diameter: 3.25
Depth From: 0
Depth To: 30
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

282 | ***1 of 1*** | ***NNE/220.5*** | ***79.8 / 0.97*** | ***TORONTO PUBLIC LIBRARY 765 QUEEN STREET EAST TORONTO ON M4M 1H3*** | ***GEN***

Generator No: ON1855625
Status:
Approval Years: 94,95,96,97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 8541

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

SIC Description: LIBRARY SERVICES

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

283 *1 of 2* *SSW/220.6* *78.8 / -0.02* *WWIS*

TORONTO ON

Well ID: 7185102
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: 0
Water Type:
Casing Material:
Audit No: Z127691
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004101601
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 5/22/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.726249
Elevrc:
Zone: 17
East83: 632939
North83: 4834690
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1004395443
Layer: 1
Plug From: 22.833
Plug To: 0
Plug Depth UOM: ft

Pipe Information

Pipe ID: 1004395436
Casing No: 0

Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395440
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395441
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395438
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

283 ***2 of 2*** ***SSW/220.6*** ***78.8 / -0.02*** ***TORONTO ON*** ***WWIS***

Well ID: 7185051
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127694
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004100432	**Elevation:**	77.726249
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632939
Code OB Desc:		**North83:**	4834691
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/22/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004394735
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004394736
Layer:	1
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004394728
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004394732
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004394733
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft

Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004394730
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

284 **1 of 4** **ENE/221.7** **79.8 / 0.97** **ON** **BORE**

Borehole ID: 643550
OGF ID: 215543937
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1961
Static Water Level: 0.9
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 9.4
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Orig Ground Elev m: 79.2
Elev Reliabil Note:
DEM Ground Elev m: 79.4
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.658052
Longitude DD: -79.346538
UTM Zone: 17
Easting: 633325
Northing: 4835223
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218504304
Top Depth: 8.5
Bottom Depth: 9.4
Material Color: Grey
Material 1: Till
Material 2: Silt
Material 3: Clay
Material 4: Gravel
Gsc Material Description:
Stratum Description: TILL,SILT,CLAY, GRAVEL. GREY,GLACIAL,STIFF, AGE GLACIAL. 000450050012000500150004002800160000 7 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency: Stiff
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Geology Stratum ID: 218504300
Top Depth: 0
Bottom Depth: 1.4
Material Color:
Material 1: Fill
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: FILL. LOOSE.

Mat Consistency: Loose
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Geology Stratum ID: 218504303
Mat Consistency: Soft

Top Depth:	4.6	**Material Moisture:**	
Bottom Depth:	8.5	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY,SILT,SAND MEDIUM. GREY,LACUSTRINE,SOFT,LAYERED, AGE GLACIAL.		

Geology Stratum ID:	218504301	**Mat Consistency:**	Stiff
Top Depth:	1.4	**Material Moisture:**	
Bottom Depth:	3.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,SAND,CLAY. GREY,BROWN,LACUSTRINE,STIFF, AGE GLACIAL, WATER STABLE AT 256.9 FEET.		

Geology Stratum ID:	218504302	**Mat Consistency:**	Loose
Top Depth:	3.7	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SILT,SANDMEDIUM. GREY,LACUSTRINE,LOOSE,LAYERED,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 115710 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

284 **2 of 4** **ENE/221.7** **79.8 / 0.97** **ON** **BORE**

Borehole ID:	643549	**Inclin FLG:**	No
OGF ID:	215543936	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1961	**Municipality:**	
Static Water Level:	0.5	**Lot:**	
Primary Water Use:	Not Used	**Township:**	

Sec. Water Use:		**Latitude DD:**	43.658052
Total Depth m:	4.9	**Longitude DD:**	-79.346538
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633325
Drill Method:	Diamond Drill	**Northing:**	4835223
Orig Ground Elev m:	79.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218504296	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Asphalt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,ASPHALT,SAND. LOOSE.		

Geology Stratum ID:	218504297	**Mat Consistency:**	Stiff
Top Depth:	2	**Material Moisture:**	
Bottom Depth:	2.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND. GREY,BROWN,LACUSTRINE,STIFF, AGE GLACIAL, WATER STABLE AT 258.4 FEET.		

Geology Stratum ID:	218504299	**Mat Consistency:**	Soft
Top Depth:	3.7	**Material Moisture:**	
Bottom Depth:	4.9	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY,SILT. GREY,LACUSTRINE,SOFT,LAYERED, AGE GLACIAL. 00000003000650090009001200120004000007 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218504298	**Mat Consistency:**	Stiff
Top Depth:	2.7	**Material Moisture:**	
Bottom Depth:	3.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY,SILT,CLAY. BROWN,LACUSTRINE,STIFF,VARVED,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular

Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 115700 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

284 ***3 of 4*** ***ENE/221.7*** ***79.8 / 0.97*** ***ON*** ***BORE***

Borehole ID:	643552	**Inclin FLG:**	No
OGF ID:	215543939	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1961	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.658052
Total Depth m:	9.4	**Longitude DD:**	-79.346538
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633325
Drill Method:	Diamond Drill	**Northing:**	4835223
Orig Ground Elev m:	79.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.4		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218504310	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Soil	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,SOIL. LOOSE.		

Geology Stratum ID:	218504312	**Mat Consistency:**	Soft
Top Depth:	3.2	**Material Moisture:**	
Bottom Depth:	9	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			

Stratum Description: CLAY,SILT,SAND MEDIUM. GREY,LACUSTRINE,SOFT,LAYERED, AGE GLACIAL.

Geology Stratum ID:	218504311	**Mat Consistency:**	Stiff
Top Depth:	.8	**Material Moisture:**	
Bottom Depth:	3.2	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine

Gsc Material Description:
Stratum Description: SILT,SAND,CLAY. GREY,BROWN,LACUSTRINE,STIFF, LAYERED,AGE GLACIAL.

Geology Stratum ID:	218504313	**Mat Consistency:**	Hard
Top Depth:	9	**Material Moisture:**	
Bottom Depth:	9.4	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Gravel	**Depositional Gen:**	glacial

Gsc Material Description:
Stratum Description: TILL,SILT,CLAY, GRAVEL. GREY,GLACIAL,HARD,AGE GLACIAL.000250060010500500295020L.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 115730 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

---

284 ***4 of 4*** ***ENE/221.7*** ***79.8 / 0.97*** ***ON*** ***BORE***

Borehole ID:	643551	**Inclin FLG:**	No
OGF ID:	215543938	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1961	**Municipality:**	
Static Water Level:	1.0	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.658052
Total Depth m:	10.1	**Longitude DD:**	-79.346538
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633325
Drill Method:	Diamond Drill	**Northing:**	4835223
Orig Ground Elev m:	79.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.4		

Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218504306
Top Depth: .2
Bottom Depth: 1.4
Material Color:
Material 1: Fill
Material 2: Sand
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: FILL,SAND. LOOSE,AGE GLACIAL.
Mat Consistency: Loose
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Geology Stratum ID: 218504305
Top Depth: 0
Bottom Depth: .2
Material Color:
Material 1: Asphalt
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: ASPHALT.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218504308
Top Depth: 3.7
Bottom Depth: 8.8
Material Color: Grey
Material 1: Clay
Material 2: Silt
Material 3: Sand
Material 4:
Gsc Material Description:
Stratum Description: CLAY,SILT,SAND MEDIUM. GREY,LACUSTRINE,SOFT, AGE GLACIAL.
Mat Consistency: Soft
Material Moisture:
Material Texture: Medium
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: lacustrine

Geology Stratum ID: 218504307
Top Depth: 1.4
Bottom Depth: 3.7
Material Color: Brown
Material 1: Silt
Material 2: Sand
Material 3: Clay
Material 4:
Gsc Material Description:
Stratum Description: SILT,SAND,CLAY. GREY,BROWN,LACUSTRINE,STIFF, AGE GLACIAL, WATER STABLE AT 256.7 FEET.
Mat Consistency: Stiff
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: lacustrine

Geology Stratum ID: 218504309
Top Depth: 8.8
Bottom Depth: 10.1
Material Color:
Material 1: Till
Material 2: Silt
Material 3: Clay
Material 4: Gravel
Gsc Material Description:
Stratum Description: TILL,SILT,CLAY, GRAVEL. GLACIAL,STIFF,AGE GLACIAL. 0000500500045008001200040029001300007FF, AGE **Note: Many records provided by the department have a truncated [Stratum Description] field.
Mat Consistency: Stiff
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: glacial

Source

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: H
Observatio:
Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 115720 NTS_Sheet: 30M11C
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

285 ***1 of 2*** ***NW/222.1*** ***80.8 / 1.97*** ***Davies Ave. Investments*** ***GEN***
9 Davies Ave.
Toronto ON M4M 2A6

Generator No: ON2361444
Status:
Approval Years: 03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

285 ***2 of 2*** ***NW/222.1*** ***80.8 / 1.97*** ***Backbone Special Effects*** ***SCT***
9 Davies Ave Suite 204B
Toronto ON M4M 2A6

Established: 1997
Plant Size (ft²):
Employment: 3

--Details--
Description: Post-Production and Other Motion Picture and Video Industries
SIC/NAICS Code: 512190

---

286 ***1 of 1*** ***W/222.5*** ***78.5 / -0.36*** ***WWIS***
Toronto ON

Well ID: 7248144
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z194303
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Data Entry Status:
Data Src:
Date Received: 9/14/2015
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 6032
Form Version: 7
Owner:
Street Name: 51 TROLLEY CRESCENT
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:

Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1005684070	***Elevation:***	78.954811
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632632
Code OB Desc:		***North83:***	4835084
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	8/18/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1005716207
Layer:	2
Plug From:	1
Plug To:	45
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005716206
Layer:	1
Plug From:	0
Plug To:	1
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005716205
Layer:	1
Plug From:	2
Plug To:	10
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID: 1005716197
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005716201
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 35
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005716202
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1005716199
Diameter: 8
Depth From: 0
Depth To: 45
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

287 ***1 of 1*** ***W/222.6*** ***79.0 / 0.11*** ***TORONTO ON*** ***WWIS***

Well ID: 7185105
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127697
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004101648	***Elevation:***	78.952468
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632633
Code OB Desc:		***North83:***	4835105
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	5
Date Completed:	5/23/2012	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395467
Layer:	1
Plug From:	32
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395460
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395464
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395465
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395462
Diameter:	

Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

288 **1 of 1** **NE/224.2** **79.8 / 0.97** **Toronto ON** **WWIS**

Well ID: 7190993
Construction Date:
Primary Water Use: Monitoring and Test Hole
Sec. Water Use: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z158371
Tag: A138506
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 11/9/2012
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 53 SAULTER ST
County: YORK
Municipality: TORONTO CITY
Site Info: WKQ-005332
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004199759
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/3/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 79.723121
Elevrc:
Zone: 17
East83: 633300
North83: 4835287
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1004487036
Layer: 2
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Other Materials: CLAY
Mat3:
Other Materials:
Formation Top Depth: 12
Formation End Depth: 16
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	1004487035
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	12
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004487045
Layer:	2
Plug From:	5
Plug To:	1
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004487044
Layer:	1
Plug From:	16
Plug To:	5
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1004487046
Layer:	3
Plug From:	1
Plug To:	0
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004487034
Casing No:	0
Comment:	
Alt Name:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Construction Record - Casing

Casing ID:	1004487039
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	6
Casing Diameter:	1.25
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004487040
Layer:	1
Slot:	10
Screen Top Depth:	6
Screen End Depth:	16
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.5

Hole Diameter

Hole ID:	1004487037
Diameter:	2.25
Depth From:	0
Depth To:	16
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
289	1 of 7	SSW/225.0	76.9 / -1.97	CANADA PACKERS INC. FEDERAL COLD STORAGE & WAREHOUSING 521 FRONT STREET EAST TORONTO ON M5A 1H1	GEN

Generator No:	ON0044212	***PO Box No:***	
Status:		***Country:***	
Approval Years:	90	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	4791		
SIC Description:	REFRIG. WAREHOUSING		

Detail(s)

Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
289	2 of 7	SSW/225.0	76.9 / -1.97	CANADA PACKERS INC. 521 FRONT ST., EAST TORONTO ON	GEN

Generator No:	301-85A043	***PO Box No:***	
Status:		***Country:***	
Approval Years:	86	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	

MHSW Facility: **Phone No Admin:**
SIC Code: 030
SIC Description:

---

289 **3 of 7** **SSW/225.0** **76.9 / -1.97** **GEN**

CANADA PACKERS INC
FEDERAL COLD STORAGE & WAREHOUSING
521 FRONT STREET EAST
TORONTO ON M5A 1H1

Generator No: ON0044212 **PO Box No:**
Status: **Country:**
Approval Years: 86,87,88,89 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No Admin:**
SIC Code: 4791
SIC Description: REFRIG. WAREHOUSING

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

289 **4 of 7** **SSW/225.0** **76.9 / -1.97** **GEN**

MAPLE LEAF FOODS INC.
FEDERAL COLD STORAGE & WAREHOUSING
521 FRONT STREET EAST
TORONTO ON M5A 1H1

Generator No: ON0044212 **PO Box No:**
Status: **Country:**
Approval Years: 98 **Choice of Contact:**
Contam. Facility: **Co Admin:**
MHSW Facility: **Phone No Admin:**
SIC Code: 4791
SIC Description: REFRIG. WAREHOUSING

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

289 **5 of 7** **SSW/225.0** **76.9 / -1.97** **MAPLE LEAF FOODS INC. 08-029** **GEN**
FEDERAL COLD STORAGE & WAREHOUSING
521 FRONT STREET EAST
TORONTO ON M5A 1H1

Generator No: ON0044212
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 4791
SIC Description: REFRIG. WAREHOUSING

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

---

289 **6 of 7** **SSW/225.0** **76.9 / -1.97** **CANADA PACKERS INC.** **REC**
521 FRONT ST., EAST
TORONTO ON

Rec Op Div:
Co Admin:
Phone No Admin:
Rec Div:
Rec Op Name:
Choice of Contact:
Site Bldg:
Site PO Box:
Receiver #: 301-85A043
Facility Type: TRANSFER STATION
Approval Yrs: 87,88,89,90,92,94,95,96,97,98,99,00

--Details--

Waste Code: 243
Waste Description: PCB'S

---

289 | ***7 of 7*** | ***SSW/225.0*** | ***76.9 / -1.97*** | ***CANADA PACKERS INC.*** ***521 FRONT ST., EAST*** ***TORONTO ON*** | ***REC***

Rec Op Div:
Co Admin:
Phone No Admin:
Rec Div:
Rec Op Name:
Choice of Contact:
Site Bldg:
Site PO Box:
Receiver #: 301-85A043
Facility Type: PCB STORAGE SITE
Approval Yrs: 01,02,03,04,05,06,07,08

--Details--
Waste Code: 243
Waste Description: PCB'S

---

290 | ***1 of 1*** | ***E/225.1*** | ***79.8 / 0.97*** | ***LAFARGE CANADA*** ***397 EASTERN AVENUE*** ***TORONTO ON M4M 1B7*** | ***GEN***

Generator No: ON0213919
Status:
Approval Years: 89,90,92,93,94
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

291 | ***1 of 1*** | ***SW/225.2*** | ***75.8 / -3.03*** | ***TORONTO ON*** | ***WWIS***

Well ID: 7185064
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z127729
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/9/2012
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 4102
Form Version: 7
Owner:
Street Name: WEST DON LANDS KING/RIVER ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004100903	**Elevation:**	76.107238
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632802
Code OB Desc:		**North83:**	4834796
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/18/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395007
Layer:	1
Plug From:	35.917
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395000
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395004
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004395005
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004395002
Diameter:	
Depth From:	

Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

292 **1 of 1** **WSW/225.4** **79.0 / 0.09** **TORONTO ON** **WWIS**

Well ID: 7247715
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z203434
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 9/2/2015
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 7215
Form Version: 7
Owner:
Street Name: WEST DON LANDS
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1005665830
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 6/15/2015
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.449783
Elevrc:
Zone: 17
East83: 632709
North83: 4834905
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005742144
Layer: 1
Color: 2
General Color: GREY
Mat1:
Most Common Material:
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 0
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	1005742145
Layer:	2
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	10
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005742152
Layer:	1
Plug From:	20
Plug To:	1
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1005742143
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005742148
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	10
Depth To:	0
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005742149
Layer:	1
Slot:	10
Screen Top Depth:	20
Screen End Depth:	10
Screen Material:	5

Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2

Hole Diameter

Hole ID: 1005742146
Diameter: 9
Depth From: 20
Depth To: 0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

293 **1 of 1** **W/226.5** **78.8 / -0.10** **TORONTO ON** **WWIS**

Well ID: 7137795
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: 0
Water Type:
Casing Material:
Audit No: Z109096
Tag: A091095

Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 1/13/2010
Selected Flag: Yes
Abandonment Rec:
Contractor: 6946
Form Version: 7
Owner:
Street Name: WEST DONLANDS: VACANT CORNER OF KING ST E& BAYVIEW

County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1002919324
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 1/4/2010
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 79.07196
Elevrc:
Zone: 17
East83: 632628
North83: 4835084
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1003022502
Layer: 2
Color: 2

General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	61
Other Materials:	CLAYEY
Mat3:	12
Other Materials:	STONES
Formation Top Depth:	9
Formation End Depth:	20
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003022501
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	27
Other Materials:	OTHER
Formation Top Depth:	0
Formation End Depth:	9
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003022505
Layer:	2
Plug From:	3
Plug To:	0.1
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003022506
Layer:	3
Plug From:	0.1
Plug To:	0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003022504
Layer:	1
Plug From:	6.05
Plug To:	3
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6
Method Construction:	Boring
Other Method Construction:	

Pipe Information

Pipe ID:	1003022500
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003022508
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	3
Depth To:	3
Casing Diameter:	5.2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1003022509
Layer:	1
Slot:	10
Screen Top Depth:	3
Screen End Depth:	6.05
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03

Hole Diameter

Hole ID:	1003022503
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

294 ***1 of 1*** ***NE/227.4*** ***79.8 / 0.97*** ***71 & 73 Saulter Street Toronto ON*** ***EHS***

Order No:	20080825020	***Nearest Intersection:***	Queen Street East
Status:	C	***Municipality:***	Toronto
Report Type:	Complete Report	***Client Prov/State:***	ON
Report Date:	9/4/2008	***Search Radius (km):***	0.25
Date Received:	8/25/2008	***X:***	-79.346983
Previous Site Name:		***Y:***	43.658938
Lot/Building Size:	0.046 ha		
Additional Info Ordered:	Fire Insur. Maps And /or Site Plans		

---

295 ***1 of 1*** ***W/227.6*** ***79.8 / 0.97*** ***ON*** ***BORE***

Borehole ID:	635158	***Inclin FLG:***	No
OGF ID:	215535555	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No

Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAR-1962	**Municipality:**	
Static Water Level:	0.9	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.655921
Total Depth m:	9.3	**Longitude DD:**	-79.354905
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	632655
Drill Method:	Power auger	**Northing:**	4834973
Orig Ground Elev m:	79.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	82.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218472164	**Mat Consistency:**	
Top Depth:	9.2	**Material Moisture:**	
Bottom Depth:	9.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Boulders	**Geologic Formation:**	
Material 2:	Shale	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			

Stratum Description: BOULDERS,SHALE. 0120110220000000500070019001200140005 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218472161	**Mat Consistency:**	Firm
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.1	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Granuls	**Depositional Gen:**	fill
Gsc Material Description:			

Stratum Description: FILL,CLAY,SILT, CINDERS. GREY,FIRM.

Geology Stratum ID:	218472162	**Mat Consistency:**	Stiff
Top Depth:	2.1	**Material Moisture:**	
Bottom Depth:	3.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			

Stratum Description: CLAY,SILT. GREY,LACUSTRINE,STIFF, AGE GLACIAL, WATER STABLE AT 257.1 FEET.

Geology Stratum ID:	218472163	**Mat Consistency:**	Stiff
Top Depth:	3.7	**Material Moisture:**	
Bottom Depth:	9.2	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	glacial
Gsc Material Description:			

Stratum Description: TILL,CLAY,SILT,SAND.GREY,GLACIAL,STIFF, AGE NON-GLACIAL.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 031140 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

---

296 ***1 of 1*** ***NE/227.9*** ***79.8 / 0.97*** ***57 Saulter Street Toronto ON*** ***EHS***

Order No:	20120717007	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Standard Select Report	***Client Prov/State:***	ON
Report Date:	25-JUL-12	***Search Radius (km):***	.25
Date Received:	17-JUL-12	***X:***	-79.346787
Previous Site Name:		***Y:***	43.658677
Lot/Building Size:			
Additional Info Ordered:			

---

297 ***1 of 1*** ***NE/228.8*** ***79.8 / 0.97*** ***ON*** ***WWIS***

Well ID:	7198330	***Data Entry Status:***	Yes
Construction Date:		***Data Src:***	
Primary Water Use:		***Date Received:***	3/8/2013
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:		***Abandonment Rec:***	
Water Type:		***Contractor:***	7147
Casing Material:		***Form Version:***	8
Audit No:	C19663	***Owner:***	
Tag:	A107318	***Street Name:***	
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004261931	***Elevation:***	79.736389
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633306

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Code OB Desc:		**North83:**	4835286
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	2/15/2013	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

298 **1 of 1** **SW/232.8** **76.7 / -2.16**

ON **WWIS**

Well ID:	7188830	**Data Entry Status:**	Yes
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/2/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:		**Abandonment Rec:**	
Water Type:		**Contractor:**	6809
Casing Material:		**Form Version:**	8
Audit No:	C18138	**Owner:**	
Tag:	A089273	**Street Name:**	
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004197842	**Elevation:**	76.426994
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632769
Code OB Desc:		**North83:**	4834823
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	2
Date Completed:	3/1/2012	**UTMRC Desc:**	margin of error : 3 - 10 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

299 **1 of 1** **NNE/233.8** **79.8 / 0.97**

Sherkin Wagman Barristers, Solicitors
756A Queen Street East
Toronto ON M4M 1H4 **GEN**

Generator No:	ON9922364	**PO Box No:**	
Status:		**Country:**	
Approval Years:	06	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	

SIC Code: 541110
SIC Description: Offices of Lawyers

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

---

300 ***1 of 1*** ***WNW/234.0*** ***79.4 / 0.55*** ***ON*** ***WWIS***

Well ID: 7231298
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: C02929
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status: Yes
Data Src:
Date Received: 8/8/2011
Selected Flag: Yes
Abandonment Rec:
Contractor: 6032
Form Version: 5
Owner:
Street Name:
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1005280953
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 4/25/2011
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Elevation: 79.547332
Elevrc:
Zone: 17
East83: 632622
North83: 4835109
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Supplier Comment:

---

301 | **1 of 1** | **NE/234.9** | **79.8 / 0.97** | **73 Saulter St. Toronto ON** | **EHS**

Order No:	20180319045	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	26-MAR-18	**Search Radius (km):**	.25
Date Received:	19-MAR-18	**X:**	-79.347003
Previous Site Name:		**Y:**	43.658978
Lot/Building Size:			
Additional Info Ordered:			

---

302 | **1 of 2** | **NNW/235.4** | **81.9 / 3.06** | **CARROLL STREET AND THOMPSON STREET, TORONTO ON** | **INC**

Incident No:	182214
Incident ID:	2333130
Attribute Category:	FS-Incident
Status Code:	Causal Analysis Complete
Incident Location:	CARROLL STREET AND THOMPSON STREET, TORONTO - 2" PIPELINE HIT
Drainage System:	
Sub Surface Contam.:	
Aff. Prop. Use Water:	
Contam. Migrated:	
Contact Natural Env.:	
Near Body of Water:	
Approx. Quant. Rel.:	
Equipment Model:	
Serial No:	
Residential App. Type:	
Commercial App. Type:	
Industrial App. Type:	
Institutional App. Type:	
Venting Type:	
Vent Connector Mater:	
Vent Chimney Mater:	
Pipeline Type:	Main Distribution Pipeline
Pipeline Involved:	
Pipe Material:	Plastic
Depth Ground Cover:	24"
Regulator Location:	Outside
Regulator Type:	
Operation Pressure:	IP
Liquid Prop Make:	
Liquid Prop Model:	
Liquid Prop Serial No:	
Equipment Type:	
Cylinder Capacity:	
Cylinder Capac. Units:	
Cylinder Material Type:	
Tank Capacity:	
Fuels Occurence Type:	
Fuel Type Involved:	
Date of Occurence:	
Time of Occurence:	
Occur Insp Start Date:	
Any Health Impact:	
Any Environmental Impact:	
Was Service Interrupted:	
Was Property Damaged:	

Operation Type Involved:
Enforcement Policy:
Prc Escalation Required:
Task No:
Notes:
Occurence Narrative:
Tank Material Type:
Tank Storage Type:
Tank Location Type:
Pump Flow Rate Capac:
Liquid Prop Notes:

---

302 | **2 of 2** | **NNW/235.4** | **81.9 / 3.06** | **Enbridge Gas Distribution Inc.**
Carroll Street and Thompson Street
Toronto ON | **SPL**

Ref No:	6334-7VQQPC	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Discharge or Emission to Air	**Sector Type:**	Pipeline
Incident Event:		**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	NATURAL GAS (METHANE)	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	
Nature of Impact:	Air Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	Referral to others	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/9/2009	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Primary Assessment of Spills
Incident Reason:	Spill	**Source Type:**	

Site Name: Carroll Street and Thompson Street<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: TSSA: 2" two way fed plastic main hit
Contaminant Qty: 0 other - see incident description

---

303 | **1 of 1** | **SSW/236.4** | **79.0 / 0.09** | **TORONTO ON** | **WWIS**

Well ID:	7185055	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127731	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	

Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1004100444	***Elevation:***	77.844879
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632942
Code OB Desc:		***North83:***	4834673
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	5/19/2012	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004394850
Layer:	1
Plug From:	16.333
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004394843
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004394847
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1004394848
Layer:	
Slot:	
Screen Top Depth:	
Screen End Depth:	
Screen Material:	
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	

Hole Diameter

Hole ID:	1004394845
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

304 ***1 of 1*** ***WSW/237.6*** ***77.8 / -1.03*** ***ECA***

EllisDon Ledcor PAAV Inc.
NE Cherry Street and Front Street East Block 1/14 and 2, West Donlands
Toronto ON M5A 1H3

Approval No:	1577-9UXN7R	***MOE District:***	Metro Toronto
Approval Date:	2015-06-18	***City:***	
Status:	Approved	***Longitude:***	-79.35406499999999
Record Type:	ECA	***Latitude:***	43.654964
Link Source:	IDS	***Geometry X:***	
SWP Area Name:	Toronto	***Geometry Y:***	
Approval Type:	ECA-AIR		
Project Type:	AIR		
Address:	NE Cherry Street and Front Street East Block 1/14 and 2, West Donlands		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/2787-9P9QYV-14.pdf		

---

305 ***1 of 1*** ***NE/237.7*** ***79.8 / 0.97*** ***RSC***

Steven James Mackinnon
67 SAULTER ST, TORONTO, ON, M4M 2H8
ON

RSC ID:	97319	***Cert Date:***	30-Nov-10
RA No:		***Cert Prop Use No:***	No CPU
RSC Type:		***Intended Prop Use:***	Residential
Curr Property Use:	Industrial	***Qual Person Name:***	
Ministry District:	TORONTO	***Stratified (Y/N):***	
Filing Date:	18-Feb-11	***Audit (Y/N):***	
Date Ack:		***Entire Leg Prop. (Y/N):***	No
Date Returned:		***Accuracy Estimate:***	2 to 5 meters
Restoration Type:		***Telephone:***	416-4576995
Soil Type:		***Fax:***	
Criteria:		***Email:***	mac@stevenmackinnon.com
CPU Issued Sect 1686:	No		
Asmt Roll No:	1.90407E+18		
Prop ID No (PIN):	PART OF 21076 - 0381 LT		
Property Municipal Address:	67 SAULTER ST, TORONTO, ON, M4M 2H8		
Mailing Address:	Suite 2ND FLOOR, 432 MARKHAM ST, TORONTO, ON, M6G 2L2		
Latitude & Latitude:	43.65879680N 79.34688620W (converted from UTM)		
UTM Coordinates:	NAD83 17-633295-4835305		
Consultant:			
Filing Owner:			
Legal Desc:	ENTIRE LEGAL DESCRIPTION LOT 137 ON PLN 105 TORONTO DESIGNATED AS PART 1 ON PLN 66R-24364. CITY OF TORONTO; RSC LEGAL DESCRIPTION WESTERLY 19.6m OF LOT 137 ON PLN 105 TORONTO DESIGNATED AS PART 1 ON PLN 66R-24364. CITY OF TORONTO		
Measurement Method:	Digitized from a satellite image		
Applicable Standards:	Full Depth Site Conditions Standard, with Nonpotable Ground Water, Medium/Fine Textured Soil, for Residential/Parkland/Institutional property use		
RSC PDF:			

---

306 ***1 of 1*** ***SSW/237.9*** ***79.0 / 0.09*** ***WWIS***

TORONTO ON

Well ID:	7185092	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127736	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101533	**Elevation:**	77.779953
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632937
Code OB Desc:		**North83:**	4834673
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/22/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395318
Layer:	1
Plug From:	21.083
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID:	1004395311
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004395315
Layer:	
Material:	
Open Hole or Material:	
Depth From:	

Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395316
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395313
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

307 ***1 of 23*** ***ENE/238.4*** ***79.8 / 0.97*** ***CITY GAS BAR SELBY WEMYSS LTD***
398 EASTERN AVE
TORONTO ON M4M 1B9 ***EXP***

Instance No: 11385470
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 5/2/2002

---

307 ***2 of 23*** ***ENE/238.4*** ***79.8 / 0.97*** ***DIRECT PROPANE INC***
398 EASTERN AVE
TORONTO ON ***EXP***

Instance No: 11254276
Instance ID: 75196
Instance Type: FS Propane Tank
Description: FS Propane Tank
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

307 ***3 of 23*** ***ENE/238.4*** ***79.8 / 0.97*** ***CITY GAS BAR SELBY WEMYSS LTD***
398 EASTERN AVE
TORONTO ON M4M 1B9 ***EXP***

Instance No: 11013016
Instance ID:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 5/2/2002

---

307 | ***4 of 23*** | ***ENE/238.4*** | ***79.8 / 0.97*** | ***CITY GAS BAR SELBY WEMYSS LTD***
398 EASTERN AVE
TORONTO ON M4M 1B9 | ***EXP***

Instance No: 11013016
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: FS Gasoline Station - Split Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 5/2/2002

---

307 | ***5 of 23*** | ***ENE/238.4*** | ***79.8 / 0.97*** | ***CITY GAS BAR SELBY WEMYSS LTD***
398 EASTERN AVE
TORONTO ON M4M 1B9 | ***EXP***

Instance No: 11385571
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 5/2/2002

---

307 | ***6 of 23*** | ***ENE/238.4*** | ***79.8 / 0.97*** | ***CITY GAS BAR SELBY WEMYSS LTD***
398 EASTERN AVE
TORONTO ON | ***EXP***

Instance No: 11385584
Instance ID: 81969
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

307 | ***7 of 23*** | ***ENE/238.4*** | ***79.8 / 0.97*** | ***DIRECT PROPANE INC***
398 EASTERN AVE
TORONTO ON | ***EXP***

Instance No: 9642159
Instance ID: 391731
Instance Type: FS Facility
Description: FS Propane Refill Cntr - Cylr Fill
Status: EXPIRED

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

307 | ***8 of 23*** | ***ENE/238.4*** | ***79.8 / 0.97*** | ***CITY GAS BAR SELBY WEMYSS LTD*** ***398 EASTERN AVE*** ***TORONTO ON*** | ***EXP***

Instance No: 11385488
Instance ID: 81204
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

307 | ***9 of 23*** | ***ENE/238.4*** | ***79.8 / 0.97*** | ***CITY GAS BAR SELBY WEMYSS LTD*** ***398 EASTERN AVE*** ***TORONTO ON M4M 1B9*** | ***EXP***

Instance No: 11385436
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 5/2/2002

---

307 | ***10 of 23*** | ***ENE/238.4*** | ***79.8 / 0.97*** | ***CITY GAS BAR SELBY WEMYSS LTD*** ***398 EASTERN AVE*** ***TORONTO ON*** | ***EXP***

Instance No: 11385458
Instance ID: 81086
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date:

---

307 | ***11 of 23*** | ***ENE/238.4*** | ***79.8 / 0.97*** | ***CITY GAS BAR SELBY WEMYSS LTD*** ***398 EASTERN AVE*** ***TORONTO ON*** | ***EXP***

Instance No: 11385412
Instance ID: 81968
Instance Type: FS Piping
Description: FS Piping
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Expired Date:					

307	12 of 23	ENE/238.4	79.8 / 0.97	CITY GAS BAR SELBY WEMYSS LTD 398 EASTERN AVE TORONTO ON M4M 1B9	EXP

Instance No:	11385436
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	FS Gasoline Station - Split Serve
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	FS Liquid Fuel Tank
Expired Date:	5/2/2002

307	13 of 23	ENE/238.4	79.8 / 0.97	CITY GAS BAR SELBY WEMYSS LTD 398 EASTERN AVE TORONTO ON M4M 1B9	EXP

Instance No:	11385470
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	FS Gasoline Station - Split Serve
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	FS Liquid Fuel Tank
Expired Date:	5/2/2002

307	14 of 23	ENE/238.4	79.8 / 0.97	DIRECT PROPANE INC 398 EASTERN AVE TORONTO ON	EXP

Instance No:	11013007
Instance ID:	61793
Instance Type:	FS Propane Tank
Description:	FS Propane Tank
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	
Expired Date:	

307	15 of 23	ENE/238.4	79.8 / 0.97	CITY GAS BAR SELBY WEMYSS LTD 398 EASTERN AVE TORONTO ON M4M 1B9	EXP

Instance No:	11385571
Instance ID:	
Instance Type:	FS Liquid Fuel Tank
Description:	FS Gasoline Station - Split Serve
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	FS Liquid Fuel Tank
Expired Date:	5/2/2002

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
307	16 of 23	ENE/238.4	79.8 / 0.97	CITY GAS BAR SELBY WEMYSS LTD 398 EASTERN AVE TORONTO ON M4M 1B9	EXP

Instance No: 9757476
Instance ID:
Instance Type: FS Facility
Description:
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type:
Expired Date: 5/2/2002

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
307	17 of 23	ENE/238.4	79.8 / 0.97	CITY GAS BAR SELBY WEMYSS LTD 398 EASTERN AV TORONTO ON M4M 1B9	PRT

Location ID: 15344
Type: retail
Expiry Date: 1995-05-31
Capacity (L): 25000
Licence #: 0053340001

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
307	18 of 23	ENE/238.4	79.8 / 0.97	CITY GAS BAR 398 EASTERN AV TORONTO ON M4M 1B9	PRT

Location ID: 15344
Type: retail
Expiry Date: 1994-05-31
Capacity (L): 2000
Licence #: 0033883001

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
307	19 of 23	ENE/238.4	79.8 / 0.97	CITY GAS BAR 398 EASTERN AVE TORONTO ON M4M1B9	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 4164651444
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
307	20 of 23	ENE/238.4	79.8 / 0.97	PRIME FUELS INC 398 EASTERN AVE TORONTO ON M4M1B9	RST

Headcode: 1186800
Headcode Desc: Service Stations-Gasoline, Oil & Natural Gas
Phone: 4164652400
List Name:
Description:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
307	21 of 23	ENE/238.4	79.8 / 0.97	DIRECT PROPANE INC 398 EASTERN AVE	RST

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				TORONTO ON M4M 1B9	

Headcode: 1070460
Headcode Desc: Propane Gas
Phone: 4164652400
List Name:
Description:

307	22 of 23	ENE/238.4	79.8 / 0.97	Dibble [Robert] 398 Eastern Ave Toronto ON M4M 1B9	TANK

Permit Date: 11/26/1932
Permit Type: BP A45632
User Type:
Installation Type: gas tank
Installation Size:
Installation Config.: gas tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 350
Capacity(gal):
Reference: CTA Building Permits
Location Desc: 398 Eastern Ave

307	23 of 23	ENE/238.4	79.8 / 0.97	Dibble [Robert] 398 Eastern Ave Toronto ON M4M 1B9	TANK

Permit Date: 4/26/1928
Permit Type: BP A12939
User Type:
Installation Type: Gasoline tank
Installation Size:
Installation Config.: 1 x Gasoline tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 250
Capacity(gal):
Reference: CTA Building permits
Location Desc: 398 Eastern Ave

308	1 of 5	N/239.5	81.8 / 2.93	AMBER PRINTERS & PUBLISHERS LTD. 125 BROADVIEW AVENUE TORONTO ON M4M 2E9	GEN

Generator No: ON1601800
Status:
Approval Years: 04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

308	2 of 5	N/239.5	81.8 / 2.93	AMBER PRINTERS & PUBLISHERS LTD. 02-660 125 BROADVIEW AVE. TORONTO ON M4M 2E9	GEN

Generator No: ON1601800

PO Box No:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: ***Country:***
Approval Years: 92,93,94,95,96,97,98 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 2841
SIC Description: NEWSPAPER, ETC. IND.

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	3 of 5	N/239.5	81.8 / 2.93	***AMBER PRINTERS & PUBLISHERS LTD.*** ***125 BROADVIEW AVENUE*** ***TORONTO ON M4M 2E9***	GEN

Generator No: ON1601800 ***PO Box No:***
Status: ***Country:***
Approval Years: 99,00,01,03 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 2841
SIC Description: NEWSPAPER, ETC. IND.

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	4 of 5	N/239.5	81.8 / 2.93	***AMBER PRINTERS AND PUBLISHERS*** ***125 BROADVIEW AVE*** ***TORONTO ON M4M 2E9***	SCT

Established: 1950
Plant Size (ft²): 0
Employment: 5

--Details--
Description: NEWSPAPERS: PUBLISHING, OR PUBLISHING AND PRINTING
SIC/NAICS Code: 2711

Description: COMMERCIAL PRINTING, LITHOGRAPHIC
SIC/NAICS Code: 2752

Description: COMMERCIAL PRINTING, NOT ELSEWHERE CLASSIFIED
SIC/NAICS Code: 2759

Description: Quick Printing
SIC/NAICS Code: 323114

Description: Digital Printing
SIC/NAICS Code: 323115

Description: Other Printing
SIC/NAICS Code: 323119

Description: Newspaper Publishers
SIC/NAICS Code: 511110

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
308	5 of 5	N/239.5	81.8 / 2.93	Amber Printers and Publishers Ltd. 125 Broadview Ave Toronto ON M4M 2E9	SCT

Established: 1950
Plant Size (ft²):
Employment: 5

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
309	1 of 21	E/240.1	79.8 / 0.97	Enbridge Gas Distribution Inc. 405 Eastern Ave Toronto ON M4M 1B7	CA

Certificate #: 5167-7FRKCN
Application Year: 2008
Issue Date: 7/15/2008
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
309	2 of 21	E/240.1	79.8 / 0.97	405 Eastern Avenue Toronto ON M4M 1B7	CA

Certificate #: 1061-4ZESX5
Application Year: 01
Issue Date: 8/10/01
Approval Type: Industrial air
Status: Approved
Application Type: New Certificate of Approval
Client Name: Enbridge Consumers Gas
Client Address: 500 Consumers Road
Client City: NORTH YORK
Client Postal Code: M2J 1P8
Project Description: This application is for a Certificate of Approval for one (1) HVAC unit, one (1) hot water heater, two (2) unit heaters, and a kerosene powered high pressure cleaner.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
309	3 of 21	E/240.1	79.8 / 0.97	Enbridge Gas Distribution Inc. 405 Eastern Ave Toronto ON M2J 1P8	ECA

Approval No: 5167-7FRKCN
Approval Date: 2008-07-15
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-AIR
Project Type: AIR
Address: 405 Eastern Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/3471-7CESNC-14.pdf

MOE District: Metro Toronto
City:
Longitude: -79.34743
Latitude: 43.656563
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
309	4 of 21	E/240.1	79.8 / 0.97	Enbridge Consumers Gas 405 Eastern Avenue Toronto ON M2J 1P8	ECA

Approval No: 1061-4ZESX5
Approval Date: 2001-08-10
Status: Revoked and/or Replaced
Record Type: ECA
Link Source: IDS
SWP Area Name: Toronto
Approval Type: ECA-AIR
Project Type: AIR
Address: 405 Eastern Avenue
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/6146-4RCQWM-14.pdf

MOE District: Metro Toronto
City:
Longitude: -79.34743
Latitude: 43.656563
Geometry X:
Geometry Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
309	5 of 21	E/240.1	79.8 / 0.97	Enbridge Gas Distribution Inc. 405 EASTERN AVENUE TORONTO ON M4M 1B7	GEN

Generator No: ON0060803
Status:
Approval Years: 02,03,04,05,06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 221210
SIC Description: Natural Gas Distribution

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
309	6 of 21	E/240.1	79.8 / 0.97	Enbridge Gas Distribution Inc. 405 EASTERN AVENUE TORONTO ON M4M 1B7	GEN

Generator No: ON0060803
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 221210

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

SIC Description: Natural Gas Distribution

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

309 ***7 of 21*** ***E/240.1*** ***79.8 / 0.97*** ***CONSUMERS GAS COMPANY 11-111***
405 EASTERN AVENUE
TORONTO ON M4M 1B7 ***GEN***

Generator No: ON0060803
Status:
Approval Years: 92,93,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 4921
SIC Description: GAS DISTIRB. SYS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

309 ***8 of 21*** ***E/240.1*** ***79.8 / 0.97*** ***CONSUMERS GAS COMPANY LIMITED***
405 EASTERN AVENUE
TORONTO ON M4M 1B7 ***GEN***

Generator No: ON0060803
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4921
SIC Description: GAS DISTIRB. SYS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

309 **9 of 21** **E/240.1** **79.8 / 0.97** **Enbridge Gas Distribution Inc.**
405 EASTERN AVENUE
TORONTO ON M4M 1B7 **GEN**

Generator No: ON0060803
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 221210
SIC Description: NATURAL GAS DISTRIBUTION

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

---

309 **10 of 21** **E/240.1** **79.8 / 0.97** **Enbridge Gas Distribution Inc.**
405 EASTERN AVENUE
TORONTO ON M4M 1B7 **GEN**

Generator No:	ON0060803	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2010	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	221210		
SIC Description:	Natural Gas Distribution		

Detail(s)

Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	232
Waste Class Desc:	POLYMERIC RESINS
Waste Class:	121
Waste Class Desc:	ALKALINE WASTES - HEAVY METALS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	243
Waste Class Desc:	PCBS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES

---

309 ***11 of 21*** ***E/240.1*** ***79.8 / 0.97*** ***Enbridge Gas Distribution Inc.***
405 EASTERN AVENUE
TORONTO ON M4M 1B7 ***GEN***

Generator No:	ON0060803	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2012	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	221210		
SIC Description:	Natural Gas Distribution		

Detail(s)

Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	243
Waste Class Desc:	PCBS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

---

309 | ***12 of 21*** | ***E/240.1*** | ***79.8 / 0.97*** | ***CONSUMERS' GAS COMPANY LTD. 11-111 STATION "B" SERVICE CENTRE 405 EASTERN AVENUE TORONTO ON M4M 1B7*** | ***GEN***

Generator No: ON0060803
Status:
Approval Years: 94,95
Contam. Facility:
MHSW Facility:
SIC Code: 4921
SIC Description: GAS DISTIRB. SYS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

309 | ***13 of 21*** | ***E/240.1*** | ***79.8 / 0.97*** | ***Enbridge Gas Distribution Inc. 405 EASTERN AVENUE TORONTO ON M4M 1B7*** | ***GEN***

Generator No: ON0060803
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 221210
SIC Description: NATURAL GAS DISTRIBUTION

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 146

Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

---

309 ***14 of 21*** ***E/240.1*** ***79.8 / 0.97***

Enbridge Gas Distribution Inc.
405 EASTERN AVENUE
TORONTO ON M4M 1B7

GEN

Generator No: ON0060803
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 221210
SIC Description: NATURAL GAS DISTRIBUTION

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

309 **15 of 21** **E/240.1** **79.8 / 0.97**

CONSUMERS' GAS COMPANY LTD.
STATION "B" SERVICE CENTRE 405 EASTERN AVENUE
TORONTO ON M4M 1B7

GEN

Generator No: ON0060803
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 4921
SIC Description: GAS DISTIRB. SYS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

309 **16 of 21** **E/240.1** **79.8 / 0.97**

Enbridge Gas Inc.
405 EASTERN AVENUE
TORONTO ON M4M 1B7

GEN

Generator No: ON0060803
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 146 L
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 243 D
Waste Class Desc: PCB

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 252 L

Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

---

309 **17 of 21** **E/240.1** **79.8 / 0.97** **Enbridge Gas Distribution Inc.**
405 EASTERN AVENUE
TORONTO ON
GEN

Generator No: ON0060803
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 221210
SIC Description: NATURAL GAS DISTRIBUTION

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
309	18 of 21	E/240.1	79.8 / 0.97	Enbridge Gas Distribution Inc. 405 EASTERN AVENUE TORONTO ON M4M 1B7	GEN

Generator No: ON0060803
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 221210
SIC Description: Natural Gas Distribution

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
309	19 of 21	E/240.1	79.8 / 0.97	405 Eastern Ave Toronto ON M4M 1B7	SPL

Ref No: 3485-8MUH5U
Site No:
Incident Dt: 10/21/2011
Year:
Incident Cause: Discharge or Emission to Air
Incident Event:
Contaminant Code: 35
Contaminant Name: NATURAL GAS (METHANE)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Confirmed
Nature of Impact: Air Pollution
Receiving Medium:
Receiving Env:
MOE Response: Referral to others
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/21/2011
Dt Document Closed:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Other
Agency Involved:
Nearest Watercourse:
Site Address: 405 Eastern Ave
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: Toronto
Site Lot:
Site Conc:
Northing: NA
Easting: NA
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Air Spills - Gases and Vapours

Incident Reason:	Other - Reason not otherwise defined	**Source Type:**	
Site Name:	405 Eastern Avenue		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Enbridge: Venting from regulators due to unknown cause		
Contaminant Qty:	0 L		

---

309 **20 of 21** **E/240.1** **79.8 / 0.97** **Enbridge Gas Distribution**
405 Eastern Avenue
Toronto ON **SPL**

Ref No:	7183-9BTG4B	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	2013/09/23	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Start up/Shut down	**Sector Type:**	Pipeline/Components
Incident Event:		**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	NATURAL GAS (METHANE)	**Site Address:**	405 Eastern Avenue
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Toronto
Nature of Impact:	Air Pollution	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	Not MOE mandate	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2013/09/23	**Site Map Datum:**	
Dt Document Closed:	2013/11/01	**SAC Action Class:**	TSSA - Fuel Safety Branch - Hydrocarbon Fuel Release/Spill
Incident Reason:	Intentional Discharge	**Source Type:**	
Site Name:	405 Eastern Avenue<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Enbridge: Planned Natural Gas Release to charge pipeline		
Contaminant Qty:	0 other - see incident description		

---

309 **21 of 21** **E/240.1** **79.8 / 0.97** **Enbridge Gas Distribution**
405 Eastern Ave
Toronto ON **SPL**

Ref No:	6668-97WP4U	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	21-MAY-13	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Start up/Shut down	**Sector Type:**	Pipeline/Components
Incident Event:		**Agency Involved:**	
Contaminant Code:	35	**Nearest Watercourse:**	
Contaminant Name:	METHANE GAS, COMPRESSED (NATURAL GAS)	**Site Address:**	405 Eastern Ave
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Toronto
Nature of Impact:	Air Pollution; Human Health/Safety	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	21-MAY-13	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Air Spills - Gases and Vapours

Incident Reason: Maintenance
Site Name: purging<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: TSSA: purging 405 Eastern Ave, Toronto
Contaminant Qty: 1 other - see incident description
Source Type:

---

310 *1 of 2* *E/240.3* *79.8 / 0.97*

Enbridge - Toronto Yard
Private
Toronto ON M4M 1B7

CNG

ID:	117810	**Owner Type Cd:**	T
Status Code:	E	**Owner Type Cd Desc:**	Utility owned
Status Code Desc:	Open: The station is open.	**Open Date:**	2019-02-01
Facility Type:	UTILITY	**Date Last Confirmed:**	2019-04-09
Fuel Type Code:	CNG	**Updated At:**	2019-05-14 21:16:45 UTC
Fuel Type Desc:	Compressed Natural Gas	**BD Blends:**	
CNG Dispenser No:		**BD Blends French:**	
CNG Fill Type Code:	T	**Intersect Dir:**	
CNG OnSite Renw Sr:		**Intersect Dir French:**	
CNG PSI:	3600	**LNG OnSite Renw Sr:**	
CNG Stor Capacity:		**LNG Vehicle Class:**	
CNG Tot Cmpres Cap:		**LPG Nozzle Types:**	
CNG Vehicle Class:	HD	**LPG Primary:**	
E85 Oth EOTH Blnd:		**Ng Fill Type Code:**	T
Ev Pricing:		**Ng Fill Type Desc:**	Timed fill
Ev Pricing French:		**NG PSI:**	3600
Hydrogen Is Retail:		**Geocode Status:**	200-9
Hydrogen Pressures:		**Geocode Status Desc:**	Premise (building name, property name, shopping center, etc.) level accuracy.
Hydrogen Standards:		**Latitude:**	43.656268
Hydrogen Status Link:		**Longitude:**	-79.345599

---

310 *2 of 2* *E/240.3* *79.8 / 0.97*

Enbridge Gas Inc.
405 EASTERN AVENUE
TORONTO ON M4M 1B7

GEN

Generator No:	ON0060803	**PO Box No:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Jul 2019	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 146 L
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 251 L

Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 243 D
Waste Class Desc: PCB

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

---

311 **1 of 1** **WSW/241.8** **79.2 / 0.29** **TORONTO ON** **WWIS**

Well ID:	7185076	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:		**Date Received:**	8/9/2012
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Abandoned-Other	**Abandonment Rec:**	Yes
Water Type:		**Contractor:**	4102
Casing Material:		**Form Version:**	7
Audit No:	Z127709	**Owner:**	
Tag:		**Street Name:**	WEST DON LANDS KING/RIVER ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004101371	**Elevation:**	77.835739
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632696
Code OB Desc:		**North83:**	4834895
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	5/14/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1004395182
Layer:	1
Plug From:	28.25
Plug To:	0
Plug Depth UOM:	ft

Pipe Information

Pipe ID: 1004395175
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1004395179
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1004395180
Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter:

Hole Diameter

Hole ID: 1004395177
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

312 ***1 of 1*** ***WNW/242.1*** ***77.6 / -1.26*** ***ON*** ***BORE***

Borehole ID: 632556
OGF ID: 215532960
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: SEP-1956
Static Water Level: 0.3
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 3
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Power auger
Orig Ground Elev m: 77.6
Elev Reliabil Note:
DEM Ground Elev m: 79.4
Concession:
Location D:
Survey D:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.657993
Longitude DD: -79.354973
UTM Zone: 17
Easting: 632645
Northing: 4835203
Location Accuracy:
Accuracy: Not Applicable

Comments:

Borehole Geology Stratum

Geology Stratum ID:	218463138	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	.3	***Material Texture:***	
Material Color:	Dark	***Non Geo Mat Type:***	
Material 1:	Soil	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Soil	***Geologic Period:***	
Material 4:		***Depositional Gen:***	
Gsc Material Description:			
Stratum Description:	SOIL,SAND,SOIL. DARK,LOOSE.		

Geology Stratum ID:	218463139	***Mat Consistency:***	Loose
Top Depth:	.3	***Material Moisture:***	
Bottom Depth:	1.5	***Material Texture:***	
Material Color:	Brown	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Clay	***Geologic Group:***	
Material 3:	Sand	***Geologic Period:***	
Material 4:		***Depositional Gen:***	lacustrine
Gsc Material Description:			
Stratum Description:	SILT,CLAY,SAND. BROWN,LACUSTRINE,LOOSE, AGE GLACIAL, WATER STABLE AT 253.7 FEET.		

Geology Stratum ID:	218463140	***Mat Consistency:***	Loose
Top Depth:	1.5	***Material Moisture:***	
Bottom Depth:	2.7	***Material Texture:***	Fine to Medium
Material Color:	Dark	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Gravel	***Geologic Period:***	
Material 4:		***Depositional Gen:***	beach
Gsc Material Description:			
Stratum Description:	SAND(45)-FINE TO MEDIUM,SILT(40), GRAVEL(15). DARK,BEACH,LOOSE,GRADED, AGE GLACIAL.		

Geology Stratum ID:	218463141	***Mat Consistency:***	
Top Depth:	2.7	***Material Moisture:***	Wet
Bottom Depth:	3	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	beach
Gsc Material Description:			
Stratum Description:	SAND,SILT. BEACH,WET,LAYERED,AGE GLACIAL.00006,LO **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	***Source Appl:***	Spatial/Tabular
Source Orig:	Geological Survey of Canada	***Source Iden:***	1
Source Date:	1956-1972	***Scale or Res:***	Varies
Confidence:	H	***Horizontal:***	NAD27
Observatio:		***Verticalda:***	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1A.txt RecordID: 005030 NTS_Sheet: 30M11C		
Confiden 1:	Logged by professional. Exact and complete description of material and properties.		

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

313 **1 of 1** **SE/242.5** **80.1 / 1.21** **ON** **BORE**

Borehole ID:	644970	**Inclin FLG:**	No
OGF ID:	215545353	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	1946	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.654097
Total Depth m:	9.2	**Longitude DD:**	-79.347019
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633295
Drill Method:	Diamond Drill	**Northing:**	4834783
Orig Ground Elev m:	77.5	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	77.6		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509581	**Mat Consistency:**	
Top Depth:	7.5	**Material Moisture:**	
Bottom Depth:	9.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND,CLAY. AGE POST **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218509579	**Mat Consistency:**	
Top Depth:	3	**Material Moisture:**	
Bottom Depth:	6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SILT,CLAY.		

Geology Stratum ID:	218509578	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			

Stratum Description: FILL.

Geology Stratum ID: 218509580
Top Depth: 6
Bottom Depth: 7.5
Material Color:
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: CLAY.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 129920 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

314 ***1 of 1*** ***S/243.5*** ***81.0 / 2.12*** ***Toronto ON*** ***WWIS***

Well ID: 7277709
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: Abandoned-Other
Water Type:
Casing Material:
Audit No: Z240283
Tag:
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 12/23/2016
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 6607
Form Version: 7
Owner:
Street Name: 470 LAKESHORE BLVD E
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1006318612
DP2BR:
Spatial Status:

Elevation: 81.260833
Elevrc:
Zone: 17

Code OB:		**East83:**	633040
Code OB Desc:		**North83:**	4834658
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/25/2016	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1006516774
Layer:	1
Plug From:	0
Plug To:	0.3
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1006516775
Layer:	2
Plug From:	0.3
Plug To:	8.2
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	8
Method Construction:	Jetting
Other Method Construction:	

Pipe Information

Pipe ID:	1006516766
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1006516770
Layer:	
Material:	
Open Hole or Material:	
Depth From:	
Depth To:	
Casing Diameter:	
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1006516771

Layer:
Slot:
Screen Top Depth:
Screen End Depth:
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter:

Water Details

Water ID: 1006516769
Layer: 1
Kind Code:
Kind:
Water Found Depth: 5.7
Water Found Depth UOM: m

Hole Diameter

Hole ID: 1006516768
Diameter: 21
Depth From: 0
Depth To: 8.2
Hole Depth UOM: m
Hole Diameter UOM: cm

---

315 **1 of 2** **SSW/245.4** **78.9 / 0.02** **ON** **WWIS**

Well ID: 7101162
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: 0
Water Type:
Casing Material:
Audit No: M00190
Tag: _NO_TAG
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 10/22/2007
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 7241
Form Version: 5
Owner:
Street Name: 100 MILL ST.
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1001480649
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 8/17/2007
Remarks:

Elevation: 77.285385
Elevrc:
Zone: 17
East83: 632898
North83: 4834681
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002523524
Layer: 3
Plug From: 2.13
Plug To: 12.7
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002523523
Layer: 2
Plug From: 0.3
Plug To: 2.13
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002523522
Layer: 1
Plug From: 0
Plug To: 0.3
Plug Depth UOM: m

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 6
Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1002523521
Casing No: 0
Comment:
Alt Name:

Construction Record - Screen

Screen ID: 1002523525
Layer: 1
Slot: 10
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5.08

Bore Hole Information

Bore Hole ID:	1002523485	***Elevation:***	79.26123
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632950
Code OB Desc:		***North83:***	4834642
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	8/17/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002523489
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1002523490
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002523492
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.83
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002523491
Layer:	
Slot:	
Screen Top Depth:	1.83
Screen End Depth:	4.9

Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002523493
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002523487
Diameter: 5.08
Depth From:
Depth To: 4.9
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002523476
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 77.580375
Elevrc:
Zone: 17
East83: 632920
North83: 4834676
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002523480
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID:
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002523481
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002523483
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.83
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002523482
Layer:
Slot:
Screen Top Depth: 1.83
Screen End Depth: 4.9
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002523484
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002523478
Diameter: 5.08
Depth From:
Depth To: 4.9

Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID:	1002523440	**Elevation:**	77.181999
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632879
Code OB Desc:		**North83:**	4834643
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	8/17/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002523444
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID:
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002523445
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002523447
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 6.71
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002523446
Layer:

Slot:
Screen Top Depth: 6.71
Screen End Depth: 9.8
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002523448
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002523442
Diameter: 5.08
Depth From:
Depth To: 9.8
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002523503
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 77.2714
Elevrc:
Zone: 17
East83: 632848
North83: 4834602
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002523507
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID:
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002523508
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002523510
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 3.1
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002523509
Layer:
Slot:
Screen Top Depth: 3.1
Screen End Depth: 6.1
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002523511
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002523505
Diameter: 5.08
Depth From:
Depth To: 6.1
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002523449
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.872612
Elevrc:
Zone: 17
East83: 632923
North83: 4834651
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002523453
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID:
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002523454
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002523456
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 3.66
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID:	1002523455
Layer:	
Slot:	
Screen Top Depth:	3.66
Screen End Depth:	6.7
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1002523457
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002523451
Diameter:	5.08
Depth From:	
Depth To:	6.7
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002523458	***Elevation:***	77.419395
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632902
Code OB Desc:		***North83:***	4834654
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	8/17/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002523462

Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID:
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002523463
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002523465
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.83
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002523464
Layer:
Slot:
Screen Top Depth: 1.83
Screen End Depth: 4.9
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002523466
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID:	1002523460
Diameter:	5.08
Depth From:	
Depth To:	4.9
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002523512	***Elevation:***	77.2714
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632848
Code OB Desc:		***North83:***	4834602
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	8/17/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002523516
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1002523517
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002523519
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.5
Casing Diameter:	

Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002523518
Layer:
Slot:
Screen Top Depth: 1.5
Screen End Depth: 4.57
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002523520
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002523514
Diameter: 5.08
Depth From:
Depth To: 4.57
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002523467
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.375114
Elevrc:
Zone: 17
East83: 632896
North83: 4834643
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment

Sealing Record

Plug ID:	1002523471
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	
Method Construction:	
Other Method Construction:	BORING

Pipe Information

Pipe ID:	1002523472
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002523474
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.83
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002523473
Layer:	
Slot:	
Screen Top Depth:	1.83
Screen End Depth:	4.9
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1002523475
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	

Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002523469
Diameter: 5.08
Depth From:
Depth To: 4.9
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002523494
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.2714
Elevrc:
Zone: 17
East83: 632848
North83: 4834602
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002523498
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Method of Construction & Well Use

Method Construction ID:
Method Construction Code:
Method Construction:
Other Method Construction: BORING

Pipe Information

Pipe ID: 1002523499
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002523501
Layer:
Material: 5
Open Hole or Material: PLASTIC

Depth From:
Depth To: 6.1
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002523500
Layer:
Slot:
Screen Top Depth: 6.1
Screen End Depth: 9.14
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002523502
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002523496
Diameter: 5.08
Depth From:
Depth To: 9.14
Hole Depth UOM: m
Hole Diameter UOM: cm

---

315 ***2 of 2*** ***SSW/245.4*** ***78.9 / 0.02*** ***lot M ON*** ***WWIS***

Well ID: 7102282
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status: 0
Water Type:
Casing Material:
Audit No: M00910
Tag: _NO_TAG
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:

Data Entry Status:
Data Src:
Date Received: 2/21/2008
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 7241
Form Version: 5
Owner:
Street Name: 100 MILL ST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot: M

Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1002650391	***Elevation:***	77.945632
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632920
Code OB Desc:		***North83:***	4834643
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	8/17/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002650395
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Pipe Information

Pipe ID:	1002650396
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002650398
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.83
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002650397
Layer:	
Slot:	
Screen Top Depth:	1.83
Screen End Depth:	4.9
Screen Material:	

Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002650399
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002650393
Diameter: 5.08
Depth From:
Depth To: 4.9
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002650373
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 78.205146
Elevrc:
Zone: 17
East83: 632823
North83: 4834561
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002650377
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Pipe Information

Pipe ID: 1002650378

Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002650380
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 3.66
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002650379
Layer:
Slot:
Screen Top Depth: 3.66
Screen End Depth: 6.7
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002650381
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002650375
Diameter: 5.08
Depth From:
Depth To: 6.7
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002650364
DP2BR:
Spatial Status:
Code OB:
Elevation: 77.181999
Elevrc:
Zone: 17
East83: 632879

Code OB Desc:		***North83:***	4834643
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	8/17/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002650368
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Pipe Information

Pipe ID:	1002650369
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002650371
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	6.71
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002650370
Layer:	
Slot:	
Screen Top Depth:	6.71
Screen End Depth:	9.8
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1002650372
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	

Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002650366
Diameter: 5.08
Depth From:
Depth To: 9.8
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002650418
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.2714
Elevrc:
Zone: 17
East83: 632848
North83: 4834602
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002650422
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Pipe Information

Pipe ID: 1002650423
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002650425
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 6.1
Casing Diameter:
Casing Diameter UOM:

Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002650424
Layer:
Slot:
Screen Top Depth: 6.1
Screen End Depth: 9.14
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002650426
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002650420
Diameter: 5.08
Depth From:
Depth To: 9.14
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002650409
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 76.912559
Elevrc:
Zone: 17
East83: 632848
North83: 4834642
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002650413
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Pipe Information

Pipe ID: 1002650414
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002650416
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.83
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002650415
Layer:
Slot:
Screen Top Depth: 1.83
Screen End Depth: 4.9
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002650417
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002650411
Diameter: 5.08
Depth From:

Depth To: 4.9
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID:	1002650427	**Elevation:**	77.25373
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632484
Code OB Desc:		**North83:**	4834602
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	8/17/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002650431
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Pipe Information

Pipe ID: 1002650432
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002650434
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 3.1
Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002650433
Layer:
Slot:
Screen Top Depth: 3.1
Screen End Depth: 6.1
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID:	1002650435
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002650429
Diameter:	5.08
Depth From:	
Depth To:	6.1
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002650445	***Elevation:***	76.381355
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	632790
Code OB Desc:		***North83:***	4834632
Open Hole:		***Org CS:***	UTM83
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	3
Date Completed:	8/22/2007	***UTMRC Desc:***	margin of error : 10 - 30 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002650449
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Pipe Information

Pipe ID:	1002650450
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002650452
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	3.66
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002650451
Layer:	
Slot:	
Screen Top Depth:	3.66
Screen End Depth:	6.7
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1002650453
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002650447
Diameter:	5.08
Depth From:	
Depth To:	6.7
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002650454	***Elevation:***	
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	
Code OB:		***East83:***	
Code OB Desc:		***North83:***	
Open Hole:		***Org CS:***	
Cluster Kind:	This is a record from cluster log sheet	***UTMRC:***	9
Date Completed:		***UTMRC Desc:***	unknown UTM

Remarks: ***Location Method:*** na
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Hole Diameter

Hole ID: 1002650456
Diameter:
Depth From:
Depth To:
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1001524500 ***Elevation:*** 77.285385
DP2BR: ***Elevrc:***
Spatial Status: ***Zone:*** 17
Code OB: ***East83:*** 632898
Code OB Desc: ***North83:*** 4834681
Open Hole: ***Org CS:*** UTM83
Cluster Kind: ***UTMRC:*** 3
Date Completed: 1/23/2008 ***UTMRC Desc:*** margin of error : 10 - 30 m
Remarks: ***Location Method:*** wwr
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Annular Space/Abandonment Sealing Record

Plug ID: 1002650459
Layer: 1
Plug From: 0
Plug To: 0.3
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002650460
Layer: 2
Plug From: 0.3
Plug To: 2.13
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1002650461
Layer: 3
Plug From: 2.13
Plug To: 12.7
Plug Depth UOM: m

Pipe Information

Pipe ID: 1002650458
Casing No: 0
Comment:
Alt Name:

Construction Record - Screen

Screen ID: 1002650462
Layer: 1
Slot: 10
Screen Top Depth:
Screen End Depth:
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5.08

Bore Hole Information

Bore Hole ID: 1002650382
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 76.469467
Elevrc:
Zone: 17
East83: 632816
North83: 4834654
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 1002650386
Layer:
Plug From:
Plug To:
Plug Depth UOM:

Pipe Information

Pipe ID: 1002650387
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002650389
Layer:
Material: 5
Open Hole or Material: PLASTIC
Depth From:
Depth To: 1.83

Casing Diameter:
Casing Diameter UOM:
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 1002650388
Layer:
Slot:
Screen Top Depth: 1.83
Screen End Depth: 4.9
Screen Material:
Screen Depth UOM: m
Screen Diameter UOM:
Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002650390
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002650384
Diameter: 5.08
Depth From:
Depth To: 4.9
Hole Depth UOM: m
Hole Diameter UOM: cm

Bore Hole Information

Bore Hole ID: 1002650400
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind: This is a record from cluster log sheet
Date Completed: 8/17/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 77.920684
Elevrc:
Zone: 17
East83: 632950
North83: 4834676
Org CS: UTM83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID:	1002650404
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Pipe Information

Pipe ID:	1002650405
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002650407
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.83
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002650406
Layer:	
Slot:	
Screen Top Depth:	1.83
Screen End Depth:	4.9
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	
Screen Diameter:	

Results of Well Yield Testing

Pump Test ID:	1002650408
Pump Set At:	
Static Level:	
Final Level After Pumping:	
Recommended Pump Depth:	
Pumping Rate:	
Flowing Rate:	
Recommended Pump Rate:	
Levels UOM:	
Rate UOM:	
Water State After Test Code:	
Water State After Test:	
Pumping Test Method:	
Pumping Duration HR:	
Pumping Duration MIN:	
Flowing:	

Hole Diameter

Hole ID:	1002650402

Diameter:	5.08
Depth From:	
Depth To:	4.9
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Bore Hole Information

Bore Hole ID:	1002650436	**Elevation:**	77.25373
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	632484
Code OB Desc:		**North83:**	4834602
Open Hole:		**Org CS:**	UTM83
Cluster Kind:	This is a record from cluster log sheet	**UTMRC:**	3
Date Completed:	8/17/2007	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Annular Space/Abandonment Sealing Record

Plug ID:	1002650440
Layer:	
Plug From:	
Plug To:	
Plug Depth UOM:	

Pipe Information

Pipe ID:	1002650441
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002650443
Layer:	
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	
Depth To:	1.5
Casing Diameter:	
Casing Diameter UOM:	
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002650442
Layer:	
Slot:	
Screen Top Depth:	1.5
Screen End Depth:	4.57
Screen Material:	
Screen Depth UOM:	m
Screen Diameter UOM:	

Screen Diameter:

Results of Well Yield Testing

Pump Test ID: 1002650444
Pump Set At:
Static Level:
Final Level After Pumping:
Recommended Pump Depth:
Pumping Rate:
Flowing Rate:
Recommended Pump Rate:
Levels UOM:
Rate UOM:
Water State After Test Code:
Water State After Test:
Pumping Test Method:
Pumping Duration HR:
Pumping Duration MIN:
Flowing:

Hole Diameter

Hole ID: 1002650438
Diameter: 5.08
Depth From:
Depth To: 4.57
Hole Depth UOM: m
Hole Diameter UOM: cm

---

316 ***1 of 5*** ***SSW/246.0*** ***76.2 / -2.62*** ***TORONTO, CORPORATION OF THE CITY OF 515 FRONT STREEET EAST ATARATIRI TORONTO ON*** ***GEN***

Generator No: ON1631621
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 8359
SIC Description: OTHER GEN. ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

316 ***2 of 5*** ***SSW/246.0*** ***76.2 / -2.62*** ***TORONTO, CITY OF 515 FRONT STREEET EAST ATARATIRI TORONTO ON*** ***GEN***

Generator No: ON1631621
Status:
Approval Years: 93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 8359
SIC Description: OTHER GEN. ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		251			
Waste Class Desc:		OIL SKIMMINGS & SLUDGES			

316 **3 of 5** **SSW/246.0** **76.2 / -2.62** **PPM CANADA INC.** **REC**
CITY OF TORONTO, 515 FRONT ST.EAST C/O 6 CHELSEA LANE
BRAMPTON ON L6T 3Y4

Rec Op Div:
Co Admin:
Phone No Admin:
Rec Div:
Rec Op Name:
Choice of Contact:
Site Bldg:
Site PO Box:
Receiver #: A230336
Facility Type: TRANSFER STATION
Approval Yrs: 93,94,95,96,97,98

--Details--
Waste Code: 243
Waste Description: PCB'S

316 **4 of 5** **SSW/246.0** **76.2 / -2.62** **PPM CANADA INC.** **REC**
CITY OF TORONTO 515 FRONT STREET EAST
TORONTO ON

Rec Op Div:
Co Admin:
Phone No Admin:
Rec Div:
Rec Op Name:
Choice of Contact:
Site Bldg:
Site PO Box:
Receiver #: A230336
Facility Type:
Approval Yrs: 06,07,08

316 **5 of 5** **SSW/246.0** **76.2 / -2.62** **PRIVATE OWNER** **SPL**
515 FRONT ST. E. STORAGE TANK/BARREL
TORONTO CITY ON

Ref No:	152292	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	2/10/1998	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	01106
Nature of Impact:	Air Pollution	**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MOE Reported Dt:	2/10/1998	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	(OLD) CANADA PACKERS-UNK VOL OF AMMONIA GAS TO ATMOS.		
Contaminant Qty:			

317 **1 of 1** **NE/246.3** **79.8 / 0.97** **TORONTO ON** **WWIS**

Well ID:	7113626	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Other	**Date Received:**	10/21/2008
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	0	**Abandonment Rec:**	
Water Type:		**Contractor:**	6946
Casing Material:		**Form Version:**	7
Audit No:	Z91271	**Owner:**	
Tag:	A080291	**Street Name:**	71 SAULTER STREET
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1001840919	**Elevation:**	79.615921
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633259
Code OB Desc:		**North83:**	4835365
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/14/2008	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1002457300
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY

Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	1.5
Formation End Depth:	5.3
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1002457299
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	02
Other Materials:	TOPSOIL
Formation Top Depth:	0
Formation End Depth:	1.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1002457301
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	12
Other Materials:	STONES
Mat3:	66
Other Materials:	DENSE
Formation Top Depth:	5.3
Formation End Depth:	6.65
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002457305
Layer:	2
Plug From:	2.5
Plug To:	0.3
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002457306
Layer:	3
Plug From:	0.3
Plug To:	0
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1002457304

Layer:	1
Plug From:	6.65
Plug To:	2.5
Plug Depth UOM:	m

Pipe Information

Pipe ID:	1002457298
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1002457308
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	2.9
Casing Diameter:	5.2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1002457309
Layer:	1
Slot:	10
Screen Top Depth:	2.9
Screen End Depth:	6.65
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03

Water Details

Water ID:	1002457307
Layer:	1
Kind Code:	9
Kind:	Other
Water Found Depth:	6.18
Water Found Depth UOM:	m

Hole Diameter

Hole ID:	1002457303
Diameter:	11.4
Depth From:	0.3
Depth To:	6.65
Hole Depth UOM:	m
Hole Diameter UOM:	cm

Hole Diameter

Hole ID:	1002457302
Diameter:	15.2
Depth From:	0
Depth To:	0.3
Hole Depth UOM:	m

Hole Diameter UOM: cm

---

318 *1 of 1* *N/247.7* *81.8 / 2.97* ***134-136 Broadview Ave Toronto ON M4M 2G2*** ***EHS***

Order No:	20091118048	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	11/27/2009	**Search Radius (km):**	0.25
Date Received:	11/18/2009	**X:**	-79.350535
Previous Site Name:		**Y:**	43.659698
Lot/Building Size:			
Additional Info Ordered:			

---

319 *1 of 1* *S/248.5* *78.6 / -0.27* ***ON*** ***BORE***

Borehole ID:	643537	**Inclin FLG:**	No
OGF ID:	215543924	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	MAY-1961	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.653054
Total Depth m:	6.6	**Longitude DD:**	-79.349651
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633085
Drill Method:	Diamond Drill	**Northing:**	4834663
Orig Ground Elev m:	81.1	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	79.8		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218504228	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.3	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Soil	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SOIL. BLACK,AGE POST-GLACIAL.		

Geology Stratum ID:	218504230	**Mat Consistency:**	Stiff
Top Depth:	1.7	**Material Moisture:**	
Bottom Depth:	2.9	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,SAND,CLAY. BROWN,STIFF,AGE GLACIAL.		

Geology Stratum ID:	218504233	**Mat Consistency:**	Stiff
Top Depth:	4.5	**Material Moisture:**	
Bottom Depth:	6	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Clay	**Geologic Period:**	
Material 4:	Stones	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,CLAY, STONES. GREY,GLACIAL,STIFF, AGE GLACIAL.		

Geology Stratum ID:	218504231	**Mat Consistency:**	Soft
Top Depth:	2.9	**Material Moisture:**	
Bottom Depth:	3.8	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT. GREY,VERY SOFT,AGE GLACIAL.		

Geology Stratum ID:	218504229	**Mat Consistency:**	Firm
Top Depth:	.3	**Material Moisture:**	
Bottom Depth:	1.7	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	organic material	**Geologic Group:**	
Material 3:	Silt	**Geologic Period:**	
Material 4:		**Depositional Gen:**	organic
Gsc Material Description:			
Stratum Description:	CLAY,ORGANIC,SILT. BROWN,FIRM,AGE GLACIAL.		

Geology Stratum ID:	218504232	**Mat Consistency:**	Stiff
Top Depth:	3.8	**Material Moisture:**	
Bottom Depth:	4.5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SILT,CLAY. GREY,BROWN,STIFF,LAYERED, AGE GLACIAL.		

Geology Stratum ID:	218504234	**Mat Consistency:**	Hard
Top Depth:	6	**Material Moisture:**	
Bottom Depth:	6.6	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Till	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Sand	**Geologic Period:**	
Material 4:	Clay	**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	TILL,SILT,SAND,CLAY.GREY,GLACIAL,HARD,AGE GLACIAL. 021 015 018 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 115580 NTS_Sheet: 30M11C		

Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

320 ***1 of 16*** ***NW/248.6*** ***80.8 / 1.97*** ***Colourgenics Inc.*** ***11 Davis Avenue SUITE 102*** ***Toronto ON M4M 2A9*** ***GEN***

Generator No: ON5168060
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

---

320 ***2 of 16*** ***NW/248.6*** ***80.8 / 1.97*** ***Colourgenics Inc.*** ***11 Davis Avenue SUITE 102*** ***Toronto ON*** ***GEN***

Generator No: ON5168060
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 519190
SIC Description: All Other Information Services
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

320 ***3 of 16*** ***NW/248.6*** ***80.8 / 1.97*** ***Colourgenics Inc.*** ***11 Davis Avenue SUITE 102*** ***Toronto ON*** ***GEN***

Generator No: ON5168060
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 519190
SIC Description: All Other Information Services
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145

Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

320 **4 of 16** **NW/248.6** **80.8 / 1.97** **GEN**

Colourgenics Inc.
11 Davis Avenue SUITE 102
Toronto ON M4M 2A9

Generator No:	ON5168060	**PO Box No:**	
Status:		**Country:**	Canada
Approval Years:	2014	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	Al Pettman
MHSW Facility:	No	**Phone No Admin:**	905-333-3004 Ext.
SIC Code:	519190		
SIC Description:	ALL OTHER INFORMATION SERVICES		

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

320 **5 of 16** **NW/248.6** **80.8 / 1.97** **GEN**

Colourgenics Inc.
11 Davis Avenue SUITE 101
Toronto ON

Generator No:	ON5168060	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2009	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	519190		
SIC Description:	All Other Information Services		

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

320 **6 of 16** **NW/248.6** **80.8 / 1.97** **GEN**

COLOURGENICS INC. 09-321
11 DAVIES AVENUE
TORONTO ON M4M 2A9

Generator No:	ON0760201	**PO Box No:**	
Status:		**Country:**	
Approval Years:	94,95,96	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	2819		
SIC Description:	OTHER COMM. PRINTING		

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

---

320 **7 of 16** **NW/248.6** **80.8 / 1.97** **GEN**

Colourgenics Inc.
11 Davis Avenue SUITE 102
Toronto ON

Generator No:	ON5168060	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2013	**Choice of Contact:**	

Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 519190
SIC Description: ALL OTHER INFORMATION SERVICES

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

320 ***8 of 16*** ***NW/248.6*** ***80.8 / 1.97*** ***Colourgenics Inc.*** ***GEN***
11 Davis Avenue
Toronto ON M4M 2A9

Generator No: ON5168060 ***PO Box No:***
Status: ***Country:***
Approval Years: 05,06,07,08 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 519190
SIC Description: All Other Information Services

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

320 ***9 of 16*** ***NW/248.6*** ***80.8 / 1.97*** ***Colourgenics Inc.*** ***GEN***
11 Davis Avenue SUITE 102
Toronto ON M4M 2A9

Generator No: ON5168060 ***PO Box No:***
Status: ***Country:***
Approval Years: 2012 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 519190
SIC Description: All Other Information Services

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

---

320 ***10 of 16*** ***NW/248.6*** ***80.8 / 1.97*** ***Colourgenics Inc.*** ***GEN***
11 Davis Avenue SUITE 102
Toronto ON M4M 2A9

Generator No: ON5168060 ***PO Box No:***
Status: Registered ***Country:*** Canada
Approval Years: As of Dec 2018 ***Choice of Contact:***
Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code:
SIC Description:

Detail(s)

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
320	11 of 16	NW/248.6	80.8 / 1.97	Colourgenics Inc. 11 Davis Avenue SUITE 102 Toronto ON M4M 2A9	GEN

Generator No: ON5168060
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 519190
SIC Description: ALL OTHER INFORMATION SERVICES

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Al Pettman
Phone No Admin: 905-333-3004 Ext.

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
320	12 of 16	NW/248.6	80.8 / 1.97	COLOURGENICS INC. 11 DAVIES AVENUE TORONTO ON M4M 2A9	GEN

Generator No: ON0760201
Status:
Approval Years: 88,89,90,92,93,97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 0000
SIC Description: *** NOT DEFINED ***

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
320	13 of 16	NW/248.6	80.8 / 1.97	Colourgenics Inc. 11 Davis Avenue SUITE 102 Toronto ON M4M 2A9	GEN

Generator No: ON5168060
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 519190
SIC Description: ALL OTHER INFORMATION SERVICES

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Al Pettman
Phone No Admin: 905-333-3004 Ext.

Detail(s)

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
320	14 of 16	NW/248.6	80.8 / 1.97	Colourgenics Inc. 11 Davies Ave Suite 101 Toronto ON M4M 2A9	SCT

Established: 01-JUL-83
Plant Size (ft²): 9000
Employment:

--Details--

Description:	Print and Picture Frame Stores
SIC/NAICS Code:	442292
Description:	All Other Miscellaneous Manufacturing
SIC/NAICS Code:	339990
Description:	Support Activities for Printing
SIC/NAICS Code:	323120
Description:	Photographic Services
SIC/NAICS Code:	541920
Description:	Data Processing, Hosting, and Related Services
SIC/NAICS Code:	518210
Description:	Data Processing, Hosting, and Related Services
SIC/NAICS Code:	518210
Description:	Other Publishers
SIC/NAICS Code:	511190
Description:	Other Printing
SIC/NAICS Code:	323119

---

320 ***15 of 16*** ***NW/248.6*** ***80.8 / 1.97*** ***Canada Transport Co***
11 Davies Ave
Toronto ON M4M 2A9 ***TANK***

Permit Date:	7/24/1934
Permit Type:	BP A52150
User Type:	Trucking
Installation Type:	public garage addition
Installation Size:	
Installation Config.:	public garage addition
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	450
Capacity(gal):	
Reference:	CTA Building Permits
Location Desc:	Davies NE cor Thomson St

---

320 ***16 of 16*** ***NW/248.6*** ***80.8 / 1.97*** ***Canada Transport Co***
11 Davies Ave
Toronto ON M4M 2A9 ***TANK***

Permit Date:	5/22/1935
Permit Type:	BP A55579
User Type:	Trucking
Installation Type:	gas tank
Installation Size:	
Installation Config.:	gas tank
No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	300
Capacity(gal):	
Reference:	CTA Building Permits
Location Desc:	11 Davies Ave

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
321	1 of 1	W/248.7	78.9 / 0.07	TORONTO ON	WWIS

Well ID: 6929600
Construction Date:
Primary Water Use: Not Used
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z33954
Tag: A025547
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 11/24/2005
Selected Flag: Yes
Abandonment Rec: Yes
Contractor: 7215
Form Version: 3
Owner:
Street Name: 611 KING STREET EAST
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11328569
DP2BR:
Spatial Status:
Code OB: _
Code OB Desc: No formation data
Open Hole:
Cluster Kind:
Date Completed: 11/2/2005
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation: 79.460586
Elevrc:
Zone: 17
East83: 632607
North83: 4835057
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Annular Space/Abandonment Sealing Record

Plug ID: 933281685
Layer: 1
Plug From: 25
Plug To: 4
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 933281686
Layer: 2
Plug From: 4
Plug To: 0
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 11343424
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930873574
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 5
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 933415627
Layer: 1
Slot: 10
Screen Top Depth: 5
Screen End Depth: 25
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2

Hole Diameter

Hole ID: 11549688
Diameter: 8
Depth From: 0
Depth To: 25
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

322 **1 of 1** **NNE/249.1** **79.8 / 0.97** **Toronto ON** **WWIS**

Well ID: 7228684
Construction Date:
Primary Water Use: Monitoring
Sec. Water Use:
Final Well Status: 0
Water Type:
Casing Material:
Audit No: Z192880
Tag: A156106
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:

Data Entry Status:
Data Src:
Date Received: 10/1/2014
Selected Flag: Yes
Abandonment Rec:
Contractor: 7295
Form Version: 7
Owner:
Street Name: 770 QUEEN ST E
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:

Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1005144589
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 8/5/2014
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:
Elevation: 79.879623
Elevrc:
Zone: 17
East83: 633244
North83: 4835379
Org CS: dms83
UTMRC: 3
UTMRC Desc: margin of error : 10 - 30 m
Location Method: wwr

Overburden and Bedrock Materials Interval

Formation ID: 1005371993
Layer: 2
Color: 6
General Color: BROWN
Mat1: 01
Most Common Material: FILL
Mat2:
Other Materials:
Mat3: 77
Other Materials: LOOSE
Formation Top Depth: 5
Formation End Depth: 10
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005371994
Layer: 3
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2: 34
Other Materials: TILL
Mat3: 85
Other Materials: SOFT
Formation Top Depth: 10
Formation End Depth: 15
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID:	1005371992
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005371995
Layer:	4
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	34
Other Materials:	TILL
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	15
Formation End Depth:	25
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005371996
Layer:	5
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Other Materials:	
Mat3:	68
Other Materials:	DRY
Formation Top Depth:	25
Formation End Depth:	35
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005372003
Layer:	1
Plug From:	0
Plug To:	13
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	6

Method Construction: Boring
Other Method Construction:

Pipe Information

Pipe ID: 1005371991
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005371999
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 15
Casing Diameter: 1.8
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005372000
Layer: 1
Slot: 10
Screen Top Depth: 15
Screen End Depth: 25
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2

Hole Diameter

Hole ID: 1005371997
Diameter:
Depth From:
Depth To:
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

323 ***1 of 4*** ***N/250.0*** ***81.9 / 3.03*** ***ROYAL CANADIAN CURLING CLUB***
131 BROADVIEW AVE.
TORONTO ON M4M 2E9 ***GEN***

Generator No: ON1393800
Status:
Approval Years: 90
Contam. Facility:
MHSW Facility:
SIC Code: 9652
SIC Description: CURLING CLUBS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
323	2 of 4	N/250.0	81.9 / 3.03	ROYAL CANADIAN CURLING CLUB 33-750 131 BROADVIEW AVE. TORONTO ON M4M 2E9	GEN

Generator No: ON1393800
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 9652
SIC Description: CURLING CLUBS

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
323	3 of 4	N/250.0	81.9 / 3.03	ROYAL CANADIAN CURLING CLUB 131 BROADVIEW AVENUE TORONTO ON M4M 2E9	GEN

Generator No: ON1393800
Status:
Approval Years: 98,99,00,01,02,03,04
Contam. Facility:
MHSW Facility:
SIC Code: 9652
SIC Description: CURLING CLUBS

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
323	4 of 4	N/250.0	81.9 / 3.03	ETC NEWSPAPER 131 BROADVIEW AVE FLOOR 2 TORONTO ON M4M 2E9	SCT

Established: 1988
Plant Size (ft²): 0
Employment: 6

--Details--
Description: NEWSPAPERS: PUBLISHING, OR PUBLISHING AND PRINTING
SIC/NAICS Code: 2711

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
324	1 of 1	NNE/250.0	79.8 / 0.97	772 QUEEN STREET EAST, TORONTO, ON M4M 1H4 Toronto ON	RSC

RSC ID: 224211
RA No:
RSC Type: Phase 1 RSC
Curr Property Use: Commercial
Ministry District: Toronto District Office
Filing Date: 2018/02/07
Date Ack:
Date Returned:
Restoration Type:
Soil Type:
Cert Date:
Cert Prop Use No:
Intended Prop Use: Residential
Qual Person Name: DAVID MARKS
Stratified (Y/N):
Audit (Y/N):
Entire Leg Prop. (Y/N):
Accuracy Estimate:
Telephone:
Fax:

Criteria: ***Email:***
CPU Issued Sect 1686:
Asmt Roll No: 19-04-07-3-110-04100-0000-00
Prop ID No (PIN): 21074-0319 (LT)
Property Municipal Address: 772 QUEEN STREET EAST, TORONTO, ON M4M 1H4
Mailing Address:
Latitude & Latitude:
UTM Coordinates:
Consultant:
Filing Owner: 772 QUEEN ST. E. LTD.
Legal Desc:
Measurement Method:
Applicable Standards:
RSC PDF: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=91688&fileName=BROWNFIELDS-E.pdf

Document(s) Detail

Document Heading: Supporting Documents
Document Name: 1-Certificate of Status-772 Queen E.pdf
Document Type: Certificate of Status
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=91693&fileName=1-Certificate+of+Status-772+Queen+E.pdf

Document Heading: Supporting Documents
Document Name: 5-Site Survey-772 Queen E.pdf
Document Type: A Current plan of Survey
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=91685&fileName=5-Site+Survey-772+Queen+E.pdf

Document Heading: Supporting Documents
Document Name: 4-Deed_Transfer-772 Queen E.pdf
Document Type: Copy of any deed(s), transfer(s) or other document(s)
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=91689&fileName=4-Deed_Transfer-772+Queen+E.pdf

Document Heading: Supporting Documents
Document Name: 2-Owner Authorization-772 Queen E.pdf
Document Type: Proof of the owner's authorization
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=91691&fileName=2-Owner+Authorization-772+Queen+E.pdf

Document Heading: Supporting Documents
Document Name: 6-Current and Past Uses Table-772 Queen E.pdf
Document Type: Table of Current and Past Property Use
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=91684&fileName=6-Current+and+Past+Uses+Table-772+Queen+E.pdf

Document Heading: Supporting Documents
Document Name: 7-Conceptual Site Model-772 Queen E.pdf
Document Type: Phase 1 Conceptual Site Model
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=91690&fileName=7-Conceptual+Site+Model-772+Queen+E.pdf

Document Heading: Supporting Documents
Document Name: 3-Lawyers Letter-772 Queen E.pdf
Document Type: Lawyer's letter consisting of a legal description of the property
Document Link: https://www.lrcsde.lrc.gov.on.ca/BFISWebPublic/pub/viewDocument.action?attachmentId=91694&fileName=3-Lawyers+Letter-772+Queen+E.pdf

325	*1 of 87*	*SE/250.0*	*80.8 / 1.95*	***Korex Don Valley ULC*** ***21 Don Valley Parkway*** ***Toronto ON M4M 3P2***	*CA*

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Certificate #: 2279-64SNDN
Application Year: 2004
Issue Date: 9/13/2004
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

---

325 **2 of 87** **SE/250.0** **80.8 / 1.95** **LEVER A DIVISION OF U L CANADA INC.** **CA**
21 DON VALLEY PARKWAY
TORONTO CITY ON M4M 3P2

Certificate #: 8-3178-93-
Application Year: 93
Issue Date: 6/9/1993
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: MIST ELIMINATOR AT SULPHONATION PLANT
Contaminants: Sulphuric Acid
Emission Control: Mist Eliminator,

---

325 **3 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway** **CA**
Toronto ON M4M 3P2

Certificate #: 8/300/035/89/896
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: This application is requesting a name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

---

325 **4 of 87** **SE/250.0** **80.8 / 1.95** **LEVER BROTHERS LIMITED** **CA**
21 DON VALLEY PARKWAY
TORONTO CITY ON M4M 3P2

Certificate #: 8-3063-91-
Application Year: 91
Issue Date: 6/4/1991
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client Address:
Client City:
Client Postal Code:
Project Description: TRANSFER SYSTEM, DUST COLLECTORS-BLDG 36
Contaminants:
Emission Control: Baghouse (Incl Vent Fil.)

---

325 ***5 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***LEVER A DIVISION OF U L CANADA INC.***
21 DON VALLEY PARKWAY
TORONTO CITY ON M4M 3P2 ***CA***

Certificate #: 8-3223-93-
Application Year: 93
Issue Date: 3/3/1994
Approval Type: Industrial air
Status: Underwent 1st revision in 1994
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: SYHTH.SOAP SURFACTANT PROC. IN BLDG.# 36
Contaminants: Nitrogen Oxides
Emission Control: No Controls

---

325 ***6 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***LEVER BROTHERS LIMITED***
21 DON VALLEY PARKWAY
TORONTO CITY ON M4M 3P2 ***CA***

Certificate #: 8-3152-88-
Application Year: 88
Issue Date: 12/12/1988
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: LIQUID DETRAERENT FILLING EXHAUST
Contaminants:
Emission Control:

---

325 ***7 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***21 Don Valley Parkway***
Toronto ON M4M 3P2 ***CA***

Certificate #: 8-3069-82-837
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	8 of 87	SE/250.0	80.8 / 1.95	21 Don Valley Parkway Toronto ON M4M 3P2	CA

Certificate #: 8-3165-98-006
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	9 of 87	SE/250.0	80.8 / 1.95	LEVER BROTHERS LIMITED 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2	CA

Certificate #: 8-3180-89-
Application Year: 89
Issue Date: 9/1/1989
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: MODIF. TO DETERGENT ADDITIVE/CONVEYOR S.
Contaminants: Suspended Particulate Matter
Emission Control: Baghouse (Incl Vent Fil.)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	10 of 87	SE/250.0	80.8 / 1.95	LEVER BROTHERS LTD. DON VALLEY PARKWAY & LAKESHORE TORONTO CITY ON	CA

Certificate #: 8-3052-87-
Application Year: 87
Issue Date: 8/13/1987
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: MIST ELIMINATOR
Contaminants: Suspended Particulate Matter, Sulphur Dioxide, Other Contaminant
Emission Control: Mist Eliminator,

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	11 of 87	SE/250.0	80.8 / 1.95	LEVER POND'S, DIV. OF U.L. CANADA INC. 21 DON VALLEY PARKWAY TORONTO ON M4M 3P2	CA

Certificate #: 8-3165-98-
Application Year: 98
Issue Date: 5/25/1998

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: VENT MAIN MIXER AND LIQUID SCALE
Contaminants:
Emission Control:

---

325 **12 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **CA**

Certificate #: 8-3054-77-006
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC
Contaminants:
Emission Control:

---

325 **13 of 87** **SE/250.0** **80.8 / 1.95** **LEVER A DIVISION OF U L CANADA INC. 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2** **CA**

Certificate #: 8-3444-95-967
Application Year: 95
Issue Date: 12/2/96
Approval Type: Industrial air
Status: First Ammendment in 1996
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: ADD TWO AREA VENTS
Contaminants:
Emission Control:

---

325 **14 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **CA**

Certificate #: 8-3050-99-007
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Contaminants:					
Emission Control:					

325	15 of 87	SE/250.0	80.8 / 1.95	LEVER BROTHERS LIMITED 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2	CA

Certificate #:	8-3020-87-
Application Year:	87
Issue Date:	6/19/1987
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	LIQUID DETERGENT MIXING
Contaminants:	
Emission Control:	

325	16 of 87	SE/250.0	80.8 / 1.95	LEVER A DIVISION OF U L CANADA INC. 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2	CA

Certificate #:	8-3445-93-
Application Year:	93
Issue Date:	11/1/1993
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	DUST COLL. & EXH. FAN (X#3/300/110/90)
Contaminants:	
Emission Control:	

325	17 of 87	SE/250.0	80.8 / 1.95	21 Don Valley Parkway Toronto ON M4M 3P2	CA

Certificate #:	8-3178-93-006
Application Year:	02
Issue Date:	9/30/02
Approval Type:	Industrial air
Status:	Approved
Application Type:	Notice
Client Name:	Korex Don Valley ULC
Client Address:	21 Don Valley Parkway
Client City:	Toronto
Client Postal Code:	M4M 3P2
Project Description:	Administrative name change from U L Canada Inc. to Korex Don Valley ULC
Contaminants:	
Emission Control:	

325	18 of 87	SE/250.0	80.8 / 1.95	21 Don Valley Parkway Toronto ON M4M 3P2	CA

Certificate #:	8-3152-88-006
Application Year:	02
Issue Date:	9/30/02
Approval Type:	Industrial air
Status:	Approved
Application Type:	Notice
Client Name:	Korex Don Valley ULC
Client Address:	21 Don Valley Parkway
Client City:	Toronto
Client Postal Code:	M4M 3P2
Project Description:	Administrative name change from U L Canada Inc. to Korex Don Valley ULC
Contaminants:	
Emission Control:	

---

325 | ***19 of 87*** | ***SE/250.0*** | ***80.8 / 1.95*** | ***21 Don Valley Parkway Toronto ON M4M 3P2*** | ***CA***

Certificate #:	8-3070-82-006
Application Year:	02
Issue Date:	9/30/02
Approval Type:	Industrial air
Status:	Approved
Application Type:	Notice
Client Name:	Korex Don Valley ULC
Client Address:	21 Don Valley Parkway
Client City:	Toronto
Client Postal Code:	M4M 3P2
Project Description:	Administrative name change from U L Canada Inc. to Korex Don Valley ULC
Contaminants:	
Emission Control:	

---

325 | ***20 of 87*** | ***SE/250.0*** | ***80.8 / 1.95*** | ***LEVER A DIVISION OF U L CANADA INC. 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2*** | ***CA***

Certificate #:	8-3179-93-REV
Application Year:	93
Issue Date:	6/18/93
Approval Type:	Industrial air
Status:	Revised
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	CLOSE DISHWASHER DET. POWDER MFG. FAC.
Contaminants:	
Emission Control:	

---

325 | ***21 of 87*** | ***SE/250.0*** | ***80.8 / 1.95*** | ***21 Don Valley Parkway Toronto ON M4M 3P2*** | ***CA***

Certificate #:	8-3445-93-006
Application Year:	02
Issue Date:	9/30/02
Approval Type:	Industrial air
Status:	Approved
Application Type:	Notice
Client Name:	Korex Don Valley ULC
Client Address:	21 Don Valley Parkway

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

---

325 | 22 of 87 | SE/250.0 | 80.8 / 1.95 | 21 Don Valley Parkway Toronto ON M4M 3P2 | CA

Certificate #: 8/300/093/90/906
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: This application is requesting a name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

---

325 | 23 of 87 | SE/250.0 | 80.8 / 1.95 | 21 Don Valley Parkway Toronto ON M4M 3P2 | CA

Certificate #: 8-3222-88-896
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC
Contaminants:
Emission Control:

---

325 | 24 of 87 | SE/250.0 | 80.8 / 1.95 | Korex Don Valley ULC 21 Don Valley Parkway Toronto ON M4M 3P2 | CA

Certificate #: 3089-63ZQ5X
Application Year: 2004
Issue Date: 9/2/2004
Approval Type: Air
Status: Revoked and/or Replaced
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	25 of 87	SE/250.0	80.8 / 1.95	21 Don Valley Parkway TORONTO ON M4M 3P2	CA

Certificate #: 4111-4H7K4S
Application Year: 00
Issue Date: 3/23/00
Approval Type: Industrial air
Status: Amended
Application Type: New Certificate of Approval
Client Name: Lever Pond's
Client Address: 160 Bloor Street East Suite 300
Client City: Toronto
Client Postal Code: M4W 3W3
Project Description: Install natural gas indirect fired air make-up unit for comfort heating.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	26 of 87	SE/250.0	80.8 / 1.95	LEVER BROTHERS LIMITED 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2	CA

Certificate #: 8-3111-92-
Application Year: 92
Issue Date: 5/7/1992
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: BAGHOUSE FOR PNEUMATIC CONVEYOR SYSTEM
Contaminants: Suspended Particulate Matter, Sodium Nitrilotriacetate
Emission Control: Baghouse (Incl Vent Fil.)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	27 of 87	SE/250.0	80.8 / 1.95	21 Don Valley Parkway TORONTO ON M4M 3P2	CA

Certificate #: 2780-4P5RW8
Application Year: 00
Issue Date: 10/13/00
Approval Type: Industrial air
Status: Amended
Application Type: New Certificate of Approval
Client Name: Lever Pond's
Client Address: 160 Bloor Street East Suite 300
Client City: Toronto
Client Postal Code: M4W 3W3
Project Description: This application is for the installation of dust collector emitting purified salicylic acid crystals exhausting to the atmosphere, connected to a bag dumping station.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	28 of 87	SE/250.0	80.8 / 1.95	LEVER BROTHERS LIMITED 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2	CA

Certificate #: 8-3021-87-
Application Year: 87
Issue Date: 6/19/1987
Approval Type: Industrial air

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: LIQUID DETERGENT MIXING
Contaminants:
Emission Control:

---

325 **29 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **CA**

Certificate #: 8-3101-96-006
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC
Contaminants:
Emission Control:

---

325 **30 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **CA**

Certificate #: 8/300/029/80/806
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: This application is requesting a name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

---

325 **31 of 87** **SE/250.0** **80.8 / 1.95** **LEVER BROTHERS LIMITED 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2** **CA**

Certificate #: 8-3022-87-
Application Year: 87
Issue Date: 6/19/1987
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: LIQUID DETERGENT MIXING
Contaminants:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Emission Control:

---

325 **32 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **CA**

Certificate #: 2780-4P5RW8
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: This application is requesting a name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

---

325 **33 of 87** **SE/250.0** **80.8 / 1.95** **LEVER BROTHERS 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2** **CA**

Certificate #: 8-3118-88-
Application Year: 88
Issue Date: 9/12/1989
Approval Type: Industrial air
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: DUST COLL FOR STORAGE AND PROCESS
Contaminants:
Emission Control:

---

325 **34 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **CA**

Certificate #: 8-3063-91-006
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

---

325 **35 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **CA**

Certificate #: 4111-4H7K4S
Application Year: 02

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: This application is requesting a name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

325	36 of 87	SE/250.0	80.8 / 1.95	LEVER A DIVISION OF U L CANADA INC. 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2	CA

Certificate #: 8-3101-96-
Application Year: 96
Issue Date: 5/9/1996
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: SEC. CONT.FOR TWO ALKYLATE STORAGE TANKS
Contaminants: Other Organic Compounds
Emission Control: No Controls

325	37 of 87	SE/250.0	80.8 / 1.95	LEVER BROTHERS LIMITED 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2	CA

Certificate #: 8-3222-88-
Application Year: 88
Issue Date: 5/3/1989
Approval Type: Industrial air
Status: Approved in 1989
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: 3 BAGHOUSES FOR POWDER PACKING MACHINES
Contaminants: Suspended Particulate Matter
Emission Control: Baghouse (Incl Vent Fil.)

325	38 of 87	SE/250.0	80.8 / 1.95	LEVER A DIVISION OF U L CANADA INC. 21 DON VALLEY PARKWAY TORONTO ON M4M 3P2	CA

Certificate #: 8-3657-98-
Application Year: 98
Issue Date: 12/18/1998
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Client City:
Client Postal Code:
Project Description: REPLACE GAS BOILER/STACK+REROUTE VENTS
Contaminants: Nitrogen Oxides
Emission Control: No Controls

---

325 | 39 of 87 | SE/250.0 | 80.8 / 1.95 | LEVER POND'S, DIV. OF U.L. CANADA INC.
21 DON VALLEY PARKWAY
TORONTO CITY ON M4M 3P2 | CA

Certificate #: 8-3418-96-
Application Year: 96
Issue Date: 9/5/1996
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: SINGLE ALCOHOL STORAGE TANK
Contaminants: Ethyl Alcohol,Denat,D
Emission Control: No Controls

---

325 | 40 of 87 | SE/250.0 | 80.8 / 1.95 | 21 Don Valley Parkway
Toronto ON M4M 3P2 | CA

Certificate #: 8-3111-92-006
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

---

325 | 41 of 87 | SE/250.0 | 80.8 / 1.95 | 21 Don Valley Parkway
Toronto ON M4M 3P2 | CA

Certificate #: 8-3418-96-006
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	42 of 87	SE/250.0	80.8 / 1.95	21 Don Valley Parkway Toronto ON M4M 3P2	CA

Certificate #: 8/300/139/90/906
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: This application is requesting a name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	43 of 87	SE/250.0	80.8 / 1.95	21 Don Valley Parkway Toronto ON M4M 3P2	CA

Certificate #: 8-3180-89-006
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: Administrative name change from U L Canada Inc. to Korex Don Valley ULC
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	44 of 87	SE/250.0	80.8 / 1.95	LEVER A DIVISION OF U L CANADA INC. 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2	CA

Certificate #: 8-3179-93-
Application Year: 93
Issue Date: 4/28/1993
Approval Type: Industrial air
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: CLOSE DISHWASHER DET. POWDER MFG. FAC.
Contaminants:
Emission Control:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	45 of 87	SE/250.0	80.8 / 1.95	LEVER POND'S, DIV. OF U.L. CANADA INC. 21 DON VALLEY PARKWAY TORONTO CITY ON M4M 3P2	CA

Certificate #: 8-3050-99-
Application Year: 99
Issue Date: 3/9/1999
Approval Type: Industrial air
Status: Approved

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: INSTALL FOUR NEW STEAM BOILERS
Contaminants:
Emission Control:

---

325 **46 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **CA**

Certificate #: 8/300/034/89/896
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: This application is requesting a name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

---

325 **47 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **CA**

Certificate #: 8-3108-78-006
Application Year: 02
Issue Date: 9/30/02
Approval Type: Industrial air
Status: Approved
Application Type: Notice
Client Name: Korex Don Valley ULC
Client Address: 21 Don Valley Parkway
Client City: Toronto
Client Postal Code: M4M 3P2
Project Description: This application is requesting a name change from U L Canada Inc. to Korex Don Valley ULC.
Contaminants:
Emission Control:

---

325 **48 of 87** **SE/250.0** **80.8 / 1.95** **21 The Don Roadway Toronto ON M4M** **EHS**

Order No: 20181130056
Status: C
Report Type: Custom Report
Report Date: 04-DEC-18
Date Received: 30-NOV-18
Previous Site Name:
Lot/Building Size: 116,848 m2
Additional Info Ordered: Fire Insur. Maps and/or Site Plans
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .3
X: -79.345948
Y: 43.653802

---

325 **49 of 87** **SE/250.0** **80.8 / 1.95** **21 Don Valley Parkway Toronto ON M4M 3P2** **EHS**

Order No: 20110705010
Nearest Intersection:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Status:	C	**Municipality:**	
Report Type:	Custom Report	**Client Prov/State:**	ON
Report Date:	7/11/2011	**Search Radius (km):**	0.25
Date Received:	7/5/2011 9:56:40 AM	**X:**	-79.347721
Previous Site Name:		**Y:**	43.653204
Lot/Building Size:			
Additional Info Ordered:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	50 of 87	SE/250.0	80.8 / 1.95	21 Don Valley Parkway Toronto ON M4M 3P2	EHS

Order No:	20070730063	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	CAN - Custom Report	**Client Prov/State:**	
Report Date:	9/13/2007	**Search Radius (km):**	1
Date Received:	7/30/2007	**X:**	0.000002
Previous Site Name:		**Y:**	43.653504
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps And /or Site Plans		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	51 of 87	SE/250.0	80.8 / 1.95	First Gulf Don Valley Limited 21 Don Roadway Toronto ON M4M2M2	GEN

Generator No:	ON7218415	**PO Box No:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Dec 2018	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class:	251 L
Waste Class Desc:	Waste oils/sludges (petroleum based)

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	52 of 87	SE/250.0	80.8 / 1.95	Unilever Canada Inc. 21 Don Valley Parkway Toronto ON M4M 3P2	GEN

Generator No:	ON4600725	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2012	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	325610		
SIC Description:	Soap and Cleaning Compound Manufacturing		

Detail(s)

Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

325 ***53 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***Toronto Transit Commission*** ***GEN***
21 DON ROADWAY BUILDING 41
TORONTO ON M4M 3P2

Generator No: ON4701954
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 253 L
Waste Class Desc: Emulsified oils

---

325 ***54 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***North Tunnel Constructors ULC North Tunnel Constructors ULC*** ***GEN***
21 Don Roadway
Toronto ON M4M1B7

Generator No: ON7812986
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

325 ***55 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***ENBRIDGE GAS DISTRIBUTION INC.*** ***GEN***
21 DON ROADWAY
TORONTO ON M4M 3P2

Generator No: ON7077830
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 221210
SIC Description: NATURAL GAS DISTRIBUTION

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

325 ***56 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***Unilever Canada Inc.*** ***GEN***
21 Don Valley Parkway
Toronto ON M4M 3P2

Generator No: ON4600725
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 325610
SIC Description: Soap and Cleaning Compound Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

325 ***57 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***Unilever Canada Inc.*** ***GEN***
21 Don Valley Parkway
Toronto ON M4M 3P2

Generator No: ON4600725
Status:
Approval Years: 06,07,08
Contam. Facility:
MHSW Facility:
SIC Code: 325610
SIC Description: Soap and Cleaning Compound Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

325 ***58 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***KOREX DON VALLEY ULC*** ***GEN***
21 DON VALLEY PARKWAY
TORONTO ON M4M 3P2

Generator No:	ON0171007	**PO Box No:**	
Status:		**Country:**	
Approval Years:	02,03,04,05,06,07,08	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	325610		
SIC Description:	Soap & Cleaning Compound Mfg.		

Detail(s)

Waste Class:	268
Waste Class Desc:	AMINES
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	123
Waste Class Desc:	ALKALINE PHOSPHATES
Waste Class:	133
Waste Class Desc:	BRINES, CHLOR-ALKALI WASTES
Waste Class:	242
Waste Class Desc:	HALOGENATED PESTICIDES
Waste Class:	243
Waste Class Desc:	PCB'S
Waste Class:	150
Waste Class Desc:	INERT INORGANIC WASTES
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	261
Waste Class Desc:	PHARMACEUTICALS
Waste Class:	262
Waste Class Desc:	DETERGENTS/SOAPS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	265

Waste Class Desc: GRAPHIC ART WASTES

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

---

325 ***59 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***ENBRIDGE GAS DISTRIBUTION INC.***
21 DON ROADWAY
TORONTO ON M4M 3P2 ***GEN***

Generator No: ON7077830
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 221210
SIC Description: NATURAL GAS DISTRIBUTION

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

325 ***60 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***S. Funtig & Associates Inc.***
21 Don Valley Parkway
Toronto ON M4M 3P2 ***GEN***

Generator No: ON8766561
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 339990
SIC Description: All Other Miscellaneous Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

325 | **61 of 87** | **SE/250.0** | **80.8 / 1.95** | **UNILEVER CANADA HPCNA TORONTO**
21 DON VALLEY PARKWAY
TORONTO ON M4M 3P2 | **GEN**

Generator No: ON0171007
Status:
Approval Years: 00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3761
SIC Description: SOAP/CLEANING COMP.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 243
Waste Class Desc: PCB'S

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 123
Waste Class Desc: ALKALINE PHOSPHATES

Waste Class: 133
Waste Class Desc: BRINES, CHLOR-ALKALI WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

---

325 ***62 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***First Gulf Don Valley Limited*** ***GEN***
21 Don Roadway
Toronto ON M4M2M2

Generator No: ON7218415
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

325 ***63 of 87*** ***SE/250.0*** ***80.8 / 1.95*** ***KOREX DON VALLEY ULC*** ***GEN***
21 DON VALLEY PARKWAY
TORONTO ON M4M 3P2

Generator No: ON0171007
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 325610
SIC Description: Soap and Cleaning Compound Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145

Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	150
Waste Class Desc:	INERT INORGANIC WASTES
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	261
Waste Class Desc:	PHARMACEUTICALS
Waste Class:	262
Waste Class Desc:	DETERGENTS/SOAPS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	265
Waste Class Desc:	GRAPHIC ART WASTES
Waste Class:	267
Waste Class Desc:	ORGANIC ACIDS
Waste Class:	312
Waste Class Desc:	PATHOLOGICAL WASTES
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES

325	***64 of 87***	***SE/250.0***	***80.8 / 1.95***	***LEVER (SEE & USE ON0171007)*** ***21 DON VALLEY PARKWAY*** ***TORONTO ON M4M 3P2***	***GEN***

Generator No:	ON2489202	***PO Box No:***	
Status:		***Country:***	
Approval Years:	00,01	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	3761		
SIC Description:	SOAP/CLEANING COMP.		

Detail(s)

Waste Class:	133
Waste Class Desc:	BRINES, CHLOR-ALKALI WASTES
Waste Class:	121
Waste Class Desc:	ALKALINE WASTES - HEAVY METALS
Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	123
Waste Class Desc:	ALKALINE PHOSPHATES
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	261
Waste Class Desc:	PHARMACEUTICALS
Waste Class:	262
Waste Class Desc:	DETERGENTS/SOAPS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	267
Waste Class Desc:	ORGANIC ACIDS
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS
Waste Class:	242
Waste Class Desc:	HALOGENATED PESTICIDES
Waste Class:	243
Waste Class Desc:	PCB'S

325 | ***65 of 87*** | ***SE/250.0*** | ***80.8 / 1.95*** | ***ENBRIDGE GAS DISTRIBUTION INC.***
21 DON ROADWAY
TORONTO ON M4M 3P2 | ***GEN***

Generator No:	ON7077830	***PO Box No:***	
Status:		***Country:***	Canada
Approval Years:	2016	***Choice of Contact:***	CO_OFFICIAL
Contam. Facility:	No	***Co Admin:***	

MHSW Facility: No
SIC Code: 221210
SIC Description: NATURAL GAS DISTRIBUTION
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

325 | **66 of 87** | **SE/250.0** | **80.8 / 1.95** | **Unilever Canada Inc.**
21 Don Valley Parkway
Toronto ON M4M 3P2 | **GEN**

Generator No: ON4600725
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 325610
SIC Description: Soap and Cleaning Compound Manufacturing
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 267
Waste Class Desc: ORGANIC ACIDS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 114

Waste Class Desc: OTHER INORGANIC ACID WASTES

---

325 | **67 of 87** | **SE/250.0** | **80.8 / 1.95** | **Jellystone Films Inc.** | **GEN**
21 Don Roadway
Toronto ON M4M 3P2

Generator No: ON3701724
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 512110
SIC Description: MOTION PICTURE AND VIDEO PRODUCTION

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

325 | **68 of 87** | **SE/250.0** | **80.8 / 1.95** | **North Tunnel Constructors ULC North Tunnel Constructors ULC** | **GEN**
21 Don Roadway
Toronto ON M4M1B7

Generator No: ON7812986
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

325 | **69 of 87** | **SE/250.0** | **80.8 / 1.95** | **Unilever Canada Inc.** | **GEN**
21 Don Valley Parkway
Toronto ON M4M 3P2

Generator No: ON4600725
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 325610
SIC Description: Soap and Cleaning Compound Manufacturing

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 221

Waste Class Desc:	LIGHT FUELS
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	262
Waste Class Desc:	DETERGENTS/SOAPS
Waste Class:	222
Waste Class Desc:	HEAVY FUELS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	114
Waste Class Desc:	OTHER INORGANIC ACID WASTES
Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	267
Waste Class Desc:	ORGANIC ACIDS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES

325 | ***70 of 87*** | ***SE/250.0*** | ***80.8 / 1.95*** | ***21 DON VALLEY PARKWAY TORONTO ON M4M 3P2*** | ***HINC***

External File Num:	FS INC 0905-02848
Fuel Occurrence Type:	
Date of Occurrence:	
Fuel Type Involved:	
Status Desc:	Completed - No Action Required
Job Type Desc:	Incident/Near-Miss Occurrence (FS)
Oper. Type Involved:	
Service Interruptions:	
Property Damage:	
Fuel Life Cycle Stage:	
Root Cause:	
Reported Details:	Non-mandated. FS Inspector Ralph Schubert has declined investigation since Controlled vapour release
Fuel Category:	Gaseous Fuel
Occurrence Type:	Incident
Affiliation:	Industry Stakeholder (Licensee/Registration/Certificate Holder, Facility Owner, etc.)
County Name:	Toronto
Approx. Quant. Rel:	
Nearby body of water:	
Enter Drainage Syst.:	
Approx. Quant. Unit:	
Environmental Impact:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	71 of 87	SE/250.0	80.8 / 1.95	21 DON VALLEY PARKWAY TORONTO ON M4M 3P2	HINC

External File Num: FS INC 0905-02482
Fuel Occurrence Type: Vapour Release
Date of Occurrence: 5/8/2009
Fuel Type Involved: Propane
Status Desc: Completed - Causal Analysis(End)
Job Type Desc: Incident/Near-Miss Occurrence (FS)
Oper. Type Involved: Industrial/Manufacturing Facility (including OEM)
Service Interruptions: No
Property Damage: No
Fuel Life Cycle Stage: Utilization
Root Cause: Root Cause: Equipment/Material/Component:No Procedures:No Maintenance:No Design:No Training:No Management:No Human Factors:Yes
Reported Details: Korex Don Valley ULC.
Fuel Category: Gaseous Fuel
Occurrence Type: Near-miss
Affiliation: Emergency Services (Fire, Police,etc)
County Name: Toronto
Approx. Quant. Rel:
Nearby body of water:
Enter Drainage Syst.:
Approx. Quant. Unit:
Environmental Impact:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	72 of 87	SE/250.0	80.8 / 1.95	LEVER POND'S A DIV. OF UL CANADA INC. 1 SUNLIGHT PARK ROAD TORONTO ON M4M 1B6	NPRI

NPRI ID: 0000003658
Other ID: Y
No Other ID: 1
Track ID:
Report ID:
Report Type:
Rpt Type ID:
Report Year: 1997
Not-Current Rpt?:
Yr of Last Filed Rpt:
Fac ID:
Fac Name:
Fac Address1:
Fac Address2:
Fac Postal Zip:
Facility Lat:
Facility Long:
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts: FALSE
URL:
No of Empl.: 670
Parent Co.: Y
No Parent Co.: 1
Pollut Prev Cmnts: FALSE
Stacks:
No of Stacks:
Canadian SIC Code (2 digit): 37
Canadian SIC Code: 3761
SIC Code Description: Soap & Cleaning Compounds Ind.
American SIC Code: 2841
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing

Org ID:
Submit Date:
Last Modified:
Contact ID:
Cont Type: MED
Contact Title: Mrs.
Cont First Name: CATHERINE
Cont Last Name: MCVITTY
Contact Position: ENVTL. & CORP. AFFAIRS MANAGER
Contact Fax:
Contact Ph.:
Cont Area Code: 416
Contact Tel.: 4153000
Contact Ext.: 3164
Cont Fax Area Cde: 416
Contact Fax: 4153133
Contact Email:
Latitude: 43.6534
Longitude: -79.3475
UTM Zone: 17
UTM Northing: 4834700
UTM Easting: 633000
Waste Streams: FALSE
No Streams: 0
Waste Off Sites: TRUE
No Off Sites: 2
Shutdown:
No of Shutdown:

NAICS Code (4 digit):	3256
NAICS 4 Description:	Soap, Cleaning Compound and Toilet Preparation Manufacturing
NAICS Code (6 digit):	325610
NAICS 6 Description:	Soap and Cleaning Compound Manufacturing

Substance Release Report

CAS No:	NA - 14
Report ID:	
Rpt Period:	1997
Subst Released:	Zinc (and its compounds)
Air:	
Water:	
Land:	
Total Releases:	.002
Units:	tonnes

CAS No:	139-13-9
Report ID:	
Rpt Period:	1997
Subst Released:	Nitrilotriacetic acid (and its salts)
Air:	2.6
Water:	
Land:	
Total Releases:	2.6
Units:	tonnes

CAS No:	7664-93-9
Report ID:	
Rpt Period:	1997
Subst Released:	Sulphuric acid
Air:	
Water:	
Land:	
Total Releases:	.13
Units:	tonnes

---

325 | ***73 of 87*** | ***SE/250.0*** | ***80.8 / 1.95*** | ***KOREX DON VALLEY ULC***
21 DON VALLEY PARKWAY NOT AVAILABLE
TORONTO ON M4M3P2 | ***NPRI***

NPRI ID:	3658	**Org ID:**	54310
Other ID:	N	**Submit Date:**	5/22/2009
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	63489	**Contact ID:**	
Report ID:	124928	**Cont Type:**	
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2008	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2008	**Contact Fax:**	
Fac ID:	115158	**Contact Ph.:**	
Fac Name:	DON VALLEY PLANT	**Cont Area Code:**	
Fac Address1:	21 DON VALLEY PARKWAY	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	M4M3P2	**Cont Fax Area Cde:**	
Facility Lat:	43.6534	**Contact Fax:**	
Facility Long:	-79.3475	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.6534
Facility DLS:		**Longitude:**	-79.3475
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:	www.korex-us.com	**UTM Easting:**	
No of Empl.:	226	**Waste Streams:**	No

Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	No
Pollut Prev Cmnts:	No	**No Off Sites:**	
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3256
NAICS 4 Description: Soap, cleaning compound and toilet preparation manufacturing
NAICS Code (6 digit): 325610
NAICS 6 Description: Soap and Cleaning Compound Manufacturing

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: .868
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Nitrilotriacetic acid (and its salts)
Chem (fr): Acide nitrilotriacétique (et ses sels)
Quantity: .069
Unit: tonnes
Basis of Estimate Cd: E1
Basis of Estimate Desc: E1- Site Specific Emission Factors - In use from 2003 and onward

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: .835
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: Sulphuric acid
Chem (fr): Acide sulfurique
Quantity: .15
Unit: tonnes
Basis of Estimate Cd: C
Basis of Estimate Desc: C- Mass Balance

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
325	74 of 87	SE/250.0	80.8 / 1.95	Lever Pond's - A Division of U L Canada Inc. 1 Sunlight Park Road Toronto ON M4M 1B6	NPRI

NPRI ID:	0000003658	**Org ID:**	
Other ID:	Y	**Submit Date:**	
No Other ID:	1	**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	Mrs.
Rpt Type ID:		**Cont First Name:**	Catherine
Report Year:	1998	**Cont Last Name:**	McVitty
Not-Current Rpt?:		**Contact Position:**	Corporate Affairs Manager
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:		**Cont Area Code:**	416
Fac Address1:		**Contact Tel.:**	4153000
Fac Address2:		**Contact Ext.:**	3164
Fac Postal Zip:		**Cont Fax Area Cde:**	416
Facility Lat:		**Contact Fax:**	4153133
Facility Long:		**Contact Email:**	Catherine.McVitty@Unilever.com
DLS (Last Filed Rpt):		**Latitude:**	43.6534
Facility DLS:		**Longitude:**	-79.3475
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	False	**UTM Northing:**	4834700
URL:	www.unilever.com	**UTM Easting:**	633000
No of Empl.:	670	**Waste Streams:**	False
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	Fals
Pollut Prev Cmnts:	False	**No Off Sites:**	2
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):	37
Canadian SIC Code:	3761
SIC Code Description:	Soap & Cleaning Compounds Ind.
American SIC Code:	2841
NAICS Code (2 digit):	31-33
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3256
NAICS 4 Description:	Soap, Cleaning Compound and Toilet Preparation Manufacturing
NAICS Code (6 digit):	325610
NAICS 6 Description:	Soap and Cleaning Compound Manufacturing

Substance Release Report

CAS No:	7664-93-9
Report ID:	
Rpt Period:	1998
Subst Released:	Sulphuric acid
Air:	
Water:	
Land:	
Total Releases:	.025
Units:	tonnes

CAS No:	139-13-9
Report ID:	
Rpt Period:	1998
Subst Released:	Nitrilotriacetic acid (and its salts)
Air:	1.7
Water:	
Land:	
Total Releases:	1.7

Units: tonnes

CAS No: NA - 14
Report ID:
Rpt Period: 1998
Subst Released: Zinc (and its compounds)
Air:
Water:
Land:
Total Releases: .002
Units: tonnes

---

325 | **75 of 87** | **SE/250.0** | **80.8 / 1.95** | **LEVER, A DIVISION OF UL CANADA INC.**
1 SUNLIGHT PARK ROAD
TORONTO ON M4M 1B6 | **NPRI**

NPRI ID:	0000003658	**Org ID:**	
Other ID:	TRUE	**Submit Date:**	
No Other ID:	1	**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	
Rpt Type ID:		**Cont First Name:**	CATHERINE
Report Year:	1994	**Cont Last Name:**	MCVITTY
Not-Current Rpt?:		**Contact Position:**	
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:		**Cont Area Code:**	416
Fac Address1:		**Contact Tel.:**	4619432
Fac Address2:		**Contact Ext.:**	2523
Fac Postal Zip:		**Cont Fax Area Cde:**	416
Facility Lat:		**Contact Fax:**	7782524
Facility Long:		**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.6534
Facility DLS:		**Longitude:**	-79.3475
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	FALSE	**UTM Northing:**	4834700
URL:		**UTM Easting:**	633000
No of Empl.:	493	**Waste Streams:**	FALSE
Parent Co.:	TRUE	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	TRUE
Pollut Prev Cmnts:		**No Off Sites:**	1
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit): 37
Canadian SIC Code: 3761
SIC Code Description: Soap & Cleaning Compounds Ind.
American SIC Code: 2841
NAICS Code (2 digit): 32
NAICS 2 Description: Manufacturing
NAICS Code (4 digit): 3256
NAICS 4 Description: Soap, Cleaning Compound and Toilet Preparation Manufacturing
NAICS Code (6 digit): 325610
NAICS 6 Description: Soap and Cleaning Compound Manufacturing

Substance Release Report

CAS No: 139-13-9
Report ID:
Rpt Period: 1994
Subst Released: Nitrilotriacetic acid
Air:
Water:
Land:

Total Releases:	.49
Units:	tonnes
CAS No:	7664-93-9
Report ID:	
Rpt Period:	1994
Subst Released:	Sulphuric acid
Air:	
Water:	
Land:	
Total Releases:	0
Units:	tonnes

325 | **76 of 87** | **SE/250.0** | **80.8 / 1.95** | **Lever Pond's, A Division of U L Canada Inc.**
1 Sunlight Park Road
Toronto ON M4M 1B6 | **NPRI**

NPRI ID:	0000003658	**Org ID:**	
Other ID:	Y	**Submit Date:**	
No Other ID:	1	**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	
Rpt Type ID:		**Cont First Name:**	Catherine
Report Year:	1995	**Cont Last Name:**	McVitty
Not-Current Rpt?:		**Contact Position:**	
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:		**Cont Area Code:**	416
Fac Address1:		**Contact Tel.:**	4619432
Fac Address2:		**Contact Ext.:**	2523
Fac Postal Zip:		**Cont Fax Area Cde:**	416
Facility Lat:		**Contact Fax:**	7782524
Facility Long:		**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.6534
Facility DLS:		**Longitude:**	-79.3475
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	FALSE	**UTM Northing:**	4834700
URL:		**UTM Easting:**	633000
No of Empl.:	473	**Waste Streams:**	FALSE
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	TRUE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	1
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):	37
Canadian SIC Code:	3761
SIC Code Description:	Soap & Cleaning Compounds Ind.
American SIC Code:	2841
NAICS Code (2 digit):	32
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3256
NAICS 4 Description:	Soap, Cleaning Compound and Toilet Preparation Manufacturing
NAICS Code (6 digit):	325610
NAICS 6 Description:	Soap and Cleaning Compound Manufacturing

Substance Release Report

CAS No:	139-13-9
Report ID:	
Rpt Period:	1995
Subst Released:	Nitrilotriacetic acid (and its salts)
Air:	
Water:	

Land:	
Total Releases:	.5
Units:	tonnes
CAS No:	7664-93-9
Report ID:	
Rpt Period:	1995
Subst Released:	Sulphuric acid
Air:	
Water:	
Land:	
Total Releases:	.005
Units:	tonnes

---

325 | ***77 of 87*** | ***SE/250.0*** | ***80.8 / 1.95*** | ***Lever Pond's, A Division of U L Canada Inc.***
1 Sunlight Pk. Rd.
Toronto ON M4M 1B6 | ***NPRI***

NPRI ID:	0000003658	**Org ID:**	
Other ID:	Y	**Submit Date:**	
No Other ID:	1	**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	Mrs.
Rpt Type ID:		**Cont First Name:**	Catherine
Report Year:	1996	**Cont Last Name:**	McVitty
Not-Current Rpt?:		**Contact Position:**	Environmental Affairs Manager
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:		**Cont Area Code:**	416
Fac Address1:		**Contact Tel.:**	4622200
Fac Address2:		**Contact Ext.:**	2523
Fac Postal Zip:		**Cont Fax Area Cde:**	416
Facility Lat:		**Contact Fax:**	7782524
Facility Long:		**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.6534
Facility DLS:		**Longitude:**	-79.3475
Datum:	1983	**UTM Zone:**	17
Facility Cmnts:	FALSE	**UTM Northing:**	4834700
URL:		**UTM Easting:**	633000
No of Empl.:	600	**Waste Streams:**	FALSE
Parent Co.:	Y	**No Streams:**	0
No Parent Co.:	1	**Waste Off Sites:**	TRUE
Pollut Prev Cmnts:	FALSE	**No Off Sites:**	3
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):	37
Canadian SIC Code:	3761
SIC Code Description:	Soap & Cleaning Compounds Ind.
American SIC Code:	2841
NAICS Code (2 digit):	32
NAICS 2 Description:	Manufacturing
NAICS Code (4 digit):	3256
NAICS 4 Description:	Soap, Cleaning Compound and Toilet Preparation Manufacturing
NAICS Code (6 digit):	325610
NAICS 6 Description:	Soap and Cleaning Compound Manufacturing

Substance Release Report

CAS No:	84-66-2
Report ID:	
Rpt Period:	1996
Subst Released:	Diethyl phthalate
Air:	

Water:	
Land:	
Total Releases:	0
Units:	tonnes
CAS No:	139-13-9
Report ID:	
Rpt Period:	1996
Subst Released:	Nitrilotriacetic acid (and its salts)
Air:	
Water:	
Land:	
Total Releases:	.52
Units:	tonnes
CAS No:	7664-93-9
Report ID:	
Rpt Period:	1996
Subst Released:	Sulphuric acid
Air:	
Water:	
Land:	
Total Releases:	.004
Units:	tonnes

---

325 | ***78 of 87*** | ***SE/250.0*** | ***80.8 / 1.95*** | ***Korex Don Valley ULC***
21 Don Valley Pky
Toronto ON M4M 3P2 | ***SCT***

Established:	6/1/2001
Plant Size (ft²):	
Employment:	

--Details--

Description:	Soap and Cleaning Compound Manufacturing
SIC/NAICS Code:	325610
Description:	Soap and Cleaning Compound Manufacturing
SIC/NAICS Code:	325610

---

325 | ***79 of 87*** | ***SE/250.0*** | ***80.8 / 1.95*** | ***Tesla Environmental Services Inc.***
21 Don Roadway
Toronto ON | ***SPL***

Ref No:	0334-A3VNPQ	**Discharger Report:**	
Site No:	NA	**Material Group:**	
Incident Dt:	10/31/2015	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Miscellaneous Industrial
Incident Event:		**Agency Involved:**	
Contaminant Code:	15	**Nearest Watercourse:**	
Contaminant Name:	Oily Water	**Site Address:**	21 Don Roadway
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	Toronto
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	4834519
MOE Response:	No	**Easting:**	633265
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	11/2/2015	**Site Map Datum:**	

Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:	Equipment Failure	**Source Type:**	
Site Name:	DVP ramp <UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Toronto- Watermain break		
Contaminant Qty:	20000 L		

---

325 | **80 of 87** | **SE/250.0** | **80.8 / 1.95** | **Korex Don Valley ULC**
21 Don Valley Pky
Toronto ON M4M 3P2 | **SPL**

Ref No:	0684-6YUR5B	**Discharger Report:**	
Site No:		**Material Group:**	Chemicals
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Pipe Or Hose Leak	**Sector Type:**	Other
Incident Event:		**Agency Involved:**	
Contaminant Code:	27	**Nearest Watercourse:**	
Contaminant Name:	Sulphonic acid	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Toronto
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:	Land	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:	No Field Response	**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2/28/2007	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:		**Source Type:**	
Site Name:	21 Don Valley Parkway		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Korex Don Valley: spill sulphonic acid to grnd, cleaning		
Contaminant Qty:	300 L		

---

325 | **81 of 87** | **SE/250.0** | **80.8 / 1.95** | **Korex Don Valley ULC**
21 Don Valley Parkway
Toronto ON M4M 3P2 | **SPL**

Ref No:	0216-5PW6TW	**Discharger Report:**	
Site No:		**Material Group:**	Miscellaneous
Incident Dt:	7/28/2003	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Discharge or Emission to Air	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:	96	**Nearest Watercourse:**	
Contaminant Name:	FATTY ACID	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Toronto
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	Central
Environment Impact:	Possible	**Site Municipality:**	Toronto
Nature of Impact:	Other Impact(s)	**Site Lot:**	
Receiving Medium:	Air	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:		**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/28/2003	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Spill to Air
Incident Reason:	Overstress/Pressure - Any form of overloading	**Source Type:**	

wherein the design strength of the container was exceeded

Site Name: 21 DON VALLEY PARKWAY
Site County/District:
Site Geo Ref Meth:
Incident Summary: Korex- strong odours large area, FD.
Contaminant Qty:

---

325 | **82 of 87** | **SE/250.0** | **80.8 / 1.95** | **Korex Don Valley ULC**
21 Don Valley Pky
Toronto ON M4M 3P2 | **SPL**

Ref No:	6023-7CAS4J	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:		**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Unknown	**Sector Type:**	Sewer
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Toronto - District
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Toronto
Nature of Impact:	Other Impact(s)	**Site Lot:**	
Receiving Medium:		**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:	Referral to others	**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	2/29/2008	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Notifications
Incident Reason:	Process upset	**Source Type:**	

Site Name: 21 Don Valley Parkway
Site County/District:
Site Geo Ref Meth:
Incident Summary: Korex - Abnormal discharge of process effluent to sani-sewer
Contaminant Qty:

---

325 | **83 of 87** | **SE/250.0** | **80.8 / 1.95** | **s21**
21 Don Valley Parkway 21 DON VALLEY PARKWAY
Toronto ON M4M 3P2 | **SPL**

Ref No:	7321-6LFQSR	**Discharger Report:**	
Site No:		**Material Group:**	Chemicals
Incident Dt:	12/11/2005	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Unknown	**Sector Type:**	Other Plant - Organic Chemicals Manufacturing (MISA)
Incident Event:		**Agency Involved:**	
Contaminant Code:	24	**Nearest Watercourse:**	
Contaminant Name:	PROPYLENE GLYCOL %50	**Site Address:**	141 MCLEOD AVE
Contaminant Limit 1:		**Site District Office:**	Timmins
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Timmins
Nature of Impact:	Other Impact(s)	**Site Lot:**	
Receiving Medium:	Water	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:		**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	5/4/2006	**Site Map Datum:**	

Dt Document Closed:
Incident Reason: Fire/Explosion - Resulting from fires/explosions (Not occurrences which cause a fire or explosion)
Site Name: 141 MCLEOD AVE
Site County/District:
Site Geo Ref Meth:
Incident Summary: 2000LPropylene Glycol to Sanitary sewer
Contaminant Qty: 2000 L
SAC Action Class:
Source Type:

---

325 | **84 of 87** | **SE/250.0** | **80.8 / 1.95** | **Korex Don Valley ULC**
21 Don Valley Parkway
Toronto ON M4M 3P2 | **SPL**

Ref No: 6862-65FS7C
Site No:
Incident Dt: 10/1/2004
Year:
Incident Cause: Other Discharges
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Soil Contamination
Receiving Medium: Land
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 10/4/2004
Dt Document Closed:
Incident Reason: Other - Reason not otherwise defined
Site Name: 21 DON VALLEY PARKWAY
Site County/District:
Site Geo Ref Meth:
Incident Summary: Korex Don Valley - Water and Sani Line Break
Contaminant Qty:
Discharger Report:
Material Group: Miscellaneous
Health/Env Conseq:
Client Type:
Sector Type: Other Plant
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Toronto
Site Postal Code:
Site Region: Central
Site Municipality: Toronto
Site Lot:
Site Conc:
Northing: NA
Easting: NA
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Spill to Land
Source Type:

---

325 | **85 of 87** | **SE/250.0** | **80.8 / 1.95** | **Korex Don Valley ULC**
21 Don Valley Pky
Toronto ON M4M 3P2 | **SPL**

Ref No: 7726-7GRPYP
Site No:
Incident Dt:
Year:
Incident Cause: Other Discharges
Incident Event:
Contaminant Code: 21
Contaminant Name: SULFONIC ACID
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Possible
Nature of Impact: Groundwater Pollution; Soil Contamination; Surface Water Pollution
Receiving Medium:
Receiving Env:
MOE Response: Referral to others
Dt MOE Arvl on Scn:
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Train
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office: Toronto - District
Site Postal Code:
Site Region:
Site Municipality: Toronto
Site Lot:
Site Conc:
Northing: NA
Easting: NA
Site Geo Ref Accu:

MOE Reported Dt:	7/21/2008	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Notifications
Incident Reason:	Unknown - Reason not determined	**Source Type:**	
Site Name:	21 Don Valley Parkway		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Korex:Possible tampering with railcar carrying sulfonic acid		
Contaminant Qty:	other - see incident description		

---

325 | **86 of 87** | **SE/250.0** | **80.8 / 1.95** | **Korex Don Valley ULC**
21 Don Valley Parkway
Toronto ON M4M 3P2 | **SPL**

Ref No:	1425-6FMMDB	**Discharger Report:**	0
Site No:		**Material Group:**	Chemical
Incident Dt:	8/26/2005	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Other Plant
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:	Fabric Softener	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Toronto
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Not Anticipated	**Site Municipality:**	Toronto
Nature of Impact:		**Site Lot:**	
Receiving Medium:	Water	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:		**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/26/2005	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Primary Assessment of Spills
Incident Reason:		**Source Type:**	
Site Name:	21 Don Valley Parkway		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Korex, 16.5 MT of fabric softener to Toronto Sanitary Sewer		
Contaminant Qty:			

---

325 | **87 of 87** | **SE/250.0** | **80.8 / 1.95** | **Korex Don Valley ULC**
21 Don Valley Parkway
Toronto ON M4M 3P2 | **SPL**

Ref No:	4286-6FRKPA	**Discharger Report:**	0
Site No:		**Material Group:**	Chemical
Incident Dt:	8/30/2005	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:		**Sector Type:**	Pipeline
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:	Fabric Softener	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Toronto
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Confirmed	**Site Municipality:**	Toronto
Nature of Impact:		**Site Lot:**	
Receiving Medium:	Land	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:		**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	8/30/2005	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Primary Assessment of Spills

Incident Reason:		***Source Type:***	
Site Name:	21 Don Valley Parkway		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Underground pipe leak of fabric softener.		
Contaminant Qty:			

Unplottable Summary

Total: 95 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	TORONTO CITY DR. #LA-1162	QUEEN ST. EAST	TORONTO CITY ON	
CA	TORONTO CITY DR. #LA-1150	QUEEN ST. EAST	TORONTO CITY ON	
CA	CITY	QUEEN ST. E.	TORONTO ON	
CA		Queen Street East	Toronto ON	
CA	TORONTO CITY DR. NO. LA-1178	LANE 34.4. M. S. OF QUEEN ST.	TORONTO CITY ON	
CA	TORONTO CITY DR. # R-726	KING STREET EAST	TORONTO CITY ON	
CA		King Street East from Berkeley St to Sumach St	Toronto ON	
CA	TORONTO CITY DR. #R-699	FRONT ST. EAST	TORONTO CITY ON	
CA	CITY	FRONT ST.E.	TORONTO ON	
CA	CITY	FRONT ST.E.	TORONTO ON	
CA	BCE DEVELOPMENT CORPORATION-DWG.#W1-W10	FRONT ST./PEDESTRIAN TUNNEL	TORONTO CITY ON	
CA	BCE DEVELOPMENT CORPORATION DWG. #C1-C8	FRONT ST./REL. TTC FORCEMAIN C	TORONTO CITY ON	
CA	BCE DEVELOPMENT CORPORATION	FRONT STREET	TORONTO CITY ON	
CA	BCE DEVELOPMENT CORPORATION	FRONT STREET	TORONTO CITY ON	
CA	Ontario Realty Corporation	Eastern Ave	Toronto ON	
CA		Carroll Street, Public lane	Toronto ON	
CA	CITY	E.OF BROADVIEW AVE. (LANE)	TORONTO ON	

CA	TORONTO CITY	ADELAIDE ST. EAST	TORONTO CITY ON	
CA		Adelaide Street East	Toronto ON	
CA	TORONTO CITY	ADELAIDE ST./FRONT ST.E.	TORONTO CITY ON	
CA	PPM CANADA INC.	MOBILE PCB UNIT	TORONTO CITY ON	
CA	PPM CANADA INC.	WITHIN THE PROVINCE OF ONTARIO	TORONTO CITY ON	
CA	PPM CANADA INC.	MOBILE PCB UNIT	TORONTO CITY ON	
CA	Lafarge Canada Inc.	Mobile Facility - Model S	Toronto ON	
CA	Toronto Community Housing Corporation	Thompson St	Toronto ON	
CA	TORONTO CITY DWG. #LA-1199/CONT.#59405	LANE 92M N. OF QUEEN STREET E.	TORONTO CITY ON	
CA	TORONTO CITY QUEEN ST. E.	QUEEN ST. E. DR. #SB-438	TORONTO CITY ON	
CA	TORONTO CITY QUEEN ST. E. LA-1142	LANE 32.0 M N. OF QUEEN ST. E	TORONTO CITY ON	
CA	Her Majesty the Queen in Right of Ontario as Represented by the Minister of Ener	River Street, Mill Street and Bayview Ave	Toronto ON	
CA	City of Toronto	Adelaide Subdiv W	Toronto ON	
CHEM	LEVER BROTHERS LIMITED		TORONTO ON	
CONV	CANADIAN NATIONAL RAILWAY COMPANY		TORONTO ON	
CONV	ONTARIO SALVAGE LIMITED		TORONTO ON	
CONV	ONTARIO SALVAGE LIMITED		TORONTO ON	
EBR	Lafarge Canada Inc.	Mobile Unit Toronto CITY OF TORONTO	ON	
ECA	Toronto Community Housing Corporation	Thompson St	Toronto ON	M4W 2H2
ECA	Her Majesty the Queen in Right of Ontario as Represented by the Minister of	Public Infrastructure Renewal North of Mill Street between River Street and Bayview Avenue	Toronto ON	M5G 2L5
ECA	Her Majesty the Queen in Right of Ontario as Represented by the Minister of	Energy & Infrastructure River Street, Mill Street and Bayview Ave	Toronto ON	M5G 2L5
ECA	Ontario Realty Corporation	Eastern Ave	Toronto ON	M7A 2G3

ECA	City of Toronto	Carroll Street, Public Lane	Toronto ON	M2N 5V7
ECA	City of Toronto	Adelaide Street East	Toronto ON	M5V 3C6
ECA	City of Toronto	Adelaide Street East	Toronto ON	M5H 2N2
ECA	Toronto Community Housing Corporation	Thompson St	Toronto ON	M4W 2H2
ECA	Ontario Realty Corporation	Eastern Ave	Toronto ON	M7A 2G3
ECA	Lafarge Canada Inc.	Mobile Facility - Model S	Toronto ON	L4K 4G7
ECA	City of Toronto	Adelaide Subdiv W	Toronto ON	M5V 3C6
GEN	CANADIAN NATIONAL RAILWAY	VARIOUS SITES WITHIN THE MOEE CENTRAL REGION	(SEE SCHEDULE "B") ON	CNRAIL
GEN	TORONTO HYDRO	QUEEN STREET EAST ADJ. 468 VAULT #4176	TORONTO ON	
GEN	MIJO Corporation	Ste, 201	Toronto ON	M4T 1Z4
GEN	CANADIAN NATIONAL RAILWAY	CN SITES IN MOE S.W. REGION	(SEE SCHEDULE "B") ON	CNRAIL
GEN	CANADIAN NATIONAL RAILWAY	CN SITES IN MOE S.W. REGION	(SEE SCHEDULE "B") ON	CNRAIL
GEN	IMPERIAL OIL LTD. 21-164	PART LOT 4, CONC. 7 - TWP. OF TORONTO C/O P.O. BOX 380	WATERDOWN ON	L0R 2H0
GEN	IMPERIAL OIL LTD.	PART LOT 4, CONC. 7 - TWP. OF TORONTO C/O P.O. BOX 380	WATERDOWN ON	L0R 2H0
GEN	TORONTO HYDRO 38-544	QUEEN ST. E. ADJ. 468, VAULT 4176 C/O 14 CARLTON ST.	TORONTO ON	M5B 1K5
GEN	CANADIAN NATIONAL RAILWAY	CN SITES IN MOE S.W. REGION	(SEE SCHEDULE "B") ON	
GEN	CANADIAN NATIONAL RAILWAY	VARIOUS SITES WITHIN THE MOEE CENTRAL REGION	(SEE SCHEDULE "B") ON	
GEN	TORONTO, CITY OF	RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET	TORONTO ON	
GEN	TORONTO, CITY OF	RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET	TORONTO ON	
GEN	TORONTO, CITY OF	RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET	TORONTO ON	
GEN	D.M.Robichaud and Associates Ltd	Bayview Avenue	Toronto ON	M5A2E2
GEN	CANADIAN NATIONAL RAILWAY	CN SITES IN MOE S.W. REGION	(SEE SCHEDULE "B") ON	CNRAIL

GEN	TORONTO, CITY OF	RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET	TORONTO ON	
GEN	TORONTO, CITY OF	RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET	TORONTO ON	
GEN	CANADIAN NATIONAL RAILWAY	VARIOUS SITES WITHIN THE MOEE CENTRAL REGION	(SEE SCHEDULE "B") ON	CNRAIL
GEN	METRO TRANSPORTATION	DON VALLEY PARKWAY AT BRIDGE OVER CNBALA SUBDIV./DON RIVER(S. OF GRENOBLE DR.	TORONTO ON	
GEN	METRO TRANSPORTATION	DON VALLEY PKWY AT BRIDGE OVER CN BALA SUBDIVISION/DON RIVER S. OF GRENOBLE DR.	TORONTO ON	
GEN	METRO TRANSPORTATION	DON VALLEY PARKWAY AT BRIDGE OVER CNBALA SUBDIV./DON RIVER (S. OF GRENOBLE DR.)	TORONTO ON	
GEN	CANADIAN NATIONAL RAILWAY	VARIOUS SITES WITHIN THE MOEE CENTRAL REGION	(SEE SCHEDULE "B") ON	CNRAIL
GEN	TRANS-NORTHERN PIPELINES INC.	TORONTO METER STATION DON VALLEY PARKWAY AND LAKESHORE	TORONTO ON	
GEN	GAZZOLA PAVING LIMITED	BAYVIEW&BLOOR OFF THE DON VALLEY PARKWAY BETWEEN D.V.P. AND BAYVIEW NORTH SIDE	TORONTO ON	x0x0x0
GEN	CANADIAN NATIONAL RAILWAY	VARIOUS SITES WITHIN THE MOEE CENTRAL REGION	(SEE SCHEDULE "B") ON	
GEN	TORONTO, CITY OF	RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET	TORONTO ON	
GEN	TORONTO HYDRO	QUEEN ST. E. ADJ. 468, VAULT 4176 C/O 14 CARLTON ST.	TORONTO ON	M5B 1K5
LIMO	City of Toronto Riverdale Landfill	Between Broadview Ave and the DVP Between Montcrest Blvd and Victor Ave Toronto	ON	
LIMO	Sun Valley Landfill City of Toronto City of Toronto	Bayview Avenue, CPR & Don River Toronto	ON	
PTTW	EllisDon Ledcor PAAV Inc.	West Don Lands - Pan Am Games Athletes Village, Plan 66M-2488, City of Toronto CITY OF TORONTO	ON	
SCT	Molex Incorporated	Broadview Ave Suite 1580	Toronto ON	M4K 2R1
SCT	Motorcade Auto Parts		ON	
SPL	CANADA TRANSPORT GROUP	TRANSPORT TRUCK (CARGO)	TORONTO CITY ON	
SPL	CANADA PACKERS	CANADA PACKERS-SOAP PLANT TORONTO PLANT [ST. CLAIR AVENUE]	TORONTO CITY ON	
SPL	City of Toronto	on River St, South of King St East, 400 meters on eastside	Toronto ON	

SPL	CANADIAN NATIONAL RAILWAY	FROM TORONTO STN. TO GUILDWOOD STN. TRAIN	TORONTO CITY ON
SPL	CANADIAN NATIONAL RAILWAYS	TANK TRUCK (CARGO)	TORONTO CITY ON
SPL	IMPERIAL OIL	ESSO SERVICE STATION	TORONTO CITY ON
SPL	IMPERIAL OIL	ESSO SERVICE STATION	TORONTO CITY ON
SPL	LEVER BROS.	ATMOSPHERE TORONTO PLANT 1 SUNLIGHT PARK ROAD	TORONTO CITY ON
SPL	LEVER BROTHERS LTD.	LAKE ONTARIO TORONTO PLANT 1 SUNLIGHT PARK ROAD	TORONTO CITY ON
SPL		Bayview Ave. (Gerrad St. E to Queen St. E)	Toronto ON
SPL	SHANNON ENVIRONMENTAL	FROM THE WATERFRONT TO SUMMERHILL FROM BROADVIEW TO BAY ST. TORONTO PLANT 309 CHERRY STREET	TORONTO CITY ON
SPL	METROPOLITAN TORONTO, MUNICIPA	IN TAYLOR CREEK PARK EAST OF THE DON VALLEY AND SOUTH OF DON MILLS SANITARY SEWER/ SEWAGE PUMPING STATION	TORONTO CITY ON
SPL	METROPOLITAN TORONTO, MUNICIPA	PUMP STATION IN THE "T" BUILDING ON EASTERN AVENUE. SANITARY SEWER/ SEWAGE PUMPING STATION	TORONTO CITY ON
SPL	TORONTO HYDRO	EASTERN AVE POLE #255	TORONTO CITY ON
SRDS	IMPERIAL OIL LIMITED		TORONTO ON
WWIS			TORONTO ON
WWIS			TORONTO ON

Unplottable Report

Site: ***TORONTO CITY DR. #LA-1162***
QUEEN ST. EAST TORONTO CITY ON

Database: ***CA***

Certificate #: 3-0496-87-
Application Year: 87
Issue Date: 5/15/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TORONTO CITY DR. #LA-1150***
QUEEN ST. EAST TORONTO CITY ON

Database: ***CA***

Certificate #: 3-1696-86-
Application Year: 86
Issue Date: 11/20/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CITY***
QUEEN ST. E. TORONTO ON

Database: ***CA***

Certificate #: 3-0129-85-006
Application Year: 85
Issue Date: 4/10/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site:
Queen Street East Toronto ON

Database: ***CA***

Certificate #: 8832-53JQEJ

Application Year: 01
Issue Date: 10/17/01
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Joy Realty Limited
Client Address: 48 St. Clair Avenue West, Suite 1100
Client City: Toronto
Client Postal Code: M4V 2Z2
Project Description: This application is for the construction of a storm sewer on Queen Street East and easement in the City of Toronto.
Contaminants:
Emission Control:

Site: ***TORONTO CITY DR. NO. LA-1178***
LANE 34.4. M. S. OF QUEEN ST. TORONTO CITY ON

Database: ***CA***

Certificate #: 3-2409-88-
Application Year: 88
Issue Date: 1/26/1989
Approval Type: Municipal sewage
Status: Approved in 1989
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TORONTO CITY DR. # R-726***
KING STREET EAST TORONTO CITY ON

Database: ***CA***

Certificate #: 7-0095-87-
Application Year: 87
Issue Date: 3/24/1987
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site:
King Street East from Berkeley St to Sumach St Toronto ON

Database: ***CA***

Certificate #: 5781-5DNNDD
Application Year: 02
Issue Date: 9/5/02
Approval Type: Municipal & Private water
Status: Approved
Application Type: New Certificate of Approval
Client Name: City of Toronto
Client Address: 100 Queen Street West
Client City: Toronto
Client Postal Code: M5H 2N2
Project Description: King Street East watermain reconstruction
Contaminants:
Emission Control:

Site: ***TORONTO CITY DR. #R-699***
FRONT ST. EAST TORONTO CITY ON

Database: ***CA***

Certificate #: 7-1889-87-
Application Year: 87
Issue Date: 1/19/1988
Approval Type: Municipal water
Status: Approved in 1988
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CITY***
FRONT ST.E. TORONTO ON

Database: ***CA***

Certificate #: 3-0698-85-006
Application Year: 85
Issue Date: 7/31/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CITY***
FRONT ST.E. TORONTO ON

Database: ***CA***

Certificate #: 3-0651-85-006
Application Year: 85
Issue Date: 7/30/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BCE DEVELOPMENT CORPORATION-DWG.#W1-W10***
FRONT ST./PEDESTRIAN TUNNEL TORONTO CITY ON

Database: ***CA***

Certificate #: 7-0967-90-
Application Year: 90
Issue Date: 8/23/1990
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:

Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BCE DEVELOPMENT CORPORATION DWG. #C1-C8***
FRONT ST./REL. TTC FORCEMAIN C TORONTO CITY ON

Database: ***CA***

Certificate #: 3-0096-90-
Application Year: 90
Issue Date: 3/4/1991
Approval Type: Municipal sewage
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BCE DEVELOPMENT CORPORATION***
FRONT STREET TORONTO CITY ON

Database: ***CA***

Certificate #: 3-0946-90-
Application Year: 90
Issue Date: 6/11/1990
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***BCE DEVELOPMENT CORPORATION***
FRONT STREET TORONTO CITY ON

Database: ***CA***

Certificate #: 3-1217-89-
Application Year: 89
Issue Date: 6/11/1990
Approval Type: Municipal sewage
Status: Underwent 2nd revision in 1990
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Ontario Realty Corporation***
Eastern Ave Toronto ON

Database: ***CA***

Certificate #: 5074-7A2LEH
Application Year: 2007

Issue Date: 12/19/2007
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Database:*** ***CA***
Carroll Street, Public lane Toronto ON

Certificate #: 5227-4WYNJF
Application Year: 01
Issue Date: 5/31/01
Approval Type: Municipal & Private sewage
Status: Approved
Application Type: New Certificate of Approval
Client Name: Corporation of the City of Toronto
Client Address: 5100 Yonge Street
Client City: Toronto
Client Postal Code: M2N 5V7
Project Description: Installation of Sanitary Sewers on Carroll Street and Public Lane
Contaminants:
Emission Control:

Site: ***CITY*** ***Database:*** ***CA***
E.OF BROADVIEW AVE. (LANE) TORONTO ON

Certificate #: 3-0359-85-006
Application Year: 85
Issue Date: 5/27/85
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TORONTO CITY*** ***Database:*** ***CA***
ADELAIDE ST. EAST TORONTO CITY ON

Certificate #: 3-1462-92-
Application Year: 92
Issue Date: 11/4/1992
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site:
Adelaide Street East Toronto ON

Database:
CA

Certificate #:	6126-4TKQL8
Application Year:	01
Issue Date:	2/2/01
Approval Type:	Municipal & Private water
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	Corporation of the City of Toronto
Client Address:	100 Queen Street West
Client City:	Toronto
Client Postal Code:	M5H 2N2
Project Description:	Reconstruction of existing 150 mm watermain on Adelaide Street East from Yonge Street to Toronto Street
Contaminants:	
Emission Control:	

Site: ***TORONTO CITY***
ADELAIDE ST./FRONT ST.E. TORONTO CITY ON

Database:
CA

Certificate #:	3-1567-94-
Application Year:	94
Issue Date:	12/8/1994
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***PPM CANADA INC.***
MOBILE PCB UNIT TORONTO CITY ON

Database:
CA

Certificate #:	8-3017-87-
Application Year:	87
Issue Date:	4/8/1987
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	OPERATION OF CLASS 2 MOBILE PCB DESTRUCT
Contaminants:	Azinphos Methyl
Emission Control:	Adsorption

Site: ***PPM CANADA INC.***
WITHIN THE PROVINCE OF ONTARIO TORONTO CITY ON

Database:
CA

Certificate #:	8-3090-87-
Application Year:	87
Issue Date:	9/8/1988
Approval Type:	Industrial air
Status:	Underwent 1st revision in 1988
Application Type:	
Client Name:	
Client Address:	
Client City:	

Client Postal Code:
Project Description: MOBILE PCB DESTRUCTION UNIT
Contaminants: Other Organic Compounds, Polychlorinated Biphenyls
Emission Control: Act. Charcoal Filter

Site: ***PPM CANADA INC.***
MOBILE PCB UNIT TORONTO CITY ON

Database: ***CA***

Certificate #: 8-3071-87-
Application Year: 87
Issue Date: 8/1/1987
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: MOBILE PCB DESTRUCTION UNIT
Contaminants: Other Organic Compounds, Polychlorinated Biphenyls
Emission Control: Act. Charcoal Filter

Site: ***Lafarge Canada Inc.***
Mobile Facility - Model S Toronto ON

Database: ***CA***

Certificate #: 3584-7CHQDQ
Application Year: 2009
Issue Date: 6/1/2009
Approval Type: Air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Toronto Community Housing Corporation***
Thompson St Toronto ON

Database: ***CA***

Certificate #: 1784-775QBB
Application Year: 2007
Issue Date: 9/18/2007
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TORONTO CITY DWG. #LA-1199/CONT.#59405***
LANE 92M N. OF QUEEN STREET E. TORONTO CITY ON

Database: ***CA***

Certificate #: 3-0172-90-
Application Year: 90
Issue Date: 4/9/1990

Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TORONTO CITY QUEEN ST. E.***
QUEEN ST. E. DR. #SB-438 TORONTO CITY ON

Database: ***CA***

Certificate #: 3-0668-86-
Application Year: 86
Issue Date: 6/6/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TORONTO CITY QUEEN ST. E. LA-1142***
LANE 32.0 M N. OF QUEEN ST. E TORONTO CITY ON

Database: ***CA***

Certificate #: 3-0571-86-
Application Year: 86
Issue Date: 5/26/1986
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***Her Majesty the Queen in Right of Ontario as Represented by the Minister of Ener***
River Street, Mill Street and Bayview Ave Toronto ON

Database: ***CA***

Certificate #: 7775-7WLTFG
Application Year: 2009
Issue Date: 10/9/2009
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***City of Toronto***
Adelaide Subdiv W Toronto ON

Database: ***CA***

Certificate #: 6236-8KCHAS
Application Year: 2011
Issue Date: 8/3/2011
Approval Type: Municipal and Private Sewage Works
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***LEVER BROTHERS LIMITED***
TORONTO ON

Database: ***CHEM***

Headcode:
Headcode Desc:
Phone:
List Name:
Description:

Head Office Province: ON
Head Office Postal: M4M1B6
Mailing Address: 1 SUNLIGHT PARK ROAD
Mailing Address 2:
Mailing City: TORONTO

Site: ***CANADIAN NATIONAL RAILWAY COMPANY***
TORONTO ON

Database: ***CONV***

File No:
Crown Brief No:
Court Location:
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: FAILED TO NOTIFY THE MINISTRY CONCERNING A DISCHARGE OF USED OIL THAT ENTERED A STORM SEWER, WHICH MAY IMPAIR THE QUALITY OF WATER.
Background:
URL:

Location:
Region:
Ministry District:

Additional Details

Publication Date:
Count: 1
Act: OWRA
Regulation:
Section: 30(2)
Act/Regulation/Section: OWRA- -30(2)
Date of Offence:
Date of Conviction:
Date Charged: 06/20/1995
Charge Disposition:
Fine: $8000.00
Synopsis:

Site: ***ONTARIO SALVAGE LIMITED***
TORONTO ON

Database: ***CONV***

File No: ***Location:***
Crown Brief No: ***Region:***
Court Location: ***Ministry District:***
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: WHILE USING A WASTE TRANSPORTATION SYSTEM FOR MUNICIPAL WASTE, FAILED TO KEEP A CERTIFICATE OF APPROVAL IN THE VEHICLE.
Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation: 347
Section: 16(11)
Act/Regulation/Section: EPA-347-16(11)
Date of Offence:
Date of Conviction:
Date Charged: 06/02/1995
Charge Disposition:
Fine: $300.00
Synopsis:

Site: ***ONTARIO SALVAGE LIMITED***
TORONTO ON

Database: ***CONV***

File No: ***Location:***
Crown Brief No: ***Region:***
Court Location: ***Ministry District:***
Publication City:
Publication Title:
Act:
Act(s):
First Matter:
Second Matter:
Investigation 1:
Investigation 2:
Penalty Imposed:
Description: WHILE USING A WASTE TRANSPORTATION SYSTEM FOR MUNICIPAL WASTE, FAILED TO CLEARLY MARK VEHICLE WITH NAME AND NUMBER OF A CERTIFICATE OF APPROVAL.
Background:
URL:

Additional Details

Publication Date:
Count: 1
Act: EPA
Regulation: 347
Section: 16(10)
Act/Regulation/Section: EPA-347-16(10)
Date of Offence:
Date of Conviction:
Date Charged: 06/02/1995
Charge Disposition:
Fine: $300.00
Synopsis:

Site: ***Lafarge Canada Inc.***
Mobile Unit Toronto CITY OF TORONTO ON

Database: ***EBR***

EBR Registry No:	010-1815	***Decision Posted:***	
Ministry Ref No:	8722-76CLKC	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:	803005474	***Act 1:***	
Notice Date:	June 09, 2009	***Act 2:***	
Proposal Date:	October 03, 2007	***Site Location Map:***	
Year:	2007		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Lafarge Canada Inc.		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	7880 Keele Street, Vaughan Ontario, Canada L4K 4G7		
Comment Period:			
URL:			

Site Location Details:

Mobile Unit Toronto CITY OF TORONTO

Site: ***Toronto Community Housing Corporation***
Thompson St Toronto ON M4W 2H2

Database: ***ECA***

Approval No:	5712-775QMK	***MOE District:***	
Approval Date:	2007-09-18	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-Municipal Drinking Water Systems		
Project Type:	Municipal Drinking Water Systems		
Address:	Thompson St		
Full Address:			
Full PDF Link:			

Site: ***Her Majesty the Queen in Right of Ontario as Represented by the Minister of***
Public Infrastructure Renewal North of Mill Street between River Street and Bayview Avenue Toronto ON M5G 2L5

Database: ***ECA***

Approval No:	3063-7KMNR4	***MOE District:***	
Approval Date:	2008-11-03	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	
Link Source:	IDS	***Geometry X:***	
SWP Area Name:		***Geometry Y:***	
Approval Type:	ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS		
Project Type:	MUNICIPAL AND PRIVATE SEWAGE WORKS		
Address:	North of Mill Street between River Street and Bayview Avenue		
Full Address:			
Full PDF Link:	https://www.accessenvironment.ene.gov.on.ca/instruments/7590-7K2PR7-14.pdf		

Site: ***Her Majesty the Queen in Right of Ontario as Represented by the Minister of***
Energy & Infrastructure River Street, Mill Street and Bayview Ave Toronto ON M5G 2L5

Database: ***ECA***

Approval No:	7775-7WLTFG	***MOE District:***	
Approval Date:	2009-10-09	***City:***	
Status:	Approved	***Longitude:***	
Record Type:	ECA	***Latitude:***	

Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: River Street, Mill Street and Bayview Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5171-7W4MPD-14.pdf
Geometry X:
Geometry Y:

Site: ***Ontario Realty Corporation***
Eastern Ave Toronto ON M7A 2G3
Database: ***ECA***

Approval No: 7896-7BRM6C
Approval Date: 2008-02-13
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Address: Eastern Ave
Full Address:
Full PDF Link:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***City of Toronto***
Carroll Street, Public Lane Toronto ON M2N 5V7
Database: ***ECA***

Approval No: 5227-4WYNJF
Approval Date: 2001-05-31
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Carroll Street, Public Lane
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/1050-4WSNBS-14.pdf
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***City of Toronto***
Adelaide Street East Toronto ON M5V 3C6
Database: ***ECA***

Approval No: 5323-68ZTSH
Approval Date: 2005-01-28
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
Approval Type: ECA-Municipal Drinking Water Systems
Project Type: Municipal Drinking Water Systems
Address: Adelaide Street East
Full Address:
Full PDF Link:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Site: ***City of Toronto***
Adelaide Street East Toronto ON M5H 2N2
Database: ***ECA***

Approval No: 6126-4TKQL8
Approval Date: 2001-02-02
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:

Approval Type: ECA-Municipal and Private Water Works
Project Type: Municipal and Private Water Works
Address: Adelaide Street East
Full Address:
Full PDF Link:

Site: ***Toronto Community Housing Corporation***
Thompson St Toronto ON M4W 2H2

Database: ***ECA***

Approval No: 1784-775QBB
Approval Date: 2007-09-18
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Thompson St
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5010-772TGF-14.pdf

---

Site: ***Ontario Realty Corporation***
Eastern Ave Toronto ON M7A 2G3

Database: ***ECA***

Approval No: 5074-7A2LEH
Approval Date: 2007-12-19
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS
Address: Eastern Ave
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/7125-79CTC6-14.pdf

---

Site: ***Lafarge Canada Inc.***
Mobile Facility - Model S Toronto ON L4K 4G7

Database: ***ECA***

Approval No: 3584-7CHQDQ
Approval Date: 2009-06-01
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-AIR
Project Type: AIR
Address: Mobile Facility - Model S
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/8722-76CLKC-14.pdf

---

Site: ***City of Toronto***
Adelaide Subdiv W Toronto ON M5V 3C6

Database: ***ECA***

Approval No: 6236-8KCHAS
Approval Date: 2011-08-03
Status: Approved
Record Type: ECA
Link Source: IDS
SWP Area Name:
MOE District:
City:
Longitude:
Latitude:
Geometry X:
Geometry Y:
Approval Type: ECA-MUNICIPAL AND PRIVATE SEWAGE WORKS
Project Type: MUNICIPAL AND PRIVATE SEWAGE WORKS

Address: Adelaide Subdiv W
Full Address:
Full PDF Link: https://www.accessenvironment.ene.gov.on.ca/instruments/5224-8JWJ6T-14.pdf

---

Site: ***CANADIAN NATIONAL RAILWAY***
VARIOUS SITES WITHIN THE MOEE CENTRAL REGION (SEE SCHEDULE "B") ON CNRAIL

Database: ***GEN***

Generator No:	ONR000703	***PO Box No:***	
Status:		***Country:***	Canada
Approval Years:	2014	***Choice of Contact:***	CO_ADMIN
Contam. Facility:	No	***Co Admin:***	Aaron Stadnyk
MHSW Facility:	No	***Phone No Admin:***	416-575-3647 Ext.
SIC Code:	482113		
SIC Description:	MAINLINE FREIGHT RAIL TRANSPORTATION		

Detail(s)

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 270
Waste Class Desc: OTHER SPECIFIED ORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 254
Waste Class Desc: TRANSFER STATION OILS WASTES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 266
Waste Class Desc: PHENOLIC WASTES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 211

Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 135
Waste Class Desc: REACTIVE ANION WASTES

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 231
Waste Class Desc: LATEX WASTES

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Site: ***TORONTO HYDRO***
QUEEN STREET EAST ADJ. 468 VAULT #4176 TORONTO ON

Database: ***GEN***

Generator No: ON0173243
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 9911
SIC Description: IND. MACH. RENTAL

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 243
Waste Class Desc: PCB'S

Site: ***MIJO Corporation***
Ste, 201 Toronto ON M4T 1Z4

Database: ***GEN***

Generator No: ON6096321
Status:
Approval Years: 02,03,04
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Site: ***CANADIAN NATIONAL RAILWAY***
CN SITES IN MOE S.W. REGION (SEE SCHEDULE "B") ON CNRAIL

Database: ***GEN***

Generator No:	ONR000701	***PO Box No:***	
Status:		***Country:***	Canada
Approval Years:	2015	***Choice of Contact:***	CO_OFFICIAL
Contam. Facility:	No	***Co Admin:***	
MHSW Facility:	No	***Phone No Admin:***	
SIC Code:	482113		
SIC Description:	MAINLINE FREIGHT RAIL TRANSPORTATION		

Detail(s)

Waste Class:	232
Waste Class Desc:	POLYMERIC RESINS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	268
Waste Class Desc:	AMINES
Waste Class:	243
Waste Class Desc:	PCBS
Waste Class:	266
Waste Class Desc:	PHENOLIC WASTES
Waste Class:	113
Waste Class Desc:	ACID WASTE - OTHER METALS
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS
Waste Class:	231
Waste Class Desc:	LATEX WASTES
Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	121
Waste Class Desc:	ALKALINE WASTES - HEAVY METALS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	269
Waste Class Desc:	NON-HALOGENATED PESTICIDES
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 270
Waste Class Desc: OTHER SPECIFIED ORGANICS

Waste Class: 254
Waste Class Desc: TRANSFER STATION OILS WASTES

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Site: ***CANADIAN NATIONAL RAILWAY***
CN SITES IN MOE S.W. REGION (SEE SCHEDULE "B") ON CNRAIL

Database: ***GEN***

Generator No: ONR000701
Status:
Approval Years: 2016
Contam. Facility: No
MHSW Facility: No
SIC Code: 482113
SIC Description: MAINLINE FREIGHT RAIL TRANSPORTATION

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 254
Waste Class Desc: TRANSFER STATION OILS WASTES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 231
Waste Class Desc: LATEX WASTES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 266
Waste Class Desc: PHENOLIC WASTES

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 270
Waste Class Desc: OTHER SPECIFIED ORGANICS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Site: ***IMPERIAL OIL LTD. 21-164***
PART LOT 4, CONC. 7 - TWP. OF TORONTO C/O P.O. BOX 380 WATERDOWN ON L0R 2H0

Database: ***GEN***

Generator No: ON0000735
Status:
Approval Years: 94
Contam. Facility:
MHSW Facility:
SIC Code: 4619
SIC Description: OTHER PIPELINE TRANS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Site: ***IMPERIAL OIL LTD.***
PART LOT 4, CONC. 7 - TWP. OF TORONTO C/O P.O. BOX 380 WATERDOWN ON L0R 2H0

Database: ***GEN***

Generator No:	ON0000735	***PO Box No:***	
Status:		***Country:***	
Approval Years:	86,87,88,89,90	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	4619		
SIC Description:	OTHER PIPELINE TRANS.		

Detail(s)

Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES

Site: ***TORONTO HYDRO 38-544***
QUEEN ST. E. ADJ. 468, VAULT 4176 C/O 14 CARLTON ST. TORONTO ON M5B 1K5

Database: ***GEN***

Generator No:	ON0173243	***PO Box No:***	
Status:		***Country:***	
Approval Years:	92,93,94,95,96,97	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	9911		
SIC Description:	IND. MACH. RENTAL		

Detail(s)

Waste Class:	243
Waste Class Desc:	PCB'S

Site: ***CANADIAN NATIONAL RAILWAY***
CN SITES IN MOE S.W. REGION (SEE SCHEDULE "B") ON

Database: ***GEN***

Generator No:	ONR000701	***PO Box No:***	
Status:		***Country:***	
Approval Years:	2012	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	482113		
SIC Description:	Mainline Freight Rail Transportation		

Detail(s)

Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	113
Waste Class Desc:	ACID WASTE - OTHER METALS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS

Waste Class:	222
Waste Class Desc:	HEAVY FUELS
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	231
Waste Class Desc:	LATEX WASTES
Waste Class:	262
Waste Class Desc:	DETERGENTS/SOAPS
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	243
Waste Class Desc:	PCBS
Waste Class:	121
Waste Class Desc:	ALKALINE WASTES - HEAVY METALS
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	268
Waste Class Desc:	AMINES
Waste Class:	269
Waste Class Desc:	NON-HALOGENATED PESTICIDES
Waste Class:	270
Waste Class Desc:	OTHER SPECIFIED ORGANICS
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	266
Waste Class Desc:	PHENOLIC WASTES
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	254
Waste Class Desc:	TRANSFER STATION OILS WASTES
Waste Class:	232
Waste Class Desc:	POLYMERIC RESINS
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	211
Waste Class Desc:	AROMATIC SOLVENTS

Site: ***CANADIAN NATIONAL RAILWAY***
VARIOUS SITES WITHIN THE MOEE CENTRAL REGION (SEE SCHEDULE "B") ON

Database: ***GEN***

Generator No:	ONR000703	***PO Box No:***	
Status:		***Country:***	

Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 482113
SIC Description: MAINLINE FREIGHT RAIL TRANSPORTATION

Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 266
Waste Class Desc: PHENOLIC WASTES

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 135
Waste Class Desc: REACTIVE ANION WASTES

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 254
Waste Class Desc: TRANSFER STATION OILS WASTES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 270
Waste Class Desc: OTHER SPECIFIED ORGANICS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 231
Waste Class Desc: LATEX WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Site: ***TORONTO, CITY OF***
RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET TORONTO ON

Database: ***GEN***

Generator No: ON0146260
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: Waste Collection

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***TORONTO, CITY OF***
RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET TORONTO ON

Database: ***GEN***

Generator No: ON0146260
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: Waste Collection

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Site: ***TORONTO, CITY OF***
RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET TORONTO ON

Database: ***GEN***

Generator No: ON0146260
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: Waste Collection

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Site: ***D.M.Robichaud and Associates Ltd***
Bayview Avenue Toronto ON M5A2E2

Database: ***GEN***

Generator No: ON4826009
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 150 L
Waste Class Desc: Inert organic wastes

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Site: ***CANADIAN NATIONAL RAILWAY***
CN SITES IN MOE S.W. REGION (SEE SCHEDULE "B") ON CNRAIL

Database: ***GEN***

Generator No: ONR000701
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 482113
SIC Description: MAINLINE FREIGHT RAIL TRANSPORTATION

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 122

Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	266
Waste Class Desc:	PHENOLIC WASTES
Waste Class:	262
Waste Class Desc:	DETERGENTS/SOAPS
Waste Class:	222
Waste Class Desc:	HEAVY FUELS
Waste Class:	231
Waste Class Desc:	LATEX WASTES
Waste Class:	254
Waste Class Desc:	TRANSFER STATION OILS WASTES
Waste Class:	269
Waste Class Desc:	NON-HALOGENATED PESTICIDES
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	270
Waste Class Desc:	OTHER SPECIFIED ORGANICS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	243
Waste Class Desc:	PCBS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS
Waste Class:	113
Waste Class Desc:	ACID WASTE - OTHER METALS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES

Site: ***TORONTO, CITY OF***
RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET TORONTO ON

Database: ***GEN***

Generator No:	ON0146260	***PO Box No:***	
Status:		***Country:***	
Approval Years:	01,02,03,04,05,06,07,08	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	8373		
SIC Description:	ENVIRON. ADMIN.		

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Site: ***TORONTO, CITY OF***
RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET TORONTO ON

Database: ***GEN***

Generator No: ON0146260
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: Waste Collection

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 264
Waste Class Desc: PHOTOPROCESSING WASTES

Waste Class: 112

Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Site: ***CANADIAN NATIONAL RAILWAY***
VARIOUS SITES WITHIN THE MOEE CENTRAL REGION (SEE SCHEDULE "B") ON CNRAIL

Database: ***GEN***

Generator No: ONR000703
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 482113
SIC Description: MAINLINE FREIGHT RAIL TRANSPORTATION

PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Aaron Stadnyk
Phone No Admin: 416-575-3647 Ext.

Detail(s)

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 268

Waste Class Desc: AMINES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 135
Waste Class Desc: REACTIVE ANION WASTES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 231
Waste Class Desc: LATEX WASTES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 270
Waste Class Desc: OTHER SPECIFIED ORGANICS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 254
Waste Class Desc: TRANSFER STATION OILS WASTES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 266
Waste Class Desc: PHENOLIC WASTES

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 145

Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 243
Waste Class Desc: PCBS

Site: ***METRO TRANSPORTATION***
DON VALLEY PARKWAY AT BRIDGE OVER CNBALA SUBDIV./DON RIVER(S. OF GRENOBLE DR. TORONTO ON

Database: ***GEN***

Generator No: ON0654814
Status:
Approval Years: 97,98
Contam. Facility:
MHSW Facility:
SIC Code: 4591
SIC Description: HIGHWAY, ETC. IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Site: ***METRO TRANSPORTATION***
DON VALLEY PKWY AT BRIDGE OVER CN BALA SUBDIVISION/DON RIVER S. OF GRENOBLE DR. TORONTO ON

Database: ***GEN***

Generator No: ON0654812
Status:
Approval Years: 97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 8371
SIC Description: TRANSPORTATION ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Site: ***METRO TRANSPORTATION***
DON VALLEY PARKWAY AT BRIDGE OVER CNBALA SUBDIV./DON RIVER (S. OF GRENOBLE DR.) TORONTO ON

Database: ***GEN***

Generator No: ON0654814
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4591
SIC Description: HIGHWAY, ETC. IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Site: ***CANADIAN NATIONAL RAILWAY***
VARIOUS SITES WITHIN THE MOEE CENTRAL REGION (SEE SCHEDULE "B") ON CNRAIL

Database: ***GEN***

Generator No: ONR000703
Status:

PO Box No:
Country: Canada

Approval Years:	2016	***Choice of Contact:***	CO_ADMIN
Contam. Facility:	No	***Co Admin:***	Aaron Stadnyk
MHSW Facility:	No	***Phone No Admin:***	416-575-3647 Ext.
SIC Code:	482113		
SIC Description:	MAINLINE FREIGHT RAIL TRANSPORTATION		

Detail(s)

Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	121
Waste Class Desc:	ALKALINE WASTES - HEAVY METALS
Waste Class:	253
Waste Class Desc:	EMULSIFIED OILS
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	241
Waste Class Desc:	HALOGENATED SOLVENTS
Waste Class:	135
Waste Class Desc:	REACTIVE ANION WASTES
Waste Class:	269
Waste Class Desc:	NON-HALOGENATED PESTICIDES
Waste Class:	266
Waste Class Desc:	PHENOLIC WASTES
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	222
Waste Class Desc:	HEAVY FUELS
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	211
Waste Class Desc:	AROMATIC SOLVENTS
Waste Class:	262
Waste Class Desc:	DETERGENTS/SOAPS
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	114
Waste Class Desc:	OTHER INORGANIC ACID WASTES
Waste Class:	270
Waste Class Desc:	OTHER SPECIFIED ORGANICS
Waste Class:	113
Waste Class Desc:	ACID WASTE - OTHER METALS
Waste Class:	232
Waste Class Desc:	POLYMERIC RESINS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 254
Waste Class Desc: TRANSFER STATION OILS WASTES

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 231
Waste Class Desc: LATEX WASTES

Site: ***TRANS-NORTHERN PIPELINES INC.***
TORONTO METER STATION DON VALLEY PARKWAY AND LAKESHORE TORONTO ON

Database: ***GEN***

Generator No: ON0174733
Status:
Approval Years: 93,94,95,96,97,98,99,00,01,02,03,04
Contam. Facility:
MHSW Facility:
SIC Code: 0711
SIC Description: CONV. OIL & GAS IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***GAZZOLA PAVING LIMITED***
BAYVIEW&BLOOR OFF THE DON VALLEY PARKWAY BETWEEN D.V.P. AND BAYVIEW NORTH SIDE TORONTO ON x0x0x0

Database: ***GEN***

Generator No: ON1258001
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Site: ***CANADIAN NATIONAL RAILWAY***
VARIOUS SITES WITHIN THE MOEE CENTRAL REGION (SEE SCHEDULE "B") ON

Database: ***GEN***

Generator No: ONR000703
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 482113
SIC Description: Mainline Freight Rail Transportation

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 222
Waste Class Desc: HEAVY FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 253
Waste Class Desc: EMULSIFIED OILS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 262
Waste Class Desc: DETERGENTS/SOAPS

Waste Class: 270
Waste Class Desc: OTHER SPECIFIED ORGANICS

Waste Class: 114
Waste Class Desc: OTHER INORGANIC ACID WASTES

Waste Class: 231
Waste Class Desc: LATEX WASTES

Waste Class: 232
Waste Class Desc: POLYMERIC RESINS

Waste Class: 266
Waste Class Desc: PHENOLIC WASTES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 241
Waste Class Desc: HALOGENATED SOLVENTS

Waste Class: 268
Waste Class Desc: AMINES

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 135
Waste Class Desc: REACTIVE ANION WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 113
Waste Class Desc: ACID WASTE - OTHER METALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 254
Waste Class Desc: TRANSFER STATION OILS WASTES

Site: ***TORONTO, CITY OF***
RIVERDALE PARK EAST BROADVIEW AVE. NORTH OF GERRARD STREET TORONTO ON

Database: ***GEN***

Generator No: ON0146260
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: WASTE COLLECTION

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	261
Waste Class Desc:	PHARMACEUTICALS
Waste Class:	147
Waste Class Desc:	CHEMICAL FERTILIZER WASTES
Waste Class:	264
Waste Class Desc:	PHOTOPROCESSING WASTES
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	269
Waste Class Desc:	NON-HALOGENATED PESTICIDES
Waste Class:	312
Waste Class Desc:	PATHOLOGICAL WASTES
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	121
Waste Class Desc:	ALKALINE WASTES - HEAVY METALS

Site: ***TORONTO HYDRO***
QUEEN ST. E. ADJ. 468, VAULT 4176 C/O 14 CARLTON ST. TORONTO ON M5B 1K5

Database: ***GEN***

Generator No:	ON0173243	***PO Box No:***	
Status:		***Country:***	
Approval Years:	88,89,90	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	9911		
SIC Description:	IND. MACH. RENTAL		

Site: ***City of Toronto Riverdale Landfill***
Between Broadview Ave and the DVP Between Montcrest Blvd and Victor Ave Toronto ON

Database: ***LIMO***

ECA/Instrument No:	X3071	***Natural Attenuation:***	
Oper Status 2016:	Historic	***Liners:***	
C of A Issue Date:		***Cover Material:***	
C of A Issued to:		***Leachate Off-Site:***	
Lndfl Gas Mgmt (P):		***Leachate On Site:***	
Lndfl Gas Mgmt (F):		***Req Coll Lndfll Gas:***	
Lndfl Gas Mgmt (E):		***Lndfll Gas Coll:***	
Lndfl Gas Mgmt Sys:		***Total Waste Rec:***	
Landfill Gas Mntr:		***TWR Methodology:***	
Leachate Coll Sys:		***TWR Unit:***	
ERC Est Vol (m3):		***Tot Aprv Cap Unit:***	
ERC Volume Unit:		***Financial Assurance:***	
ERC Dt Last Det:		***Last Report Year:***	
Landfill Type:		***MOE Region:***	
Source File Type:	Historic and Closed Landfills	***MOE District:***	
Fill Rate:		***Site County:***	
Fill Rate Unit:		***Lot:***	
Tot Fill Area (ha):		***Concession:***	
Tot Site Area (ha):		***Latitude:***	
Footprint:		***Longitude:***	
Tot Apprv Cap (m3):		***Easting:***	

Contam Atten Zone: ***Northing:***
Grndwtr Mntr: ***UTM Zone:***
Surf Wtr Mntr: ***Data Source:***
Air Emis Monitor:
Approved Waste Type:
Client Site Name: City of Toronto
Riverdale Landfill
ERC Methodology:
Site Name:
Site Location Details: Between Broadview Ave and the DVP
Between Montcrest Blvd and Victor Ave

Toronto
Service Area:
Page URL:

Site: ***Sun Valley Landfill City of Toronto City of Toronto***
Bayview Avenue, CPR & Don River Toronto ON

Database: ***LIMO***

ECA/Instrument No: A280601
Oper Status 2016: Closed
C of A Issue Date:
C of A Issued to:
Lndfl Gas Mgmt (P):
Lndfl Gas Mgmt (F):
Lndfl Gas Mgmt (E):
Lndfl Gas Mgmt Sys:
Landfill Gas Mntr:
Leachate Coll Sys:
ERC Est Vol (m3):
ERC Volume Unit:
ERC Dt Last Det:
Landfill Type:
Source File Type:
Fill Rate:
Fill Rate Unit:
Tot Fill Area (ha):
Tot Site Area (ha):
Footprint:
Tot Apprv Cap (m3):
Contam Atten Zone:
Grndwtr Mntr:
Surf Wtr Mntr:
Air Emis Monitor:
Approved Waste Type:
Client Site Name:
ERC Methodology:
Site Name: Sun Valley Landfill
City of Toronto
City of Toronto
Site Location Details:
Service Area:
Page URL:

Natural Attenuation:
Liners:
Cover Material:
Leachate Off-Site:
Leachate On Site:
Req Coll Lndfll Gas:
Lndfll Gas Coll:
Total Waste Rec:
TWR Methodology:
TWR Unit:
Tot Aprv Cap Unit:
Financial Assurance:
Last Report Year:
MOE Region:
MOE District:
Site County:
Lot:
Concession:
Latitude:
Longitude:
Easting:
Northing:
UTM Zone:
Data Source:

Site: ***EllisDon Ledcor PAAV Inc.***
West Don Lands - Pan Am Games Athletes Village, Plan 66M-2488, City of Toronto CITY OF TORONTO ON

Database: ***PTTW***

EBR Registry No: 011-5145
Ministry Ref No: 1781-8NLK2T
Notice Type: Instrument Decision
Notice Stage:
Notice Date: November 28, 2011
Proposal Date: November 21, 2011
Year: 2011
Instrument Type: (OWRA s. 34) - Permit to Take Water
Off Instrument Name:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Posted By:
Company Name: EllisDon Ledcor PAAV Inc.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 89 Queensway Avenue, Mississauga Ontario, Canada L5B 2V2
Comment Period:
URL:

Site Location Details:

West Don Lands - Pan Am Games Athletes Village, Plan 66M-2488, City of Toronto CITY OF TORONTO

Site: ***Molex Incorporated***
Broadview Ave Suite 1580 Toronto ON M4K 2R1

Database: ***SCT***

Established:
Plant Size (ft²):
Employment:

--Details--
Description: Other Metalworking Machinery Manufacturing
SIC/NAICS Code: 333519

Description: Semiconductor and Other Electronic Component Manufacturing
SIC/NAICS Code: 334410

Description: Communication and Energy Wire and Cable Manufacturing
SIC/NAICS Code: 335920

Description: Lighting Fixture Manufacturing
SIC/NAICS Code: 335120

Site: ***Motorcade Auto Parts***
ON

Database: ***SCT***

Established: 1958
Plant Size (ft²):
Employment: 13

--Details--
Description: Other New Motor Vehicle Parts and Accessories Wholesaler-Distributors
SIC/NAICS Code: 415290

Site: ***CANADA TRANSPORT GROUP***
TRANSPORT TRUCK (CARGO) TORONTO CITY ON

Database: ***SPL***

Ref No:	31454	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/28/1990	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER TRANSPORTATION ACCIDENT	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	01106
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	

Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	MOT
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/28/1990	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ADVERSE ROAD CONDITION	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	CANADA TRANSPORT GROUP - VEHICLE ACCIDENT. 900L FUEL TO ROADWAY, SEWER.		
Contaminant Qty:			

Site: ***CANADA PACKERS***
CANADA PACKERS-SOAP PLANT TORONTO PLANT [ST. CLAIR AVENUE] TORONTO CITY ON

Database: ***SPL***

Ref No:	8736	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/31/1988	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PROCESS UPSET	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	1106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	8/31/1988	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	CANADA PACKERS-SOAP PLANT45 KG DETERGENT FOAM FOAM FROM STACK		
Contaminant Qty:			

Site: ***City of Toronto***
on River St, South of King St East, 400 meters on eastside Toronto ON

Database: ***SPL***

Ref No:	2476-8X5LNX	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	13-AUG-12	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Unknown	***Sector Type:***	Motor Vehicle
Incident Event:		***Agency Involved:***	
Contaminant Code:	12	***Nearest Watercourse:***	
Contaminant Name:	GASOLINE	***Site Address:***	on River St, South of King St East, 400 meters on eastside
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Toronto
Nature of Impact:	Other Impact(s)	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:	Planned Field Response	***Easting:***	
Dt MOE Arvl on Scn:	15-AUG-12	***Site Geo Ref Accu:***	
MOE Reported Dt:	13-AUG-12	***Site Map Datum:***	
Dt Document Closed:	30-AUG-12	***SAC Action Class:***	Land Spills
Incident Reason:		***Source Type:***	
Site Name:	gas to CB<UNOFFICIAL>		

Site County/District:
Site Geo Ref Meth:
Incident Summary: River St: gas to CB and road, ctd clng ~15L
Contaminant Qty: 15 L

Site: ***CANADIAN NATIONAL RAILWAY***
FROM TORONTO STN. TO GUILDWOOD STN. TRAIN TORONTO CITY ON

Database: SPL

Ref No:	10749	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	10/21/1988	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	1106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	10/21/1988	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	

Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: CN-RAIL -DIESEL FUEL TO RAIL BED FOR 20 MILES.
Contaminant Qty:

Site: ***CANADIAN NATIONAL RAILWAYS***
TANK TRUCK (CARGO) TORONTO CITY ON

Database: SPL

Ref No:	53959	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	7/12/1991	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	01106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	7/12/1991	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	

Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: CNR TANKER TRUCK-50 L VEGETABLE OIL TO PARKING LOT.
Contaminant Qty:

Site: ***IMPERIAL OIL***

Database:

ESSO SERVICE STATION TORONTO CITY ON **SPL**

Ref No:	110205	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/18/1995	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	1106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/20/1995	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	MATERIAL FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	IMPERIAL OIL: 8-12 L GAS CONTAINED UNDER PUMP CAVITY		
Contaminant Qty:			

Site: ***IMPERIAL OIL***
ESSO SERVICE STATION TORONTO CITY ON

Database: ***SPL***

Ref No:	14737	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/9/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	CONTAINER OVERFLOW	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/13/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO SERVICE STATION		
Contaminant Qty:			

Site: ***LEVER BROS.***
ATMOSPHERE TORONTO PLANT 1 SUNLIGHT PARK ROAD TORONTO CITY ON

Database: ***SPL***

Ref No:	32919	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/6/1990	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	UNKNOWN	***Sector Type:***	
Incident Event:		***Agency Involved:***	

Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	AIR	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	4/6/1990	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	FIRE/EXPLOSION	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER BROS. - RAILCAR OF SULFUR ON FIRE, STEAM COMING OFF, UNDER CONTROL		
Contaminant Qty:			

Site: ***LEVER BROTHERS LTD.***
LAKE ONTARIO TORONTO PLANT 1 SUNLIGHT PARK ROAD TORONTO CITY ON

Database: ***SPL***

Ref No:	126072	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	5/5/1996	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	01106
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/8/1996	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	LEVER BROTHERS-UKN QTY HIGH PH (11.5)WATER TO STORM SEWER,CLAMP BREAK.		
Contaminant Qty:			

Site:
Bayview Ave. (Gerrad St. E to Queen St. E) Toronto ON

Database: ***SPL***

Ref No:	7130-86UA8P	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:		***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:		***Sector Type:***	Sewer
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	
Nature of Impact:		***Site Lot:***	

Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:	Planned Field Response	***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	6/27/2010	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Sewage Bypasses / Overflows
Incident Reason:		***Source Type:***	
Site Name:	Bayview Ave.<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Bayview Flood/CSO - Gerrard St. E to Queen St. E.		
Contaminant Qty:			

Site: ***SHANNON ENVIRONMENTAL***
FROM THE WATERFRONT TO SUMMERHILL FROM BROADVIEW TO BAY ST. TORONTO PLANT 309 CHERRY STREET TORONTO CITY ON

Database: ***SPL***

Ref No:	82185	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/25/1993	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PROCESS UPSET	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	01106
Nature of Impact:	Air Pollution	***Site Lot:***	
Receiving Medium:	AIR	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	F.D. WORKS DEPT, WTP
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/25/1993	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SHANNON ENVIRONMENTAL: INCINERATOR FUMES FROM REFINING OPERATION TO AIR		
Contaminant Qty:			

Site: ***METROPOLITAN TORONTO, MUNICIPA***
IN TAYLOR CREEK PARK EAST OF THE DON VALLEY AND SOUTH OF DON MILLS SANITARY SEWER/ SEWAGE PUMPING STATION TORONTO CITY ON

Database: ***SPL***

Ref No:	121103	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	11/22/1995	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CAUSE (N.O.S.)	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	POSSIBLE	***Site Municipality:***	1106
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	METRO WORKS DEPT.
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	11/22/1995	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	

Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	METRO TORONTO WORKS DEPT.- 4500 L OF SEWAGE TO GROUND FROM TRUCK SEWER.		
Contaminant Qty:			

Site: ***METROPOLITAN TORONTO, MUNICIPA***
PUMP STATION IN THE "T" BUILDING ON EASTERN AVENUE. SANITARY SEWER/ SEWAGE PUMPING STATION
TORONTO CITY ON

Database: ***SPL***

Ref No:	166850	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/22/1999	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	1106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	4/22/1999	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	OTHER	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TORONTO PUC-1 M3 RAW SEWAGE TO GROUND, CONTAINED,CLEANED-UP.		
Contaminant Qty:			

Site: ***TORONTO HYDRO***
EASTERN AVE POLE #255 TORONTO CITY ON

Database: ***SPL***

Ref No:	21748	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	7/10/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	COOLING SYSTEM LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND / WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	MOE, TORONTO WORKS
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	7/10/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	DAMAGE BY MOVING EQUIPMENT	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TORONTO HYDRO -APPROX. 130L TRANSFORMER OIL TO SEWERS.		
Contaminant Qty:			

Site: ***IMPERIAL OIL LIMITED***
TORONTO ON

Database: ***SRDS***

Company Code:
Works ID:
SIC:
SIC1:
SIC1 Desc:
SIC2:
SIC2 Desc:
SIC3:
SIC3 Desc:
Body of Water:
Terminal Stream:
SIC Desc:
Mailing Address:
Corp Address:

Sector:
Region:
District:
UTM Zone:
UTM Easting:
UTM Northing:
UTM Precision:
Minor Basin:
Major Basin:
Report Year: 1990-1994

Site:
TORONTO ON

Database: ***WWIS***

Well ID: 7048533
Construction Date:
Primary Water Use: Not Used
Sec. Water Use:
Final Well Status: Observation Wells
Water Type:
Casing Material:
Audit No: Z57652
Tag: A049009
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 8/23/2007
Selected Flag: Yes
Abandonment Rec:
Contractor: 7201
Form Version: 3
Owner:
Street Name: FRONT ST.
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 23048533
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 6/4/2007
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone:
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 30148533
Layer: 1

Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 84
Other Materials: SILTY
Mat3: 34
Other Materials: TILL
Formation Top Depth: 0
Formation End Depth: 10
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 30248533
Layer: 2
Color: 2
General Color: GREY
Mat1: 26
Most Common Material: ROCK
Mat2: 15
Other Materials: LIMESTONE
Mat3: 17
Other Materials: SHALE
Formation Top Depth: 10
Formation End Depth: 30
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 44004028
Layer: 3
Plug From: 5
Plug To: 0
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 44004030
Layer: 1
Plug From: 30
Plug To: 10
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 44004029
Layer: 2
Plug From: 10
Plug To: 5
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 7
Method Construction: Diamond
Other Method Construction:

Pipe Information

Pipe ID:	29048533
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	42148533
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	5
Casing Diameter:	50
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	43148533
Layer:	1
Slot:	
Screen Top Depth:	5
Screen End Depth:	10
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	50

Hole Diameter

Hole ID:	46002885
Diameter:	3
Depth From:	10
Depth To:	30
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Hole Diameter

Hole ID:	46002884
Diameter:	4
Depth From:	0
Depth To:	10
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Site:

TORONTO ON

Database:
WWIS

Well ID:	6928597	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Not Used	***Date Received:***	1/14/2005
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	3
Audit No:	Z21789	***Owner:***	
Tag:	A017557	***Street Name:***	BAYVIEW
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	

Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 11329442
DP2BR:
Spatial Status:
Code OB: o
Code OB Desc: Overburden
Open Hole:
Cluster Kind:
Date Completed: 12/15/2004
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Elevation:
Elevrc:
Zone:
East83:
North83:
Org CS:
UTMRC: 9
UTMRC Desc: unknown UTM
Location Method: na

Overburden and Bedrock Materials Interval

Formation ID: 933036580
Layer: 1
Color: 6
General Color: BROWN
Mat1: 06
Most Common Material: SILT
Mat2: 28
Other Materials: SAND
Mat3: 11
Other Materials: GRAVEL
Formation Top Depth: 0
Formation End Depth: 1
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 933036581
Layer: 2
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 06
Other Materials: SILT
Mat3: 11
Other Materials: GRAVEL
Formation Top Depth: 1
Formation End Depth: 5
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933286095
Layer: 1

Plug From: 5
Plug To: 1
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 933286096
Layer: 2
Plug From: 1
Plug To: 0
Plug Depth UOM: m

Pipe Information

Pipe ID: 11344297
Casing No: 1
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 930872539
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 1
Depth To: 0
Casing Diameter: 5
Casing Diameter UOM: cm
Casing Depth UOM: m

Construction Record - Screen

Screen ID: 933416668
Layer: 1
Slot:
Screen Top Depth: 1
Screen End Depth: 5
Screen Material: 5
Screen Depth UOM: m
Screen Diameter UOM: cm
Screen Diameter: 5

Water Details

Water ID: 934070539
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 4
Water Found Depth UOM: m

Hole Diameter

Hole ID: 11548721
Diameter: 15
Depth From: 0
Depth To: 5
Hole Depth UOM: m
Hole Diameter UOM: cm

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Natural Resources maintains a database of all active pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Sep 2018

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Oct 2018

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Jul 31, 2019

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2017

Commercial Fuel Oil Tanks: Provincial CFOT

List of commercial underground fuel oil tanks made available by the Fuels Safety Program of the Technical Standards & Safety Authority (TSSA). Ontario Regulation 213/01 of the Technical Standards and Safety Act (2000) requires that all underground tanks be registered with the TSSA. Note: the Fuels Safety Division does not register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of commercial fuel tanks in the province. The TSSA updates information in its system on an ongoing basis; this listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Chemical Register: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jul 31, 2019

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 - Jun 2019

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Jul 2019

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994-Sep 30, 2019

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Oct 2018

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-Sep 30, 2019

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994-Sep 30, 2019

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011-Sep 30, 2019

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Jul 31, 2019

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Dec 31, 2016

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2018

List of TSSA Expired Facilities: Provincial EXP

List of facilities and tanks - for which there was once a registration - no longer registered with the Fuels Safety Program of the Technical Standards and Safety Authority (TSSA). Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc. Tanks which have been removed from the ground are included in the expired facilities inventory held by the TSSA. Notes: the Fuels Safety Division did not register private fuel underground/aboveground storage tanks prior to January of 1990, or furnace oil tanks prior to May 1, 2002; nor does the Division register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government.

Government Publication Date: Jun 2000-May 2019

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2018

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks made available by the Fuels Safety Program of the Technical Standards & Safety Authority (TSSA). Ontario Regulation 213/01 of the Technical Standards and Safety Act (2000) requires that all underground tanks be registered with the TSSA. Notes: the Fuels Safety Division did not register private fuel underground/aboveground storage tanks prior to January of 1990, or furnace oil tanks prior to May 1, 2002; nor does the Division register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of fuel storage tanks/tank facilities in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Jul 31, 2019

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2017

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

TSSA Incidents: Provincial INC

List of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC) and made available by the Technical Standards and Safety Authority (TSSA). Under the Technical Standards & Safety Act (2000), the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors, and equipment or appliances that use fuels. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the ministry compiles new and updated information. The inventory will include small and large landfills. Additionally, each year the ministry will request operators of the larger landfills complete a landfill data collection form that will be used to update LIMO and will include the following information from the previous operating year. This will include additional information such as estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills will include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Feb 28, 2019

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Jan 2019

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2017

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2019

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Aug 31, 2019

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Jun 2019

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994-Sep 30, 2019

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: 1988-Mar 2019

TSSA Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills) made available by the Technical Standards and Safety Authority (TSSA). Under the Technical Standards & Safety Act (2000), the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors, and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of pipeline incidents in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994-Sep 30, 2019

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-2016

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-Jul 2019

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Jul 31, 2019

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Feb 2019

Wastewater Discharger Registration Database: Provincial SRDS

Information under this heading is combination of the following 2 programs. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment maintained a database of all direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation; Mining; Petroleum Refining; Organic Chemicals; Inorganic Chemicals; Pulp & Paper; Metal Casting; Iron & Steel; and Quarries. All sampling information is now collected and stored within the Sample Result Data Store (SRDS).

Government Publication Date: 1990-Dec 31, 2017

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970-Aug 2018

TSSA Variances for Abandonment of Underground Storage Tanks: Provincial VAR

List of variances granted for abandoned tanks. Under the Technical Standards and Safety Authority (TSSA) Liquid Fuels Handling Code and Fuel Oil Code, all underground storage tanks must be removed within two years of disuse. If removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of tank variances in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Sep 30, 2019

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Feb 28, 2019

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

ENVIRONMENTAL RISK INFORMATION SERVICES

DATABASE REPORT

Project Property:	*Broadview EA* *225 Commissioners St* *Toronto ON M4M 0A1*
Project No:	*191243*
Report Type:	*Quote - Custom-Build Your Own Report*
Order No:	*20191015053*
Requested by:	*Dillon Consulting Limited*
Date Completed:	*October 18, 2019*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....6
Executive Summary: Site Report Summary - Surrounding Properties.....26
Executive Summary: Summary By Data Source.....27
Map.....47
Aerial.....48
Topographic Map.....49
Detail Report.....50
Unplottable Summary.....198
Unplottable Report.....201
Appendix: Database Descriptions.....219
Definitions.....228

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Limited Partnership ("ERIS") using various sources of information, including information provided by Federal and Provincial government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Limited Partnership. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*Broadview EA* *225 Commissioners St Toronto ON M4M 0A1*
Project No:	*191243*

Order Information:

Order No:	*20191015053*
Date Requested:	*October 15, 2019*
Requested by:	*Dillon Consulting Limited*
Report Type:	*Quote - Custom-Build Your Own Report*

Historical/Products:

Aerial Photographs	*Aerials - National Collection - .tiff files*
City Directory Search	*CD - Subject Site plus 10 Adjacent Properties*
Excel Add-On	*Excel Add-On*

Executive Summary: Report Summary

Database	Name	Searched	Project Property	Boundary to 0.00km	Total
AAGR	Abandoned Aggregate Inventory	Y	0	0	0
AGR	Aggregate Inventory	Y	0	0	0
AMIS	Abandoned Mine Information System	Y	0	0	0
ANDR	Anderson's Waste Disposal Sites	Y	2	0	2
AST	Aboveground Storage Tanks	Y	0	0	0
AUWR	Automobile Wrecking & Supplies	Y	7	0	7
BORE	Borehole	Y	12	1	13
CA	Certificates of Approval	Y	5	0	5
CDRY	Dry Cleaning Facilities	Y	0	0	0
CFOT	Commercial Fuel Oil Tanks	Y	0	0	0
CHEM	Chemical Register	Y	0	0	0
CNG	Compressed Natural Gas Stations	Y	0	0	0
COAL	Inventory of Coal Gasification Plants and Coal Tar Sites	Y	0	0	0
CONV	Compliance and Convictions	Y	0	0	0
CPU	Certificates of Property Use	Y	0	0	0
DRL	Drill Hole Database	Y	0	0	0
EASR	Environmental Activity and Sector Registry	Y	1	0	1
EBR	Environmental Registry	Y	2	0	2
ECA	Environmental Compliance Approval	Y	0	0	0
EEM	Environmental Effects Monitoring	Y	0	0	0
EHS	ERIS Historical Searches	Y	11	0	11
EIIS	Environmental Issues Inventory System	Y	0	0	0
EMHE	Emergency Management Historical Event	Y	0	0	0
EPAR	Environmental Penalty Annual Report	Y	0	0	0
EXP	List of TSSA Expired Facilities	Y	4	0	4
FCON	Federal Convictions	Y	0	0	0
FCS	Contaminated Sites on Federal Land	Y	0	0	0
FOFT	Fisheries & Oceans Fuel Tanks	Y	0	0	0
FST	Fuel Storage Tank	Y	1	0	1
FSTH	Fuel Storage Tank - Historic	Y	4	0	4
GEN	Ontario Regulation 347 Waste Generators Summary	Y	49	1	50
GHG	Greenhouse Gas Emissions from Large Facilities	Y	0	0	0
HINC	TSSA Historic Incidents	Y	0	0	0
IAFT	Indian & Northern Affairs Fuel Tanks	Y	0	0	0
INC	TSSA Incidents	Y	0	0	0
LIMO	Landfill Inventory Management Ontario	Y	0	0	0

Database	Name	Searched	Project Property	Boundary to 0.00km	Total
MINE	Canadian Mine Locations	Y	0	0	0
MNR	Mineral Occurrences	Y	0	0	0
NATE	National Analysis of Trends in Emergencies System (NATES)	Y	0	0	0
NCPL	Non-Compliance Reports	Y	0	0	0
NDFT	National Defense & Canadian Forces Fuel Tanks	Y	0	0	0
NDSP	National Defense & Canadian Forces Spills	Y	0	0	0
NDWD	National Defence & Canadian Forces Waste Disposal Sites	Y	0	0	0
NEBI	National Energy Board Pipeline Incidents	Y	0	0	0
NEBP	National Energy Board Wells	Y	0	0	0
NEES	National Environmental Emergencies System (NEES)	Y	0	0	0
NPCB	National PCB Inventory	Y	0	0	0
NPRI	National Pollutant Release Inventory	Y	12	0	12
OGWE	Oil and Gas Wells	Y	0	0	0
OOGW	Ontario Oil and Gas Wells	Y	0	0	0
OPCB	Inventory of PCB Storage Sites	Y	0	0	0
ORD	Orders	Y	0	0	0
PAP	Canadian Pulp and Paper	Y	0	0	0
PCFT	Parks Canada Fuel Storage Tanks	Y	0	0	0
PES	Pesticide Register	Y	0	0	0
PINC	TSSA Pipeline Incidents	Y	0	0	0
PRT	Private and Retail Fuel Storage Tanks	Y	2	0	2
PTTW	Permit to Take Water	Y	0	0	0
REC	Ontario Regulation 347 Waste Receivers Summary	Y	0	0	0
RSC	Record of Site Condition	Y	2	0	2
RST	Retail Fuel Storage Tanks	Y	0	0	0
SCT	Scott's Manufacturing Directory	Y	1	0	1
SPL	Ontario Spills	Y	16	0	16
SRDS	Wastewater Discharger Registration Database	Y	0	0	0
TANK	Anderson's Storage Tanks	Y	0	5	5
TCFT	Transport Canada Fuel Storage Tanks	Y	0	0	0
VAR	TSSA Variances for Abandonment of Underground Storage Tanks	Y	0	0	0
WDS	Waste Disposal Sites - MOE CA Inventory	Y	37	0	37
WDSH	Waste Disposal Sites - MOE 1991 Historical Approval Inventory	Y	0	0	0
WWIS	Water Well Information System	Y	13	0	13
	Total:		181	7	188

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
1	BORE		ON	-/0.0	-1.01	50
2	WWIS		Toronto ON ***Well ID:*** 7156208	-/0.0	0.00	51
3	WWIS		TORONTO ON ***Well ID:*** 7242115	-/0.0	-2.54	54
4	CA	ARCTURUS ENVIRONMENTAL LIMITED	300 COMMISSIONERS STREET TORONTO CITY ON	-/0.0	-2.14	57
4	EBR	Arcturus Environmental Limited	300 Commissioners Street Toronto ON	-/0.0	-2.14	57
4	EXP	NOCO LUBRICANTS CANADA	300 COMMISSIONERS ST TORONTO ON	-/0.0	-2.14	57
4	FST	SMS PETROLEUMS DIVISION OF SUNOCO NANCY NG	300 COMMISSIONERS ST TORONTO ON NULL	-/0.0	-2.14	58
4	FSTH	SMS PETROLEUMS DIVISION OF SUNOCO NANCY NG	300 COMMISSIONERS ST TORONTO ON	-/0.0	-2.14	58

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
4	FSTH	SMS PETROLEUMS DIVISION OF SUNOCO NANCY NG	300 COMMISSIONERS ST TORONTO ON	-/0.0	-2.14	58
4	GEN	Toronto Port Lands Company	300 Commissioners Street Toronto ON M4M 1A4	-/0.0	-2.14	59
4	GEN	SUNOCO INC. 36-136	300 COMMISSIONERS ST., TORONTO C/O 36 YORK MILLS RD. NORTH YORK ON M2P 2C5	-/0.0	-2.14	59
4	GEN	SUNOCO INC.	300 COMMISSIONERS ST., TORONTO C/O 36 YORK MILLS RD. NORTH YORK ON M2P 2C5	-/0.0	-2.14	59
4	GEN	SUNOCO INC.	300 COMMISSIONERS STREET TORONTO ON M4M 1A4	-/0.0	-2.14	60
4	GEN	SUN-(OUT OF BUS) 36-439	LIMITED 300 COMMISSIONERS ST. TORONTO ON M4M 1A4	-/0.0	-2.14	60
4	GEN	SUN-(OUT OF BUSINESS)	300 COMMISSIONERS STREET TORONTO ON M4M 1A4	-/0.0	-2.14	60
4	GEN	SUN-CANADIAN PIPE LINE COMPANY 36-439	LIMITED 300 COMMISSIONERS ST. TORONTO ON M4M 1A4	-/0.0	-2.14	61
4	GEN	SUN-CANADIAN PIPE LINE COMPANY	LIMITED 300 COMMISSIONERS ST. TORONTO ON M4M 1A4	-/0.0	-2.14	61
4	GEN	SUNOCO INC.	300 COMMISSIONERS ST., TORONTO ON M4M 1A4	-/0.0	-2.14	61

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
4	PRT	SMS PETROLEUMS DIVISION OF SUNOCO	300 COMMISSIONERS ST TORONTO ON M4M 1A4	-/0.0	-2.14	62
4	RSC	City of Toronto Economic Development Corporation (TEDCO)	300 COMMISSIONERS ST, TORONTO, ON, M4M 1A4 TORONTO ON M4M 1A4	-/0.0	-2.14	62
4	SPL	SUNOCO	300 COMMISSIONER TANK FARM TORONTO CITY ON	-/0.0	-2.14	62
4	SPL	SUN-CANADIAN PIPE LINE COMPANY	300 COMMISIONERS ST. TRANSPORT TRUCK (CARGO) TORONTO CITY ON	-/0.0	-2.14	63
4	SPL	SUNOCO	300 COMMISSIONER ST. TANK FARM TORONTO CITY ON	-/0.0	-2.14	63
4	SPL	SUNOCO	300 COMISSIONER ST. BULK STATION TORONTO CITY ON	-/0.0	-2.14	64
4	SPL	SUNOCO	SUNOCO 300 COMMISSIONERS STREET TANK FARM TORONTO CITY ON	-/0.0	-2.14	64
5	WWIS		TORONTO ON ***Well ID:*** 7116763	-/0.0	-2.56	65
6	EHS		Commissioners Street Toronto ON	-/0.0	-2.84	67

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
7	AUWR	A J SELF STORAGE INC	280 COMMISSIONERS ST TORONTO ON M4M 1A4	-/0.0	0.00	67
7	AUWR	SCRAP WASTE & SALT	280 COMMISSIONERS ST TORONTO ON M4M 1A4	-/0.0	0.00	68
7	AUWR	TEPERMAN SCRAP METAL	280 COMMISSIONERS ST TORONTO ON M4M 1A4	-/0.0	0.00	68
7	AUWR	A J SELF STORAGE INC	280 COMMISSIONERS ST TORONTO ON M4M1A4	-/0.0	0.00	68
7	AUWR	TEPERMAN DEMOLITION & WASTE INC	280 COMMISSIONERS ST TORONTO ON M4M 1A4	-/0.0	0.00	68
7	AUWR	TEPERMAN	280 COMMISSIONERS ST TORONTO ON M4M 1A4	-/0.0	0.00	68
7	AUWR	SCRAP WASTE & SALT	280 COMMISSIONERS ST TORONTO ON M4M1A4	-/0.0	0.00	69
7	GEN	TEPERMAN AND SONS INC. 37-220	280 COMMISSIONERS ST. TORONTO ON M4M 1A4	-/0.0	0.00	69
7	GEN	TEPERMAN AND SONS INC.	280 COMMISSIONERS ST. TORONTO ON M4M 1A4	-/0.0	0.00	69
7	GEN	TEPERMAN AND SONS INC.	280 COMMISSIONERS STREET TORONTO ON M4M 1A4	-/0.0	0.00	69

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
7	SCT	TEPERMAN & SONS INC	280 COMMISSIONERS ST TORONTO ON M4M 1A4	-/0.0	0.00	70
7	SPL	CANADIAN NORTHERN RECYCLING.	280 COMMISSIONERS RD. 280 COMMISSIONERS RD. TORONTO CITY ON M4M 1A4	-/0.0	0.00	70
7	SPL	PRIVATE BUSINESS	280 COMISSIONER STREET,(WATERFRONT) (N.O.S.) TORONTO CITY ON	-/0.0	0.00	70
8	EHS		300 Commissioners Street Toronto ON M4M 1A4	-/0.0	-2.02	71
8	EHS		300 Commissioners St Toronto ON M4M1A4	-/0.0	-2.02	71
9	WWIS		TORONTO ON ***Well ID:*** 7242114	-/0.0	-2.56	71
10	WWIS		Toronto ON ***Well ID:*** 7247923	-/0.0	-0.63	74
11	WWIS		TORONTO ON ***Well ID:*** 7242116	-/0.0	-2.02	77
12	EHS		115 Saulter, 41 Basin, 811 Lake Shore Toronto ON	-/0.0	0.00	80

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
13	GEN	TRUCKERS GARAGE LTD.	69 SAULTER ST. SOUTH TORONTO ON M4M 1A4	-/0.0	-1.07	80
13	GEN	TRUCKERS (SEE & USE ON0693900) 38-481	69 SAULTER ST. SOUTH TORONTO ON M4M 1A4	-/0.0	-1.07	80
14	BORE		ON	-/0.0	-0.06	80
15	EHS		Lake Shore Blvd E and Don Roadway in Toronto Toronto ON M4M	-/0.0	-2.22	82
16	GEN	Chai Kosher Poultry	115 Saulter Street South Toronto ON M4M 3K8	-/0.0	-1.85	82
17	SPL	City of Toronto	Commissioners and Bouchette Toronto ON	-/0.0	-1.60	82
18	BORE		ON	-/0.0	-1.01	83
19	BORE		ON	-/0.0	-1.03	84
20	EHS		115 Saulter Street Toronto ON	-/0.0	-1.98	86
21	WWIS		TORONTO ON	-/0.0	0.00	86

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
			Well ID: 7192708			
22	WWIS		Toronto ON	-/0.0	-1.02	89
			Well ID: 7247922			
23	BORE		ON	-/0.0	-1.03	93
24	BORE		ON	-/0.0	-4.11	94
25	EHS		Commissioners St & Saulter St South 281 Commissioners Street Toronto ON	-/0.0	-1.84	95
25	RSC	City of Toronto Economic Development Corporation	281 Commissioners Street, Pursuant to Committee of Adjustment approval, addresse ON	-/0.0	-1.84	95
26	BORE		ON	-/0.0	0.00	96
27	WWIS		Toronto ON	-/0.0	-3.99	98
			Well ID: 7138467			
28	BORE		ON	-/0.0	-0.47	100
29	WWIS		Toronto ON	-/0.0	-1.07	103

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
			Well ID: 7192710			
30	BORE		ON	-/0.0	0.00	105
31	CA	TORONTO CITY-SAULTER ST-CONTRACT #58317	SAULTER ST/COMMISSIONERS ST. TORONTO CITY ON	-/0.0	-0.97	10
31	SPL	TEPPERMAN AND SONS	COMMISSIONERS AND SAULTAR ST. TORONTO CITY ON	-/0.0	-0.97	10
32	BORE		ON	-/0.0	0.00	108
33	EHS		685 Lakeshore Boulevard East Toronto ON M4M 3J9	-/0.0	0.00	109
34	WWIS		ON ***Well ID:*** 7238823	-/0.0	-1.88	109
35	EHS		Don Roadway Toronto ON	-/0.0	-3.94	110
36	WWIS		TORONTO ON ***Well ID:*** 6927829	-/0.0	-1.62	110
37	WWIS		TORONTO ON ***Well ID:*** 7192709	-/0.0	0.00	113

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
38	CA	TORONTO HARBOUR COMMISSIONERS	185 COMMISSIONERS STREET TORONTO CITY ON	-/0.0	-0.98	11
38	CA	CITY OF TORONTO HOUSING DEPARTMENT	185 COMMISSIONERS ST. TORONTO CITY ON	-/0.0	-0.98	11
39	SPL	UNKNOWN	VILLIERS & COMMISSIONERS STS. TORONTO CITY ON	-/0.0	-2.93	11
39	SPL	UNKNOWN	VILLIERS ST. COMMISSIONERS ST. TORONTO CITY ON	-/0.0	-2.93	11
40	EASR	PT Studios Inc.	225 Commissioners ST Toronto ON M4M 0A1	-/0.0	-0.96	117
40	GEN	PT Studios Inc.	225 Commissioners St Suite 303 Toronto ON M4M 0A1	-/0.0	-0.96	117
40	GEN	Stage 49 Ltd	225 Commissioners St Toronto ON M4M 0A1	-/0.0	-0.96	118
40	GEN	Still Seas Production	225 Commissioners St. Suite 402 Toronto ON	-/0.0	-0.96	118
40	GEN	Haunted Peak Inc.	225 Commissioners St., Suite 401 Toronto, ON ON M4M 0A1	-/0.0	-0.96	118
40	GEN	High Park/Locke and Key Production Inc.	225 Commissioners St. suite 201 Toronto ON M4M 0A1	-/0.0	-0.96	119

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
40	GEN	Rekall Productions Ltd.	225 Commisioners St Toronto ON	-/0.0	-0.96	119
40	GEN	GEP Productions Inc.	225 Commissioner's Street Suite 201 Toronto ON M4M 0A1	-/0.0	-0.96	119
40	GEN	PT Studios Inc.	225 Commissioners St Suite 303 Toronto ON M4M 0A1	-/0.0	-0.96	119
40	GEN	Toronto Water Front Studios Development Inc	225 Commissioners Street Toronto ON M4M 1A1	-/0.0	-0.96	120
40	GEN	14 Hours Productions Inc.	225 Commissioners Street Suite 401 Toronto ON M4M 0A1	-/0.0	-0.96	120
41	BORE		ON	-/0.0	0.00	120
42	CA	MUNICIPALITY OF METRO TORONTO	400 COMMISSIONERS STREET TORONTO CITY ON M4M 3K2	-/0.0	0.00	122
42	EBR	Municipality of Metro Toronto	400 Commissioners Street Toronto ON	-/0.0	0.00	123
42	EHS		400 Commissioners St Toronto ON M4M 3K2	-/0.0	0.00	123

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
42	EHS		400 Commissioner Street n/a ON	-/0.0	0.00	123
42	EXP	CITY OF TORONTO - FLEET SERVICES	400 COMMISSIONERS ST TORONTO ON M4M 3K2	-/0.0	0.00	123
42	EXP	CITY OF TORONTO - FLEET SERVICES	400 COMMISSIONERS ST TORONTO ON M4M 3K2	-/0.0	0.00	124
42	EXP	CITY OF TORONTO - FLEET SERVICES	400 COMMISSIONERS ST TORONTO ON M4M 3K2	-/0.0	0.00	124
42	FSTH	CITY OF TORONTO - FLEET SERVICES ATTN DON LEEBODY	400 COMMISSIONERS ST TORONTO ON M4M 3K2	-/0.0	0.00	124
42	FSTH	CITY OF TORONTO - FLEET SERVICES ATTN DON LEEBODY	400 COMMISSIONERS ST TORONTO ON M4M 3K2	-/0.0	0.00	125
42	GEN	CITY OF TORONTO SOLID WASTE MANAGEMENT SERVICES	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	125
42	GEN	CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON	-/0.0	0.00	126
42	GEN	CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	127
42	GEN	City of Toronto	400 Commissioners St Toronto ON M4M 3K2	-/0.0	0.00	128

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
42	GEN	CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	-/0.0	0.00	129
42	GEN	METROPOLITAN TORONTO WORKS DEPT. 26-051	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	-/0.0	0.00	130
42	GEN	OJCR Commissioners St. Job Site	400 Commissioners St. Toronto ON M4M 3K2	-/0.0	0.00	131
42	GEN	METROPOLITAN TORONTO WORKS DEPT	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	-/0.0	0.00	131
42	GEN	METROPOLITAN TORONTO WORKS DEPARTMENT	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	-/0.0	0.00	132
42	GEN	CITY OF TORONTO SOLID WASTE MANAGEMENT SERVICES	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	133
42	GEN	CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	134
42	GEN	CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	135
42	GEN	CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	137

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
42	GEN	CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	138
42	GEN	METROPOLITAN TORONTO WORKS DEPT.	COMMISSIONERS INCINERATOR 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	139
42	GEN	CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	-/0.0	0.00	140
42	GEN	CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	141
42	GEN	INTERNORTH CONSTRUCTION CO. LTD. 21-518	400 COMMISSIONER STREET, TORONTO C/O DIXIE ROAD MISISSAUGA ON L4W 1N2	-/0.0	0.00	142
42	GEN	CANADA CRINC, LTD.	400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	142
42	GEN	CANADA CRINC, LTD. 07-534	400 COMMISSIONERS STREET TORONTO ON M4M 3K2	-/0.0	0.00	142
42	NPRI	CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	-/0.0	0.00	143
42	NPRI	CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	-/0.0	0.00	144
42	NPRI	CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	-/0.0	0.00	146

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
42	NPRI	CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	-/0.0	0.00	147
42	NPRI	CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	-/0.0	0.00	149
42	NPRI	CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	-/0.0	0.00	150
42	NPRI	CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	-/0.0	0.00	152
42	NPRI	City of Toronto	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	-/0.0	0.00	154
42	PRT	METROPOLITAN WORKS DEPT SOLID WASTE MANAGEMENT DIV	400 COMMISSIONERS ST TORONTO ON M4M 3K2	-/0.0	0.00	15
42	SPL		400 Commissioners Street Toronto ON M4M 3K2	-/0.0	0.00	155
42	SPL	City of Toronto	400 Commissioners St Toronto ON M4M 3K2	-/0.0	0.00	156
42	SPL	Badger Daylighting Ltd.	400 Commissioners st Toronto ON	-/0.0	0.00	156

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
42	SPL	City of Toronto	400 Commissioners St Toronto ON NA	-/0.0	0.00	157
42	SPL	METROPOLITAN TORONTO, MUNICIPA	400 COMMISSIONERS STREET HOUSEHOLD HAZARDOUS WASTE FACILITY 400 COMMISSIONERS STREET TORONTO CITY ON M4M 3K2	-/0.0	0.00	15
42	WDS		400 COMMISSIONERS ST. TORONTO ON M4M 3K2	-/0.0	0.00	158
42	WDS		400 COMMISSIONERS ST. TORONTO ON M4M 3K2	-/0.0	0.00	158
42	WDS		400 COMMISSIONERS ST. TORONTO ON M4M 3K2	-/0.0	0.00	159
42	WDS		400 COMMISSIONERS ST. TORONTO ON M4M 3K2	-/0.0	0.00	160
42	WDS	COMMISSIONER STREET WASTE TRAN	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	-/0.0	0.00	160
42	WDS		400 COMMISSIONERS ST. TORONTO ON M4M 3K2	-/0.0	0.00	161
42	WDS		400 COMMISSIONERS ST. TORONTO ON M4M 3K2	-/0.0	0.00	162

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
42	WDS		400 COMMISSIONERS ST. TORONTO ON M4M 3K2	-/0.0	0.00	163
42	WDS		400 COMMISSIONERS ST. TORONTO ON M4M 3K2	-/0.0	0.00	163
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M4M 3K2	-/0.0	0.00	164
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	165
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	-/0.0	0.00	166
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	-/0.0	0.00	166
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	167
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	-/0.0	0.00	168
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	-/0.0	0.00	168
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	-/0.0	0.00	169

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	-/0.0	0.00	170
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	-/0.0	0.00	170
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	171
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	-/0.0	0.00	172
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	173
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	173
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	174
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	175
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	-/0.0	0.00	175

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	176
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	177
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	-/0.0	0.00	177
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	-/0.0	0.00	178
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	179
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	-/0.0	0.00	180
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	-/0.0	0.00	180
42	WDS	City of Toronto	400 Commissioners St Toronto ON M5H 2N2	-/0.0	0.00	181
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	182
42	WDS	City of Toronto	400 Commissioners St Toronto ON M3J 2B7	-/0.0	0.00	182

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
42	WDS	City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	-/0.0	0.00	183
43	NPRI	CITY OF TORONTO	400 COMMISSIONERS Street TORONTO ON M4M3K2	-/0.0	0.00	184
43	NPRI	CITY OF TORONTO	400 COMMISSIONERS Street TORONTO ON M4M3K2	-/0.0	0.00	186
43	NPRI	CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	-/0.0	0.00	187
43	NPRI	CITY OF TORONTO	400 COMMISSIONERS Street TORONTO ON M4M3K2	-/0.0	0.00	189
44	ANDR	Commissioners St Incinerator 1985	Toronto ON M4M	-/0.0	0.00	19
45	ANDR	Commissioners St Incinerator 1969	Toronto ON M4M	-/0.0	0.00	19
46	BORE		ON	-/0.0	0.00	191
47	GEN	ESSO PETROLUEM CANADA	185 VILLIERS STREET C/O 55 ST. CLAIR AVE. WEST TORONTO ON M5W 2J8	-/0.0	-4.00	193

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev diff (m)	Page Number
47	GEN	Toronto Port Lands Company	185 Villiers Street Toronto ON M5A 1A1	-/0.0	-4.00	193
47	GEN	ESSO PETROLUEM CANADA 14-857	185 VILLIERS STREET C/O 55 ST. CLAIR AVE. WEST TORONTO ON M5W 2J8	-/0.0	-4.00	193
47	GEN	ESSO PETROLUEM CANADA	185 VILLIERS STREET TORONTO ON	-/0.0	-4.00	194

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Dir/Dist (m)	Elev Diff (m)	Page Number
48	GEN	Hydro One Networks Inc.	Cable Joint Bay #2 N. Side of Villiers St., 52m W. of Saulter St. Toronto ON M4M 3J4	W/0.1	-2.93	194
49	BORE		ON	ENE/1.9	0.00	194
50	TANK	Barrett Roofing Co	701 Lake Shore Blvd E Toronto ON	N/2.7	-1.90	196
50	TANK	Barrett Co Ltd	701 Lake Shore Blvd E Toronto ON	N/2.7	-1.90	196
50	TANK	Barrett Co Ltd	701 Lake Shore Blvd E Toronto ON	N/2.7	-1.90	196
50	TANK	Barrett Co Ltd	701 Lake Shore Blvd E Toronto ON	N/2.7	-1.90	196
50	TANK	Barrett Co Ltd	701 Lake Shore Blvd E Toronto ON	N/2.7	-1.90	197

Executive Summary: Summary By Data Source

ANDR - Anderson's Waste Disposal Sites

A search of the ANDR database, dated 1860s-Present has found that there are 2 ANDR site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Commissioners St Incinerator 1985	Toronto ON M4M	0.0	44
Commissioners St Incinerator 1969	Toronto ON M4M	0.0	45

AUWR - Automobile Wrecking & Supplies

A search of the AUWR database, dated 1999-Jul 31, 2019 has found that there are 7 AUWR site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
TEPERMAN	280 COMMISSIONERS ST TORONTO ON M4M 1A4	0.0	7
SCRAP WASTE & SALT	280 COMMISSIONERS ST TORONTO ON M4M 1A4	0.0	7
A J SELF STORAGE INC	280 COMMISSIONERS ST TORONTO ON M4M 1A4	0.0	7
A J SELF STORAGE INC	280 COMMISSIONERS ST TORONTO ON M4M1A4	0.0	7
SCRAP WASTE & SALT	280 COMMISSIONERS ST TORONTO ON M4M1A4	0.0	7
TEPERMAN SCRAP METAL	280 COMMISSIONERS ST TORONTO ON M4M 1A4	0.0	7

Site	Address	Distance (m)	Map Key
TEPERMAN DEMOLITION & WASTE INC	280 COMMISSIONERS ST TORONTO ON M4M 1A4	0.0	7

BORE - Borehole

A search of the BORE database, dated 1875-Jul 2018 has found that there are 13 BORE site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	ON	0.0	1
	ON	0.0	14
	ON	0.0	18
	ON	0.0	19
	ON	0.0	23
	ON	0.0	24
	ON	0.0	26
	ON	0.0	28

Site	Address	Distance (m)	Map Key
	ON	0.0	30
	ON	0.0	32
	ON	0.0	41
	ON	0.0	46
	ON	1.9	49

CA - Certificates of Approval

A search of the CA database, dated 1985-Oct 30, 2011* has found that there are 5 CA site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
ARCTURUS ENVIRONMENTAL LIMITED	300 COMMISSIONERS STREET TORONTO CITY ON	0.0	4
TORONTO CITY-SAULTER ST-CONTRACT #58317	SAULTER ST/COMMISSIONERS ST. TORONTO CITY ON	0.0	31
CITY OF TORONTO HOUSING DEPARTMENT	185 COMMISSIONERS ST. TORONTO CITY ON	0.0	38
TORONTO HARBOUR COMMISSIONERS	185 COMMISSIONERS STREET TORONTO CITY ON	0.0	38
MUNICIPALITY OF METRO TORONTO	400 COMMISSIONERS STREET TORONTO CITY ON M4M 3K2	0.0	42

Site	Address	Distance (m)	Map Key

EASR - Environmental Activity and Sector Registry

A search of the EASR database, dated Oct 2011-Sep 30, 2019 has found that there are 1 EASR site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
PT Studios Inc.	225 Commissioners ST Toronto ON M4M 0A1	0.0	40

EBR - Environmental Registry

A search of the EBR database, dated 1994-Sep 30, 2019 has found that there are 2 EBR site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Arcturus Environmental Limited	300 Commissioners Street Toronto ON	0.0	4
Municipality of Metro Toronto	400 Commissioners Street Toronto ON	0.0	42

EHS - ERIS Historical Searches

A search of the EHS database, dated 1999-Jul 31, 2019 has found that there are 11 EHS site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	Commissioners Street Toronto ON	0.0	6
	300 Commissioners St Toronto ON M4M1A4	0.0	8
	300 Commissioners Street Toronto ON M4M 1A4	0.0	8

Site	Address	Distance (m)	Map Key
	115 Saulter, 41 Basin, 811 Lake Shore Toronto ON	0.0	12
	Lake Shore Blvd E and Don Roadway in Toronto Toronto ON M4M	0.0	15
	115 Saulter Street Toronto ON	0.0	20
	Commissioners St & Saulter St South 281 Commissioners Street Toronto ON	0.0	25
	685 Lakeshore Boulevard East Toronto ON M4M 3J9	0.0	33
	Don Roadway Toronto ON	0.0	35
	400 Commissioner Street n/a ON	0.0	42
	400 Commissioners St Toronto ON M4M 3K2	0.0	42

EXP - List of TSSA Expired Facilities

A search of the EXP database, dated Feb 28, 2017 has found that there are 4 EXP site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
NOCO LUBRICANTS CANADA	300 COMMISSIONERS ST TORONTO ON	0.0	4

Site	Address	Distance (m)	Map Key
CITY OF TORONTO - FLEET SERVICES	400 COMMISSIONERS ST TORONTO ON M4M 3K2	0.0	42
CITY OF TORONTO - FLEET SERVICES	400 COMMISSIONERS ST TORONTO ON M4M 3K2	0.0	42
CITY OF TORONTO - FLEET SERVICES	400 COMMISSIONERS ST TORONTO ON M4M 3K2	0.0	42

FST - Fuel Storage Tank

A search of the FST database, dated Feb 28, 2017 has found that there are 1 FST site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SMS PETROLEUMS DIVISION OF SUNOCO NANCY NG	300 COMMISSIONERS ST TORONTO ON NULL	0.0	4

FSTH - Fuel Storage Tank - Historic

A search of the FSTH database, dated Pre-Jan 2010* has found that there are 4 FSTH site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SMS PETROLEUMS DIVISION OF SUNOCO NANCY NG	300 COMMISSIONERS ST TORONTO ON	0.0	4
SMS PETROLEUMS DIVISION OF SUNOCO NANCY NG	300 COMMISSIONERS ST TORONTO ON	0.0	4
CITY OF TORONTO - FLEET SERVICES ATTN DON LEEBODY	400 COMMISSIONERS ST TORONTO ON M4M 3K2	0.0	42
CITY OF TORONTO - FLEET SERVICES ATTN DON LEEBODY	400 COMMISSIONERS ST TORONTO ON M4M 3K2	0.0	42

GEN - Ontario Regulation 347 Waste Generators Summary

A search of the GEN database, dated 1986-Jul 31, 2019 has found that there are 50 GEN site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Toronto Port Lands Company	300 Commissioners Street Toronto ON M4M 1A4	0.0	4
SUNOCO INC. 36-136	300 COMMISSIONERS ST., TORONTO C/O 36 YORK MILLS RD. NORTH YORK ON M2P 2C5	0.0	4
SUNOCO INC.	300 COMMISSIONERS ST., TORONTO C/O 36 YORK MILLS RD. NORTH YORK ON M2P 2C5	0.0	4
SUNOCO INC.	300 COMMISSIONERS STREET TORONTO ON M4M 1A4	0.0	4
SUN-(OUT OF BUS) 36-439	LIMITED 300 COMMISSIONERS ST. TORONTO ON M4M 1A4	0.0	4
SUN-(OUT OF BUSINESS)	300 COMMISSIONERS STREET TORONTO ON M4M 1A4	0.0	4
SUN-CANADIAN PIPE LINE COMPANY 36-439	LIMITED 300 COMMISSIONERS ST. TORONTO ON M4M 1A4	0.0	4
SUN-CANADIAN PIPE LINE COMPANY	LIMITED 300 COMMISSIONERS ST. TORONTO ON M4M 1A4	0.0	4
SUNOCO INC.	300 COMMISSIONERS ST., TORONTO ON M4M 1A4	0.0	4
TEPERMAN AND SONS INC. 37-220	280 COMMISSIONERS ST. TORONTO ON M4M 1A4	0.0	7
TEPERMAN AND SONS INC.	280 COMMISSIONERS ST. TORONTO ON M4M 1A4	0.0	7

Site	Address	Distance (m)	Map Key
TEPERMAN AND SONS INC.	280 COMMISSIONERS STREET TORONTO ON M4M 1A4	0.0	7
TRUCKERS GARAGE LTD.	69 SAULTER ST. SOUTH TORONTO ON M4M 1A4	0.0	13
TRUCKERS (SEE & USE ON0693900) 38-481	69 SAULTER ST. SOUTH TORONTO ON M4M 1A4	0.0	13
Chai Kosher Poultry	115 Saulter Street South Toronto ON M4M 3K8	0.0	16
PT Studios Inc.	225 Commissioners St Suite 303 Toronto ON M4M 0A1	0.0	40
Stage 49 Ltd	225 Commissioners St Toronto ON M4M 0A1	0.0	40
Still Seas Production	225 Commissioners St. Suite 402 Toronto ON	0.0	40
Haunted Peak Inc.	225 Commissioners St., Suite 401 Toronto, ON ON M4M 0A1	0.0	40
High Park/Locke and Key Production Inc.	225 Commissioners St. suite 201 Toronto ON M4M 0A1	0.0	40
Rekall Productions Ltd.	225 Commisioners St Toronto ON	0.0	40
GEP Productions Inc.	225 Commissioner's Street Suite 201 Toronto ON M4M 0A1	0.0	40

Site	Address	Distance (m)	Map Key
PT Studios Inc.	225 Commissioners St Suite 303 Toronto ON M4M 0A1	0.0	40
Toronto Water Front Studios Development Inc	225 Commissioners Street Toronto ON M4M 1A1	0.0	40
14 Hours Productions Inc.	225 Commissioners Street Suite 401 Toronto ON M4M 0A1	0.0	40
CITY OF TORONTO SOLID WASTE MANAGEMENT SERVICES	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON	0.0	42
CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
City of Toronto	400 Commissioners St Toronto ON M4M 3K2	0.0	42
CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	0.0	42
METROPOLITAN TORONTO WORKS DEPT. 26-051	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	0.0	42
OJCR Commissioners St. Job Site	400 Commissioners St. Toronto ON M4M 3K2	0.0	42
METROPOLITAN TORONTO WORKS DEPT	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	0.0	42
METROPOLITAN TORONTO WORKS DEPARTMENT	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	0.0	42

Site	Address	Distance (m)	Map Key
CITY OF TORONTO SOLID WASTE MANAGEMENT SERVICES	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
METROPOLITAN TORONTO WORKS DEPT.	COMMISSIONERS INCINERATOR 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	0.0	42
CITY OF TORONTO	COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
INTERNORTH CONSTRUCTION CO. LTD. 21-518	400 COMMISSIONER STREET, TORONTO C/O DIXIE ROAD MISISSAUGA ON L4W 1N2	0.0	42
CANADA CRINC, LTD.	400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42
CANADA CRINC, LTD. 07-534	400 COMMISSIONERS STREET TORONTO ON M4M 3K2	0.0	42

Site	Address	Distance (m)	Map Key
ESSO PETROLUEM CANADA	185 VILLIERS STREET C/O 55 ST. CLAIR AVE. WEST TORONTO ON M5W 2J8	0.0	47
Toronto Port Lands Company	185 Villiers Street Toronto ON M5A 1A1	0.0	47
ESSO PETROLUEM CANADA 14-857	185 VILLIERS STREET C/O 55 ST. CLAIR AVE. WEST TORONTO ON M5W 2J8	0.0	47
ESSO PETROLUEM CANADA	185 VILLIERS STREET TORONTO ON	0.0	47
Hydro One Networks Inc.	Cable Joint Bay #2 N. Side of Villiers St., 52m W. of Saulter St. Toronto ON M4M 3J4	0.1	48

NPRI - National Pollutant Release Inventory

A search of the NPRI database, dated 1993-May 2017 has found that there are 12 NPRI site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	0.0	42
CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	0.0	42
CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	0.0	42
City of Toronto	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	0.0	42
CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	0.0	42

Site	Address	Distance (m)	Map Key
CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	0.0	42
CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	0.0	42
CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	0.0	42
CITY OF TORONTO	400 COMMISSIONERS Street TORONTO ON M4M3K2	0.0	43
CITY OF TORONTO	400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	0.0	43
CITY OF TORONTO	400 COMMISSIONERS Street TORONTO ON M4M3K2	0.0	43
CITY OF TORONTO	400 COMMISSIONERS Street TORONTO ON M4M3K2	0.0	43

PRT - Private and Retail Fuel Storage Tanks

A search of the PRT database, dated 1989-1996* has found that there are 2 PRT site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SMS PETROLEUMS DIVISION OF SUNOCO	300 COMMISSIONERS ST TORONTO ON M4M 1A4	0.0	4
METROPOLITAN WORKS DEPT SOLID WASTE MANAGEMENT DIV	400 COMMISSIONERS ST TORONTO ON M4M 3K2	0.0	42

RSC - Record of Site Condition

A search of the RSC database, dated 1997-Sept 2001, Oct 2004-Jul 2019 has found that there are 2 RSC site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
City of Toronto Economic Development Corporation (TEDCO)	300 COMMISSIONERS ST, TORONTO, ON, M4M 1A4 TORONTO ON M4M 1A4	0.0	4
City of Toronto Economic Development Corporation	281 Commissioners Street, Pursuant to Committee of Adjustment approval, addresse ON	0.0	25

SCT - Scott's Manufacturing Directory

A search of the SCT database, dated 1992-Mar 2011* has found that there are 1 SCT site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
TEPERMAN & SONS INC	280 COMMISSIONERS ST TORONTO ON M4M 1A4	0.0	7

SPL - Ontario Spills

A search of the SPL database, dated 1988-Feb 2019 has found that there are 16 SPL site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
SUNOCO	300 COMMISSIONER ST. TANK FARM TORONTO CITY ON	0.0	4
SUNOCO	300 COMISSIONER ST. BULK STATION TORONTO CITY ON	0.0	4
SUNOCO	SUNOCO 300 COMMISSIONERS STREET TANK FARM TORONTO CITY ON	0.0	4
SUNOCO	300 COMMISSIONER TANK FARM TORONTO CITY ON	0.0	4

Site	Address	Distance (m)	Map Key
SUN-CANADIAN PIPE LINE COMPANY	300 COMMISIONERS ST. TRANSPORT TRUCK (CARGO) TORONTO CITY ON	0.0	4
CANADIAN NORTHERN RECYCLING.	280 COMMISSIONERS RD. 280 COMMISSIONERS RD. TORONTO CITY ON M4M 1A4	0.0	7
PRIVATE BUSINESS	280 COMISSIONER STREET,(WATERFRONT) (N.O.S.) TORONTO CITY ON	0.0	7
City of Toronto	Commissioners and Bouchette Toronto ON	0.0	17
TEPPERMAN AND SONS	COMMISSIONERS AND SAULTAR ST. TORONTO CITY ON	0.0	31
UNKNOWN	VILLIERS ST. COMMISSIONERS ST. TORONTO CITY ON	0.0	39
UNKNOWN	VILLIERS & COMMISSIONERS STS. TORONTO CITY ON	0.0	39
	400 Commissioners Street Toronto ON M4M 3K2	0.0	42
City of Toronto	400 Commissioners St Toronto ON M4M 3K2	0.0	42
Badger Daylighting Ltd.	400 Commissioners st Toronto ON	0.0	42
City of Toronto	400 Commissioners St Toronto ON NA	0.0	42
METROPOLITAN TORONTO, MUNICIPA	400 COMMISSIONERS STREET HOUSEHOLD HAZARDOUS WASTE FACILITY 400 COMMISSIONERS STREET TORONTO CITY ON M4M 3K2	0.0	42

Site	Address	Distance (m)	Map Key

TANK - Anderson's Storage Tanks

A search of the TANK database, dated 1915-1953* has found that there are 5 TANK site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
Barrett Roofing Co	701 Lake Shore Blvd E Toronto ON	2.7	50
Barrett Co Ltd	701 Lake Shore Blvd E Toronto ON	2.7	50
Barrett Co Ltd	701 Lake Shore Blvd E Toronto ON	2.7	50
Barrett Co Ltd	701 Lake Shore Blvd E Toronto ON	2.7	50
Barrett Co Ltd	701 Lake Shore Blvd E Toronto ON	2.7	50

WDS - Waste Disposal Sites - MOE CA Inventory

A search of the WDS database, dated Oct 2011-Sep 30, 2019 has found that there are 37 WDS site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42

Site	Address	Distance (m)	Map Key
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners St Toronto ON M5H 2N2	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	0.0	42
	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	0.0	42

Site	Address	Distance (m)	Map Key
	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	0.0	42
	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	0.0	42
	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	0.0	42
COMMISSIONER STREET WASTE TRAN	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	0.0	42
	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	0.0	42
	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	0.0	42
	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	0.0	42
	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M4M 3K2	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	0.0	42

Site	Address	Distance (m)	Map Key
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5V 3C6	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners Street Toronto ON M5H 2N2	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42
City of Toronto	400 Commissioners St Toronto ON M3J 2B7	0.0	42

WWIS - Water Well Information System

A search of the WWIS database, dated Feb 28, 2019 has found that there are 13 WWIS site(s) within approximately 0.00 kilometers of the project property.

Site	Address	Distance (m)	Map Key
	Toronto ON ***Well ID:*** 7156208	0.0	2
	TORONTO ON ***Well ID:*** 7242115	0.0	3
	TORONTO ON ***Well ID:*** 7116763	0.0	5
	TORONTO ON ***Well ID:*** 7242114	0.0	9
	Toronto ON ***Well ID:*** 7247923	0.0	10
	TORONTO ON ***Well ID:*** 7242116	0.0	11
	TORONTO ON ***Well ID:*** 7192708	0.0	21
	Toronto ON ***Well ID:*** 7247922	0.0	22
	Toronto ON ***Well ID:*** 7138467	0.0	27
	Toronto ON ***Well ID:*** 7192710	0.0	29
	ON	0.0	34

Site	Address	Distance (m)	Map Key
	Well ID: 7238823		
	TORONTO ON ***Well ID:*** 6927829	0.0	36
	TORONTO ON ***Well ID:*** 7192709	0.0	37

79°20'30"W

Map : 0.005 Kilometer Radius

Order No: 20191015053

Address: 225 Commissioners St, Toronto, ON, M4M 0A1

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Expressway
- Principal Highway
- Secondary Highway
- Major Road
- Local road
- Trail
- Proposed Road
- Ferry Route/Ice Road
- Industrial and Resource - Regions
- Main Line
- Sidetrack
- Transit Line
- Abandoned Line
- National Park
- Provincial or Territorial Park
- Other Park
- Golf Course or Driving Range
- Park or Sports Field
- Other Recreation Area

Source: © 2015 DMTI Spatial Inc.

© ERIS Information Limited Partnership

79°21'W



Aerial (2017)

Address: 225 Commissioners St, Toronto, ON, M4M 0A1

Source: ESRI World Imagery

Order No: 20191015053

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership



Topographic Map

Address: 225 Commissioners St, Toronto, ON, M4M 0A1

Source: ESRI World Topographic Map

Order No: 20191015053

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Limited Partnership

Detail Report

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
1	1 of 1	-/0.0	78.8 / -1.01	ON	BORE

Borehole ID:	654204	**Inclin FLG:**	No
OGF ID:	215554550	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	SEP-1960	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.650859
Total Depth m:	10.7	**Longitude DD:**	-79.341031
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633785
Drill Method:	Boring	**Northing:**	4834433
Orig Ground Elev m:	76.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	77.1		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218542365	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:	Wood Fragments	**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND(30),SILT(20), WOOD.		

Geology Stratum ID:	218542368	**Mat Consistency:**	Compact
Top Depth:	8.7	**Material Moisture:**	
Bottom Depth:	10.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND,SILT. GREY,COMPACT. 0000000300060002001700030028505 2M. BRO **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218542366	**Mat Consistency:**	
Top Depth:	1.8	**Material Moisture:**	
Bottom Depth:	5.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Peat	**Geologic Group:**	

Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	peat
Gsc Material Description:			
Stratum Description:	SILT(20),PEAT.		

Geology Stratum ID:	218542367	**Mat Consistency:**	
Top Depth:	5.2	**Material Moisture:**	
Bottom Depth:	8.7	**Material Texture:**	
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Silt	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND,SILT. GREY.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR3.txt RecordID: 248690 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

2	1 of 1	-/0.0	79.8 / 0.00	Toronto ON	WWIS

Well ID:	7156208	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	12/9/2010
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	7
Audit No:	Z122232	**Owner:**	
Tag:	A107413	**Street Name:**	115 SAULTER ST. S
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1003435126	**Elevation:**	77.349388
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633683
Code OB Desc:		**North83:**	4834455
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	11/5/2010	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1003741014
Layer:	3
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	05
Other Materials:	CLAY
Mat3:	68
Other Materials:	DRY
Formation Top Depth:	7
Formation End Depth:	15
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003741012
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	68
Other Materials:	DRY
Formation Top Depth:	0
Formation End Depth:	5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003741013
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	68

Other Materials:	DRY
Formation Top Depth:	5
Formation End Depth:	7
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1003741015
Layer:	4
Color:	2
General Color:	GREY
Mat1:	28
Most Common Material:	SAND
Mat2:	05
Other Materials:	CLAY
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	15
Formation End Depth:	20
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003741024
Layer:	2
Plug From:	1
Plug To:	9
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003741025
Layer:	3
Plug From:	9
Plug To:	20
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1003741023
Layer:	1
Plug From:	0
Plug To:	1
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	2
Method Construction:	Rotary (Convent.)
Other Method Construction:	

Pipe Information

Pipe ID:	1003741011
Casing No:	0

Comment:
Alt Name:

Construction Record - Casing

Casing ID:	1003741018
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	10
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003741019
Layer:	1
Slot:	10
Screen Top Depth:	10
Screen End Depth:	20
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2

Hole Diameter

Hole ID:	1003741016
Diameter:	8.25
Depth From:	0
Depth To:	20
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

3 ***1 of 1*** ***-/0.0*** ***77.3 / -2.54*** ***WWIS***

TORONTO ON

Well ID:	7242115	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring and Test Hole	***Date Received:***	5/28/2015
Sec. Water Use:	0	***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	7
Audit No:	Z207848	***Owner:***	
Tag:	A180148	***Street Name:***	300 COMMISSIONERS ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005386611	***Elevation:***	76.905685
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633774
Code OB Desc:		***North83:***	4834388
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	4/22/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1005613862
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005613863
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	11
Other Materials:	GRAVEL
Formation Top Depth:	5
Formation End Depth:	18
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005613872
Layer:	2
Plug From:	7
Plug To:	0
Plug Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1005613871
Layer:	1
Plug From:	18
Plug To:	7
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005613873
Layer:	3
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005613861
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005613866
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	8
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005613867
Layer:	1
Slot:	.10
Screen Top Depth:	8
Screen End Depth:	18
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Hole Diameter

Hole ID:	1005613864
Diameter:	8
Depth From:	0

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Depth To:		18			
Hole Depth UOM:		ft			
Hole Diameter UOM:		inch			

4	1 of 22	-/0.0	77.7 / -2.14	**ARCTURUS ENVIRONMENTAL LIMITED** **300 COMMISSIONERS STREET** **TORONTO CITY ON**	CA

Certificate #:	8-3248-96-
Application Year:	96
Issue Date:	7/25/1996
Approval Type:	Industrial air
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	SOIL VAP. EXTRACTION/BIOFILTER TREATMENT
Contaminants:	
Emission Control:	

4	2 of 22	-/0.0	77.7 / -2.14	**Arcturus Environmental Limited** **300 Commissioners Street Toronto ON**	EBR

EBR Registry No:	IA6E0827	**Decision Posted:**	
Ministry Ref No:	8324896 19960514	**Exception Posted:**	
Notice Type:	Instrument Decision	**Section:**	
Notice Stage:	800469081	**Act 1:**	
Notice Date:	July 30, 1996	**Act 2:**	
Proposal Date:	May 23, 1996	**Site Location Map:**	
Year:	1996		
Instrument Type:	(EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)		
Off Instrument Name:			
Posted By:			
Company Name:	Arcturus Environmental Limited		
Site Address:			
Location Other:			
Proponent Name:			
Proponent Address:	7900 Canadian Drive, Niagara Falls Ontario, L2E 6S5		
Comment Period:			
URL:			

Site Location Details:

300 Commissioners Street Toronto

4	3 of 22	-/0.0	77.7 / -2.14	**NOCO LUBRICANTS CANADA** **300 COMMISSIONERS ST** **TORONTO ON**	EXP

Instance No:	10462450
Instance ID:	19834
Instance Type:	FS Highway Tank - Gas/Diesel
Description:	FS HIGHWAY TANK - GASOLINE/DIESEL
Status:	EXPIRED
TSSA Program Area:	
Maximum Hazard Rank:	
Facility Type:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Expired Date:					

4	4 of 22	-/0.0	77.7 / -2.14	SMS PETROLEUMS DIVISION OF SUNOCO NANCY NG 300 COMMISSIONERS ST TORONTO ON NULL	FST

Instance No: 11009874
Cont Name:
Instance Type: FS Liquid Fuel Tank
Fuel Type: Diesel
Status: Active
Capacity: 36368
Tank Material: Steel
Corrosion Protection: Impressed Current
Tank Type: Single Wall UST
Install Year: 1978
Parent Facility Type: Fuels Safety Private Fuel Outlet - Self Serve
Facility Type: FS Liquid Fuel Tank

4	5 of 22	-/0.0	77.7 / -2.14	SMS PETROLEUMS DIVISION OF SUNOCO NANCY NG 300 COMMISSIONERS ST TORONTO ON	FSTH

License Issue Date: 12/23/1991
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1978
Corrosion Protection:
Capacity: 36368
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

4	6 of 22	-/0.0	77.7 / -2.14	SMS PETROLEUMS DIVISION OF SUNOCO NANCY NG 300 COMMISSIONERS ST TORONTO ON	FSTH

License Issue Date: 12/23/1991
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1978
Corrosion Protection:
Capacity: 36368
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	7 of 22	-/0.0	77.7 / -2.14	Toronto Port Lands Company 300 Commissioners Street Toronto ON M4M 1A4	GEN

Generator No: ON6374513
Status:
Approval Years: 2015
Contam. Facility: No
MHSW Facility: No
SIC Code: 531310
SIC Description: REAL ESTATE PROPERTY MANAGERS

PO Box No:
Country: Canada
Choice of Contact: CO_OFFICIAL
Co Admin: Tim Speirs
Phone No Admin: 905-567-4444 Ext.1476

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	8 of 22	-/0.0	77.7 / -2.14	SUNOCO INC. 36-136 300 COMMISSIONERS ST., TORONTO C/O 36 YORK MILLS RD. NORTH YORK ON M2P 2C5	GEN

Generator No: ON0004903
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 3611
SIC Description: REFINED PETRO. PROD.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	9 of 22	-/0.0	77.7 / -2.14	SUNOCO INC. 300 COMMISSIONERS ST., TORONTO C/O 36 YORK MILLS RD. NORTH YORK ON M2P 2C5	GEN

Generator No: ON0004903
Status:
Approval Years: 90
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

4 | **10 of 22** | **-/0.0** | **77.7 / -2.14** | **SUNOCO INC.**
300 COMMISSIONERS STREET
TORONTO ON M4M 1A4 | **GEN**

Generator No: ON0004903
Status:
Approval Years: 86,87,88,89
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

4 | **11 of 22** | **-/0.0** | **77.7 / -2.14** | **SUN-(OUT OF BUS) 36-439**
LIMITED 300 COMMISSIONERS ST.
TORONTO ON M4M 1A4 | **GEN**

Generator No: ON0166706
Status:
Approval Years: 97
Contam. Facility:
MHSW Facility:
SIC Code: 4619
SIC Description: OTHER PIPELINE TRANS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

4 | **12 of 22** | **-/0.0** | **77.7 / -2.14** | **SUN-(OUT OF BUSINESS)**
300 COMMISSIONERS STREET
TORONTO ON M4M 1A4 | **GEN**

Generator No: ON0166706
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 4619
SIC Description: OTHER PIPELINE TRANS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

4 | ***13 of 22*** | ***-/0.0*** | ***77.7 / -2.14*** | ***SUN-CANADIAN PIPE LINE COMPANY 36-439 LIMITED 300 COMMISSIONERS ST. TORONTO ON M4M 1A4*** | ***GEN***

Generator No: ON0166706
Status:
Approval Years: 92,93,94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 4619
SIC Description: OTHER PIPELINE TRANS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

4 | ***14 of 22*** | ***-/0.0*** | ***77.7 / -2.14*** | ***SUN-CANADIAN PIPE LINE COMPANY LIMITED 300 COMMISSIONERS ST. TORONTO ON M4M 1A4*** | ***GEN***

Generator No: ON0166706
Status:
Approval Years: 88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 4619
SIC Description: OTHER PIPELINE TRANS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

4 | ***15 of 22*** | ***-/0.0*** | ***77.7 / -2.14*** | ***SUNOCO INC. 300 COMMISSIONERS ST., TORONTO ON M4M 1A4*** | ***GEN***

Generator No: ON0004903
Status:
Approval Years: 92,93,97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 3611
SIC Description: REFINED PETRO. PROD.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Waste Class:		252			
Waste Class Desc:		WASTE OILS & LUBRICANTS			
4	16 of 22	-/0.0	77.7 / -2.14	SMS PETROLEUMS DIVISION OF SUNOCO 300 COMMISSIONERS ST TORONTO ON M4M 1A4	PRT
Location ID:		15231			
Type:		private			
Expiry Date:					
Capacity (L):		36368.00			
Licence #:		0001063413			
4	17 of 22	-/0.0	77.7 / -2.14	City of Toronto Economic Development Corporation (TEDCO) 300 COMMISSIONERS ST, TORONTO, ON, M4M 1A4 TORONTO ON M4M 1A4	RSC
RSC ID:		36901		**Cert Date:**	
RA No:				**Cert Prop Use No:**	
RSC Type:				**Intended Prop Use:**	
Curr Property Use:				**Qual Person Name:**	
Ministry District:		TORONTO		**Stratified (Y/N):**	
Filing Date:		Oct 16, 2008		**Audit (Y/N):**	
Date Ack:				**Entire Leg Prop. (Y/N):**	
Date Returned:				**Accuracy Estimate:**	
Restoration Type:				**Telephone:**	
Soil Type:				**Fax:**	
Criteria:				**Email:**	
CPU Issued Sect 1686:					
Asmt Roll No:					
Prop ID No (PIN):					
Property Municipal Address:					
Mailing Address:					
Latitude & Latitude:					
UTM Coordinates:					
Consultant:					
Filing Owner:					
Legal Desc:					
Measurement Method:					
Applicable Standards:					
RSC PDF:					
4	18 of 22	-/0.0	77.7 / -2.14	SUNOCO 300 COMMISSIONER TANK FARM TORONTO CITY ON	SPL
Ref No:		57111		**Discharger Report:**	
Site No:				**Material Group:**	
Incident Dt:		9/10/1991		**Health/Env Conseq:**	
Year:				**Client Type:**	
Incident Cause:		VALVE/FITTING LEAK OR FAILURE		**Sector Type:**	
Incident Event:				**Agency Involved:**	
Contaminant Code:				**Nearest Watercourse:**	
Contaminant Name:				**Site Address:**	
Contaminant Limit 1:				**Site District Office:**	
Contam Limit Freq 1:				**Site Postal Code:**	
Contaminant UN No 1:				**Site Region:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Environment Impact:	CONFIRMED	**Site Municipality:**	01106
Nature of Impact:	Soil contamination	**Site Lot:**	
Receiving Medium:	LAND / AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/10/1991	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	EQUIPMENT FAILURE	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SUNOCO STORAGE TANK-100 LGASOLINE TO GROUND FROM SEAL LEAK.		
Contaminant Qty:			

---

4 | ***19 of 22*** | ***-/0.0*** | ***77.7 / -2.14*** | ***SUN-CANADIAN PIPE LINE COMPANY***
300 COMMISIONERS ST. TRANSPORT TRUCK (CARGO)
TORONTO CITY ON | ***SPL***

Ref No:	71128	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	5/25/1992	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	PIPE/HOSE LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	CONFIRMED	**Site Municipality:**	01106
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	5/25/1992	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	ERROR	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SUN CANADIAN PIPELINE: 25-50 L DIESEL FUEL TO GRND FROM PIPE.		
Contaminant Qty:			

---

4 | ***20 of 22*** | ***-/0.0*** | ***77.7 / -2.14*** | ***SUNOCO***
300 COMMISSIONER ST. TANK FARM
TORONTO CITY ON | ***SPL***

Ref No:	21184	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	6/28/1989	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No		**Site Region:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

1:

Environment Impact:	NOT ANTICIPATED	Site Municipality:	01106
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	6/28/1989	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	UNKNOWN	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	BUMSTEAD TRUCKING -600 L.GASOLINE TO GROUND AT SUNOCO TANK FARM.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	21 of 22	-/0.0	77.7 / -2.14	SUNOCO 300 COMISSIONER ST. BULK STATION TORONTO CITY ON	SPL

Ref No:	55061	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	8/2/1991	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	OTHER CONTAINER LEAK	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	
Contaminant UN No 1:		Site Region:	
Environment Impact:	NOT ANTICIPATED	Site Municipality:	01106
Nature of Impact:		Site Lot:	
Receiving Medium:	LAND	Site Conc:	
Receiving Env:		Northing:	
MOE Response:		Easting:	
Dt MOE Arvl on Scn:		Site Geo Ref Accu:	
MOE Reported Dt:	8/2/1991	Site Map Datum:	
Dt Document Closed:		SAC Action Class:	
Incident Reason:	EQUIPMENT FAILURE	Source Type:	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SUN OIL -50 L. GASOLINE TO CONCRETE PAD DUE TO SUMP OVERFLOW.		
Contaminant Qty:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
4	22 of 22	-/0.0	77.7 / -2.14	SUNOCO SUNOCO 300 COMMISSIONERS STREET TANK FARM TORONTO CITY ON	SPL

Ref No:	2578	Discharger Report:	
Site No:		Material Group:	
Incident Dt:	4/18/1988	Health/Env Conseq:	
Year:		Client Type:	
Incident Cause:	UNKNOWN	Sector Type:	
Incident Event:		Agency Involved:	
Contaminant Code:		Nearest Watercourse:	
Contaminant Name:		Site Address:	
Contaminant Limit 1:		Site District Office:	
Contam Limit Freq 1:		Site Postal Code:	

Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	1106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	4/18/1988	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	

Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: SUNOCO-50000 L OF UNLEAD-ED GASOLINE SPILLED TO GROUND
Contaminant Qty:

---

5 **1 of 1** **-/0.0** **77.3 / -2.56** **TORONTO ON** **WWIS**

Well ID:	7116763	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Test Hole	**Date Received:**	12/18/2008
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7215
Casing Material:		**Form Version:**	7
Audit No:	Z90060	**Owner:**	
Tag:	A079245	**Street Name:**	COMMISSIONERS & BOUCHETTE ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1001912202	**Elevation:**	76.786026
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633797
Code OB Desc:		**North83:**	4834398
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	3
Date Completed:	10/14/2008	**UTMRC Desc:**	margin of error : 10 - 30 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1002026976
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	
Other Materials:	
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	0
Formation End Depth:	4
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1002026977
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	05
Most Common Material:	CLAY
Mat2:	28
Other Materials:	SAND
Mat3:	91
Other Materials:	WATER-BEARING
Formation Top Depth:	4
Formation End Depth:	10
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1002026981
Layer:	3
Plug From:	1
Plug To:	0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1002026979
Layer:	1
Plug From:	10
Plug To:	4
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1002026980
Layer:	2
Plug From:	4
Plug To:	1
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1002026975
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1002026983
Layer:
Material:
Open Hole or Material:
Depth From:
Depth To:
Casing Diameter:
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1002026984
Layer: 1
Slot: 10
Screen Top Depth: 5
Screen End Depth: 10
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2

Hole Diameter

Hole ID: 1002026978
Diameter: 8
Depth From: 10
Depth To: 0
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

6 | **1 of 1** | **-/0.0** | **77.0 / -2.84** | **Commissioners Street Toronto ON** | **EHS**

Order No: 20080909017
Status: C
Report Type: Standard Report
Report Date: 9/12/2008
Date Received: 9/9/2008
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection: East of Don Roadway
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: -79.341079
Y: 43.650437

---

7 | **1 of 13** | **-/0.0** | **79.8 / 0.00** | **A J SELF STORAGE INC 280 COMMISSIONERS ST** | **AUWR**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
				TORONTO ON M4M 1A4	

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone:
List Name:
Description:

7	2 of 13	-/0.0	79.8 / 0.00	SCRAP WASTE & SALT 280 COMMISSIONERS ST TORONTO ON M4M 1A4	AUWR

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone:
List Name:
Description:

7	3 of 13	-/0.0	79.8 / 0.00	TEPERMAN SCRAP METAL 280 COMMISSIONERS ST TORONTO ON M4M 1A4	AUWR

Headcode: 1169400
Headcode Desc: Scrap Metals
Phone: 4164636644
List Name:
Description:

7	4 of 13	-/0.0	79.8 / 0.00	A J SELF STORAGE INC 280 COMMISSIONERS ST TORONTO ON M4M1A4	AUWR

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone: 4164636644
List Name:
Description:

7	5 of 13	-/0.0	79.8 / 0.00	TEPERMAN DEMOLITION & WASTE INC 280 COMMISSIONERS ST TORONTO ON M4M 1A4	AUWR

Headcode: 1169400
Headcode Desc: Scrap Metals
Phone: 4164636344
List Name:
Description: Other Waste Materials, Wholesale

7	6 of 13	-/0.0	79.8 / 0.00	TEPERMAN 280 COMMISSIONERS ST TORONTO ON M4M 1A4	AUWR

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone:
List Name:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
Description:					

7	7 of 13	-/0.0	79.8 / 0.00	SCRAP WASTE & SALT 280 COMMISSIONERS ST TORONTO ON M4M1A4	AUWR

Headcode: 01169400
Headcode Desc: SCRAP METALS
Phone: 4164636644
List Name:
Description:

7	8 of 13	-/0.0	79.8 / 0.00	TEPERMAN AND SONS INC. 37-220 280 COMMISSIONERS ST. TORONTO ON M4M 1A4	GEN

Generator No: ON0693900
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 4499
SIC Description: OTHER CONST. SERVICE

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

7	9 of 13	-/0.0	79.8 / 0.00	TEPERMAN AND SONS INC. 280 COMMISSIONERS ST. TORONTO ON M4M 1A4	GEN

Generator No: ON0693900
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 4499
SIC Description: OTHER CONST. SERVICES

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

7	10 of 13	-/0.0	79.8 / 0.00	TEPERMAN AND SONS INC. 280 COMMISSIONERS STREET TORONTO ON M4M 1A4	GEN

Generator No: ON0693900
Status:
Approval Years: 92,93,97,98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4499

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

SIC Description: OTHER CONST. SERVICE

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

7 | **11 of 13** | **-/0.0** | **79.8 / 0.00** | **TEPERMAN & SONS INC**
280 COMMISSIONERS ST
TORONTO ON M4M 1A4 | **SCT**

Established: 1918
Plant Size (ft²):
Employment: 25

--Details--
Description: LUMBER, PLYWOOD, MILLWORK, & WOOD PANELS
SIC/NAICS Code: 5031

---

7 | **12 of 13** | **-/0.0** | **79.8 / 0.00** | **CANADIAN NORTHERN RECYCLING.**
280 COMMISSIONERS RD. 280 COMMISSIONERS RD.
TORONTO CITY ON M4M 1A4 | **SPL**

Ref No: 170849
Site No:
Incident Dt: 7/29/1999
Year:
Incident Cause: UNKNOWN
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: POSSIBLE
Nature of Impact: Multi Media Pollution
Receiving Medium: LAND / AIR
Receiving Env:
MOE Response:
Dt MOE Arvl on Scn:
MOE Reported Dt: 7/29/1999
Dt Document Closed:
Incident Reason: FIRE/EXPLOSION
Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: CANADIAN NORTHERN RECY- CLING-50 CARS ON FIRE,EX-TINGUISHED,OILY RUNOFF,FD
Contaminant Qty:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 1106
Site Lot:
Site Conc:
Northing:
Easting: FD & WORKS
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class:
Source Type:

---

7 | **13 of 13** | **-/0.0** | **79.8 / 0.00** | **PRIVATE BUSINESS**
280 COMISSIONER STREET,(WATERFRONT) (N.O.S.)
TORONTO CITY ON | **SPL**

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Ref No:	228739	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	6/19/2002	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CAUSE (N.O.S.)	**Sector Type:**	
Incident Event:		**Agency Involved:**	TORONTO FIRE DEPARTMENT
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	POSSIBLE	**Site Municipality:**	01106
Nature of Impact:	Multi Media Pollution	**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/19/2002	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	FIRE, EXPLOSION	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	FIRE AT SCRAPYARD.LARGE AMT OF SMOKE GOING DOWN TOWN. REQUEST FOR TAGA		
Contaminant Qty:			

8	*1 of 2*	*-/0.0*	*77.8 / -2.02*	***300 Commissioners Street Toronto ON M4M 1A4***	***EHS***

Order No:	20180619035	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	25-JUN-18	**Search Radius (km):**	.3
Date Received:	19-JUN-18	**X:**	-79.34138
Previous Site Name:		**Y:**	43.651244
Lot/Building Size:			
Additional Info Ordered:			

8	*2 of 2*	*-/0.0*	*77.8 / -2.02*	***300 Commissioners St Toronto ON M4M1A4***	***EHS***

Order No:	20150327084	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	RSC Report (Urban)	**Client Prov/State:**	ON
Report Date:	02-APR-15	**Search Radius (km):**	.3
Date Received:	27-MAR-15	**X:**	-79.34064
Previous Site Name:		**Y:**	43.650544
Lot/Building Size:			
Additional Info Ordered:			

9	*1 of 1*	*-/0.0*	*77.3 / -2.56*	***TORONTO ON***	***WWIS***

Well ID:	7242114	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	5/28/2015
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241

Casing Material:		***Form Version:***	7
Audit No:	Z207850	***Owner:***	
Tag:	A176695	***Street Name:***	300 COMMISSIONERS ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005386608	***Elevation:***	76.760139
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633801
Code OB Desc:		***North83:***	4834399
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	4/22/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005613829
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	5
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005613830
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	11

Other Materials:	GRAVEL
Formation Top Depth:	5
Formation End Depth:	18
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005613839
Layer:	2
Plug From:	7
Plug To:	0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005613840
Layer:	3
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005613838
Layer:	1
Plug From:	18
Plug To:	7
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005613828
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005613833
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	8
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005613834
Layer:	1
Slot:	.10
Screen Top Depth:	8
Screen End Depth:	18
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Hole Diameter

Hole ID:	1005613831
Diameter:	8
Depth From:	0
Depth To:	18
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

10 ***1 of 1*** ***-/0.0*** ***79.2 / -0.63*** ***WWIS***

Toronto ON

Well ID:	7247923	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring	**Date Received:**	9/8/2015
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Observation Wells	**Abandonment Rec:**	
Water Type:		**Contractor:**	7201
Casing Material:		**Form Version:**	7
Audit No:	Z141621	**Owner:**	
Tag:	A164212	**Street Name:**	85 COMMISSIONERS ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005669694	**Elevation:**	77.591369
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633653
Code OB Desc:		**North83:**	4834416
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	8/27/2015	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1005734950
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	
Most Common Material:	
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	15
Formation End Depth:	30
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005734948
Layer:	1
Color:	2
General Color:	GREY
Mat1:	34
Most Common Material:	TILL
Mat2:	
Other Materials:	
Mat3:	01
Other Materials:	FILL
Formation Top Depth:	0
Formation End Depth:	10
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005734951
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	30
Formation End Depth:	52
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005734952
Layer:	5
Color:	2
General Color:	GREY
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	

Mat3:
Other Materials:
Formation Top Depth: 52
Formation End Depth: 70
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1005734949
Layer: 2
Color: 2
General Color: GREY
Mat1: 05
Most Common Material: CLAY
Mat2:
Other Materials:
Mat3:
Other Materials:
Formation Top Depth: 10
Formation End Depth: 15
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005734960
Layer: 1
Plug From: 0
Plug To: 58
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1005734961
Layer: 2
Plug From: 58
Plug To: 70
Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005734947
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005734956
Layer: 1
Material: 5

Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	60
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005734957
Layer:	1
Slot:	.10
Screen Top Depth:	60
Screen End Depth:	70
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Hole Diameter

Hole ID:	1005734954
Diameter:	4
Depth From:	52
Depth To:	70
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

Hole Diameter

Hole ID:	1005734953
Diameter:	8
Depth From:	0
Depth To:	52
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

---

11 ***1 of 1*** ***-/0.0*** ***77.8 / -2.02*** ***TORONTO ON*** ***WWIS***

Well ID:	7242116	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring and Test Hole	***Date Received:***	5/28/2015
Sec. Water Use:	0	***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	7
Audit No:	Z207849	***Owner:***	
Tag:	A176697	***Street Name:***	300 COMMISSIONERS ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1005386614	***Elevation:***	76.635574
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633835
Code OB Desc:		***North83:***	4834420
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	4/20/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1005613888
Layer:	2
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	11
Other Materials:	GRAVEL
Formation Top Depth:	5
Formation End Depth:	15
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005613887
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	06
Most Common Material:	SILT
Mat2:	28
Other Materials:	SAND
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	5
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005613896
Layer:	1
Plug From:	15
Plug To:	4
Plug Depth UOM:	ft

Annular Space/Abandonment

Sealing Record

Plug ID:	1005613897
Layer:	2
Plug From:	4
Plug To:	0
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005613898
Layer:	3
Plug From:	
Plug To:	
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1005613886
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1005613891
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	5
Casing Diameter:	2
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1005613892
Layer:	1
Slot:	.10
Screen Top Depth:	5
Screen End Depth:	15
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	2.25

Hole Diameter

Hole ID:	1005613889
Diameter:	8
Depth From:	0

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Depth To: 15
Hole Depth UOM: ft
Hole Diameter UOM: inch

---

12 | **1 of 1** | **-/0.0** | **79.8 / 0.00** | **115 Saulter, 41 Basin, 811 Lake Shore Toronto ON** | **EHS**

Order No: 20001128012
Status: C
Report Type: Complete Report
Report Date: 12/7/00
Date Received: 11/28/00
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.55
X: -79.34056
Y: 43.651682

---

13 | **1 of 2** | **-/0.0** | **78.8 / -1.07** | **TRUCKERS GARAGE LTD. 69 SAULTER ST. SOUTH TORONTO ON M4M 1A4** | **GEN**

Generator No: ON1013900
Status:
Approval Years: 88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

13 | **2 of 2** | **-/0.0** | **78.8 / -1.07** | **TRUCKERS (SEE & USE ON0693900) 38-481 69 SAULTER ST. SOUTH TORONTO ON M4M 1A4** | **GEN**

Generator No: ON1013900
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 6351
SIC Description: GARAGES(GEN. REPAIR)

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

---

14 | **1 of 1** | **-/0.0** | **79.8 / -0.06** | **ON** | **BORE**

Borehole ID: 644981
OGF ID: 215545364
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1950
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: -999
Depth Ref: Ground Surface
Depth Elev:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.651296
Longitude DD: -79.340151
UTM Zone: 17
Easting: 633855

Drill Method:	Diamond Drill	**Northing:**	4834483
Orig Ground Elev m:	77.1	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	77.5		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509627	**Mat Consistency:**	
Top Depth:	2.3	**Material Moisture:**	
Bottom Depth:	4.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	SAND,CLAY.		

Geology Stratum ID:	218509626	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218509628	**Mat Consistency:**	
Top Depth:	4.7	**Material Moisture:**	
Bottom Depth:	12.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach
Gsc Material Description:			
Stratum Description:	SAND. BEACH,AGE POST-GLACIAL.		

Geology Stratum ID:	218509629	**Mat Consistency:**	
Top Depth:	12.6	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK. AND,G **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 130030 NTS_Sheet: 30M11C		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

15 | **1 of 1** | **-/0.0** | **77.6 / -2.22** | **Lake Shore Blvd E and Don Roadway in Toronto**
Toronto ON M4M | **EHS**

Order No: 20180927150
Status: C
Report Type: Custom Report
Report Date: 24-OCT-18
Date Received: 27-SEP-18
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.34162
Y: 43.649985

---

16 | **1 of 1** | **-/0.0** | **78.0 / -1.85** | **Chai Kosher Poultry**
115 Saulter Street South
Toronto ON M4M 3K8 | **GEN**

Generator No: ON7483847
Status:
Approval Years: 05
Contam. Facility:
MHSW Facility:
SIC Code: 311615
SIC Description: Poultry Processing
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

17 | **1 of 1** | **-/0.0** | **78.2 / -1.60** | **City of Toronto**
Commissioners and Bouchette
Toronto ON | **SPL**

Ref No: 1762-89GM78
Site No:
Incident Dt:
Year:
Incident Cause: Pipe Or Hose Leak
Incident Event:
Contaminant Code: 15
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact: Other Impact(s)
Receiving Medium:
Receiving Env:
Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Motor Vehicle
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Northing:

MOE Response:	No Field Response	**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	9/20/2010	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Land Spills
Incident Reason:	Spill	**Source Type:**	

Site Name: Spill site<UNOFFICIAL>
Site County/District:
Site Geo Ref Meth:
Incident Summary: City of Toronto- 50 Litres hyd oil to rd. Comm & Bouchette
Contaminant Qty: 50 L

---

18 | **1 of 1** | **-/0.0** | **78.8 / -1.01** | **ON** | **BORE**

Borehole ID:	644982	**Inclin FLG:**	No
OGF ID:	215545365	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1950	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.650977
Total Depth m:	-999	**Longitude DD:**	-79.339912
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633875
Drill Method:	Diamond Drill	**Northing:**	4834448
Orig Ground Elev m:	77.1	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	77.1		

Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218509633	**Mat Consistency:**	
Top Depth:	13.4	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: BEDROCK.

Geology Stratum ID:	218509630	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill

Gsc Material Description:
Stratum Description: FILL.

Geology Stratum ID:	218509631	**Mat Consistency:**	
Top Depth:	2.3	**Material Moisture:**	
Bottom Depth:	7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	

Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY. LACUSTRINE.		

Geology Stratum ID:	218509632	**Mat Consistency:**	
Top Depth:	7	**Material Moisture:**	
Bottom Depth:	13.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach
Gsc Material Description:			
Stratum Description:	SAND. BEACH,AGE POST-GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 130040 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
19	1 of 1	-/0.0	78.8 / -1.03	ON	BORE

Borehole ID:	640172	**Inclin FLG:**	No
OGF ID:	215540568	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	SEP-1950	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.650887
Total Depth m:	14.7	**Longitude DD:**	-79.339915
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633875
Drill Method:	Diamond Drill	**Northing:**	4834438
Orig Ground Elev m:	77.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	76.9		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218491238	***Mat Consistency:***	Soft
Top Depth:	3.1	***Material Moisture:***	
Bottom Depth:	5	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:	Organic	***Geologic Period:***	
Material 4:		***Depositional Gen:***	alluvial

Gsc Material Description:
Stratum Description: SILT,SAND,ORGANIC. ALLUVIAL,VERY SOFT, AGE POST-GLACIAL.

Geology Stratum ID:	218491241	***Mat Consistency:***	Dense
Top Depth:	8.9	***Material Moisture:***	
Bottom Depth:	13.1	***Material Texture:***	Medium
Material Color:	Grey	***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:		***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	glacial

Gsc Material Description:
Stratum Description: SAND-MEDIUM. GREY,FLUVIO-GLACIAL, VERY DENSE,AGE GLACIAL.

Geology Stratum ID:	218491242	***Mat Consistency:***	Soft
Top Depth:	13.1	***Material Moisture:***	
Bottom Depth:	14.7	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Bedrock	***Geologic Formation:***	
Material 2:	Marl	***Geologic Group:***	
Material 3:		***Geologic Period:***	Ordovician
Material 4:		***Depositional Gen:***	marine

Gsc Material Description:
Stratum Description: BEDROCK,MARL. MARINE,SOFT,AGE ORDOVICIAN.
00000008000430020007300500103001001630050025301900293l0 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218491235	***Mat Consistency:***	Loose
Top Depth:	0	***Material Moisture:***	
Bottom Depth:	1.3	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Gravel	***Geologic Group:***	
Material 3:		***Geologic Period:***	
Material 4:		***Depositional Gen:***	alluvial

Gsc Material Description:
Stratum Description: SAND,GRAVEL. ALLUVIAL,LOOSE, AGE POST-GLACIAL.

Geology Stratum ID:	218491239	***Mat Consistency:***	
Top Depth:	5	***Material Moisture:***	
Bottom Depth:	7.7	***Material Texture:***	
Material Color:		***Non Geo Mat Type:***	
Material 1:	Sand	***Geologic Formation:***	
Material 2:	Silt	***Geologic Group:***	
Material 3:	Organic	***Geologic Period:***	
Material 4:		***Depositional Gen:***	alluvial

Gsc Material Description:
Stratum Description: SAND,SILT,ORGANIC. ALLUVIAL,AGE POST-GLACIAL.

Geology Stratum ID:	218491236	***Mat Consistency:***	Soft
Top Depth:	1.3	***Material Moisture:***	
Bottom Depth:	2.2	***Material Texture:***	
Material Color:	Red	***Non Geo Mat Type:***	
Material 1:	Silt	***Geologic Formation:***	
Material 2:	Sand	***Geologic Group:***	
Material 3:		***Geologic Period:***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Material 4:		**Depositional Gen:**	alluvial
Gsc Material Description:			
Stratum Description:	SILT,SAND. ALLUVIAL,VERY SOFT,LAYERED, AGE POST-GLACIAL.		

Geology Stratum ID:	218491237	**Mat Consistency:**	Loose
Top Depth:	2.2	**Material Moisture:**	
Bottom Depth:	3.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	organic material	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	alluvial
Gsc Material Description:			
Stratum Description:	SAND,ORGANIC. ALLUVIAL,LOOSE, AGE POST-GLACIAL.		

Geology Stratum ID:	218491240	**Mat Consistency:**	
Top Depth:	7.7	**Material Moisture:**	
Bottom Depth:	8.9	**Material Texture:**	Fine to Medium
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Gravel	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-FINE TO MEDIUM,GRAVEL. FLUVIO-GLACIAL,AGE GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 081370 NTS_Sheet: 30M11F		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
20	1 of 1	-/0.0	77.9 / -1.98	115 Saulter Street Toronto ON	EHS

Order No:	20101029034	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	Standard Report	**Client Prov/State:**	ON
Report Date:	11/9/2010	**Search Radius (km):**	0.25
Date Received:	10/29/2010 3:39:25 PM	**X:**	-79.343224
Previous Site Name:		**Y:**	43.650948
Lot/Building Size:			
Additional Info Ordered:	Fire Insur. Maps and/or Site Plans; City Directory		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
21	1 of 1	-/0.0	79.8 / 0.00	TORONTO ON	WWIS

Well ID:	7192708	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	12/4/2012
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z160670	**Owner:**	
Tag:	A120962	**Street Name:**	120 BOUCHETTE STREET
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	WKQ-005399 A0-A02
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004214366	**Elevation:**	77.195663
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633656
Code OB Desc:		**North83:**	4834560
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/25/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004676405
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	85
Other Materials:	SOFT
Formation Top Depth:	3.1
Formation End Depth:	4.27
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004676404
Layer:	2
Color:	8

General Color:	BLACK
Mat1:	03
Most Common Material:	MUCK
Mat2:	06
Other Materials:	SILT
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0.61
Formation End Depth:	3.1
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004676403
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Other Materials:	SAND
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0
Formation End Depth:	0.61
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004676415
Layer:	3
Plug From:	0.91
Plug To:	4.27
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004676413
Layer:	1
Plug From:	0
Plug To:	0.3
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004676414
Layer:	2
Plug From:	0.3
Plug To:	0.91
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004676402
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004676408
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	1.22
Casing Diameter:	5.2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004676409
Layer:	1
Slot:	10
Screen Top Depth:	1.22
Screen End Depth:	4.27
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03

Hole Diameter

Hole ID:	1004676406
Diameter:	20.32
Depth From:	0
Depth To:	4.27
Hole Depth UOM:	m
Hole Diameter UOM:	cm

---

22 ***1 of 1*** ***-/0.0*** ***78.8 / -1.02*** ***WWIS***

Toronto ON

Well ID:	7247922	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring	***Date Received:***	9/8/2015
Sec. Water Use:		***Selected Flag:***	Yes
Final Well Status:	Observation Wells	***Abandonment Rec:***	
Water Type:		***Contractor:***	7201
Casing Material:		***Form Version:***	7
Audit No:	Z141622	***Owner:***	
Tag:	A172083	***Street Name:***	85 COMMISSIONERS ST
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	

Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1005669691	***Elevation:***	77.560668
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633683
Code OB Desc:		***North83:***	4834329
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	8/31/2015	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1005734870
Layer:	5
Color:	2
General Color:	GREY
Mat1:	17
Most Common Material:	SHALE
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	63
Formation End Depth:	79
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005734869
Layer:	4
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	35
Formation End Depth:	63
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005734867
Layer:	2

Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	10
Formation End Depth:	15
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005734868
Layer:	3
Color:	6
General Color:	BROWN
Mat1:	
Most Common Material:	
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	15
Formation End Depth:	35
Formation End Depth UOM:	ft

Overburden and Bedrock Materials Interval

Formation ID:	1005734866
Layer:	1
Color:	2
General Color:	GREY
Mat1:	34
Most Common Material:	TILL
Mat2:	
Other Materials:	
Mat3:	01
Other Materials:	FILL
Formation Top Depth:	0
Formation End Depth:	10
Formation End Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005734879
Layer:	2
Plug From:	67
Plug To:	79
Plug Depth UOM:	ft

Annular Space/Abandonment Sealing Record

Plug ID:	1005734878
Layer:	1
Plug From:	0
Plug To:	67

Plug Depth UOM: ft

Method of Construction & Well Use

Method Construction ID:
Method Construction Code: 2
Method Construction: Rotary (Convent.)
Other Method Construction:

Pipe Information

Pipe ID: 1005734865
Casing No: 0
Comment:
Alt Name:

Construction Record - Casing

Casing ID: 1005734874
Layer: 1
Material: 5
Open Hole or Material: PLASTIC
Depth From: 0
Depth To: 69
Casing Diameter: 2
Casing Diameter UOM: inch
Casing Depth UOM: ft

Construction Record - Screen

Screen ID: 1005734875
Layer: 1
Slot: .10
Screen Top Depth: 69
Screen End Depth: 79
Screen Material: 5
Screen Depth UOM: ft
Screen Diameter UOM: inch
Screen Diameter: 2.25

Hole Diameter

Hole ID: 1005734871
Diameter: 8
Depth From: 0
Depth To: 63
Hole Depth UOM: ft
Hole Diameter UOM: inch

Hole Diameter

Hole ID: 1005734872
Diameter: 4
Depth From: 63
Depth To: 79
Hole Depth UOM: ft
Hole Diameter UOM: inch

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
23	1 of 1	-/0.0	78.8 / -1.03	ON	BORE

Borehole ID:	640173	**Inclin FLG:**	No
OGF ID:	215540569	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	SEP-1950	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.649886
Total Depth m:	13.4	**Longitude DD:**	-79.342236
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633690
Drill Method:	Diamond Drill	**Northing:**	4834323
Orig Ground Elev m:	76.9	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	76.6		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218491243	**Mat Consistency:**	Loose
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	
Material Color:	Brown	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	alluvial
Gsc Material Description:			
Stratum Description:	SAND. BROWN,ALLUVIAL,LOOSE, AGE POST-GLACIAL.		

Geology Stratum ID:	218491245	**Mat Consistency:**	Dense
Top Depth:	7.3	**Material Moisture:**	
Bottom Depth:	9.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND. FLUVIO-GLACIAL,DENSE, AGE GLACIAL.		

Geology Stratum ID:	218491244	**Mat Consistency:**	Soft
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	7.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	organic material	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	alluvial
Gsc Material Description:			
Stratum Description:	SILT,ORGANIC. ALLUVIAL,VERY SOFT, AGE POST-GLACIAL.		

Geology Stratum ID:	218491246	**Mat Consistency:**	Dense
Top Depth:	9.1	**Material Moisture:**	
Bottom Depth:	13.4	**Material Texture:**	Coarse
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	

Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	glacial
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM TO COARSE. FLUVIO-GLACIAL,VERY DENSE, AGE GLACIAL. 0000000300050001002400300030008O **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR1B.txt RecordID: 081380 NTS_Sheet: 30M11F		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
24	1 of 1	-/0.0	75.7 / -4.11	ON	BORE

Borehole ID:	644957	**Inclin FLG:**	No
OGF ID:	215545340	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1950	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.650128
Total Depth m:	13.8	**Longitude DD:**	-79.340308
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633845
Drill Method:	Diamond Drill	**Northing:**	4834353
Orig Ground Elev m:	77.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	76		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509535	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	4.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			

Stratum Description: FILL.

Geology Stratum ID: 218509536
Top Depth: 4.6
Bottom Depth: 6.7
Material Color:
Material 1: Clay
Material 2: Muck
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: CLAY,MUCK.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: muck

Geology Stratum ID: 218509537
Top Depth: 6.7
Bottom Depth: 13.8
Material Color:
Material 1: Sand
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SAND. BEACH,AGE POST-GLACIAL. LE. M **Note: Many records provided by the department have a truncated [Stratum Description] field.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: beach

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 129790 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

25	1 of 2	-/0.0	78.0 / -1.84	**Commissioners St & Saulter St South 281 Commissioners Street Toronto ON**	EHS

Order No: 20050224024
Status: C
Report Type:
Report Date: 3/2/2005
Date Received: 2/24/2005
Previous Site Name:
Lot/Building Size:
Additional Info Ordered: Fire Insur. Maps and/or Site Plans

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.8
X: -79.342326
Y: 43.649691

25	2 of 2	-/0.0	78.0 / -1.84	**City of Toronto Economic Development Corporation 281 Commissioners Street, Pursuant to**	RSC

Committee of Adjustment approval, addresse
ON

RSC ID:	45041	***Cert Date:***	1-Feb-08
RA No:		***Cert Prop Use No:***	No CPU
RSC Type:		***Intended Prop Use:***	Industrial
Curr Property Use:	Industrial	***Qual Person Name:***	Mr. Jeffrey Steiner
Ministry District:	TORONTO	***Stratified (Y/N):***	
Filing Date:	14-Oct-08	***Audit (Y/N):***	
Date Ack:		***Entire Leg Prop. (Y/N):***	No
Date Returned:		***Accuracy Estimate:***	11 to 20 meters
Restoration Type:		***Telephone:***	416-2144640
Soil Type:		***Fax:***	416-2144660
Criteria:		***Email:***	jsteiner@tedco.ca
CPU Issued Sect 1686:	No		

Asmt Roll No: 08-1-090-0010-0000, 08-1-90-0020-0000, and 08-1-090-0020-0010 (Currently 19-04-08-1-090-00100-0000-0 6 and 19-04-08-1-090-00200 as documented in Secti

Prop ID No (PIN): Part of PIN 21385-0179 (LT), formerly PIN 21385-0122 (LT)

Property Municipal Address: 281 Commissioners Street, Pursuant to Committee of Adjustment approval, addresses changed to 275 (Formerly 281) Commissioners Street, Toronto, Ontario

Mailing Address: Metro Hall, 55 John Street, 7th Floor, Toronto, Ontario, M5V 3C6

Latitude & Latitude: 43.64797500N 79.34259530W (converted from UTM)

UTM Coordinates: NAD83 17-633665-4834110

Consultant:

Filing Owner:

Legal Desc: In the City of Toronto, in the Municipality of Metropolitan Toronto and Province of Ontario, being composed of Block A and part of Saulter Street according to Plan 673E registered in the Land Registry Office for the Metropolitan Toronto Registry Division (No. 64), the said part of Saulter Street being stopped-up and closed by City of Toronto By-law 18639 registered in the said Land Registry Office as Instrument 4984E.S., SUBJECT TO an Easement in favour of the Corporation of the City of Toronto, its successors and assigns, for watermain purposes in, over, along and upon the westerly 3.05 metres throughout of the hereinbefore described lands as set out in Instrument 35141E.S. SUBJECT TO a covenant in favour of the Corporation of the City of Toronto, its successors and assigns, allowing the Corporation of the City of Toronto to acquire a reconveyance of the hereinbefore described lands from the Toronto Harbour Commissioners, its successors and assigns, for the purposes of restoring Saulter Street to a width of 20.12 metres as set out in Instrument 35141E.S. SUBJECT TO an Easement in favour of The Hydro-Electric Power Commission of Ontario, its successors and assigns, to operate and maintain overhead wires, over that part of the said Block A as set out in Instrument 39567E.S. AND SUBJECT TO an Easement in favour of Ontario Hydro, its successors and assigns, to construct, operate and maintain an electrical transmission line or lines, in through and under that part of the said Saulter Street as closed, as set out in Instrument CT444365. This RSC covers only Parts 4, 5, 6 and 7 on Plan 66R-22808 being Part of Saulter Street, Plan 673E, City of Toronto, being part of PIN 21385-0179 (LT) formerly PIN 21385-0122 (LT) as shown on Legal Survey in Section 2.

Measurement Method: Interpolation from a map

Applicable Standards: Full Depth Site Conditions Standard, with Nonpotable Ground Water, Coarse Textured Soil, for Industrial/Commercial/Community property use

RSC PDF:

26	***1 of 1***	***-/0.0***	***79.8 / 0.00***		***BORE***

ON

Borehole ID:	644955	***Inclin FLG:***	No
OGF ID:	215545338	***SP Status:***	Initial Entry
Status:		***Surv Elev:***	No
Type:	Borehole	***Piezometer:***	No
Use:	Geotechnical/Geological Investigation	***Primary Name:***	
Completion Date:	JAN-1950	***Municipality:***	
Static Water Level:		***Lot:***	
Primary Water Use:	Not Used	***Township:***	
Sec. Water Use:		***Latitude DD:***	43.651834
Total Depth m:	13.1	***Longitude DD:***	-79.340013
Depth Ref:	Ground Surface	***UTM Zone:***	17
Depth Elev:		***Easting:***	633865
Drill Method:	Diamond Drill	***Northing:***	4834543
Orig Ground Elev m:	77.2	***Location Accuracy:***	
Elev Reliabil Note:		***Accuracy:***	Not Applicable
DEM Ground Elev m:	79.6		

Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218509527	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.7	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill

Gsc Material Description:
Stratum Description: FILL.

Geology Stratum ID:	218509529	**Mat Consistency:**	
Top Depth:	7.2	**Material Moisture:**	
Bottom Depth:	12.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach

Gsc Material Description:
Stratum Description: SAND. BEACH,AGE POST-GLACIAL.

Geology Stratum ID:	218509528	**Mat Consistency:**	
Top Depth:	2.7	**Material Moisture:**	
Bottom Depth:	7.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Muck	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	muck

Gsc Material Description:
Stratum Description: CLAY,MUCK.

Geology Stratum ID:	218509530	**Mat Consistency:**	
Top Depth:	12.8	**Material Moisture:**	
Bottom Depth:	13.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine

Gsc Material Description:
Stratum Description: SHALE. MARINE,AGE ORDOVICIAN. T 25 **Note: Many records provided by the department have a truncated [Stratum Description] field.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 129770 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source List

Source Identifier:	1	***Horizontal Datum:***	NAD27
Source Type:	Data Survey	***Vertical Datum:***	Mean Average Sea Level
Source Date:	1956-1972	***Projection Name:***	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

27	***1 of 1***	***-/0.0***	***75.9 / -3.99***	***Toronto ON***	***WWIS***

Well ID:	7138467	***Data Entry Status:***	
Construction Date:		***Data Src:***	
Primary Water Use:	Monitoring and Test Hole	***Date Received:***	1/21/2010
Sec. Water Use:	0	***Selected Flag:***	Yes
Final Well Status:	Monitoring and Test Hole	***Abandonment Rec:***	
Water Type:		***Contractor:***	7241
Casing Material:		***Form Version:***	7
Audit No:	Z106512	***Owner:***	
Tag:	A081071	***Street Name:***	25 BOOTH AVENUE
Construction Method:		***County:***	YORK
Elevation (m):		***Municipality:***	TORONTO CITY
Elevation Reliability:		***Site Info:***	WKQ-002088
Depth to Bedrock:		***Lot:***	
Well Depth:		***Concession:***	
Overburden/Bedrock:		***Concession Name:***	
Pump Rate:		***Easting NAD83:***	
Static Water Level:		***Northing NAD83:***	
Flowing (Y/N):		***Zone:***	
Flow Rate:		***UTM Reliability:***	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1002926824	***Elevation:***	75.93354
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:		***East83:***	633809
Code OB Desc:		***North83:***	4834316
Open Hole:		***Org CS:***	UTM83
Cluster Kind:		***UTMRC:***	4
Date Completed:	1/4/2010	***UTMRC Desc:***	margin of error : 30 m - 100 m
Remarks:		***Location Method:***	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1003064515
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	28
Most Common Material:	SAND
Mat2:	04
Other Materials:	PEAT

Mat3:
Other Materials:
Formation Top Depth: 8
Formation End Depth: 16
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003064514
Layer: 1
Color: 6
General Color: BROWN
Mat1: 28
Most Common Material: SAND
Mat2: 01
Other Materials: FILL
Mat3:
Other Materials:
Formation Top Depth: 0
Formation End Depth: 8
Formation End Depth UOM: ft

Overburden and Bedrock Materials Interval

Formation ID: 1003064516
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Other Materials: CLAY
Mat3:
Other Materials:
Formation Top Depth: 16
Formation End Depth: 35
Formation End Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003064520
Layer: 3
Plug From: 4
Plug To: 35
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003064518
Layer: 1
Plug From: 0
Plug To: 1
Plug Depth UOM: ft

Annular Space/Abandonment Sealing Record

Plug ID: 1003064519

Layer:	2
Plug From:	1
Plug To:	4
Plug Depth UOM:	ft

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1003064513
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1003064522
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	5
Casing Diameter:	1.5
Casing Diameter UOM:	inch
Casing Depth UOM:	ft

Construction Record - Screen

Screen ID:	1003064523
Layer:	1
Slot:	10
Screen Top Depth:	5
Screen End Depth:	35
Screen Material:	5
Screen Depth UOM:	ft
Screen Diameter UOM:	inch
Screen Diameter:	1.75

Hole Diameter

Hole ID:	1003064517
Diameter:	8.25
Depth From:	0
Depth To:	35
Hole Depth UOM:	ft
Hole Diameter UOM:	inch

28	1 of 1	-/0.0	79.4 / -0.47	ON	BORE

Borehole ID:	644983	**Inclin FLG:**	No
OGF ID:	215545366	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	

Completion Date:	JAN-1950	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.6522
Total Depth m:	-999	**Longitude DD:**	-79.340375
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633835
Drill Method:	Diamond Drill	**Northing:**	4834583
Orig Ground Elev m:	77.2	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.2		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509641	**Mat Consistency:**	
Top Depth:	11.4	**Material Moisture:**	
Bottom Depth:	13.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	SHALE. MARINE,AGE ORDOVICIAN.		

Geology Stratum ID:	218509639	**Mat Consistency:**	
Top Depth:	7.7	**Material Moisture:**	
Bottom Depth:	8.9	**Material Texture:**	Fine
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach
Gsc Material Description:			
Stratum Description:	SAND-FINE. BEACH,AGE POST-GLACIAL.		

Geology Stratum ID:	218509635	**Mat Consistency:**	
Top Depth:	.1	**Material Moisture:**	
Bottom Depth:	2.3	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:	organic material	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL,ORGANIC.		

Geology Stratum ID:	218509638	**Mat Consistency:**	
Top Depth:	5.8	**Material Moisture:**	
Bottom Depth:	7.7	**Material Texture:**	Medium
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM. BEACH,AGE POST-GLACIAL.		

Geology Stratum ID:	218509636	**Mat Consistency:**	
Top Depth:	2.3	**Material Moisture:**	
Bottom Depth:	5	**Material Texture:**	

Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Muck	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	muck
Gsc Material Description:			
Stratum Description:	CLAY,MUCK.		

Geology Stratum ID:	218509637	**Mat Consistency:**	
Top Depth:	5	**Material Moisture:**	
Bottom Depth:	5.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	organic material	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	organic
Gsc Material Description:			
Stratum Description:	SAND,ORGANIC.		

Geology Stratum ID:	218509640	**Mat Consistency:**	
Top Depth:	8.9	**Material Moisture:**	
Bottom Depth:	11.4	**Material Texture:**	Coarse
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM TO COARSE. BEACH,AGE POST-GLACIAL.		

Geology Stratum ID:	218509642	**Mat Consistency:**	
Top Depth:	13.6	**Material Moisture:**	
Bottom Depth:		**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Bedrock	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	
Gsc Material Description:			
Stratum Description:	BEDROCK.		

Geology Stratum ID:	218509634	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.1	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 130050 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

29 **1 of 1** **-/0.0** **78.8 / -1.07** **Toronto ON** **WWIS**

Well ID:	7192710	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Monitoring and Test Hole	**Date Received:**	12/4/2012
Sec. Water Use:	0	**Selected Flag:**	Yes
Final Well Status:	Monitoring and Test Hole	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	7
Audit No:	Z160669	**Owner:**	
Tag:	A109672	**Street Name:**	120 BOUETTE ST
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	
Clear/Cloudy:			

Bore Hole Information

Bore Hole ID:	1004214372	**Elevation:**	78.300582
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633724
Code OB Desc:		**North83:**	4834613
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	10/25/2012	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

Overburden and Bedrock Materials Interval

Formation ID:	1004684795
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Other Materials:	SAND
Mat3:	11

Other Materials: GRAVEL
Formation Top Depth: 0
Formation End Depth: 0.61
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004684797
Layer: 3
Color: 2
General Color: GREY
Mat1: 06
Most Common Material: SILT
Mat2: 05
Other Materials: CLAY
Mat3: 85
Other Materials: SOFT
Formation Top Depth: 3.1
Formation End Depth: 4.27
Formation End Depth UOM: m

Overburden and Bedrock Materials Interval

Formation ID: 1004684796
Layer: 2
Color: 6
General Color: BROWN
Mat1: 03
Most Common Material: MUCK
Mat2: 06
Other Materials: SILT
Mat3: 77
Other Materials: LOOSE
Formation Top Depth: 0.61
Formation End Depth: 3.1
Formation End Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004684805
Layer: 1
Plug From: 0
Plug To: 0.3
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004684807
Layer: 3
Plug From: 0.91
Plug To: 4.27
Plug Depth UOM: m

Annular Space/Abandonment Sealing Record

Plug ID: 1004684806
Layer: 2

Plug From:	0.3
Plug To:	0.91
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004684794
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004684800
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	1.22
Casing Diameter:	5.2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004684801
Layer:	1
Slot:	10
Screen Top Depth:	1.22
Screen End Depth:	4.27
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03

Hole Diameter

Hole ID:	1004684798
Diameter:	
Depth From:	
Depth To:	
Hole Depth UOM:	m
Hole Diameter UOM:	cm

30 ***1 of 1*** ***-/0.0*** ***79.8 / 0.00*** ***ON*** ***BORE***

Borehole ID:	644958	**Inclin FLG:**	No
OGF ID:	215545341	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1950	**Municipality:**	

Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.651469
Total Depth m:	13.4	**Longitude DD:**	-79.339651
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633895
Drill Method:	Diamond Drill	**Northing:**	4834503
Orig Ground Elev m:	77.1	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.5		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509538	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	1.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218509540	**Mat Consistency:**	
Top Depth:	1.9	**Material Moisture:**	
Bottom Depth:	6.2	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	lacustrine
Gsc Material Description:			
Stratum Description:	CLAY. LACUSTRINE.		

Geology Stratum ID:	218509541	**Mat Consistency:**	
Top Depth:	6.2	**Material Moisture:**	
Bottom Depth:	13.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach
Gsc Material Description:			
Stratum Description:	SAND. BEACH,AGE POST-GLACIAL.		

Geology Stratum ID:	218509539	**Mat Consistency:**	
Top Depth:	1.8	**Material Moisture:**	
Bottom Depth:	1.9	**Material Texture:**	Medium
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach
Gsc Material Description:			
Stratum Description:	SAND-MEDIUM. BEACH,AGE POST-GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Details:	File: TOR2.txt RecordID: 129800 NTS_Sheet: 30M11C		
Confiden 1:	Reliable information but incomplete.		

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		
Source Name:	Urban Geology Automated Information System (UGAIS)		
Source Originators:	Geological Survey of Canada		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	1 of 2	-/0.0	78.9 / -0.97	TORONTO CITY-SAULTER ST-CONTRACT #58317 SAULTER ST/COMMISSIONERS ST. TORONTO CITY ON	CA

Certificate #:	7-1102-90-
Application Year:	90
Issue Date:	8/13/1990
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
31	2 of 2	-/0.0	78.9 / -0.97	TEPPERMAN AND SONS COMMISSIONERS AND SAULTAR ST. TORONTO CITY ON	SPL

Ref No:	4615	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	6/2/1988	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	UNKNOWN	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:		**Site Municipality:**	1106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	AIR	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/2/1988	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	FIRE/EXPLOSION	**Source Type:**	
Site Name:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site County/District:
Site Geo Ref Meth:
Incident Summary: TEPERMAN - SMOKE TO ATM FIRE IN WASTE CONTAINER
Contaminant Qty:

---

32 **1 of 1** **-/0.0** **79.8 / 0.00** **ON** **BORE**

Borehole ID: 644960
OGF ID: 215545343
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1950
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 13.5
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Orig Ground Elev m: 77.1
Elev Reliabil Note:
DEM Ground Elev m: 78.1
Concession:
Location D:
Survey D:
Comments:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.651105
Longitude DD: -79.339413
UTM Zone: 17
Easting: 633915
Northing: 4834463
Location Accuracy:
Accuracy: Not Applicable

Borehole Geology Stratum

Geology Stratum ID: 218509548
Top Depth: 11.7
Bottom Depth: 13.5
Material Color:
Material 1: Sand
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SAND. BEACH,AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: beach

Geology Stratum ID: 218509546
Top Depth: 4.2
Bottom Depth: 8
Material Color:
Material 1: Muck
Material 2: Clay
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: MUCK,CLAY.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: muck

Geology Stratum ID: 218509547
Top Depth: 8
Bottom Depth: 11.7
Material Color:
Material 1: Clay
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: CLAY. LACUSTRINE,AGE POST-GLACIAL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen:

Geology Stratum ID: 218509545
Top Depth: 0
Bottom Depth: 4.2
Material Color:
Material 1: Fill
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: FILL.

Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 129820 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

33	1 of 1	-/0.0	79.8 / 0.00	685 Lakeshore Boulevard East Toronto ON M4M 3J9	EHS

Order No: 20140108003
Status: C
Report Type: Standard Select Report
Report Date: 16-JAN-14
Date Received: 08-JAN-14
Previous Site Name: Barrett Coal Distillation Plant,
Lot/Building Size: 4.7 acres
Additional Info Ordered: Title Searches

Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): .25
X: -79.342802
Y: 43.652091

34	1 of 1	-/0.0	78.0 / -1.88	ON	WWIS

Well ID: 7238823
Construction Date:
Primary Water Use:
Sec. Water Use:
Final Well Status:
Water Type:
Casing Material:
Audit No: C26987
Tag: A163759
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:

Data Entry Status: Yes
Data Src:
Date Received: 3/24/2015
Selected Flag: Yes
Abandonment Rec:
Contractor: 7230
Form Version: 8
Owner:
Street Name:
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID:	1005316912	**Elevation:**	77.375694
DP2BR:		**Elevrc:**	
Spatial Status:		**Zone:**	17
Code OB:		**East83:**	633620
Code OB Desc:		**North83:**	4834320
Open Hole:		**Org CS:**	UTM83
Cluster Kind:		**UTMRC:**	4
Date Completed:	6/26/2014	**UTMRC Desc:**	margin of error : 30 m - 100 m
Remarks:		**Location Method:**	wwr
Elevrc Desc:			
Location Source Date:			
Improvement Location Source:			
Improvement Location Method:			
Source Revision Comment:			
Supplier Comment:			

---

35 | ***1 of 1*** | ***-/0.0*** | ***75.9 / -3.94*** | ***Don Roadway Toronto ON*** | ***EHS***

Order No:	20070803011	**Nearest Intersection:**	
Status:	C	**Municipality:**	
Report Type:	CAN - Custom Report	**Client Prov/State:**	
Report Date:	8/15/2007	**Search Radius (km):**	0.25
Date Received:	8/3/2007	**X:**	-79.343836
Previous Site Name:		**Y:**	43.651057
Lot/Building Size:			
Additional Info Ordered:			

---

36 | ***1 of 1*** | ***-/0.0*** | ***78.2 / -1.62*** | ***TORONTO ON*** | ***WWIS***

Well ID:	6927829	**Data Entry Status:**	
Construction Date:		**Data Src:**	
Primary Water Use:	Not Used	**Date Received:**	5/4/2004
Sec. Water Use:		**Selected Flag:**	Yes
Final Well Status:	Not A Well	**Abandonment Rec:**	
Water Type:		**Contractor:**	7241
Casing Material:		**Form Version:**	3
Audit No:	Z08046	**Owner:**	
Tag:	A007971	**Street Name:**	COENER OF SAULTER STREET/BASIN STREET
Construction Method:		**County:**	YORK
Elevation (m):		**Municipality:**	TORONTO CITY
Elevation Reliability:		**Site Info:**	
Depth to Bedrock:		**Lot:**	
Well Depth:		**Concession:**	
Overburden/Bedrock:		**Concession Name:**	
Pump Rate:		**Easting NAD83:**	
Static Water Level:		**Northing NAD83:**	
Flowing (Y/N):		**Zone:**	
Flow Rate:		**UTM Reliability:**	

Clear/Cloudy:

Bore Hole Information

Bore Hole ID:	11108665	***Elevation:***	77.377166
DP2BR:		***Elevrc:***	
Spatial Status:		***Zone:***	17
Code OB:	o	***East83:***	633696.8
Code OB Desc:	Overburden	***North83:***	4834275
Open Hole:		***Org CS:***	G83a
Cluster Kind:		***UTMRC:***	5
Date Completed:	4/15/2004	***UTMRC Desc:***	margin of error : 100 m - 300 m
Remarks:		***Location Method:***	wwr

Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:
Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	932966882
Layer:	2
Color:	6
General Color:	BROWN
Mat1:	28
Most Common Material:	SAND
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0.5
Formation End Depth:	1.75
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932966881
Layer:	1
Color:	8
General Color:	BLACK
Mat1:	02
Most Common Material:	TOPSOIL
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	0
Formation End Depth:	0.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932966884
Layer:	4
Color:	2
General Color:	GREY
Mat1:	06

Most Common Material:	SILT
Mat2:	
Other Materials:	
Mat3:	
Other Materials:	
Formation Top Depth:	3
Formation End Depth:	3.5
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	932966883
Layer:	3
Color:	2
General Color:	GREY
Mat1:	05
Most Common Material:	CLAY
Mat2:	06
Other Materials:	SILT
Mat3:	
Other Materials:	
Formation Top Depth:	1.75
Formation End Depth:	3
Formation End Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	0
Method Construction:	Not Known
Other Method Construction:	

Pipe Information

Pipe ID:	11117130
Casing No:	1
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	930842029
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	1.53
Casing Diameter:	3.4
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	933408991
Layer:	1
Slot:	010
Screen Top Depth:	1.53
Screen End Depth:	3.1
Screen Material:	5
Screen Depth UOM:	m

Screen Diameter UOM: cm
Screen Diameter: 4

Water Details

Water ID: 934049710
Layer: 1
Kind Code: 1
Kind: FRESH
Water Found Depth: 1.8
Water Found Depth UOM: m

Hole Diameter

Hole ID: 11117129
Diameter:
Depth From: 0
Depth To: 3.5
Hole Depth UOM: m
Hole Diameter UOM: cm

---

37 | 1 of 1 | -/0.0 | 79.8 / 0.00 | TORONTO ON | WWIS

Well ID: 7192709
Construction Date:
Primary Water Use: Monitoring and Test Hole
Sec. Water Use: 0
Final Well Status: Test Hole
Water Type:
Casing Material:
Audit No: Z160671
Tag: A120963
Construction Method:
Elevation (m):
Elevation Reliability:
Depth to Bedrock:
Well Depth:
Overburden/Bedrock:
Pump Rate:
Static Water Level:
Flowing (Y/N):
Flow Rate:
Clear/Cloudy:

Data Entry Status:
Data Src:
Date Received: 12/4/2012
Selected Flag: Yes
Abandonment Rec:
Contractor: 7241
Form Version: 7
Owner:
Street Name: 120 BOUCHETTE STREET
County: YORK
Municipality: TORONTO CITY
Site Info:
Lot:
Concession:
Concession Name:
Easting NAD83:
Northing NAD83:
Zone:
UTM Reliability:

Bore Hole Information

Bore Hole ID: 1004214369
DP2BR:
Spatial Status:
Code OB:
Code OB Desc:
Open Hole:
Cluster Kind:
Date Completed: 10/25/2012
Remarks:
Elevrc Desc:
Location Source Date:
Improvement Location Source:
Improvement Location Method:
Source Revision Comment:

Elevation: 77.944068
Elevrc:
Zone: 17
East83: 633649
North83: 4834613
Org CS: UTM83
UTMRC: 4
UTMRC Desc: margin of error : 30 m - 100 m
Location Method: wwr

Supplier Comment:

Overburden and Bedrock Materials Interval

Formation ID:	1004676419
Layer:	3
Color:	2
General Color:	GREY
Mat1:	06
Most Common Material:	SILT
Mat2:	05
Other Materials:	CLAY
Mat3:	85
Other Materials:	SOFT
Formation Top Depth:	3.1
Formation End Depth:	4.27
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004676417
Layer:	1
Color:	6
General Color:	BROWN
Mat1:	01
Most Common Material:	FILL
Mat2:	28
Other Materials:	SAND
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0
Formation End Depth:	0.61
Formation End Depth UOM:	m

Overburden and Bedrock Materials Interval

Formation ID:	1004676418
Layer:	2
Color:	8
General Color:	BLACK
Mat1:	03
Most Common Material:	MUCK
Mat2:	06
Other Materials:	SILT
Mat3:	77
Other Materials:	LOOSE
Formation Top Depth:	0.61
Formation End Depth:	3.1
Formation End Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004676429
Layer:	3
Plug From:	0.91
Plug To:	4.27
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004676428
Layer:	2
Plug From:	0.3
Plug To:	0.91
Plug Depth UOM:	m

Annular Space/Abandonment Sealing Record

Plug ID:	1004676427
Layer:	1
Plug From:	0
Plug To:	0.3
Plug Depth UOM:	m

Method of Construction & Well Use

Method Construction ID:	
Method Construction Code:	D
Method Construction:	Direct Push
Other Method Construction:	

Pipe Information

Pipe ID:	1004676416
Casing No:	0
Comment:	
Alt Name:	

Construction Record - Casing

Casing ID:	1004676422
Layer:	1
Material:	5
Open Hole or Material:	PLASTIC
Depth From:	0
Depth To:	1.22
Casing Diameter:	5.2
Casing Diameter UOM:	cm
Casing Depth UOM:	m

Construction Record - Screen

Screen ID:	1004676423
Layer:	1
Slot:	10
Screen Top Depth:	1.22
Screen End Depth:	4.27
Screen Material:	5
Screen Depth UOM:	m
Screen Diameter UOM:	cm
Screen Diameter:	6.03

Hole Diameter

Hole ID:	1004676420
Diameter:	20.32

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Depth From: 0
Depth To: 4.27
Hole Depth UOM: m
Hole Diameter UOM: cm

---

38 | 1 of 2 | -/0.0 | 78.9 / -0.98 | TORONTO HARBOUR COMMISSIONERS
185 COMMISSIONERS STREET
TORONTO CITY ON | CA

Certificate #: 8-3089-91-
Application Year: 91
Issue Date: 3/7/1992
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: R&D DEMO OF 3 SOIL TREAT. TECHNOLOGIES
Contaminants: Benzene (Carcinogen Requires Bact), Other Organic Compounds
Emission Control: Act. Charcoal Filter

---

38 | 2 of 2 | -/0.0 | 78.9 / -0.98 | CITY OF TORONTO HOUSING DEPARTMENT
185 COMMISSIONERS ST.
TORONTO CITY ON | CA

Certificate #: 8-3073-92-
Application Year: 92
Issue Date: 5/7/1992
Approval Type: Industrial air
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: EXCAVATION OF 900 TONNES OF ATARATIRI SL
Contaminants: Benzo(A) Pyrene, Methane (Incl. Hydrocarbons Expr. As Ch4
Emission Control: No Controls

---

39 | 1 of 2 | -/0.0 | 76.9 / -2.93 | UNKNOWN
VILLIERS & COMMISSIONERS STS.
TORONTO CITY ON | SPL

Ref No: 10888
Site No:
Incident Dt: 10/25/1988
Year:
Incident Cause: UNKNOWN
Incident Event:
Contaminant Code:
Contaminant Name:
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact:
Nature of Impact:
Receiving Medium: AIR
Receiving Env:

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type:
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality: 1106
Site Lot:
Site Conc:
Northing:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

MOE Response:		**Easting:**	
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	10/25/1988	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	WORKS DEPT. -REQUESTING MOE ASSISTANCE, COMBUST- IBLES IN SEWER.		
Contaminant Qty:			

39	2 of 2	-/0.0	76.9 / -2.93	**UNKNOWN** **VILLIERS ST. COMMISSIONERS ST.** **TORONTO CITY ON**	SPL

Ref No:	32811	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	4/2/1990	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	UNKNOWN	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	NOT ANTICIPATED	**Site Municipality:**	01106
Nature of Impact:		**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	
MOE Response:		**Easting:**	PUC
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	4/2/1990	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	UNKNOWN	**Source Type:**	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	OIL IN MANHOLES FROM UNKNOWN SOURCE CLEANED BYPUC.		
Contaminant Qty:			

40	1 of 11	-/0.0	78.9 / -0.96	**PT Studios Inc.** **225 Commissioners ST** **Toronto ON M4M 0A1**	EASR

Approval No:	R-010-6110630394	**SWP Area Name:**	Toronto
Status:	REGISTERED	**MOE District:**	Metro Toronto
Date:	2018-10-12	**Municipality:**	Toronto
Record Type:	EASR	**Latitude:**	43.64916667
Link Source:	MOFA	**Longitude:**	-79.34138889
Project Type:	Air Emissions	**Geometry X:**	
Full Address:		**Geometry Y:**	
Approval Type:	EASR-Air Emissions		
Full PDF Link:	http://www.accessenvironment.ene.gov.on.ca/AEWeb/ae/ViewDocument.action?documentRefID=2097836		

40	2 of 11	-/0.0	78.9 / -0.96	**PT Studios Inc.** **225 Commissioners St Suite 303** **Toronto ON M4M 0A1**	GEN

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Generator No:	ON2976097	**PO Box No:**	
Status:	Registered	**Country:**	Canada
Approval Years:	As of Dec 2018	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class:	145 L
Waste Class Desc:	Wastes from the use of pigments, coatings and paints

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	3 of 11	-/0.0	78.9 / -0.96	**Stage 49 Ltd** **225 Commissioners St** **Toronto ON M4M 0A1**	GEN

Generator No:	ON8789990	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2009	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	512110		
SIC Description:	Motion Picture and Video Production		

Detail(s)

Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	4 of 11	-/0.0	78.9 / -0.96	**Still Seas Production** **225 Commissioners St. Suite 402** **Toronto ON**	GEN

Generator No:	ON9917616	**PO Box No:**	
Status:		**Country:**	
Approval Years:	2012	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:	711311		
SIC Description:	Live Theatres and Other Performing Arts Presenters with Facilities		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	5 of 11	-/0.0	78.9 / -0.96	**Haunted Peak Inc.** **225 Commissioners St., Suite 401** **Toronto, ON ON M4M 0A1**	GEN

Generator No:	ON3411957	**PO Box No:**	
Status:		**Country:**	Canada
Approval Years:	2014	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	
MHSW Facility:	No	**Phone No Admin:**	
SIC Code:	711311		
SIC Description:	711311		

Detail(s)

Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	6 of 11	-/0.0	78.9 / -0.96	High Park/Locke and Key Production Inc. 225 Commissioners St. suite 201 Toronto ON M4M 0A1	GEN

Generator No: ON9543567
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	7 of 11	-/0.0	78.9 / -0.96	Rekall Productions Ltd. 225 Commisioners St Toronto ON	GEN

Generator No: ON6887386
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 512110
SIC Description:

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	8 of 11	-/0.0	78.9 / -0.96	GEP Productions Inc. 225 Commissioner's Street Suite 201 Toronto ON M4M 0A1	GEN

Generator No: ON3561858
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 711111, 512110
SIC Description: Theatre (except Musical) Companies, Motion Picture and Video Production

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	9 of 11	-/0.0	78.9 / -0.96	PT Studios Inc. 225 Commissioners St Suite 303 Toronto ON M4M 0A1	GEN

Generator No: ON2976097

PO Box No:

Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	10 of 11	-/0.0	78.9 / -0.96	**Toronto Water Front Studios Development Inc** **225 Commissioners Street** **Toronto ON M4M 1A1**	GEN

Generator No: ON3908851
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
40	11 of 11	-/0.0	78.9 / -0.96	**14 Hours Productions Inc.** **225 Commissioners Street Suite 401** **Toronto ON M4M 0A1**	GEN

Generator No: ON4207641
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:
PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 148 C
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 268 C
Waste Class Desc: Amines

Waste Class: 263 L
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
41	1 of 1	-/0.0	79.8 / 0.00	ON	BORE

Borehole ID:	654205	**Inclin FLG:**	No
OGF ID:	215554551	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1971	**Municipality:**	
Static Water Level:	7.6	**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.651859
Total Depth m:	13.3	**Longitude DD:**	-79.339268
Depth Ref:	Ground Surface	**UTM Zone:**	17
Depth Elev:		**Easting:**	633925
Drill Method:	Boring	**Northing:**	4834547
Orig Ground Elev m:	76.9	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	78.2		

Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID:	218542374	**Mat Consistency:**	Dense
Top Depth:	9.8	**Material Moisture:**	
Bottom Depth:	13.3	**Material Texture:**	Fine to Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: SAND-MEDIUM,SAND FINE TO MEDIUM. GREY,DENSE. 0002600200050002000850030028000500320035
**Note: Many records provided by the department have a truncated [Stratum Description] field.

Geology Stratum ID:	218542373	**Mat Consistency:**	Soft
Top Depth:	8.5	**Material Moisture:**	
Bottom Depth:	9.8	**Material Texture:**	
Material Color:	Black	**Non Geo Mat Type:**	
Material 1:	Peat	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	peat

Gsc Material Description:
Stratum Description: PEAT. BLACK,SOFT, WATER STABLE AT 227.4 FEET.

Geology Stratum ID:	218542372	**Mat Consistency:**	Loose
Top Depth:	2.6	**Material Moisture:**	
Bottom Depth:	8.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Clay	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:	Sand	**Depositional Gen:**	organic

Gsc Material Description:
Stratum Description: SILT,CLAY,ORGANIC, SAND. LOOSE,RUBBLY.

Geology Stratum ID:	218542370	**Mat Consistency:**	Loose
Top Depth:	.8	**Material Moisture:**	
Bottom Depth:	1.5	**Material Texture:**	Medium
Material Color:	Grey	**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	

Gsc Material Description:
Stratum Description: SAND-MEDIUM. GREY,LOOSE,RUBBLY.

Geology Stratum ID:	218542369	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	.8	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill

Gsc Material Description:
Stratum Description: FILL.

Geology Stratum ID:	218542371	**Mat Consistency:**	Loose
Top Depth:	1.5	**Material Moisture:**	
Bottom Depth:	2.6	**Material Texture:**	Medium
Material Color:		**Non Geo Mat Type:**	
Material 1:	Silt	**Geologic Formation:**	
Material 2:	Sand	**Geologic Group:**	
Material 3:	Organic	**Geologic Period:**	
Material 4:		**Depositional Gen:**	organic

Gsc Material Description:
Stratum Description: SILT,SAND-MEDIUM, ORGANIC. LOOSE,RUBBLY.

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	H	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR3.txt RecordID: 248700 NTS_Sheet: 30M11F
Confiden 1: Logged by professional. Exact and complete description of material and properties.

Source List

Source Identifier:	1	**Horizontal Datum:**	NAD27
Source Type:	Data Survey	**Vertical Datum:**	Mean Average Sea Level
Source Date:	1956-1972	**Projection Name:**	Universal Transverse Mercator
Scale or Resolution:	Varies		

Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	1 of 80	-/0.0	79.8 / 0.00	MUNICIPALITY OF METRO TORONTO 400 COMMISSIONERS STREET TORONTO CITY ON M4M 3K2	CA

Certificate #: 8-3262-95-966
Application Year: 95
Issue Date: 4/30/96
Approval Type: Industrial air
Status: Received in 1995, Issued in 1996
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: (3) TIPPING AREA EXHAUST FANS
Contaminants: Odour/Fumes, Stoddard Solvent
Emission Control: No Controls

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	2 of 80	-/0.0	79.8 / 0.00	Municipality of Metro Toronto 400 Commissioners Street Toronto ON	EBR

EBR Registry No: IA5E0959
Ministry Ref No: 8326295
Notice Type: Instrument Final Decision
Notice Stage: 800468914
Notice Date: May 29, 1996
Proposal Date: May 18, 1995
Year: 1995
Instrument Type: (EPA s. 9) - Approval for discharge into the natural environment other than water (i.e. Air)
Off Instrument Name:
Posted By:
Company Name: Municipality of Metro Toronto
Site Address:
Location Other:
Proponent Name:
Proponent Address:
Comment Period:
URL:
Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

400 Commissioners Street Toronto

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	3 of 80	-/0.0	79.8 / 0.00	400 Commissioners St Toronto ON M4M 3K2	EHS

Order No: 20020424084w
Status: C
Report Type: Online Mapless Report
Report Date: 4/24/02
Date Received: 4/24/02
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State: ON
Search Radius (km): 0.25
X: 0
Y: 0

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	4 of 80	-/0.0	79.8 / 0.00	400 Commissioner Street n/a ON	EHS

Order No: 20070412035w
Status: C
Report Type: USA - Online Mapless
Report Date: 4/12/2007
Date Received: 4/12/2007
Previous Site Name:
Lot/Building Size:
Additional Info Ordered:
Nearest Intersection:
Municipality:
Client Prov/State:
Search Radius (km): 0.25
X:
Y:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	5 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO - FLEET SERVICES 400 COMMISSIONERS ST TORONTO ON M4M 3K2	EXP

Instance No: 11010085
Instance ID:
Instance Type: FS Liquid Fuel Tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 10/1/2013 10:47:00 AM

42	6 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO - FLEET SERVICES 400 COMMISSIONERS ST TORONTO ON M4M 3K2	EXP

Instance No: 11446540
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 10/16/2013 1:45:10 PM

42	7 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO - FLEET SERVICES 400 COMMISSIONERS ST TORONTO ON M4M 3K2	EXP

Instance No: 11446563
Instance ID:
Instance Type: FS Liquid Fuel Tank
Description: Fuels Safety Private Fuel Outlet - Self Serve
Status: EXPIRED
TSSA Program Area:
Maximum Hazard Rank:
Facility Type: FS Liquid Fuel Tank
Expired Date: 10/1/2013 10:45:00 AM

42	8 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO - FLEET SERVICES ATTN DON LEEBODY 400 COMMISSIONERS ST TORONTO ON M4M 3K2	FSTH

License Issue Date: 11/19/1992
Tank Status: Licensed
Tank Status As Of: December 2008
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 9092
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 0
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Status: Active
Year of Installation: 1995
Corrosion Protection:
Capacity: 11444
Tank Fuel Type: Liquid Fuel Double Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	9 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO - FLEET SERVICES ATTN DON LEEBODY 400 COMMISSIONERS ST TORONTO ON M4M 3K2	FSTH

License Issue Date: 11/19/1992
Tank Status: Licensed
Tank Status As Of: August 2007
Operation Type: Private Fuel Outlet
Facility Type: Gasoline Station - Self Serve

--Details--
Status: Active
Year of Installation: 1983
Corrosion Protection:
Capacity: 9092
Tank Fuel Type: Liquid Fuel Single Wall UST - Diesel

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	10 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO SOLID WASTE MANAGEMENT SERVICES COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	GEN

Generator No: ON0146212
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 312 P
Waste Class Desc: Pathological wastes

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 261 A
Waste Class Desc: Pharmaceuticals

Waste Class: 331 B
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 221 L
Waste Class Desc: Light fuels

Waste Class: 242 A
Waste Class Desc: Halogenated pesticides and herbicides

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Waste Class: 263 I
Waste Class Desc: Misc. waste organic chemicals

Waste Class: 212 L
Waste Class Desc: Aliphatic solvents and residues

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 148 I
Waste Class Desc: Misc. wastes and inorganic chemicals

Waste Class: 213 I
Waste Class Desc: Petroleum distillates

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 331 I
Waste Class Desc: Waste compressed gases including cylinders

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 147 I
Waste Class Desc: Chemical fertilizer wastes

Waste Class: 252 T
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 121 C
Waste Class Desc: Alkaline slutions - containing heavy metals

Waste Class: 221 I
Waste Class Desc: Light fuels

42	11 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON	GEN

Generator No: ON0146212
Status:
Approval Years: 2013
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: WASTE COLLECTION

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	242
Waste Class Desc:	HALOGENATED PESTICIDES
Waste Class:	261
Waste Class Desc:	PHARMACEUTICALS
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	211
Waste Class Desc:	AROMATIC SOLVENTS
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	269
Waste Class Desc:	NON-HALOGENATED PESTICIDES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	312
Waste Class Desc:	PATHOLOGICAL WASTES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	12 of 80	-/0.0	79.8 / 0.00	**CITY OF TORONTO** **COMMISSIONERS FACILITY 400** **COMMISSIONERS STREET** **TORONTO ON M4M 3K2**	GEN

Generator No:	ON0146212	**PO Box No:**	
Status:		**Country:**	Canada
Approval Years:	2014	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	
MHSW Facility:	Yes	**Phone No Admin:**	
SIC Code:	562110		
SIC Description:	WASTE COLLECTION		

Detail(s)

Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	211
Waste Class Desc:	AROMATIC SOLVENTS
Waste Class:	269
Waste Class Desc:	NON-HALOGENATED PESTICIDES
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	312
Waste Class Desc:	PATHOLOGICAL WASTES
Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	261
Waste Class Desc:	PHARMACEUTICALS
Waste Class:	242
Waste Class Desc:	HALOGENATED PESTICIDES
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	243
Waste Class Desc:	PCBS
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	121
Waste Class Desc:	ALKALINE WASTES - HEAVY METALS
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS

42	***13 of 80***	***-/0.0***	***79.8 / 0.00***	***City of Toronto 400 Commissioners St Toronto ON M4M 3K2***	***GEN***

Generator No:	ON5906800	***PO Box No:***	
Status:		***Country:***	Canada

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Years:	2016	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	Roger Wong
MHSW Facility:	No	**Phone No Admin:**	4163924259 Ext.
SIC Code:	562910		
SIC Description:	REMEDIATION SERVICES		

Detail(s)

Waste Class:	243
Waste Class Desc:	PCBS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	14 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	GEN

Generator No:	ON0146212	**PO Box No:**	
Status:		**Country:**	
Approval Years:	02,03,04,05,06,07,08	**Choice of Contact:**	
Contam. Facility:		**Co Admin:**	
MHSW Facility:		**Phone No Admin:**	
SIC Code:			
SIC Description:			

Detail(s)

Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	211
Waste Class Desc:	AROMATIC SOLVENTS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	121
Waste Class Desc:	ALKALINE WASTES - HEAVY METALS
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	221
Waste Class Desc:	LIGHT FUELS
Waste Class:	242
Waste Class Desc:	HALOGENATED PESTICIDES
Waste Class:	243
Waste Class Desc:	PCB'S
Waste Class:	252

Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

42	15 of 80	-/0.0	79.8 / 0.00	***METROPOLITAN TORONTO WORKS DEPT. 26-051*** ***COMMISSIONERS FACILITY 400*** ***COMMISSIONERS STREET*** ***TORONTO ON M5V 3C6***	GEN

Generator No: ON0146212
Status:
Approval Years: 92,93,94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 8373
SIC Description: ENVIRON. ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145

Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

42 | ***16 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***OJCR Commissioners St. Job Site***
400 Commissioners St.
Toronto ON M4M 3K2 | ***GEN***

Generator No: ON7125252
Status: Registered
Approval Years: As of Dec 2017
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

---

42 | ***17 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***METROPOLITAN TORONTO WORKS DEPT***
COMMISSIONERS FACILITY 400
COMMISSIONERS STREET
TORONTO ON M5V 3C6 | ***GEN***

Generator No: ON0146212
Status:
Approval Years: 97
Contam. Facility:
MHSW Facility:
SIC Code: 8373
SIC Description: ENVIRON. ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148

Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

---

42 | ***18 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***METROPOLITAN TORONTO WORKS DEPARTMENT
COMMISSIONERS FACILITY 400
COMMISSIONERS STREET
TORONTO ON M5V 3C6*** | ***GEN***

Generator No: ON0146212
Status:
Approval Years: 98,99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 8373
SIC Description: ENVIRON. ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331

Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

42 | ***19 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***CITY OF TORONTO SOLID WASTE MANAGEMENT SERVICES COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2*** | ***GEN***

Generator No: ON0146212
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112 C
Waste Class Desc: Acid solutions - containing heavy metals

Waste Class: 121 C
Waste Class Desc: Alkaline slutions - containing heavy metals

Waste Class: 122 C
Waste Class Desc: Alkaline slutions - containing other metals and non-metals (not cyanide)

Waste Class: 145 I
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 145 L
Waste Class Desc: Wastes from the use of pigments, coatings and paints

Waste Class: 146 T
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 147 I

Waste Class Desc:	Chemical fertilizer wastes
Waste Class:	148 I
Waste Class Desc:	Misc. wastes and inorganic chemicals
Waste Class:	212 L
Waste Class Desc:	Aliphatic solvents and residues
Waste Class:	213 I
Waste Class Desc:	Petroleum distillates
Waste Class:	221 I
Waste Class Desc:	Light fuels
Waste Class:	221 L
Waste Class Desc:	Light fuels
Waste Class:	242 A
Waste Class Desc:	Halogenated pesticides and herbicides
Waste Class:	251 L
Waste Class Desc:	Waste oils/sludges (petroleum based)
Waste Class:	252 L
Waste Class Desc:	Waste crankcase oils and lubricants
Waste Class:	252 T
Waste Class Desc:	Waste crankcase oils and lubricants
Waste Class:	261 A
Waste Class Desc:	Pharmaceuticals
Waste Class:	263 I
Waste Class Desc:	Misc. waste organic chemicals
Waste Class:	312 P
Waste Class Desc:	Pathological wastes
Waste Class:	331 B
Waste Class Desc:	Waste compressed gases including cylinders
Waste Class:	331 I
Waste Class Desc:	Waste compressed gases including cylinders

42 | ***20 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***CITY OF TORONTO***
COMMISSIONERS FACILITY 400
COMMISSIONERS STREET
TORONTO ON M4M 3K2 | ***GEN***

Generator No:	ON0146212	***PO Box No:***	
Status:		***Country:***	Canada
Approval Years:	2016	***Choice of Contact:***	CO_OFFICIAL
Contam. Facility:	No	***Co Admin:***	
MHSW Facility:	Yes	***Phone No Admin:***	
SIC Code:	562110		
SIC Description:	WASTE COLLECTION		

Detail(s)

Waste Class:	263
Waste Class Desc:	ORGANIC LABORATORY CHEMICALS
Waste Class:	211
Waste Class Desc:	AROMATIC SOLVENTS

Waste Class:	312
Waste Class Desc:	PATHOLOGICAL WASTES
Waste Class:	148
Waste Class Desc:	INORGANIC LABORATORY CHEMICALS
Waste Class:	251
Waste Class Desc:	OIL SKIMMINGS & SLUDGES
Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	261
Waste Class Desc:	PHARMACEUTICALS
Waste Class:	145
Waste Class Desc:	PAINT/PIGMENT/COATING RESIDUES
Waste Class:	269
Waste Class Desc:	NON-HALOGENATED PESTICIDES
Waste Class:	212
Waste Class Desc:	ALIPHATIC SOLVENTS
Waste Class:	112
Waste Class Desc:	ACID WASTE - HEAVY METALS
Waste Class:	121
Waste Class Desc:	ALKALINE WASTES - HEAVY METALS
Waste Class:	243
Waste Class Desc:	PCBS
Waste Class:	242
Waste Class Desc:	HALOGENATED PESTICIDES
Waste Class:	331
Waste Class Desc:	WASTE COMPRESSED GASES
Waste Class:	147
Waste Class Desc:	CHEMICAL FERTILIZER WASTES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS
Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS
Waste Class:	122
Waste Class Desc:	ALKALINE WASTES - OTHER METALS
Waste Class:	221
Waste Class Desc:	LIGHT FUELS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	21 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	GEN

Generator No:	ON0146212	**PO Box No:**	
Status:		**Country:**	Canada
Approval Years:	2015	**Choice of Contact:**	CO_OFFICIAL
Contam. Facility:	No	**Co Admin:**	
MHSW Facility:	Yes	**Phone No Admin:**	

SIC Code: 562110
SIC Description: WASTE COLLECTION

Detail(s)

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 147
Waste Class Desc: CHEMICAL FERTILIZER WASTES

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 243
Waste Class Desc: PCBS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	22 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	GEN

Generator No: ON0146212
Status:
Approval Years: 2009
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: Waste Collection

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 269

Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	23 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	GEN

Generator No: ON0146212
Status:
Approval Years: 2011
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: Waste Collection

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	24 of 80	-/0.0	79.8 / 0.00	METROPOLITAN TORONTO WORKS DEPT. COMMISSIONERS INCINERATOR 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	GEN

Generator No: ON0146212
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 8373
SIC Description: ENVIRON. ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	25 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M5V 3C6	GEN

Generator No: ON0146212
Status:
Approval Years: 2012
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: Waste Collection

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 331

Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	26 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO COMMISSIONERS FACILITY 400 COMMISSIONERS STREET TORONTO ON M4M 3K2	GEN

Generator No: ON0146212
Status:
Approval Years: 2010
Contam. Facility:
MHSW Facility:
SIC Code: 562110
SIC Description: Waste Collection

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 242
Waste Class Desc: HALOGENATED PESTICIDES

Waste Class: 122
Waste Class Desc: ALKALINE WASTES - OTHER METALS

Waste Class: 312
Waste Class Desc: PATHOLOGICAL WASTES

Waste Class: 148
Waste Class Desc: INORGANIC LABORATORY CHEMICALS

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 112
Waste Class Desc: ACID WASTE - HEAVY METALS

Waste Class: 243
Waste Class Desc: PCBS

Waste Class: 211
Waste Class Desc: AROMATIC SOLVENTS

Waste Class: 145
Waste Class Desc: PAINT/PIGMENT/COATING RESIDUES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Waste Class: 331
Waste Class Desc: WASTE COMPRESSED GASES

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 261
Waste Class Desc: PHARMACEUTICALS

Waste Class: 212
Waste Class Desc: ALIPHATIC SOLVENTS

Waste Class: 263
Waste Class Desc: ORGANIC LABORATORY CHEMICALS

Waste Class: 269
Waste Class Desc: NON-HALOGENATED PESTICIDES

Waste Class: 121
Waste Class Desc: ALKALINE WASTES - HEAVY METALS

---

42 | **27 of 80** | **-/0.0** | **79.8 / 0.00** | **INTERNORTH CONSTRUCTION CO. LTD. 21-518**
400 COMMISSIONER STREET, TORONTO C/O
DIXIE ROAD
MISISSAUGA ON L4W 1N2 | **GEN**

Generator No: ON1458300
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 4022
SIC Description: COMMERCIAL BUILDING

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

---

42 | **28 of 80** | **-/0.0** | **79.8 / 0.00** | **CANADA CRINC, LTD.**
400 COMMISSIONERS STREET
TORONTO ON M4M 3K2 | **GEN**

Generator No: ON1621000
Status:
Approval Years: 99,00,01
Contam. Facility:
MHSW Facility:
SIC Code: 4999
SIC Description: OTHER UTILITY IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

---

42 | **29 of 80** | **-/0.0** | **79.8 / 0.00** | **CANADA CRINC, LTD. 07-534**
400 COMMISSIONERS STREET
TORONTO ON M4M 3K2 | **GEN**

Generator No: ON1621000
Status:
Approval Years: 92,93,94,95,96,97,98
Contam. Facility:
MHSW Facility:
SIC Code: 4999

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

SIC Description: OTHER UTILITY IND.

Detail(s)

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	30 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO 400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	NPRI

NPRI ID:	11552	**Org ID:**	101368
Other ID:	N	**Submit Date:**	6/1/2010
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	85484	**Contact ID:**	141902
Report ID:	139410	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	DEREK
Report Year:	2009	**Cont Last Name:**	ANGOVE
Not-Current Rpt?:	No	**Contact Position:**	MANAGER, TRANSFER OPERATIONS
Yr of Last Filed Rpt:	2014	**Contact Fax:**	4163971348
Fac ID:	225812	**Contact Ph.:**	4163922447
Fac Name:	COMMISSIONERS STREET TRANSFER STATION	**Cont Area Code:**	416
Fac Address1:	400 COMMISSIONER STREET	**Contact Tel.:**	63922447
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	M4M3K2	**Cont Fax Area Cde:**	416
Facility Lat:	43.6518	**Contact Fax:**	63971348
Facility Long:	-79.3391	**Contact Email:**	DANGOVE@TORONTO.CA
DLS (Last Filed Rpt):		**Latitude:**	43.6518
Facility DLS:		**Longitude:**	-79.3391
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	52	**Waste Streams:**	No
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	No
Pollut Prev Cmnts:	No	**No Off Sites:**	
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and support, waste management and remediation services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste Collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste Collection

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: 0
Unit: tonnes
Basis of Estimate Cd:

Basis of Estimate Desc:

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM - Total Particulate Matter
Chem (fr): PM - Particules totales
Quantity: 1.6
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: .09
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: .32
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 0
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

42	31 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO 400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	NPRI

NPRI ID: 11552
Other ID:
No Other ID:
Track ID: 100062
Report ID: 3932
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2011
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2014

Org ID: 101368
Submit Date: 6/29/2012
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 141896
Cont Type: MED
Contact Title:
Cont First Name: DEREK
Cont Last Name: ANGOVE
Contact Position: MANAGER, TRANSFER & DISPOSAL OPERATIONS
Contact Fax: 4163971348

Fac ID:	225812	***Contact Ph.:***	4163922447
Fac Name:	COMMISSIONERS STREET TRANSFER STATION	***Cont Area Code:***	416
Fac Address1:	400 COMMISSIONER STREET	***Contact Tel.:***	63922447
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	M4M3K2	***Cont Fax Area Cde:***	416
Facility Lat:	43.6518	***Contact Fax:***	63971348
Facility Long:	-79.3391	***Contact Email:***	DANGOVE@TORONTO.CA
DLS (Last Filed Rpt):		***Latitude:***	43.6518
Facility DLS:		***Longitude:***	-79.3391
Datum:	1983	***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	52	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and support, waste management and remediation services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste Collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste Collection

Substance Release Report

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: .08
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM - Total Particulate Matter
Chem (fr): PM - Particules totales
Quantity: 1.56
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: .3
Unit: tonnes

Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	32 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO 400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	NPRI

NPRI ID: 11552
Other ID:
No Other ID:
Track ID: 111220
Report ID: 23562
Report Type: NPRI
Rpt Type ID: 1
Report Year: 2012
Not-Current Rpt?: No
Yr of Last Filed Rpt: 2014
Fac ID: 225812
Fac Name: COMMISSIONERS STREET TRANSFER STATION
Fac Address1: 400 COMMISSIONER STREET
Fac Address2: NOT AVAILABLE
Fac Postal Zip: M4M3K2
Facility Lat: 43.6518
Facility Long: -79.3391
DLS (Last Filed Rpt):
Facility DLS:
Datum: 1983
Facility Cmnts:
URL:
No of Empl.: 52
Parent Co.:
No Parent Co.:
Pollut Prev Cmnts:
Stacks:
No of Stacks:
Org ID: 101368
Submit Date: 6/6/2013
Last Modified: 5/29/2015 3:28:24 PM
Contact ID: 141895
Cont Type: MED
Contact Title:
Cont First Name: DEREK
Cont Last Name: ANGOVE
Contact Position: DIRECTOR PROCESSING & RESOURCE MANAGEMENT
Contact Fax: 4163971348
Contact Ph.: 4163922447
Cont Area Code: 416
Contact Tel.: 63922447
Contact Ext.:
Cont Fax Area Cde: 416
Contact Fax: 63971348
Contact Email: DANGOVE@TORONTO.CA
Latitude: 43.6518
Longitude: -79.3391
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams:
No Streams:
Waste Off Sites:
No Off Sites:
Shutdown:
No of Shutdown:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and support, waste management and remediation services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste collection

Substance Release Report

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: .29
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 13
Category Type Desc: All Media

Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	NA
Basis of Estimate Desc:	NA- Not Applicable

Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM - Total Particulate Matter
Chem (fr):	PM - Particules totales
Quantity:	1.48
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	NA
Basis of Estimate Desc:	NA- Not Applicable

Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	.08
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

---

42 | ***33 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***CITY OF TORONTO***
400 COMMISSIONER STREET NOT AVAILABLE
TORONTO ON M4M3K2 | ***NPRI***

NPRI ID:	11552	**Org ID:**	101368
Other ID:		**Submit Date:**	6/3/2014
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	120570	**Contact ID:**	231641
Report ID:	41198	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	
Report Year:	2013	**Cont Last Name:**	
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	225812	**Contact Ph.:**	
Fac Name:	COMMISSIONERS STREET TRANSFER STATION	**Cont Area Code:**	
Fac Address1:	400 COMMISSIONER STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	

Fac Postal Zip:	M4M3K2	**Cont Fax Area Cde:**	
Facility Lat:	43.6518	**Contact Fax:**	
Facility Long:	-79.3391	**Contact Email:**	
DLS (Last Filed Rpt):		**Latitude:**	43.6518
Facility DLS:		**Longitude:**	-79.3391
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	52	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and support, waste management and remediation services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste collection

Substance Release Report

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM - Total Particulate Matter
Chem (fr): PM - Particules totales
Quantity: 1.63
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: .08
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: .32
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	34 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO 400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	NPRI

NPRI ID:	11552	**Org ID:**	101368
Other ID:	N	**Submit Date:**	5/31/2008
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	58667	**Contact ID:**	141902
Report ID:	115332	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	DEREK
Report Year:	2007	**Cont Last Name:**	ANGOVE
Not-Current Rpt?:	No	**Contact Position:**	MANAGER, TRANSFER OPERATIONS
Yr of Last Filed Rpt:	2014	**Contact Fax:**	4163971348
Fac ID:	225812	**Contact Ph.:**	4163922447
Fac Name:	COMMISSIONERS STREET TRANSFER STATION	**Cont Area Code:**	416
Fac Address1:	400 COMMISSIONER STREET	**Contact Tel.:**	63922447
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	M4M3K2	**Cont Fax Area Cde:**	416
Facility Lat:	43.6518	**Contact Fax:**	63971348
Facility Long:	-79.3391	**Contact Email:**	DANGOVE@TORONTO.CA
DLS (Last Filed Rpt):		**Latitude:**	43.6518
Facility DLS:		**Longitude:**	-79.3391
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	False	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	52	**Waste Streams:**	True?
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	True?
Pollut Prev Cmnts:	False	**No Off Sites:**	
Stacks:	True	**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and support, waste management and remediation services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste Collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste Collection

Substance Release Report

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 0
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns

Quantity:	.43
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM - Total Particulate Matter
Chem (fr):	PM - Particules totales
Quantity:	2.18
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	.11
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

42	***35 of 80***	***-/0.0***	***79.8 / 0.00***	***CITY OF TORONTO*** ***400 COMMISSIONER STREET NOT AVAILABLE*** ***TORONTO ON M4M3K2***	***NPRI***

NPRI ID:	11552	**Org ID:**	101368
Other ID:	Y	**Submit Date:**	6/17/2011
No Other ID:	2	**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	95496	**Contact ID:**	141915
Report ID:	149548	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	DEREK
Report Year:	2010	**Cont Last Name:**	ANGOVE
Not-Current Rpt?:	No	**Contact Position:**	MANAGER, TRANSFER OPERATIONS
Yr of Last Filed Rpt:	2014	**Contact Fax:**	4163971348
Fac ID:	225812	**Contact Ph.:**	4163922447
Fac Name:	COMMISSIONERS STREET TRANSFER STATION	**Cont Area Code:**	416
Fac Address1:	400 COMMISSIONER STREET	**Contact Tel.:**	63922447
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	M4M3K2	**Cont Fax Area Cde:**	416
Facility Lat:	43.6518	**Contact Fax:**	63971348
Facility Long:	-79.3391	**Contact Email:**	DANGOVE@TORONTO.CA
DLS (Last Filed Rpt):		**Latitude:**	43.6518
Facility DLS:		**Longitude:**	-79.3391

Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	52	**Waste Streams:**	No
Parent Co.:	*	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	No
Pollut Prev Cmnts:	No	**No Off Sites:**	
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and support, waste management and remediation services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste Collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste Collection

Substance Release Report

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: .0459
Unit: tonnes
Basis of Estimate Cd: M2
Basis of Estimate Desc: M2- Predictive Emission Monitoring - In use from 2003 and onward

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: PM - Total Particulate Matter
Chem (fr): PM - Particules totales
Quantity: 0
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM - Total Particulate Matter
Chem (fr): PM - Particules totales
Quantity: .6664
Unit: tonnes
Basis of Estimate Cd: M2
Basis of Estimate Desc: M2- Predictive Emission Monitoring - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns

Quantity:	.1402
Unit:	tonnes
Basis of Estimate Cd:	M2
Basis of Estimate Desc:	M2- Predictive Emission Monitoring - In use from 2003 and onward
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr):	PM2,5 - Matière particulaire <= 2,5 microns
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	
Category Type ID:	13
Category Type Desc:	All Media
Category Type Desc (fr):	Rejets à tous les médias
Grouping:	Total All Media<1t
Trans Code:	
Chem:	PM10 - Particulate Matter <= 10 Microns
Chem (fr):	PM10 - Matière particulaire <= 10 microns
Quantity:	0
Unit:	tonnes
Basis of Estimate Cd:	
Basis of Estimate Desc:	

42	36 of 80	-/0.0	79.8 / 0.00	CITY OF TORONTO 400 COMMISSIONER STREET NOT AVAILABLE TORONTO ON M4M3K2	NPRI

NPRI ID:	11552	**Org ID:**	101368
Other ID:	N	**Submit Date:**	5/29/2009
No Other ID:		**Last Modified:**	5/29/2015 3:28:24 PM
Track ID:	68881	**Contact ID:**	141902
Report ID:	130794	**Cont Type:**	MED
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	DEREK
Report Year:	2008	**Cont Last Name:**	ANGOVE
Not-Current Rpt?:	No	**Contact Position:**	MANAGER, TRANSFER OPERATIONS
Yr of Last Filed Rpt:	2014	**Contact Fax:**	4163971348
Fac ID:	225812	**Contact Ph.:**	4163922447
Fac Name:	COMMISSIONERS STREET TRANSFER STATION	**Cont Area Code:**	416
Fac Address1:	400 COMMISSIONER STREET	**Contact Tel.:**	63922447
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	M4M3K2	**Cont Fax Area Cde:**	416
Facility Lat:	43.6518	**Contact Fax:**	63971348
Facility Long:	-79.3391	**Contact Email:**	DANGOVE@TORONTO.CA
DLS (Last Filed Rpt):		**Latitude:**	43.6518
Facility DLS:		**Longitude:**	-79.3391
Datum:	1983	**UTM Zone:**	
Facility Cmnts:	No	**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	52	**Waste Streams:**	No
Parent Co.:	N	**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	No
Pollut Prev Cmnts:	No	**No Off Sites:**	
Stacks:	No	**Shutdown:**	No
No of Stacks:		**No of Shutdown:**	
Canadian SIC Code (2 digit):			
Canadian SIC Code:			
SIC Code Description:			

American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and support, waste management and remediation services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste Collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste Collection

Substance Release Report

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM - Total Particulate Matter
Chem (fr): PM - Particules totales
Quantity: 2.07
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: 0
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: .11
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: .41
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 13
Category Type Desc: All Media
Category Type Desc (fr): Rejets à tous les médias
Grouping: Total All Media<1t
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns

Quantity: 0
Unit: tonnes
Basis of Estimate Cd:
Basis of Estimate Desc:

---

42 | **37 of 80** | **-/0.0** | **79.8 / 0.00** | **City of Toronto**
400 COMMISSIONER STREET NOT AVAILABLE
TORONTO ON M4M3K2 | **NPRI**

NPRI ID:	11552	**Org ID:**	104706
Other ID:		**Submit Date:**	5/31/2016
No Other ID:		**Last Modified:**	11/18/2016 8:28:05 AM
Track ID:	139212	**Contact ID:**	241778
Report ID:	73399	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	
Rpt Type ID:	1	**Cont First Name:**	NOT AVAILABLE
Report Year:	2015	**Cont Last Name:**	NOT AVAILABLE
Not-Current Rpt?:	No	**Contact Position:**	
Yr of Last Filed Rpt:	2014	**Contact Fax:**	
Fac ID:	225812	**Contact Ph.:**	0
Fac Name:	COMMISSIONERS STREET TRANSFER STATION	**Cont Area Code:**	0
Fac Address1:	400 COMMISSIONER STREET	**Contact Tel.:**	
Fac Address2:	NOT AVAILABLE	**Contact Ext.:**	
Fac Postal Zip:	M4M3K2	**Cont Fax Area Cde:**	
Facility Lat:	43.6518	**Contact Fax:**	
Facility Long:	-79.3391	**Contact Email:**	NOT AVAILABLE
DLS (Last Filed Rpt):		**Latitude:**	43.6518
Facility DLS:		**Longitude:**	-79.3391
Datum:	1983	**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	18	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and support, waste management and remediation services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste collection

Substance Release Report

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem:
Chem (fr):
Quantity: .37
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6

Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	
Chem (fr):	
Quantity:	1.87
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

Category Type ID:	6
Category Type Desc:	Road dust
Category Type Desc (fr):	Poussières de routes
Grouping:	Total Air
Trans Code:	
Chem:	
Chem (fr):	
Quantity:	.09
Unit:	tonnes
Basis of Estimate Cd:	E2
Basis of Estimate Desc:	E2- Published Emission Factors - In use from 2003 and onward

---

42 | ***38 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***METROPOLITAN WORKS DEPT SOLID WASTE MANAGEMENT DIV
400 COMMISSIONERS ST
TORONTO ON M4M 3K2*** | ***PRT***

Location ID:	15243
Type:	private
Expiry Date:	
Capacity (L):	9092.00
Licence #:	0001022823

---

42 | ***39 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***400 Commissioners Street
Toronto ON M4M 3K2*** | ***SPL***

Ref No:	8714-6D3899	**Discharger Report:**	0
Site No:		**Material Group:**	Gases/Particulate
Incident Dt:	6/4/2005	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	Unknown	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:	SMOKE	**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	Toronto
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	Possible	**Site Municipality:**	Toronto
Nature of Impact:	Air Pollution; Surface Water Pollution	**Site Lot:**	
Receiving Medium:	Water & Air	**Site Conc:**	
Receiving Env:		**Northing:**	NA
MOE Response:		**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	6/5/2005	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	Spills to Air - fires
Incident Reason:	Fire/Explosion - Resulting from fires/explosions (Not occurrences which cause a fire or explosion)	**Source Type:**	
Site Name:	400 Commisioners Street		
Site County/District:			
Site Geo Ref Meth:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Incident Summary: Toronto: garbage fire at waste transfer site, ERP
Contaminant Qty: unknown

---

42 | 40 of 80 | -/0.0 | 79.8 / 0.00 | City of Toronto, 400 Commissioners St, Toronto ON M4M 3K2 | SPL

Ref No: 2121-89GM8S
Site No:
Incident Dt:
Year:
Incident Cause: Other Discharges
Incident Event:
Contaminant Code: 15
Contaminant Name: HYDRAULIC OIL
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1:
Environment Impact: Not Anticipated
Nature of Impact: Other Impact(s)
Receiving Medium:
Receiving Env:
MOE Response: No Field Response
Dt MOE Arvl on Scn:
MOE Reported Dt: 9/20/2010
Dt Document Closed:
Incident Reason: Error- Operator error
Site Name: 400 Commissioners Street
Site County/District:
Site Geo Ref Meth:
Incident Summary: Toronto garbage truck, 50L hydraulic oil to road & c/b
Contaminant Qty: 50 L

Discharger Report:
Material Group:
Health/Env Conseq:
Client Type:
Sector Type: Motor Vehicle
Agency Involved:
Nearest Watercourse:
Site Address:
Site District Office:
Site Postal Code:
Site Region:
Site Municipality:
Site Lot:
Site Conc:
Northing: 4834509
Easting: 633915
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Land Spills
Source Type:

---

42 | 41 of 80 | -/0.0 | 79.8 / 0.00 | Badger Daylighting Ltd., 400 Commissioners st, Toronto ON | SPL

Ref No: 0768-B62MBU
Site No: NA
Incident Dt: 2018/10/29
Year:
Incident Cause:
Incident Event: Leak/Break
Contaminant Code: 15
Contaminant Name: OIL (PETROLEUM BASED, NOT SPECIFIED)
Contaminant Limit 1:
Contam Limit Freq 1:
Contaminant UN No 1: n/a
Environment Impact:
Nature of Impact:
Receiving Medium:
Receiving Env: Land
MOE Response: No
Dt MOE Arvl on Scn:
MOE Reported Dt: 2018/10/30
Dt Document Closed:
Incident Reason: Unknown / N/A
Site Name: spill <UNOFFICIAL>
Site County/District:

Discharger Report:
Material Group:
Health/Env Conseq: 2 - Minor Environment
Client Type: Corporation
Sector Type: Miscellaneous Communal
Agency Involved:
Nearest Watercourse:
Site Address: 400 Commissioners st
Site District Office: Toronto - District
Site Postal Code:
Site Region: Central
Site Municipality: Toronto
Site Lot:
Site Conc:
Northing: 4834474.12
Easting: 633952.46
Site Geo Ref Accu:
Site Map Datum:
SAC Action Class: Pollution Incident Reports (PIRs) and "Other" calls
Source Type: Unknown / N/A

Site Geo Ref Meth:
Incident Summary: Badger: watermain break, contaminated soil removal
Contaminant Qty: 0 other - see incident description

---

42 | **42 of 80** | **-/0.0** | **79.8 / 0.00** | **City of Toronto**
400 Commissioners St
Toronto ON NA | **SPL**

Ref No:	1368-ARUMXU	**Discharger Report:**	
Site No:	3916-8NQRL8	**Material Group:**	
Incident Dt:	2017/10/05	**Health/Env Conseq:**	2 - Minor Environment
Year:		**Client Type:**	Municipal Government
Incident Cause:		**Sector Type:**	Miscellaneous Communal
Incident Event:	Fire/Explosion	**Agency Involved:**	
Contaminant Code:	43	**Nearest Watercourse:**	
Contaminant Name:	GARBAGE	**Site Address:**	400 Commissioners St
Contaminant Limit 1:		**Site District Office:**	Toronto - District
Contam Limit Freq 1:		**Site Postal Code:**	NA
Contaminant UN No 1:	n/a	**Site Region:**	Central
Environment Impact:		**Site Municipality:**	Toronto
Nature of Impact:		**Site Lot:**	
Receiving Medium:		**Site Conc:**	NA
Receiving Env:	Air	**Northing:**	NA
MOE Response:	No	**Easting:**	NA
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	NA
MOE Reported Dt:	2017/10/05	**Site Map Datum:**	NA
Dt Document Closed:	2017/12/30	**SAC Action Class:**	Land Spills
Incident Reason:	Unknown / N/A	**Source Type:**	Unknown / N/A

Site Name: Commissioners Transfer Station
Site County/District: NA
Site Geo Ref Meth: NA
Incident Summary: Commissioners Transfer Station; fire in garbage truck, extinguished
Contaminant Qty: 0 other - see incident description

---

42 | **43 of 80** | **-/0.0** | **79.8 / 0.00** | **METROPOLITAN TORONTO, MUNICIPA**
400 COMMISSIONERS STREET HOUSEHOLD HAZARDOUS WASTE FACILITY 400 COMMISSIONERS STREET
TORONTO CITY ON M4M 3K2 | **SPL**

Ref No:	69742	**Discharger Report:**	
Site No:		**Material Group:**	
Incident Dt:	4/26/1992	**Health/Env Conseq:**	
Year:		**Client Type:**	
Incident Cause:	OTHER CONTAINER LEAK	**Sector Type:**	
Incident Event:		**Agency Involved:**	
Contaminant Code:		**Nearest Watercourse:**	
Contaminant Name:		**Site Address:**	
Contaminant Limit 1:		**Site District Office:**	
Contam Limit Freq 1:		**Site Postal Code:**	
Contaminant UN No 1:		**Site Region:**	
Environment Impact:	CONFIRMED	**Site Municipality:**	01106
Nature of Impact:	Soil Contamination	**Site Lot:**	
Receiving Medium:	LAND	**Site Conc:**	
Receiving Env:		**Northing:**	4834300.00
MOE Response:		**Easting:**	633900.00
Dt MOE Arvl on Scn:		**Site Geo Ref Accu:**	
MOE Reported Dt:	4/27/1992	**Site Map Datum:**	
Dt Document Closed:		**SAC Action Class:**	
Incident Reason:	VANDALISM	**Source Type:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Site Name:
Site County/District:
Site Geo Ref Meth:
Incident Summary: METRO WORKS: VANDAL POURED 10 L ACID ONTO GROUND
Contaminant Qty:

---

42 | **44 of 80** | **-/0.0** | **79.8 / 0.00** | **400 COMMISSIONERS ST. TORONTO ON M4M 3K2** | **WDS**

Approval No:	A280203	**Total Area (ha):**	0
Mob Unit Cert No:		**Landfill Cap (m³):**	0
EBR Registry No:		**Transfer Area (ha):**	0
Status:	Approved	**Transfer Cap (m³):**	0
Facility Type:	Transfer Station	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	0
Link Source:		**Inciner. Cap (t):**	0
Project Type:		**Process Area (m³):**	0
Application Status:		**Process Cap (m³/d):**	0
Issue Date:	03/01/1989	**Process Vol (m³):**	0
Input Date:	7/21/93	**Process Feed (m³):**	0
Date Received:	8/10/71	**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:	0	**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Toronto
Prop City:	TORONTO, ONTARIO	**Latitude:**	
Prop Postal:	M5G-1Y8	**Longitude:**	
Prop Phone:	416-392-8255	**Geometry X:**	
Serial Link:	280203	**Geometry Y:**	

Approval Type:
Proponent: WORKS DEPT., METRO TORONTO
Prop Address: 439 UNIVERSITY AVE.
Proponent County/District:
Full Address:
Site Lot:
Waste Class Code:
Waste Class:
Waste Type: domestic, commercial, solid hazardous
Waste Type Other: No
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description: AMENDMENT OF NOTICE 01/27/1988: ADD WASTE CODES 145, 242, 269 TO THE WASTE CODES LISTED.
Project Description:
Municipalities Served: POPULATION: 2 000 000
Approval Description: APPROVAL FOR A TEMPORARY WASTE TRANSFER STATION
Other Approvals/Permits:
PDF URL:

---

42 | **45 of 80** | **-/0.0** | **79.8 / 0.00** | **400 COMMISSIONERS ST. TORONTO ON M4M 3K2** | **WDS**

Approval No:	A280203	**Total Area (ha):**	0
Mob Unit Cert No:		**Landfill Cap (m³):**	0
EBR Registry No:		**Transfer Area (ha):**	0.29
Status:	Approved	**Transfer Cap (m³):**	0
Facility Type:	Transfer Station	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	0
Link Source:		**Inciner. Cap (t):**	0
Project Type:		**Process Area (m³):**	0
Application Status:		**Process Cap (m³/d):**	0
Issue Date:	07/24/1991	**Process Vol (m³):**	0

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Input Date:	7/21/93	**Process Feed (m³):**	0
Date Received:	8/10/71	**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:	0	**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Toronto
Prop City:	TORONTO, ONTARIO	**Latitude:**	
Prop Postal:	M5G-1Y8	**Longitude:**	
Prop Phone:	416-392-8255	**Geometry X:**	
Serial Link:	280203	**Geometry Y:**	

Approval Type:
Proponent: WORKS DEPT., METRO TORONTO
Prop Address: 439 UNIVERSITY AVE.
Proponent County/District:
Full Address:
Site Lot:
Waste Class Code:
Waste Class:
Waste Type: domestic
Waste Type Other: No
Waste Description: RECYCLABLE DOMESTIC: 100% INCLUDING GLASS, FERROUS/ NON-FERROUS, PLASTICS
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description: AMENDMENT OF CofA 02/27/1980: FOR ACCEPTANCE, STORAGE AND TRANSFER OF NEEDLES SYRINGES FROM PRIVATE IN-HOME MEDICAL CARE; ALL WASTES IN SECURE AREA WITH RESTRICTED ACCESS; NO WASTES TO BE STORED LONGER THAN 90 DAYS; ETC.
Project Description:
Municipalities Served: POPULATION: 2 000 000 FOR TORONTO, ETOBICOKE, YORK, EAST YORK, NORTH YORK, SCARBOROUGH
Approval Description:
Other Approvals/Permits:
PDF URL:

---

42 | **46 of 80** | **-/0.0** | **79.8 / 0.00** | **400 COMMISSIONERS ST. TORONTO ON M4M 3K2** | **WDS**

Approval No:	A280203	**Total Area (ha):**	0
Mob Unit Cert No:		**Landfill Cap (m³):**	0
EBR Registry No:		**Transfer Area (ha):**	0
Status:	Approved	**Transfer Cap (m³):**	0
Facility Type:	Transfer Station	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	0
Link Source:		**Inciner. Cap (t):**	0
Project Type:		**Process Area (m³):**	0
Application Status:		**Process Cap (m³/d):**	0
Issue Date:	05/22/1990	**Process Vol (m³):**	0
Input Date:	7/21/93	**Process Feed (m³):**	0
Date Received:	8/10/71	**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:	0	**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Toronto
Prop City:	TORONTO, ONTARIO	**Latitude:**	
Prop Postal:	M5G-1Y8	**Longitude:**	
Prop Phone:	416-392-8255	**Geometry X:**	
Serial Link:	280203	**Geometry Y:**	

Approval Type:
Proponent: WORKS DEPT., METRO TORONTO
Prop Address: 439 UNIVERSITY AVE.
Proponent County/District:
Full Address:
Site Lot:
Waste Class Code:
Waste Class:
Waste Type: domestic, commercial, solid hazardous

Waste Type Other:	Yes
Waste Description:	OTHER: LEAVES
Landfill Monitoring:	
Landfill Ctrl Type:	
Site Closing Description:	AMENDMENT OF CofA 02/27/1980: COND'N 5 OF AMENDED NOTICE 01/27/1988 CHANGED TO ALLOW STORAGE OF COMPRESSED GAS CYLINDERS AND AUTOMOTIVE BATERIES OUTSIDE THE ENCLOSED HOUSELOLD HAZ. WASTE TRANSFER FACILITY, ETC.
Project Description:	
Municipalities Served:	POPULATION: 2 000 000
Approval Description:	APPROVAL FOR LEAF TRANSFER STATION
Other Approvals/Permits:	
PDF URL:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	47 of 80	-/0.0	79.8 / 0.00	400 COMMISSIONERS ST. TORONTO ON M4M 3K2	WDS

Approval No:	A280203	**Total Area (ha):**	0
Mob Unit Cert No:		**Landfill Cap (m^3):**	0
EBR Registry No:		**Transfer Area (ha):**	0
Status:	Approved	**Transfer Cap (m^3):**	0
Facility Type:	Transfer Station	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	0
Link Source:		**Inciner. Cap (t):**	0
Project Type:		**Process Area (m^3):**	0
Application Status:		**Process Cap (m^3/d):**	0
Issue Date:	11/14/1988	**Process Vol (m^3):**	0
Input Date:	7/21/93	**Process Feed (m^3):**	0
Date Received:	8/10/71	**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:	0	**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Toronto
Prop City:	TORONTO, ONTARIO	**Latitude:**	
Prop Postal:	M5G-1Y8	**Longitude:**	
Prop Phone:	416-392-8255	**Geometry X:**	
Serial Link:	280203	**Geometry Y:**	

Approval Type:	
Proponent:	WORKS DEPT., METRO TORONTO
Prop Address:	439 UNIVERSITY AVE.
Proponent County/District:	
Full Address:	
Site Lot:	
Waste Class Code:	
Waste Class:	
Waste Type:	domestic, commercial, solid hazardous
Waste Type Other:	No
Waste Description:	APPROVAL TO ACCEPT HANDLING OF CO-MINGLED METAL CANS, GLASS AND PET BOTTLES
Landfill Monitoring:	
Landfill Ctrl Type:	
Site Closing Description:	AMENDMENT OF NOTICE 01/27/1988: AFFECTIVE 11/14/88 APPROVAL FOR USE AND OPERATION OF INCINERATOR REVOKED; APPROVAL FOR OPERATION OF A TEMPORARY REFUSE TRANSFER STATION EFFECTIVE 11/14/88, WITH EXPIRY 12/31/1991.
Project Description:	
Municipalities Served:	POPULATION: 2 000 000
Approval Description:	CHANGES: CONVERSION OF INCINERATOR OPERATION TO A TEMPORARY REFUSE TRANSFER STATION
Other Approvals/Permits:	A 121011 SYNTATH DISPOSAL
PDF URL:	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	48 of 80	-/0.0	79.8 / 0.00	COMMISSIONER STREET WASTE TRAN 400 COMMISSIONERS ST. TORONTO ON M4M 3K2	WDS

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval No:	A280203	**Total Area (ha):**	0
Mob Unit Cert No:		**Landfill Cap (m³):**	0
EBR Registry No:		**Transfer Area (ha):**	0.29
Status:	Approved	**Transfer Cap (m³):**	0
Facility Type:	Transfer Station	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	0
Link Source:		**Inciner. Cap (t):**	0
Project Type:		**Process Area (m³):**	0
Application Status:		**Process Cap (m³/d):**	0
Issue Date:	07/15/1998	**Process Vol (m³):**	0
Input Date:	11/10/98	**Process Feed (m³):**	0
Date Received:	6/16/98	**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:	0	**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Toronto
Prop City:	TORONTO, ONTARIO	**Latitude:**	
Prop Postal:	M5G-1Y8	**Longitude:**	
Prop Phone:	416-392-8255	**Geometry X:**	
Serial Link:	280203	**Geometry Y:**	

Approval Type:
Proponent: TORONTO, METRO
Prop Address: 439 UNIVERSITY AVE.
Proponent County/District:
Full Address:
Site Lot:
Waste Class Code:
Waste Class:
Waste Type: domestic, commercial
Waste Type Other: Yes
Waste Description: RECYCLABLES
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description: AMENDMENT OF CofA 02/27/1980: FOR ALLOWANCE OF HOUSEHOLD HAZARDOUS WASTE TRANSFER STATION TO ACCEPT FOR BULKING AND TEMP. STORAGE, FOR FUTURE TRANSFER, IN ACCORDANCE WITH 3 CONDITIONS (SEE NOTICE).
Project Description:
Municipalities Served: POPULATION: 2 000 000 FOR TORONTO, ETOBICOKE, YORK, EAST YORK, NORTH YORK, SCARBOROUGH
Approval Description: REQUESTS FOR CONVERSION FROM TEMPORARY TRANSFER STATION TO A TRANSFER STATION
Other Approvals/Permits:
PDF URL:

42	49 of 80	-/0.0	79.8 / 0.00	**400 COMMISSIONERS ST. TORONTO ON M4M 3K2**	**WDS**

Approval No:	A280203	**Total Area (ha):**	0
Mob Unit Cert No:		**Landfill Cap (m³):**	0
EBR Registry No:		**Transfer Area (ha):**	0.29
Status:	Approved	**Transfer Cap (m³):**	0
Facility Type:	Transfer Station	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	0
Link Source:		**Inciner. Cap (t):**	0
Project Type:		**Process Area (m³):**	0
Application Status:		**Process Cap (m³/d):**	0
Issue Date:	03/30/1994	**Process Vol (m³):**	0
Input Date:	4/5/94	**Process Feed (m³):**	0
Date Received:	8/10/71	**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:	0	**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Toronto
Prop City:	TORONTO, ONTARIO	**Latitude:**	
Prop Postal:	M5G-1Y8	**Longitude:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Prop Phone:	416-392-8255	**Geometry X:**	
Serial Link:	280203	**Geometry Y:**	
Approval Type:			
Proponent:	WORKS DEPT., METRO TORONTO		
Prop Address:	439 UNIVERSITY AVE.		
Proponent County/District:			
Full Address:			
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:	domestic, commercial		
Waste Type Other:	Yes		
Waste Description:	RECYCLABLES		
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:	AMENDMENT OF CofA 02/27/1980: FOR ALLOWANCE OF HOUSEHOLD HAZARDOUS WASTE TRANSFER STATION TO ACCEPT FOR BULKING AND TEMP. STORAGE, FOR FUTURE TRANSFER, IN ACCORDANCE WITH 3 CONDITIONS (SEE NOTICE).		
Project Description:			
Municipalities Served:	POPULATION: 2 000 000 FOR TORONTO, ETOBICOKE, YORK, EAST YORK, NORTH YORK, SCARBOROUGH		
Approval Description:	REQUESTS FOR CONVERSION FROM TEMPORARY TRANSFER STATION TO A TRANSFER STATION		
Other Approvals/Permits:			
PDF URL:			

42	50 of 80	-/0.0	79.8 / 0.00	**400 COMMISSIONERS ST. TORONTO ON M4M 3K2**	**WDS**

Approval No:	A280203	**Total Area (ha):**	0
Mob Unit Cert No:		**Landfill Cap (m^3):**	0
EBR Registry No:		**Transfer Area (ha):**	0
Status:	Approved	**Transfer Cap (m^3):**	0
Facility Type:	Transfer Station	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	0
Link Source:		**Inciner. Cap (t):**	0
Project Type:		**Process Area (m^3):**	0
Application Status:		**Process Cap (m^3/d):**	0
Issue Date:	01/27/1988	**Process Vol (m^3):**	0
Input Date:	7/21/93	**Process Feed (m^3):**	0
Date Received:	8/10/71	**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:	0	**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Toronto
Prop City:	TORONTO, ONTARIO	**Latitude:**	
Prop Postal:	M5G-1Y8	**Longitude:**	
Prop Phone:	416-392-8255	**Geometry X:**	
Serial Link:	280203	**Geometry Y:**	

Approval Type:	
Proponent:	WORKS DEPT., METRO TORONTO
Prop Address:	439 UNIVERSITY AVE.
Proponent County/District:	
Full Address:	
Site Lot:	
Waste Class Code:	
Waste Class:	
Waste Type:	
Waste Type Other:	Yes
Waste Description:	HOUSEHOLD HAZARDOUS WASTE: REVISED APPLICATION TO INCLUDE 1.135 TONNES OF HOUSEHOLD HAZARDOUS WASTE PER MONTH
Landfill Monitoring:	
Landfill Ctrl Type:	
Site Closing Description:	9 CONDITIONS: DAILY RECORD OF TYPES OF WASTES DISPOSED, HAZ. WASTE CODE NUMBER AND AMOUNTS; DAILY INSPECTION FOR SECURITY OF WASTE CONTAINERS AND RECORDS OF ANY ACCIDENTAL SPILLS; TRANSFER FACILITY TO HAVE LEAK-PROOF BASE;

Project Description:
Municipalities Served: POPULATION: 2 000 000
Approval Description: STORAGE CAPACITY: 6.8 CUBIC METRES HOUSEHOLD HAZARDOUS WASTE FACILITY
Other Approvals/Permits: A 121011 FOR SYNTATH DISPOSAL
PDF URL:

---

42 | **51 of 80** | **-/0.0** | **79.8 / 0.00** | **400 COMMISSIONERS ST. TORONTO ON M4M 3K2** | **WDS**

Approval No:	A280203	**Total Area (ha):**	0
Mob Unit Cert No:		**Landfill Cap (m³):**	0
EBR Registry No:		**Transfer Area (ha):**	0
Status:	Approved	**Transfer Cap (m³):**	0
Facility Type:	Transfer Station	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	0
Link Source:		**Inciner. Cap (t):**	0
Project Type:		**Process Area (m³):**	0
Application Status:		**Process Cap (m³/d):**	0
Issue Date:	11/01/1989	**Process Vol (m³):**	0
Input Date:	7/21/93	**Process Feed (m³):**	0
Date Received:	8/10/71	**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:	0	**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Toronto
Prop City:	TORONTO, ONTARIO	**Latitude:**	
Prop Postal:	M5G-1Y8	**Longitude:**	
Prop Phone:	416-392-8255	**Geometry X:**	
Serial Link:	280203	**Geometry Y:**	

Approval Type:
Proponent: WORKS DEPT., METRO TORONTO
Prop Address: 439 UNIVERSITY AVE.
Proponent County/District:
Full Address:
Site Lot:
Waste Class Code:
Waste Class:
Waste Type: domestic, commercial, solid hazardous
Waste Type Other: Yes
Waste Description: APPROVAL TO ACCEPT LEAVES AT TRANSFER FACILITY UNTIL 12/31/91.
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description: AMENDMENT OF NOTICE 03/01/1989: NO WASTE ACCEPTANCE UNTIL THIS NOT- ICE SHALL BE STORED ON SITE FOR LONGER THAN 60 DAYS; APPROVAL FOR THE LEAF TRANSFER FACILITY EXPIRES ON DECEMBER 31, 1991.
Project Description:
Municipalities Served: POPULATION: 2 000 000
Approval Description: ADDITIONAL 462 CUBIC METRES PER DAY IN LEAVES (INCREASED AMOUNT IN AUTUMN)
Other Approvals/Permits:
PDF URL:

---

42 | **52 of 80** | **-/0.0** | **79.8 / 0.00** | **400 COMMISSIONERS ST. TORONTO ON M4M 3K2** | **WDS**

Approval No:	A280203	**Total Area (ha):**	0
Mob Unit Cert No:		**Landfill Cap (m³):**	0
EBR Registry No:		**Transfer Area (ha):**	0
Status:	Approved	**Transfer Cap (m³):**	0
Facility Type:	Transfer Station	**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	0
Link Source:		**Inciner. Cap (t):**	0
Project Type:		**Process Area (m³):**	0

Application Status:		**Process Cap (m³/d):**	0
Issue Date:	02/14/1990	**Process Vol (m³):**	0
Input Date:	7/21/93	**Process Feed (m³):**	0
Date Received:	8/10/71	**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:	0	**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	Toronto
Prop City:	TORONTO, ONTARIO	**Latitude:**	
Prop Postal:	M5G-1Y8	**Longitude:**	
Prop Phone:	416-392-8255	**Geometry X:**	
Serial Link:	280203	**Geometry Y:**	

Approval Type:
Proponent: WORKS DEPT., METRO TORONTO
Prop Address: 439 UNIVERSITY AVE.
Proponent County/District:
Full Address:
Site Lot:
Waste Class Code:
Waste Class:
Waste Type: domestic, commercial, solid hazardous
Waste Type Other: Yes
Waste Description: OTHER: LEAVES
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description: AMENDMENT OF NOTICE 11/01/1989: DUE DATE FOR ANNUAL REPORT REQUIRED BY CONDITION 7 OF NOTICE (01/27/88) IS CHANGED TO MARCH 31 OF THE YEAR FOLLOW- ING THE YEAR FOR WHICH THE REPORT WAS PREPARED; ALL OTHER CONDITIONS IN EFFECT
Project Description:
Municipalities Served: POPULATION: 2 000 000
Approval Description: APPROVAL FOR LEAF TRANSFER STATION EXPIRING 12/31/91 INCREASES AMOUNT BY 462 CUBIC METRES PER DAY
Other Approvals/Permits:
PDF URL:

---

42 | **53 of 80** | **-/0.0** | **79.8 / 0.00** | **City of Toronto**
400 Commissioners Street
Toronto ON M4M 3K2 | **WDS**

Approval No:	A280203	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:		**Inciner. Area (ha):**	
Link Source:		**Inciner. Cap (t):**	
Project Type:		**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	4/16/14	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	Toronto
Mobile Capacity:		**SWP Area Name:**	
Mobile Units:		**MOE District:**	
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651111111111106311000185087323188781738281 25
Prop Postal:		**Longitude:**	-79.338888888888888573092117439955472946166992 1875
Prop Phone:		**Geometry X:**	
Serial Link:		**Geometry Y:**	

Approval Type:
Proponent:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Prop Address:
Proponent County/District:
Full Address: 400 Commissioners Street Toronto, Ontario M4M 3K2
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL:

42	54 of 80	-/0.0	79.8 / 0.00	***City of Toronto*** ***400 Commissioners St*** ***Toronto ON M3J 2B7***	***WDS***

Approval No:	A210615	***Total Area (ha):***	
Mob Unit Cert No:		***Landfill Cap (m³):***	
EBR Registry No:		***Transfer Area (ha):***	
Status:	Approved	***Transfer Cap (m³):***	
Facility Type:		***Transfer Cert No:***	
Record Type:	ECA	***Inciner. Area (ha):***	-79.33892
Link Source:	IDS	***Inciner. Cap (t):***	43.651188
Project Type:	WASTE DISPOSAL SITES	***Process Area (m³):***	
Application Status:		***Process Cap (m³/d):***	
Issue Date:	2019-05-27	***Process Vol (m³):***	
Input Date:		***Process Feed (m³):***	
Date Received:		***Site Concession:***	
Est Closure Date:		***Site Region/County:***	
Mobile Capacity:		***SWP Area Name:***	Toronto
Mobile Units:		***MOE District:***	Metro Toronto
Mobile Description:		***District Office:***	
Prop City:		***Latitude:***	43.651188
Prop Postal:		***Longitude:***	-79.33892
Prop Phone:		***Geometry X:***	-8831968.1745
Serial Link:		***Geometry Y:***	5411620.446199998

Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 400 Commissioners St
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/4200-B4KGHX-14.pdf

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	55 of 80	-/0.0	79.8 / 0.00	City of Toronto 400 Commissioners Street Toronto ON M5H 2N2	WDS

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Revoked and/or Replaced	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2003-10-22	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 400 Commissioners Street
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/1887-5SHSQQ-14.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	56 of 80	-/0.0	79.8 / 0.00	City of Toronto 400 Commissioners Street Toronto ON M5H 2N2	WDS

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Revoked and/or Replaced	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2003-06-27	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	400 Commissioners Street		
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:			
Waste Type Other:			
Waste Description:			
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:			
Project Description:			
Municipalities Served:			
Approval Description:			
Other Approvals/Permits:			
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/1393-5NPLY9-14.pdf		

42	**57 of 80**	**-/0.0**	**79.8 / 0.00**	**City of Toronto** **400 Commissioners St** **Toronto ON M3J 2B7**	**WDS**

Approval No:	A280203	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2014-04-16	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	400 Commissioners St		
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:			
Waste Type Other:			
Waste Description:			
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:			
Project Description:			
Municipalities Served:			

Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/9846-9E8MC8-14.pdf

---

42 | ***58 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***City of Toronto*** | ***WDS***
400 Commissioners Street
Toronto ON M5H 2N2

Approval No:	A280203	***Total Area (ha):***	
Mob Unit Cert No:		***Landfill Cap (m³):***	
EBR Registry No:		***Transfer Area (ha):***	
Status:	Approved	***Transfer Cap (m³):***	
Facility Type:		***Transfer Cert No:***	
Record Type:	ECA	***Inciner. Area (ha):***	
Link Source:	IDS	***Inciner. Cap (t):***	
Project Type:	WASTE DISPOSAL SITES	***Process Area (m³):***	
Application Status:		***Process Cap (m³/d):***	
Issue Date:	2003-05-08	***Process Vol (m³):***	
Input Date:		***Process Feed (m³):***	
Date Received:		***Site Concession:***	
Est Closure Date:		***Site Region/County:***	
Mobile Capacity:		***SWP Area Name:***	Toronto
Mobile Units:		***MOE District:***	Metro Toronto
Mobile Description:		***District Office:***	
Prop City:		***Latitude:***	43.651188
Prop Postal:		***Longitude:***	-79.33892
Prop Phone:		***Geometry X:***	-79.33892
Serial Link:		***Geometry Y:***	43.651188

Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 400 Commissioners Street
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/7110-5MAMWA-14.pdf

---

42 | ***59 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***City of Toronto*** | ***WDS***
400 Commissioners Street
Toronto ON M5V 3C6

Approval No:	A210615	***Total Area (ha):***	5.3
Mob Unit Cert No:		***Landfill Cap (m³):***	
EBR Registry No:		***Transfer Area (ha):***	
Status:	Revoked and/or Replaced	***Transfer Cap (m³):***	
Facility Type:		***Transfer Cert No:***	
Record Type:	ECA	***Inciner. Area (ha):***	
Link Source:	IDS	***Inciner. Cap (t):***	
Project Type:	WASTE DISPOSAL SITES	***Process Area (m³):***	
Application Status:		***Process Cap (m³/d):***	
Issue Date:	2001-10-12	***Process Vol (m³):***	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:	Toronto	**Latitude:**	43.651188
Prop Postal:	M5V 3C6	**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type:	ECA-WASTE DISPOSAL SITES
Proponent:	Corporation of the City of Toronto
Prop Address:	55 John St., 19th Floor
Proponent County/District:	Municipality Of Metropolitan Toronto
Full Address:	400 Commissioners Street
Site Lot:	
Waste Class Code:	
Waste Class:	
Waste Type:	
Waste Type Other:	
Waste Description:	
Landfill Monitoring:	
Landfill Ctrl Type:	
Site Closing Description:	
Project Description:	This application is to add the City of Toronto and the neighbouring Regions of Durham, Peel and York as the approved service area.
Municipalities Served:	toronto
Approval Description:	
Other Approvals/Permits:	
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/9853-4Y3Q87-14.pdf

---

42	60 of 80	-/0.0	79.8 / 0.00	***City of Toronto*** ***400 Commissioners Street*** ***Toronto ON M5V 3C6***	***WDS***

Approval No:	A280203	**Total Area (ha):**	0.0001
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2001-03-29	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:	Toronto	**Latitude:**	43.651188
Prop Postal:	M5V 3C6	**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type:	ECA-WASTE DISPOSAL SITES
Proponent:	Corporation of the City of Toronto
Prop Address:	55 John St., 19th Floor
Proponent County/District:	Municipality Of Metropolitan Toronto
Full Address:	400 Commissioners Street
Site Lot:	
Waste Class Code:	
Waste Class:	
Waste Type:	

Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description: Approval is sought for the installation of an upgraded household hazardous waste management facility to replace a temporary facility consisting of a roll-off container and a garden shed. The upgraded facility provides better spill containment, better fire suppression system and more security of the wastes during storage.
Municipalities Served: City of Toronto
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/5560-4TQPMX-14.pdf

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	61 of 80	-/0.0	79.8 / 0.00	***City of Toronto*** ***400 Commissioners Street*** ***Toronto ON M5H 2N2***	***WDS***

Approval No:	A210343	***Total Area (ha):***	
Mob Unit Cert No:		***Landfill Cap (m³):***	
EBR Registry No:		***Transfer Area (ha):***	
Status:	Approved	***Transfer Cap (m³):***	
Facility Type:		***Transfer Cert No:***	
Record Type:	ECA	***Inciner. Area (ha):***	
Link Source:	IDS	***Inciner. Cap (t):***	
Project Type:	WASTE DISPOSAL SITES	***Process Area (m³):***	
Application Status:		***Process Cap (m³/d):***	
Issue Date:	2003-03-20	***Process Vol (m³):***	
Input Date:		***Process Feed (m³):***	
Date Received:		***Site Concession:***	
Est Closure Date:		***Site Region/County:***	
Mobile Capacity:		***SWP Area Name:***	Toronto
Mobile Units:		***MOE District:***	Metro Toronto
Mobile Description:		***District Office:***	
Prop City:		***Latitude:***	43.651188
Prop Postal:		***Longitude:***	-79.33892
Prop Phone:		***Geometry X:***	-79.33892
Serial Link:		***Geometry Y:***	43.651188

Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 400 Commissioners Street
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/8622-5JJMMU-14.pdf

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	62 of 80	-/0.0	79.8 / 0.00	***City of Toronto*** ***400 Commissioners Street*** ***Toronto ON M5V 3C6***	***WDS***

Approval No:	A210615	***Total Area (ha):***	5.3

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Revoked and/or Replaced	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2001-04-27	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:	Toronto	**Latitude:**	43.651188
Prop Postal:	M5V 2C6	**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type:	ECA-WASTE DISPOSAL SITES
Proponent:	Corporation of the City of Toronto
Prop Address:	55 John Street, Station 1180, 19th Floor
Proponent County/District:	Municipality Of Metropolitan Toronto
Full Address:	400 Commissioners Street
Site Lot:	
Waste Class Code:	
Waste Class:	
Waste Type:	
Waste Type Other:	
Waste Description:	
Landfill Monitoring:	
Landfill Ctrl Type:	
Site Closing Description:	
Project Description:	This application is to request an amendment to the existing Certificate to extend the site's operating life beyond January 2002 by deleting Condition No.24 .
Municipalities Served:	
Approval Description:	
Other Approvals/Permits:	
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/7380-4TPT27-14.pdf

---

42	63 of 80	-/0.0	79.8 / 0.00	**City of Toronto** **400 Commissioners St** **Toronto ON M3J 2B7**	**WDS**

Approval No:	A210343	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2017-07-31	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Approval Type:	ECA-WASTE DISPOSAL SITES
Proponent:	
Prop Address:	
Proponent County/District:	
Full Address:	400 Commissioners St
Site Lot:	
Waste Class Code:	
Waste Class:	
Waste Type:	
Waste Type Other:	
Waste Description:	
Landfill Monitoring:	
Landfill Ctrl Type:	
Site Closing Description:	
Project Description:	
Municipalities Served:	
Approval Description:	
Other Approvals/Permits:	
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/1172-AP7Q9A-14.pdf

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	64 of 80	-/0.0	79.8 / 0.00	**City of Toronto** **400 Commissioners Street** **Toronto ON M5H 2N2**	WDS

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m^3):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Revoked and/or Replaced	**Transfer Cap (m^3):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m^3):**	
Application Status:		**Process Cap (m^3/d):**	
Issue Date:	2003-09-25	**Process Vol (m^3):**	
Input Date:		**Process Feed (m^3):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type:	ECA-WASTE DISPOSAL SITES
Proponent:	
Prop Address:	
Proponent County/District:	
Full Address:	400 Commissioners Street
Site Lot:	
Waste Class Code:	
Waste Class:	
Waste Type:	
Waste Type Other:	
Waste Description:	
Landfill Monitoring:	
Landfill Ctrl Type:	
Site Closing Description:	
Project Description:	
Municipalities Served:	
Approval Description:	
Other Approvals/Permits:	
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/2601-5RJMX6-14.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	65 of 80	-/0.0	79.8 / 0.00	City of Toronto 400 Commissioners St Toronto ON M3J 2B7	WDS

Approval No:	A210343	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2019-01-30	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 400 Commissioners St
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/7942-B3WQML-14.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	66 of 80	-/0.0	79.8 / 0.00	City of Toronto 400 Commissioners St Toronto ON M3J 2B7	WDS

Approval No:	A210343	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2016-10-03	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	400 Commissioners St		
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:			
Waste Type Other:			
Waste Description:			
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:			
Project Description:			
Municipalities Served:			
Approval Description:			
Other Approvals/Permits:			
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/5419-ACVJDJ-14.pdf		

42	67 of 80	-/0.0	79.8 / 0.00	**City of Toronto** **400 Commissioners St** **Toronto ON M3J 2B7**	**WDS**

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2018-06-07	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	400 Commissioners St		
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:			
Waste Type Other:			
Waste Description:			
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/6741-AU7MBG-14.pdf

---

42 | **68 of 80** | **-/0.0** | **79.8 / 0.00** | **City of Toronto**
400 Commissioners St
Toronto ON M3J 2B7 | **WDS**

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2016-02-16	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 400 Commissioners St
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/3311-A4JLJX-14.pdf

---

42 | **69 of 80** | **-/0.0** | **79.8 / 0.00** | **City of Toronto**
400 Commissioners Street
Toronto ON M5V 3C6 | **WDS**

Approval No:	A280203	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Application Status:		**Process Cap (m³/d):**	
Issue Date:	2006-10-31	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	400 Commissioners Street		
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:			
Waste Type Other:			
Waste Description:			
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:			
Project Description:			
Municipalities Served:			
Approval Description:			
Other Approvals/Permits:			
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/3437-6EXRFJ-14.pdf		

42	70 of 80	-/0.0	79.8 / 0.00	**City of Toronto** **400 Commissioners St** **Toronto ON M3J 2B7**	WDS

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	6/7/2018	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	
Serial Link:		**Geometry Y:**	
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	400 Commissioners St		
Site Lot:			
Waste Class Code:			
Waste Class:			

Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/6741-AU7MBG-14.pdf

---

42 | ***71 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***City of Toronto***
400 Commissioners St
Toronto ON M3J 2B7 | ***WDS***

Approval No: A210615
Mob Unit Cert No:
EBR Registry No:
Status: Approved
Facility Type:
Record Type: ECA
Link Source: IDS
Project Type: WASTE DISPOSAL SITES
Application Status:
Issue Date: 2017-06-27
Input Date:
Date Received:
Est Closure Date:
Mobile Capacity:
Mobile Units:
Mobile Description:
Prop City:
Prop Postal:
Prop Phone:
Serial Link:
Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 400 Commissioners St
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/8491-AMTGCH-13.pdf

Total Area (ha):
Landfill Cap (m³):
Transfer Area (ha):
Transfer Cap (m³):
Transfer Cert No:
Inciner. Area (ha):
Inciner. Cap (t):
Process Area (m³):
Process Cap (m³/d):
Process Vol (m³):
Process Feed (m³):
Site Concession:
Site Region/County:
SWP Area Name: Toronto
MOE District: Metro Toronto
District Office:
Latitude: 43.651188
Longitude: -79.33892
Geometry X: -79.33892
Geometry Y: 43.651188

---

42 | ***72 of 80*** | ***-/0.0*** | ***79.8 / 0.00*** | ***City of Toronto***
400 Commissioners Street
Toronto ON M5V 3C6 | ***WDS***

Approval No: A210343
Mob Unit Cert No:

Total Area (ha): 5.3
Landfill Cap (m³):

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2001-01-29	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:	Toronto	**Latitude:**	43.651188
Prop Postal:	M5V 3C6	**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type:	ECA-WASTE DISPOSAL SITES
Proponent:	Corporation of the City of Toronto
Prop Address:	55 John St., 19th Floor
Proponent County/District:	Municipality Of Metropolitan Toronto
Full Address:	400 Commissioners Street
Site Lot:	
Waste Class Code:	
Waste Class:	
Waste Type:	
Waste Type Other:	
Waste Description:	
Landfill Monitoring:	
Landfill Ctrl Type:	
Site Closing Description:	
Project Description:	This application is for amending the definition of blue box materials to include those materials listed in Schedule 1 of Regulation 101 and add a condition requiring the City of Toronto to notify the Director in writing prior to adding new materials to the blue box program. This proposal also includes installation and operation of a sorting station, conveyors and baler to process polycoat containers.
Municipalities Served:	City of Toronto
Approval Description:	
Other Approvals/Permits:	
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/7274-4S8VK4-14.pdf

---

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	73 of 80	-/0.0	79.8 / 0.00	**City of Toronto** **400 Commissioners Street** **Toronto ON M5V 3C6**	WDS

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Revoked and/or Replaced	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2006-01-13	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Serial Link:		**Geometry Y:**	
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	400 Commissioners Street		
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:			
Waste Type Other:			
Waste Description:			
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:			
Project Description:			
Municipalities Served:			
Approval Description:			
Other Approvals/Permits:			
PDF URL:			

42	74 of 80	-/0.0	79.8 / 0.00	**City of Toronto** **400 Commissioners St** **Toronto ON M3J 2B7**	WDS

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Amended	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2012-05-25	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	400 Commissioners St		
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:			
Waste Type Other:			
Waste Description:			
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:			
Project Description:			
Municipalities Served:			
Approval Description:			
Other Approvals/Permits:			
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/0188-8N9PS2-14.pdf		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	75 of 80	-/0.0	79.8 / 0.00	City of Toronto 400 Commissioners Street Toronto ON M5V 3C6	WDS

Approval No:	A210343	**Total Area (ha):**	5.3
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2001-10-12	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:	Toronto	**Latitude:**	43.651188
Prop Postal:	M5V 3C6	**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type:	ECA-WASTE DISPOSAL SITES
Proponent:	Corporation of the City of Toronto
Prop Address:	55 John St., 19th Floor
Proponent County/District:	Municipality Of Metropolitan Toronto
Full Address:	400 Commissioners Street
Site Lot:	
Waste Class Code:	
Waste Class:	
Waste Type:	
Waste Type Other:	
Waste Description:	
Landfill Monitoring:	
Landfill Ctrl Type:	
Site Closing Description:	
Project Description:	This application is to add the City of Toronto and the neighbouring Regions of Durham, Peel and York as the approved service area.
Municipalities Served:	Toronto
Approval Description:	
Other Approvals/Permits:	
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/9710-4Y3PZ2-14.pdf

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	76 of 80	-/0.0	79.8 / 0.00	City of Toronto 400 Commissioners Street Toronto ON M5V 3C6	WDS

Approval No:	A280203	**Total Area (ha):**	5.3
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Approved	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2001-03-26	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:	Toronto	**Latitude:**	43.651188
Prop Postal:	M5V 2C6	**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type: ECA-WASTE DISPOSAL SITES
Proponent: Corporation of the City of Toronto
Prop Address: 55 John Street, Station 1180, 19th Floor
Proponent County/District: Municipality Of Metropolitan Toronto
Full Address: 400 Commissioners Street
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description: Amend existing Certificate to include the establishment of a computer recycling depot and the acceptance of used computers and computer parts for recycle and reuse. It is estimated approximately 12,000 tonnes of computer waste will be generated by Toronto residents in 2005, of which 7,000 tonnes will be suitable for reuse or recycling.
Municipalities Served: City of Toronto
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/5262-4UKTL4-14.pdf

---

42	77 of 80	-/0.0	79.8 / 0.00	**City of Toronto** **400 Commissioners St** **Toronto ON M5H 2N2**	WDS

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Revoked and/or Replaced	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2012-02-02	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188

Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 400 Commissioners St
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/0373-8NQRKP-14.pdf

---

42 | 78 of 80 | -/0.0 | 79.8 / 0.00 | **City of Toronto**, **400 Commissioners St**, **Toronto ON M3J 2B7** | WDS

Approval No: A210343
Mob Unit Cert No:
EBR Registry No:
Status: Approved
Facility Type:
Record Type: ECA
Link Source: IDS
Project Type: WASTE DISPOSAL SITES
Application Status:
Issue Date: 2018-04-04
Input Date:
Date Received:
Est Closure Date:
Mobile Capacity:
Mobile Units:
Mobile Description:
Prop City:
Prop Postal:
Prop Phone:
Serial Link:
Approval Type: ECA-WASTE DISPOSAL SITES
Proponent:
Prop Address:
Proponent County/District:
Full Address: 400 Commissioners St
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL: https://www.accessenvironment.ene.gov.on.ca/instruments/5915-AV9SZ6-14.pdf

Total Area (ha):
Landfill Cap (m³):
Transfer Area (ha):
Transfer Cap (m³):
Transfer Cert No:
Inciner. Area (ha):
Inciner. Cap (t):
Process Area (m³):
Process Cap (m³/d):
Process Vol (m³):
Process Feed (m³):
Site Concession:
Site Region/County:
SWP Area Name: Toronto
MOE District: Metro Toronto
District Office:
Latitude: 43.651188
Longitude: -79.33892
Geometry X: -79.33892
Geometry Y: 43.651188

---

42 | 79 of 80 | -/0.0 | 79.8 / 0.00 | **City of Toronto**, **400 Commissioners St**, **Toronto ON M3J 2B7** | WDS

Approval No: A210615
Mob Unit Cert No:
EBR Registry No:
Status: Approved

Total Area (ha):
Landfill Cap (m³):
Transfer Area (ha):
Transfer Cap (m³):

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2017-09-29	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			
Full Address:	400 Commissioners St		
Site Lot:			
Waste Class Code:			
Waste Class:			
Waste Type:			
Waste Type Other:			
Waste Description:			
Landfill Monitoring:			
Landfill Ctrl Type:			
Site Closing Description:			
Project Description:			
Municipalities Served:			
Approval Description:			
Other Approvals/Permits:			
PDF URL:	https://www.accessenvironment.ene.gov.on.ca/instruments/9710-ARJP64-14.pdf		

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
42	80 of 80	-/0.0	79.8 / 0.00	**City of Toronto** **400 Commissioners Street** **Toronto ON M5V 3C6**	WDS

Approval No:	A210615	**Total Area (ha):**	
Mob Unit Cert No:		**Landfill Cap (m³):**	
EBR Registry No:		**Transfer Area (ha):**	
Status:	Revoked and/or Replaced	**Transfer Cap (m³):**	
Facility Type:		**Transfer Cert No:**	
Record Type:	ECA	**Inciner. Area (ha):**	
Link Source:	IDS	**Inciner. Cap (t):**	
Project Type:	WASTE DISPOSAL SITES	**Process Area (m³):**	
Application Status:		**Process Cap (m³/d):**	
Issue Date:	2006-01-13	**Process Vol (m³):**	
Input Date:		**Process Feed (m³):**	
Date Received:		**Site Concession:**	
Est Closure Date:		**Site Region/County:**	
Mobile Capacity:		**SWP Area Name:**	Toronto
Mobile Units:		**MOE District:**	Metro Toronto
Mobile Description:		**District Office:**	
Prop City:		**Latitude:**	43.651188
Prop Postal:		**Longitude:**	-79.33892
Prop Phone:		**Geometry X:**	-79.33892
Serial Link:		**Geometry Y:**	43.651188
Approval Type:	ECA-WASTE DISPOSAL SITES		
Proponent:			
Prop Address:			
Proponent County/District:			

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Full Address: 400 Commissioners Street
Site Lot:
Waste Class Code:
Waste Class:
Waste Type:
Waste Type Other:
Waste Description:
Landfill Monitoring:
Landfill Ctrl Type:
Site Closing Description:
Project Description:
Municipalities Served:
Approval Description:
Other Approvals/Permits:
PDF URL:

43	1 of 4	-/0.0	79.8 / 0.00	CITY OF TORONTO 400 COMMISSIONERS Street TORONTO ON M4M3K2	NPRI

NPRI ID: 8800001065
Other ID:
No Other ID:
Track ID:
Report ID:
Report Type:
Rpt Type ID:
Report Year: 2004
Not-Current Rpt?:
Yr of Last Filed Rpt:
Fac ID:
Fac Name: COMMISSIONERS STREET TRANSFER STATION
Fac Address1:
Fac Address2:
Fac Postal Zip:
Facility Lat:
Facility Long:
DLS (Last Filed Rpt):
Facility DLS:
Datum:
Facility Cmnts:
URL:
No of Empl.: 52
Parent Co.:
No Parent Co.:
Pollut Prev Cmnts:
Stacks:
No of Stacks:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and Support, Waste Management and Remediation Services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste Collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste Collection

Org ID:
Submit Date:
Last Modified:
Contact ID:
Cont Type: MED
Contact Title: Mr.
Cont First Name: DEREK
Cont Last Name: ANGOVE
Contact Position: Manager, Transfer Operations
Contact Fax:
Contact Ph.:
Cont Area Code: 416
Contact Tel.: 3922447
Contact Ext.:
Cont Fax Area Cde: 416
Contact Fax: 3971348
Contact Email: dangove@toronto.ca
Latitude:
Longitude:
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams:
No Streams:
Waste Off Sites:
No Off Sites:
Shutdown:
No of Shutdown:

Substance Release Report

CAS No: 124-38-9

Report ID:
Rpt Period: 2004
Subst Released: Carbon dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M09
Report ID:
Rpt Period: 2004
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air: .022
Water:
Land:
Total Releases: .022
Units: tonnes

CAS No: 630-08-0
Report ID:
Rpt Period: 2004
Subst Released: Carbon monoxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 7446-09-5
Report ID:
Rpt Period: 2004
Subst Released: Sulphur dioxide
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M16
Report ID:
Rpt Period: 2004
Subst Released: Volatile Organic Compounds (VOCs)
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 74-82-8
Report ID:
Rpt Period: 2004
Subst Released: Methane
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: 811-97-2
Report ID:
Rpt Period: 2004
Subst Released: HFC-134a Hydrofluorocarbon
Air:
Water:
Land:

Total Releases:	
Units:	tonnes
CAS No:	10024-97-2
Report ID:	
Rpt Period:	2004
Subst Released:	Nitrous oxide
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	11104-93-1
Report ID:	
Rpt Period:	2004
Subst Released:	Nitrogen oxides (expressed as NO2)
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M08
Report ID:	
Rpt Period:	2004
Subst Released:	PM - Total Particulate Matter
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M10
Report ID:	
Rpt Period:	2004
Subst Released:	PM2.5 - Particulate Matter <= 2.5 Microns
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes

43	2 of 4	-/0.0	79.8 / 0.00	**CITY OF TORONTO** **400 COMMISSIONERS Street** **TORONTO ON M4M3K2**	NPRI

NPRI ID:	8800000225	**Org ID:**	
Other ID:		**Submit Date:**	
No Other ID:		**Last Modified:**	
Track ID:		**Contact ID:**	
Report ID:		**Cont Type:**	MED
Report Type:		**Contact Title:**	Mr.
Rpt Type ID:		**Cont First Name:**	DEREK
Report Year:	2006	**Cont Last Name:**	ANGOVE
Not-Current Rpt?:		**Contact Position:**	Manager, Transfer Operations
Yr of Last Filed Rpt:		**Contact Fax:**	
Fac ID:		**Contact Ph.:**	
Fac Name:	COMMISSIONERS STREET TRANSFER STATION	**Cont Area Code:**	416
Fac Address1:		**Contact Tel.:**	3922447
Fac Address2:		**Contact Ext.:**	
Fac Postal Zip:		**Cont Fax Area Cde:**	416
Facility Lat:		**Contact Fax:**	3971348
Facility Long:		**Contact Email:**	dangove@toronto.ca

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

DLS (Last Filed Rpt):		**Latitude:**	
Facility DLS:		**Longitude:**	
Datum:		**UTM Zone:**	
Facility Cmnts:		**UTM Northing:**	
URL:		**UTM Easting:**	
No of Empl.:	52	**Waste Streams:**	
Parent Co.:		**No Streams:**	
No Parent Co.:		**Waste Off Sites:**	
Pollut Prev Cmnts:		**No Off Sites:**	
Stacks:		**Shutdown:**	
No of Stacks:		**No of Shutdown:**	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and Support, Waste Management and Remediation Services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste Collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste Collection

Substance Release Report

CAS No: NA - M08
Report ID:
Rpt Period: 2006
Subst Released: PM - Total Particulate Matter
Air:
Water:
Land:
Total Releases:
Units: tonnes

CAS No: NA - M09
Report ID:
Rpt Period: 2006
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air:
Water:
Land:
Total Releases: 0
Units: tonnes

CAS No: NA - M10
Report ID:
Rpt Period: 2006
Subst Released: PM2.5 - Particulate Matter <= 2.5 Microns
Air:
Water:
Land:
Total Releases:
Units: tonnes

43	3 of 4	-/0.0	79.8 / 0.00	***CITY OF TORONTO*** ***400 COMMISSIONER STREET NOT AVAILABLE*** ***TORONTO ON M4M3K2***	NPRI

NPRI ID:	11552	**Org ID:**	101368
Other ID:		**Submit Date:**	6/3/2015
No Other ID:		**Last Modified:**	6/10/2015 10:59:04 AM
Track ID:	131209	**Contact ID:**	231641
Report ID:	57593	**Cont Type:**	MEM
Report Type:	NPRI	**Contact Title:**	

Rpt Type ID:	1	***Cont First Name:***	
Report Year:	2014	***Cont Last Name:***	
Not-Current Rpt?:	No	***Contact Position:***	
Yr of Last Filed Rpt:	2014	***Contact Fax:***	
Fac ID:	225812	***Contact Ph.:***	
Fac Name:	COMMISSIONERS STREET TRANSFER STATION	***Cont Area Code:***	
Fac Address1:	400 COMMISSIONER STREET	***Contact Tel.:***	
Fac Address2:	NOT AVAILABLE	***Contact Ext.:***	
Fac Postal Zip:	M4M3K2	***Cont Fax Area Cde:***	
Facility Lat:	43.6518	***Contact Fax:***	
Facility Long:	-79.3391	***Contact Email:***	
DLS (Last Filed Rpt):		***Latitude:***	43.6518
Facility DLS:		***Longitude:***	-79.3391
Datum:	1983	***UTM Zone:***	
Facility Cmnts:		***UTM Northing:***	
URL:		***UTM Easting:***	
No of Empl.:	18	***Waste Streams:***	
Parent Co.:		***No Streams:***	
No Parent Co.:		***Waste Off Sites:***	
Pollut Prev Cmnts:		***No Off Sites:***	
Stacks:		***Shutdown:***	
No of Stacks:		***No of Shutdown:***	

Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and support, waste management and remediation services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste collection

Substance Release Report

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM10 - Particulate Matter <= 10 Microns
Chem (fr): PM10 - Matière particulaire <= 10 microns
Quantity: .4
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:
Chem: PM2.5 - Particulate Matter <= 2.5 Microns
Chem (fr): PM2,5 - Matière particulaire <= 2,5 microns
Quantity: .1
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

Category Type ID: 6
Category Type Desc: Road dust
Category Type Desc (fr): Poussières de routes
Grouping: Total Air
Trans Code:

Chem: PM - Total Particulate Matter
Chem (fr): PM - Particules totales
Quantity: 1.9
Unit: tonnes
Basis of Estimate Cd: E2
Basis of Estimate Desc: E2- Published Emission Factors - In use from 2003 and onward

---

43 | **4 of 4** | **-/0.0** | **79.8 / 0.00** | **CITY OF TORONTO**
400 COMMISSIONERS Street
TORONTO ON M4M3K2 | **NPRI**

NPRI ID: 8800000050
Other ID:
No Other ID:
Track ID:
Report ID:
Report Type:
Rpt Type ID:
Report Year: 2005
Not-Current Rpt?:
Yr of Last Filed Rpt:
Fac ID:
Fac Name: COMMISSIONERS STREET TRANSFER STATION
Fac Address1:
Fac Address2:
Fac Postal Zip:
Facility Lat:
Facility Long:
DLS (Last Filed Rpt):
Facility DLS:
Datum:
Facility Cmnts:
URL:
No of Empl.: 52
Parent Co.:
No Parent Co.:
Pollut Prev Cmnts:
Stacks:
No of Stacks:
Org ID:
Submit Date:
Last Modified:
Contact ID:
Cont Type: MED
Contact Title: Mr.
Cont First Name: DEREK
Cont Last Name: ANGOVE
Contact Position: Manager, Transfer Operations
Contact Fax:
Contact Ph.:
Cont Area Code: 416
Contact Tel.: 3922447
Contact Ext.:
Cont Fax Area Cde: 416
Contact Fax: 3971348
Contact Email: dangove@toronto.ca
Latitude:
Longitude:
UTM Zone:
UTM Northing:
UTM Easting:
Waste Streams:
No Streams:
Waste Off Sites:
No Off Sites:
Shutdown:
No of Shutdown:
Canadian SIC Code (2 digit):
Canadian SIC Code:
SIC Code Description:
American SIC Code:
NAICS Code (2 digit): 56
NAICS 2 Description: Administrative and Support, Waste Management and Remediation Services
NAICS Code (4 digit): 5621
NAICS 4 Description: Waste Collection
NAICS Code (6 digit): 562110
NAICS 6 Description: Waste Collection

Substance Release Report

CAS No: NA - M09
Report ID:
Rpt Period: 2005
Subst Released: PM10 - Particulate Matter <= 10 Microns
Air:
Water:
Land:
Total Releases: 0
Units: tonnes

CAS No: NA - M10

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Report ID:	
Rpt Period:	2005
Subst Released:	PM2.5 - Particulate Matter <= 2.5 Microns
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes
CAS No:	NA - M08
Report ID:	
Rpt Period:	2005
Subst Released:	PM - Total Particulate Matter
Air:	
Water:	
Land:	
Total Releases:	
Units:	tonnes

44	1 of 1	-/0.0	79.8 / 0.00	**Commissioners St Incinerator 1985** **Toronto ON M4M**	ANDR

Legal Description:	York
Location Description:	
Municipality:	Toronto City
Current Municipality:	Toronto City
RM:	Toronto City
Facility:	Incinerator
Date Active:	1955-88
Date Begun:	1955.05.00
Date Complete:	Aug 1988
Area (Ha):	
Landfill Type:	
Group Name:	
Operated By:	Toronto DSC, Metro Works
Serial:	TOR115
NTS:	30M11
Diameter (m):	

Historical Summary:

Commissioners St Incinerator 1985 In 1948 the Board of Control and the city Council authorized the installation of a new incinerator east of Cherry St. and S of Keating. It was justified because existing incinerators were at capacity. In 1949 the Department of Street Cleaning began detailed planning for this facility at 400 Commissioners St., This facility in 1954 had a capacity of 900 tons a day with mechanically stoked cylindrical furnace technology. It had cost $2,116,000 to build. Between 1964 and 1966 some kind of fly-ash collection system was installed. In 1966 it had a capacity of 140,000 tons annually and received some industrial waste. The incinerator opened in May 1955, and was shut in the summer of 1988. In the early 1970s there was a proposal to add a second incinerator here. A "proposed" incinerator was shown here in a 1970 Metro Works publication, when the plant had a rated capacity of 900 tons per day. In 1972 the plant consisted of six mechanically stoked Nicholl's Monohearth furnaces each having its own forced under fire air, gravity overfire air and combustion chamber, the furnaces were connected in pairs each pair being exhausted through a chimney, hence three chimneys in the original plant. The original plant had no emission control equipment, and in 1961 it was found to be in violation of air quality regulations, and two of its furnaces were modified to meet the new standards. The new controls managed to make these furnaces meet the codes, but improvements in the codes made the controls ineffective once more. As a result the emission control equipment was not installed on the other furnaces. In 1969 consultants were hired to modernize and enlarge the incinerator, with air pollution control equipment incorporated. The project was proceeding with OMB approval in 1972. On May 16, 1972 Metro awarded Francis Hankin Co. Ltd., a contract to install three new furnaces, air cleaning etc., for a price of $5,755,000. the overall modernization costs in 1972 were projected at more than $10 million. Without it air pollution control equipment on two of its stacks the facility was provoking violations of air pollution codes in 1970 (odors, fly ash and poor air quality). After the new furnaces were installed in 1974-5, the facility had a capacity of about 150,000 tonnes a year on a reciprocating grate system. A transfer station opened here in 1980. The incinerator ceased operations in August 1988. In January 1956 Francis Hankin stated that one of the their incineration systems was installed at Moncton (Municipal Utilities Magazine January 1956 p. 57). In January 1957 Francis Hankin again stated that one of their incineration systems was installed at Toronto. They also provided two photographs, one interior, showing their furnaces, and one exterior shot of the Commissioners St plant (Municipal Utilities Magazine January 1957 p. 45). A Hamilton area scrap dealer plans to recover metals from the Commissioners St incinerator residue ([Toronto] Globe & Mail January 7 1966). In response to Metro's exit from the waste disposal business in 1965, the region's incinerators were forced to operate 24 hours a day and to open-burn some refuse. There is a 4-week backlog at Commissioners St. so the City of Toronto has banned private waste at the incinerator [Toronto] Globe & Mail July 14 1966).

Waste Type:	MSW
UTM X Nad 27:	633930
UTM Y Nad 27:	4834320
UTM Zone:	17

---

45 | **1 of 1** | **-/0.0** | **79.8 / 0.00** | **Commissioners St Incinerator 1969** | **ANDR**

Toronto ON M4M

Legal Description:	York
Location Description:	
Municipality:	Toronto City
Current Municipality:	Toronto City
RM:	Toronto City
Facility:	Incinerator
Date Active:	1969
Date Begun:	
Date Complete:	
Area (Ha):	
Landfill Type:	
Group Name:	
Operated By:	
Serial:	TOR566 1969
NTS:	30M11
Diameter (m):	

Historical Summary:

Commissioners St Incinerator 1969 CITY-OWNED INCINERATORS POLLUTE AIR: The Commissioner's St Incinerator produces 9 truck loads of fly ash daily. There are 40 complaints a day about city garbage incinerators, and more than 2000 on file for the metro area ([Toronto] Globe & Mail Jan 25 1962). 1975 NTS 1:25,000 Map 30M11F Incinerator with 3 x 175' chimneys marked [1975 NTS 1:25,000 Map East Toronto ON Sheet 30M11F edition 3 (air photos 1969, culture check 1970, publication 1975)]. Commissioners St Incinerator 450-FOOT STACK IS LIKELY UNDER INCINERATOR PLAN: Metro Works plans to renovate and expand the Commissioners St incinerator, in a $7M scheme. The facility would get a new 450 foot smokestack, pollution control equipment, modified waste storage pits and semi-automatic grates. With the modifications it could burn 900-1000 tons daily ([Toronto] Globe & Mail Jan 28 1970). Grand Ave & Wellington St incinerators are undergoing conversion to transfer stations. Don incinerator has closed and Commissioners St is at reduced capacity while pollution controls are upgraded ([Toronto] Globe & Mail Mar 3 1973). Metro has been told to shut down some of its aging incinerators, or fix their air pollution problems. The AMB has given Metro until June 30 to address the problem. Wellington St, Grand Ave are the two incinerators most criticised (Toronto Star Jan 12 1972). The AMB has forced the closure of two Metro Incinerators by June 30 and orders the subsequent closure of 2 more and emissions controls for the rest. Metro is seeking an extension ([Toronto] Globe & Mail Jan 26 1972). Metro Toronto is engaged in a $40M refit of its incinerators. Wellington and Grand Ave will be converted to transfer stations. Commissioners St, Forest Hill and Symes are being refitted (MOE deadline Dec 31 1974) and refits at Ingram and Dufferin are to be complete by Dec 31 1975 (MOE deadline) (Toronto Sun Jul 5 1972).

Waste Type:	
UTM X Nad 27:	633900
UTM Y Nad 27:	4834375
UTM Zone:	17

---

46 | **1 of 1** | **-/0.0** | **79.8 / 0.00** | **ON** | **BORE**

Borehole ID:	644956	**Inclin FLG:**	No
OGF ID:	215545339	**SP Status:**	Initial Entry
Status:		**Surv Elev:**	No
Type:	Borehole	**Piezometer:**	No
Use:	Geotechnical/Geological Investigation	**Primary Name:**	
Completion Date:	JAN-1950	**Municipality:**	
Static Water Level:		**Lot:**	
Primary Water Use:	Not Used	**Township:**	
Sec. Water Use:		**Latitude DD:**	43.652182
Total Depth m:	13.6	**Longitude DD:**	-79.339135
Depth Ref:	Ground Surface	**UTM Zone:**	17

Depth Elev:		**Easting:**	633935
Drill Method:	Diamond Drill	**Northing:**	4834583
Orig Ground Elev m:	77.3	**Location Accuracy:**	
Elev Reliabil Note:		**Accuracy:**	Not Applicable
DEM Ground Elev m:	77.6		
Concession:			
Location D:			
Survey D:			
Comments:			

Borehole Geology Stratum

Geology Stratum ID:	218509531	**Mat Consistency:**	
Top Depth:	0	**Material Moisture:**	
Bottom Depth:	2.5	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Fill	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	fill
Gsc Material Description:			
Stratum Description:	FILL.		

Geology Stratum ID:	218509532	**Mat Consistency:**	
Top Depth:	2.5	**Material Moisture:**	
Bottom Depth:	6.9	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Clay	**Geologic Formation:**	
Material 2:	Muck	**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	muck
Gsc Material Description:			
Stratum Description:	CLAY,MUCK.		

Geology Stratum ID:	218509534	**Mat Consistency:**	
Top Depth:	13.4	**Material Moisture:**	
Bottom Depth:	13.6	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Shale	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	Ordovician
Material 4:		**Depositional Gen:**	marine
Gsc Material Description:			
Stratum Description:	SHALE. MARINE,AGE ORDOVICIAN. T 25 **Note: Many records provided by the department have a truncated [Stratum Description] field.		

Geology Stratum ID:	218509533	**Mat Consistency:**	
Top Depth:	6.9	**Material Moisture:**	
Bottom Depth:	13.4	**Material Texture:**	
Material Color:		**Non Geo Mat Type:**	
Material 1:	Sand	**Geologic Formation:**	
Material 2:		**Geologic Group:**	
Material 3:		**Geologic Period:**	
Material 4:		**Depositional Gen:**	beach
Gsc Material Description:			
Stratum Description:	SAND. BEACH,AGE POST-GLACIAL.		

Source

Source Type:	Data Survey	**Source Appl:**	Spatial/Tabular
Source Orig:	Geological Survey of Canada	**Source Iden:**	1
Source Date:	1956-1972	**Scale or Res:**	Varies
Confidence:	M	**Horizontal:**	NAD27
Observatio:		**Verticalda:**	Mean Average Sea Level

Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 129780 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

---

47 | **1 of 4** | **-/0.0** | **75.8 / -4.00** | **GEN**

ESSO PETROLUEM CANADA
185 VILLIERS STREET C/O 55 ST. CLAIR AVE. WEST
TORONTO ON M5W 2J8

Generator No: ON0000798
Status:
Approval Years: 90
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

47 | **2 of 4** | **-/0.0** | **75.8 / -4.00** | **GEN**

Toronto Port Lands Company
185 Villiers Street
Toronto ON M5A 1A1

Generator No: ON8707474
Status:
Approval Years: 2014
Contam. Facility: No
MHSW Facility: No
SIC Code: 541990
SIC Description: ALL OTHER PROFESSIONAL, SCIENTIFIC AND TECHNICAL SERVICES
PO Box No:
Country: Canada
Choice of Contact: CO_ADMIN
Co Admin: Courtney Gilbert
Phone No Admin: 4168662357 Ext.

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

47 | **3 of 4** | **-/0.0** | **75.8 / -4.00** | **GEN**

ESSO PETROLUEM CANADA 14-857
185 VILLIERS STREET C/O 55 ST. CLAIR AVE. WEST
TORONTO ON M5W 2J8

Generator No: ON0000798
Status:
Approval Years: 92,93,94,95,96,97
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.
PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

47 | ***4 of 4*** | ***-/0.0*** | ***75.8 / -4.00*** | ***ESSO PETROLUEM CANADA***
185 VILLIERS STREET
TORONTO ON | ***GEN***

Generator No: ON0000798
Status:
Approval Years: 98
Contam. Facility:
MHSW Facility:
SIC Code: 5111
SIC Description: PETROLEUM PROD., WH.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

---

48 | ***1 of 1*** | ***W/0.1*** | ***76.9 / -2.93*** | ***Hydro One Networks Inc.***
Cable Joint Bay #2 N. Side of Villiers St., 52m W. of Saulter St.
Toronto ON M4M 3J4 | ***GEN***

Generator No: ON6407060
Status:
Approval Years: 05,06
Contam. Facility:
MHSW Facility:
SIC Code: 221122
SIC Description: Electric Power Distribution

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146
Waste Class Desc: OTHER SPECIFIED INORGANICS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

---

49 | ***1 of 1*** | ***ENE/1.9*** | ***79.8 / 0.00*** | ***ON*** | ***BORE***

Borehole ID: 644959
OGF ID: 215545342
Status:
Type: Borehole
Use: Geotechnical/Geological Investigation
Completion Date: JAN-1950
Static Water Level:
Primary Water Use: Not Used
Sec. Water Use:
Total Depth m: 13.6
Depth Ref: Ground Surface
Depth Elev:
Drill Method: Diamond Drill
Orig Ground Elev m: 77.1
Elev Reliabil Note:

Inclin FLG: No
SP Status: Initial Entry
Surv Elev: No
Piezometer: No
Primary Name:
Municipality:
Lot:
Township:
Latitude DD: 43.651818
Longitude DD: -79.338897
UTM Zone: 17
Easting: 633955
Northing: 4834543
Location Accuracy:
Accuracy: Not Applicable

DEM Ground Elev m: 78.2
Concession:
Location D:
Survey D:
Comments:

Borehole Geology Stratum

Geology Stratum ID: 218509543
Top Depth: 2.6
Bottom Depth: 7.6
Material Color:
Material 1: Sand
Material 2: Clay
Material 3: Muck
Material 4:
Gsc Material Description:
Stratum Description: SAND,CLAY,MUCK.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: muck

Geology Stratum ID: 218509544
Top Depth: 7.6
Bottom Depth: 13.6
Material Color:
Material 1: Sand
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: SAND. BEACH,AGE POST-GLACIAL. I **Note: Many records provided by the department have a truncated [Stratum Description] field.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: beach

Geology Stratum ID: 218509542
Top Depth: 0
Bottom Depth: 2.6
Material Color:
Material 1: Fill
Material 2:
Material 3:
Material 4:
Gsc Material Description:
Stratum Description: FILL.
Mat Consistency:
Material Moisture:
Material Texture:
Non Geo Mat Type:
Geologic Formation:
Geologic Group:
Geologic Period:
Depositional Gen: fill

Source

Source Type: Data Survey
Source Orig: Geological Survey of Canada
Source Date: 1956-1972
Confidence: M
Observatio:
Source Name: Urban Geology Automated Information System (UGAIS)
Source Details: File: TOR2.txt RecordID: 129810 NTS_Sheet: 30M11C
Confiden 1: Reliable information but incomplete.
Source Appl: Spatial/Tabular
Source Iden: 1
Scale or Res: Varies
Horizontal: NAD27
Verticalda: Mean Average Sea Level

Source List

Source Identifier: 1
Source Type: Data Survey
Source Date: 1956-1972
Scale or Resolution: Varies
Source Name: Urban Geology Automated Information System (UGAIS)
Source Originators: Geological Survey of Canada
Horizontal Datum: NAD27
Vertical Datum: Mean Average Sea Level
Projection Name: Universal Transverse Mercator

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	1 of 5	N/2.7	77.9 / -1.90	Barrett Roofing Co 701 Lake Shore Blvd E Toronto ON	TANK

Permit Date: 3/20/1936
Permit Type: BP A58758
User Type: Manufacturers of roofing and paving materials
Installation Type: gasoline tanks
Installation Size:
Installation Config.: gasoline tanks
No. Tanks Installed: 2
Units of Measure:
Value/Tank ($): 250
Capacity(gal):
Reference: CTA Building Permits
Location Desc: Keating SE cor Villiers St

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	2 of 5	N/2.7	77.9 / -1.90	Barrett Co Ltd 701 Lake Shore Blvd E Toronto ON	TANK

Permit Date: 1/21/1921
Permit Type: BP 47076
User Type: Manufacturers of roofing and paving materials
Installation Type: Gasoline tanks
Installation Size:
Installation Config.: 2 x gasoline tanks
No. Tanks Installed: 2
Units of Measure:
Value/Tank ($): 50
Capacity(gal):
Reference: CTA Building permits
Location Desc: Keating St

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	3 of 5	N/2.7	77.9 / -1.90	Barrett Co Ltd 701 Lake Shore Blvd E Toronto ON	TANK

Permit Date: 12/2/1936
Permit Type: BP A62371
User Type: Manufacturers of roofing and paving materials
Installation Type: FO tank
Installation Size:
Installation Config.: FO tank
No. Tanks Installed: 1
Units of Measure:
Value/Tank ($): 50
Capacity(gal):
Reference: CTA Building Permits
Location Desc: SE cor Keating & Saulter

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	4 of 5	N/2.7	77.9 / -1.90	Barrett Co Ltd 701 Lake Shore Blvd E Toronto ON	TANK

Permit Date: 2/4/1921
Permit Type: BP 47205
User Type: Manufacturers of roofing and paving materials
Installation Type: Oil Tank
Installation Size:
Installation Config.: 1 x fuel oil tank

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB

No. Tanks Installed:	1
Units of Measure:	
Value/Tank ($):	20000
Capacity(gal):	
Reference:	CTA Building permits
Location Desc:	Keating St

Map Key	Number of Records	Direction/ Distance (m)	Elev/Diff (m)	Site	DB
50	5 of 5	N/2.7	77.9 / -1.90	**Barrett Co Ltd** **701 Lake Shore Blvd E** **Toronto ON**	TANK

Permit Date:	1920
Permit Type:	To install
User Type:	Manufacturers of roofing and paving materials
Installation Type:	Underground tar feed pipe 8" in 14" box, 6' below grade (later amended to 4' below grade)
Installation Size:	8
Installation Config.:	Underground tar feed pipe 8" in 14" box, 6' below grade (later amended to 4' below grade)
No. Tanks Installed:	
Units of Measure:	inches diameter
Value/Tank ($):	
Capacity(gal):	
Reference:	TCM 1920 A: 516
Location Desc:	Carries tar from Consumer's gas across Keating St to the Barrett factory

Unplottable Summary

Total: 52 Unplottable sites

DB	Company Name/Site Name	Address	City	Postal
CA	TORONTO HARBOUR COMMISSIONERS	OUTER MARINA HARBOUR PH. I	TORONTO CITY ON	
CA	CONSTELLATION COURT INC.	COMMISSIONERS ST.	TORONTO CITY ON	
CA	THE TORONTO HARBOUR COMMISSIONERS PH. 1	OUTER HARBOUR MARINA SITE SERV	TORONTO CITY ON	
CA	TORONTO CITY	HOWLAND RD./SAULTER ST./RYDING	TORONTO CITY ON	
CA	TORONTO CITY DR. # L-282	LAKE SHORE BLVD.	TORONTO CITY ON	
CA	TORONTO HARBOUR COMMISSIONERS	OUTER HARBOUR MARINA PH.I	TORONTO CITY ON	
CA	THE TORONTO HARBOUR COMMISSIONERS PH.1	OUTER HARBOUR MARINA SITE SERV	TORONTO CITY ON	
CA	METRO TORONTO WORKS DEPT. WATER SUPPLY	PRIVATE PROP.COMMISSIONER'S ST	TORONTO CITY ON	
CA	MUNICIPALITY OF METRO TORONTO	LAKESHORE BLVD. INTERCEP. SEW.	TORONTO CITY ON	
CA		Lake Shore Drive	Toronto ON	
CA	TORONTO CITY	LAKESHORE BLVD.E.,HUMBER BRID.	TORONTO CITY ON	
EBR	York Environmental Solutions Ltd.	9799 Commissioners Street Toronto M5A 1A6 CITY OF TORONTO	ON	
EBR	Harkow Recycling Ltd.	Commissioners Street, Toronto Waterfront	ON	
EHS		Southside of Lakeshore Blvd.	Toronto ON	
GEN	Sun-Canadian Pipe Line Company Ltd	Stoffel Drive	Toronto ON	M9W1A8
GEN	TORONTO HARBOUR COMMISSIONERS	GARAGE MAINTENANCE FIRE HALL HANLANS POINT, TORONTO ISLAND	TORONTO ON	
GEN	TORONTO HARBOUR COMMISSIONERS	GARAGE MAINT.FIRE HALL,N.TIP OF HANLANS PT.& WESTERN CHANNEL,	TORONTO ON	M5V 1A1

		TOR.ISLAND ARPRT		
GEN	TORONTO HARBOUR COMMISSIONERS 37-674	GARAGE MAINT.FIRE HALL,N.TIP OF HANLANS PT.& WESTERN CHANNEL, TOR.ISLAND ARPRT	TORONTO ON	M5V 1A1
GEN	MINISTRY OF GOVERNMENT SERVICES	OLD PSYCHIATRIC HOSPITAL(LK.SHOREBLVD.) C/O 171 JUDSON STREET	TORONTO ON	M8Z 1A4
GEN	MINISTRY OF GOVERNMENT SERVICES 27-205	OLD PSYCHIATRIC HOSPITAL(LK.SHOREBLVD.) C/O 171 JUDSON STREET	TORONTO ON	M8Z 1A4
GEN	City of Toronto	Between Bathurst & Spadina on the Lakeshore	Toronto ON	M5H 2N2
GEN	City of Toronto Works and Emergency Servies	Sunnyside Footbridge, over FG Gardiner Ex Lakeshore Blvd & CNR (Between Jamieson & Ellis)	Toronto ON	
GEN	METROPOLITAN TORONTO TRANSPORTA-	TION DEPT, LAKESHORE BLV/REES & JOHN ST C/O 401 BAY ST. 30 FL. SIMPSON TOWER	TORONTO ON	M5H 2Y4
GEN	METROPOLITAN TORONTO TRANSPORTA- 25-736	TION DEPT, LAKESHORE BLV/REES & JOHN ST C/O 401 BAY ST. 30 FL. SIMPSON TOWER	TORONTO ON	M5H 2Y4
GEN	Gio Crete Construction	Lakeshore Blvd E at Carlaw Ave. to Leslie St.	Toronto ON	M4M 1B4
GEN	HYDRO ONE NETWORKS INC	MH5A 100M E OF LESLIE ON LAKESHORE BLVD E	TORONTO ON	
GEN	Metrolinx	Lakeshore East Rail Corridor (Danforth GO Stn) Kitchener Subdivision Mile 329.23 to Mile 327.16	Toronto ON	M4E 2H2
GEN	Metrolinx	Lakeshore East Rail Corridor (Danforth GO Stn) Kitchener Subdivision Mile 329.23 to Mile 327.16	Toronto ON	M4E 2H2
GEN	IMPERIAL OIL LTD.	PART LOT 4, CONC. 7 - TWP. OF TORONTO C/O P.O. BOX 380	WATERDOWN ON	L0R 2H0
GEN	IMPERIAL OIL LTD. 21-164	PART LOT 4, CONC. 7 - TWP. OF TORONTO C/O P.O. BOX 380	WATERDOWN ON	L0R 2H0
PTTW	Toronto Waterfront Revitalization Corporation	Lakeshore Boulevard East from Bonnycastle Street to Cherry Street City of Toronto, Ontario CITY OF TORONTO	ON	
RST	ESSO HOME HEAT		TORONTO ON	
SPL	ESSO CHEMICAL	TANK TRUCK (CARGO)	TORONTO CITY ON	
SPL	TRANSPORT TRUCK	LAKESHORE BLVD., FROM JARVIS TO STRACHAN AVE. AT EXHIBITION PLACE MOTOR VEHICLE (OPERATING FLUID)	TORONTO CITY ON	
SPL	TRANSPORT TRUCK	LAKESHORE BLVD MOTOR VEHICLE (OPERATING FLUID)	TORONTO CITY ON	
SPL	SUNOCO	IN TRIPLE GARAGE, SOME TO PAVEMENT OUTSIDE. SERVICE STATION	TORONTO CITY ON	

SPL	IMPERIAL OIL	ESSO SERVICE STATION	TORONTO CITY ON
SPL	ESSO CHEMICAL	TANK TRUCK (CARGO)	TORONTO CITY ON
SPL	IMPERIAL OIL	ESSO SERVICE STATION	TORONTO CITY ON
SPL	ESSO PETROLEUM CANADA	SERVICE STATION	TORONTO CITY ON
SPL	ONTARIO HYDRO	LAKESHORE BLVD EAST (SOUTH SIDE) WEST OF COXWELL AVE. HIGH VOLTAGE CABLE	TORONTO CITY ON
SPL	ESSO PETROLEUM CANADA	ISLAND JR/SR PUBLIC SCHOOL, HANLON'S POINT TANK TRUCK (CARGO)	TORONTO CITY ON
SPL	ESSO PETROLEUM CANADA	TANK TRUCK (CARGO)	TORONTO CITY ON
SPL	ESSO PETROLEUM CANADA	TANK TRUCK (CARGO)	TORONTO CITY ON
SPL	UNKNOWN	HWY. #2 & ROUGE RIVER	TORONTO CITY ON
SPL	ESSO PETROLEUM CANADA	SERVICE STATION	TORONTO CITY ON
SPL	Global Waste Services Inc.	Lakeshore Blvd., west of Strachan Ave infront of the Automotive Building	Toronto ON
SPL	ESSO PETROLEUM	TANK TRUCK (CARGO)	TORONTO CITY ON
SPL		At Lakeshore Blvd.	Toronto ON
SPL	UNKNOWN	HUMBER RIVER, NOTICED AT LAKESHORE BLVD	TORONTO CITY ON
SPL	ESSO PETROLEUM	SERVICE STATION	TORONTO CITY ON
SRDS	IMPERIAL OIL LIMITED		TORONTO ON

Unplottable Report

Site: ***TORONTO HARBOUR COMMISSIONERS***
OUTER MARINA HARBOUR PH. I TORONTO CITY ON

Database: ***CA***

Certificate #: 3-1071-89-
Application Year: 89
Issue Date: 6/9/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***CONSTELLATION COURT INC.***
COMMISSIONERS ST. TORONTO CITY ON

Database: ***CA***

Certificate #: 8-3211-88-
Application Year: 88
Issue Date: 2/28/1991
Approval Type: Industrial air
Status: Cancelled
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description: PASSIVE VENTING FOR BENZENE CONTAM.SOIL
Contaminants: Benzene (Carcinogen Requires Bact)
Emission Control: No Controls

Site: ***THE TORONTO HARBOUR COMMISSIONERS PH. 1***
OUTER HARBOUR MARINA SITE SERV TORONTO CITY ON

Database: ***CA***

Certificate #: 3-1328-89-
Application Year: 89
Issue Date: 7/21/1989
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TORONTO CITY***
HOWLAND RD./SAULTER ST./RYDING TORONTO CITY ON

Database: ***CA***

Certificate #: 3-0955-97-

Application Year: 97
Issue Date: 7/29/1997
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TORONTO CITY DR. # L-282***
LAKE SHORE BLVD. TORONTO CITY ON

Database: ***CA***

Certificate #: 3-0464-87-
Application Year: 87
Issue Date: 5/22/1987
Approval Type: Municipal sewage
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***TORONTO HARBOUR COMMISSIONERS***
OUTER HARBOUR MARINA PH.I TORONTO CITY ON

Database: ***CA***

Certificate #: 7-0899-89-
Application Year: 89
Issue Date: 6/9/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***THE TORONTO HARBOUR COMMISSIONERS PH.1***
OUTER HARBOUR MARINA SITE SERV TORONTO CITY ON

Database: ***CA***

Certificate #: 7-1113-89-
Application Year: 89
Issue Date: 7/21/1989
Approval Type: Municipal water
Status: Approved
Application Type:
Client Name:
Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***METRO TORONTO WORKS DEPT. WATER SUPPLY***
PRIVATE PROP.COMMISSIONER'S ST TORONTO CITY ON

Database: ***CA***

Certificate #:	7-1454-86-
Application Year:	86
Issue Date:	1/2/1987
Approval Type:	Municipal water
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site: ***MUNICIPALITY OF METRO TORONTO***
LAKESHORE BLVD. INTERCEP. SEW. TORONTO CITY ON

Database: ***CA***

Certificate #:	3-0713-94-
Application Year:	94
Issue Date:	7/7/1994
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	
Client Address:	
Client City:	
Client Postal Code:	
Project Description:	
Contaminants:	
Emission Control:	

Site:
Lake Shore Drive Toronto ON

Database: ***CA***

Certificate #:	5750-4WYSA3
Application Year:	01
Issue Date:	5/31/01
Approval Type:	Municipal & Private sewage
Status:	Approved
Application Type:	New Certificate of Approval
Client Name:	Corporation of the City of Toronto
Client Address:	399 The West Mall
Client City:	Toronto
Client Postal Code:	M9C 2Y2
Project Description:	Installation of 300, 375 and 450 mm diameter storm sewer on Lake Shore Drive from 5th Street to 9th Street. Installation fo 375mm diameter sanitary sewer on Lake Shore Drive from 5th Street to 9th Street.
Contaminants:	
Emission Control:	

Site: ***TORONTO CITY***
LAKESHORE BLVD.E.,HUMBER BRID. TORONTO CITY ON

Database: ***CA***

Certificate #:	3-0106-99-
Application Year:	99
Issue Date:	2/25/1999
Approval Type:	Municipal sewage
Status:	Approved
Application Type:	
Client Name:	

Client Address:
Client City:
Client Postal Code:
Project Description:
Contaminants:
Emission Control:

Site: ***York Environmental Solutions Ltd.***
9799 Commissioners Street Toronto M5A 1A6 CITY OF TORONTO ON

Database: ***EBR***

EBR Registry No:	013-4678	***Decision Posted:***	
Ministry Ref No:	0226-B8EJ3P	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:		***Act 1:***	
Notice Date:	April 05, 2019	***Act 2:***	
Proposal Date:	February 06, 2019	***Site Location Map:***	
Year:	2019		

Instrument Type: Environmental Compliance Approval (project type: waste) - EPA Part II.1-waste
Off Instrument Name:
Posted By:
Company Name:
Site Address:
Location Other:
Proponent Name: York Environmental Solutions Ltd.
Proponent Address: 125 Villarboit Crescent
Vaughan Ontario
Canada L4K 4K2
Comment Period:
URL: http://www.ebr.gov.on.ca/ERS-WEB-External/displaynoticecontent.do?noticeId=MTM3MjQx&statusId=MjA5ODU3&language=en

Site Location Details:

9799 Commissioners Street
Toronto M5A 1A6
CITY OF TORONTO

Site: ***Harkow Recycling Ltd.***
Commissioners Street, Toronto Waterfront ON

Database: ***EBR***

EBR Registry No:	IA6E0716	***Decision Posted:***	
Ministry Ref No:	A210248	***Exception Posted:***	
Notice Type:	Instrument Decision	***Section:***	
Notice Stage:	800473068	***Act 1:***	
Notice Date:	July 10, 1996	***Act 2:***	
Proposal Date:	May 08, 1996	***Site Location Map:***	
Year:	1996		

Instrument Type: (EPA s. 27) - Approval for a waste disposal site.
Off Instrument Name:
Posted By:
Company Name: Harkow Recycling Ltd.
Site Address:
Location Other:
Proponent Name:
Proponent Address: 75 Commissioners St., Toronto Ontario, M5A 1A6
Comment Period:
URL:

Site Location Details:

Commissioners Street, Toronto Waterfront

Site: ***Database:*** ***EHS***

Southside of Lakeshore Blvd. Toronto ON

Order No:	20050919010	***Nearest Intersection:***	
Status:	C	***Municipality:***	
Report Type:	Complete Report	***Client Prov/State:***	ON
Report Date:	9/22/2005	***Search Radius (km):***	0.25
Date Received:	9/19/2005	***X:***	
Previous Site Name:		***Y:***	
Lot/Building Size:			
Additional Info Ordered:			

Site: ***Sun-Canadian Pipe Line Company Ltd*** ***Database:*** ***GEN***

Stoffel Drive Toronto ON M9W1A8

Generator No:	ON5456724	***PO Box No:***	
Status:		***Country:***	Canada
Approval Years:	2016	***Choice of Contact:***	CO_ADMIN
Contam. Facility:	No	***Co Admin:***	Susan Jackson
MHSW Facility:	No	***Phone No Admin:***	9056905610 Ext.
SIC Code:	486910		
SIC Description:	486910		

Detail(s)

Waste Class:	221
Waste Class Desc:	LIGHT FUELS

Site: ***TORONTO HARBOUR COMMISSIONERS*** ***Database:*** ***GEN***

GARAGE MAINTENANCE FIRE HALL HANLANS POINT, TORONTO ISLAND TORONTO ON

Generator No:	ON0173003	***PO Box No:***	
Status:		***Country:***	
Approval Years:	98,99	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	4521		
SIC Description:	AIRPORT OPER. IND.		

Detail(s)

Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES
Waste Class:	252
Waste Class Desc:	WASTE OILS & LUBRICANTS

Site: ***TORONTO HARBOUR COMMISSIONERS*** ***Database:*** ***GEN***

GARAGE MAINT.FIRE HALL,N.TIP OF HANLANS PT.& WESTERN CHANNEL, TOR.ISLAND ARPRT TORONTO ON M5V 1A1

Generator No:	ON0173003	***PO Box No:***	
Status:		***Country:***	
Approval Years:	90	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	4521		
SIC Description:	AIRPORT OPER. IND.		

Detail(s)

Waste Class:	213
Waste Class Desc:	PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Site: ***TORONTO HARBOUR COMMISSIONERS 37-674***
GARAGE MAINT.FIRE HALL,N.TIP OF HANLANS PT.& WESTERN CHANNEL, TOR.ISLAND ARPRT TORONTO ON M5V 1A1

Database: ***GEN***

Generator No: ON0173003
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 4521
SIC Description: AIRPORT OPER. IND.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 213
Waste Class Desc: PETROLEUM DISTILLATES

Waste Class: 252
Waste Class Desc: WASTE OILS & LUBRICANTS

Site: ***MINISTRY OF GOVERNMENT SERVICES***
OLD PSYCHIATRIC HOSPITAL(LK.SHOREBLVD.) C/O 171 JUDSON STREET TORONTO ON M8Z 1A4

Database: ***GEN***

Generator No: ON0123906
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 8262
SIC Description: SOCIAL SERV. ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***MINISTRY OF GOVERNMENT SERVICES 27-205***
OLD PSYCHIATRIC HOSPITAL(LK.SHOREBLVD.) C/O 171 JUDSON STREET TORONTO ON M8Z 1A4

Database: ***GEN***

Generator No: ON0123906
Status:
Approval Years: 94,95,96
Contam. Facility:
MHSW Facility:
SIC Code: 8262
SIC Description: SOCIAL SERV. ADMIN.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Site: ***City of Toronto***
Between Bathurst & Spadina on the Lakeshore Toronto ON M5H 2N2

Database: ***GEN***

Generator No: ON3752368
Status:
Approval Years: 04
Contam. Facility:
MHSW Facility:
SIC Code: 541620

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

SIC Description: Environmental Consulting Services

Site: ***City of Toronto Works and Emergency Servies***
Sunnyside Footbridge, over FG Gardiner Ex Lakeshore Blvd & CNR (Between Jamieson & Ellis) Toronto ON

Database: ***GEN***

Generator No:	ON7196486	***PO Box No:***	
Status:		***Country:***	
Approval Years:	03,04	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:			
SIC Description:			

Site: ***METROPOLITAN TORONTO TRANSPORTA-***
TION DEPT, LAKESHORE BLV/REES & JOHN ST C/O 401 BAY ST. 30 FL. SIMPSON TOWER TORONTO ON M5H 2Y4

Database: ***GEN***

Generator No:	ON0654807	***PO Box No:***	
Status:		***Country:***	
Approval Years:	90	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	4121		
SIC Description:	HIGHWAYS, STR., ETC.		

Detail(s)

Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS

Site: ***METROPOLITAN TORONTO TRANSPORTA- 25-736***
TION DEPT, LAKESHORE BLV/REES & JOHN ST C/O 401 BAY ST. 30 FL. SIMPSON TOWER TORONTO ON M5H 2Y4

Database: ***GEN***

Generator No:	ON0654807	***PO Box No:***	
Status:		***Country:***	
Approval Years:	92,93,94,95,96,97,98	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	4121		
SIC Description:	HIGHWAYS, STR., ETC.		

Detail(s)

Waste Class:	146
Waste Class Desc:	OTHER SPECIFIED INORGANICS

Site: ***Gio Crete Construction***
Lakeshore Blvd E at Carlaw Ave. to Leslie St. Toronto ON M4M 1B4

Database: ***GEN***

Generator No:	ON5110524	***PO Box No:***	
Status:		***Country:***	
Approval Years:	2012	***Choice of Contact:***	
Contam. Facility:		***Co Admin:***	
MHSW Facility:		***Phone No Admin:***	
SIC Code:	237110		
SIC Description:	Water and Sewer Line and Related Structures Construction		

Site: ***HYDRO ONE NETWORKS INC***
MH5A 100M E OF LESLIE ON LAKESHORE BLVD E TORONTO ON

Database: ***GEN***

Generator No:	ON8338370	***PO Box No:***	
Status:		***Country:***	
Approval Years:	06	***Choice of Contact:***	

Contam. Facility: ***Co Admin:***
MHSW Facility: ***Phone No Admin:***
SIC Code: 221122
SIC Description: Electric Power Distribution

Detail(s)

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Site: ***Metrolinx***
Lakeshore East Rail Corridor (Danforth GO Stn) Kitchener Subdivision Mile 329.23 to Mile 327.16 Toronto ON M4E 2H2

Database: ***GEN***

Generator No: ON9652118
Status: Registered
Approval Years: As of Dec 2018
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 146 L
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Site: ***Metrolinx***
Lakeshore East Rail Corridor (Danforth GO Stn) Kitchener Subdivision Mile 329.23 to Mile 327.16 Toronto ON M4E 2H2

Database: ***GEN***

Generator No: ON9652118
Status: Registered
Approval Years: As of Jul 2019
Contam. Facility:
MHSW Facility:
SIC Code:
SIC Description:

PO Box No:
Country: Canada
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 252 L
Waste Class Desc: Waste crankcase oils and lubricants

Waste Class: 146 L
Waste Class Desc: Other specified inorganic sludges, slurries or solids

Waste Class: 251 L
Waste Class Desc: Waste oils/sludges (petroleum based)

Site: ***IMPERIAL OIL LTD.***
PART LOT 4, CONC. 7 - TWP. OF TORONTO C/O P.O. BOX 380 WATERDOWN ON L0R 2H0

Database: ***GEN***

Generator No: ON0000735
Status:
Approval Years: 86,87,88,89,90
Contam. Facility:
MHSW Facility:
SIC Code: 4619
SIC Description: OTHER PIPELINE TRANS.

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Site: ***IMPERIAL OIL LTD. 21-164***
PART LOT 4, CONC. 7 - TWP. OF TORONTO C/O P.O. BOX 380 WATERDOWN ON L0R 2H0

Database: ***GEN***

Generator No: ON0000735
Status:
Approval Years: 94
Contam. Facility:
MHSW Facility:
SIC Code: 4619
SIC Description: OTHER PIPELINE TRANS

PO Box No:
Country:
Choice of Contact:
Co Admin:
Phone No Admin:

Detail(s)

Waste Class: 221
Waste Class Desc: LIGHT FUELS

Waste Class: 251
Waste Class Desc: OIL SKIMMINGS & SLUDGES

Site: ***Toronto Waterfront Revitalization Corporation***
Lakeshore Boulevard East from Bonnycastle Street to Cherry Street City of Toronto, Ontario CITY OF TORONTO ON

Database: ***PTTW***

EBR Registry No: 011-9435
Ministry Ref No: 3835-98MJ98
Notice Type: Instrument Decision
Notice Stage:
Notice Date: September 18, 2013
Proposal Date: June 24, 2013
Year: 2013
Instrument Type: (OWRA s. 34) - Permit to Take Water
Off Instrument Name:
Posted By:
Company Name: Toronto Waterfront Revitalization Corporation
Site Address:
Location Other:
Proponent Name:
Proponent Address: 100 Queen Street West, City Hall, 12th Floor, East Tower, Toronto Ontario, Canada M5H 2N2
Comment Period:
URL:

Decision Posted:
Exception Posted:
Section:
Act 1:
Act 2:
Site Location Map:

Site Location Details:

Lakeshore Boulevard East from Bonnycastle Street to Cherry Street City of Toronto, Ontario CITY OF TORONTO

Site: ***ESSO HOME HEAT***
TORONTO ON

Database: ***RST***

Headcode: 00924800
Headcode Desc: FUEL OIL
Phone: 4164816141
List Name:
Description:

Site: ***ESSO CHEMICAL***
TANK TRUCK (CARGO) TORONTO CITY ON

Database: ***SPL***

Ref No:	24174	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	8/24/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	8/24/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	MATERIAL FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO CHEMICAL - 75 L SOLVESSO-100 TO GROUND (AROMATIC SOLVENT).		
Contaminant Qty:			

Site: ***TRANSPORT TRUCK***
LAKESHORE BLVD., FROM JARVIS TO STRACHAN AVE. AT EXHIBITION PLACE MOTOR VEHICLE (OPERATING FLUID) TORONTO CITY ON

Database: ***SPL***

Ref No:	107170	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	11/8/1994	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	COOLING SYSTEM LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	1106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	FIRE DEPT.
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	11/8/1994	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	TRANSPORT TRUCK - 180L HYDRAULIC FLUID TO MIDDLEOF ROAD WHILE TOWED		
Contaminant Qty:			

Site: ***TRANSPORT TRUCK***
LAKESHORE BLVD MOTOR VEHICLE (OPERATING FLUID) TORONTO CITY ON

Database: ***SPL***

Ref No:	52736	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	6/21/1991	***Health/Env Conseq:***	
Year:		***Client Type:***	

Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	METRO WORKS,ETOBICOKE FD AND WORKS
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	6/21/1991	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	METRO PUC-TRUCK DUMPED SLUDGE/WATER MIX TO ROAD, CLEAN-UP COMPLETED.		
Contaminant Qty:			

Site: ***SUNOCO***
IN TRIPLE GARAGE, SOME TO PAVEMENT OUTSIDE. SERVICE STATION TORONTO CITY ON

Database: ***SPL***

Ref No:	35740	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	6/3/1990	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	6/3/1990	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	MATERIAL FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SUNOCO-13500 L WATER AND OIL TO GARAGE AND SOME TO OUTSIDE PAVEMENT		
Contaminant Qty:			

Site: ***IMPERIAL OIL***
ESSO SERVICE STATION TORONTO CITY ON

Database: ***SPL***

Ref No:	110205	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/18/1995	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	

Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	1106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/20/1995	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	MATERIAL FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	IMPERIAL OIL: 8-12 L GAS CONTAINED UNDER PUMP CAVITY		
Contaminant Qty:			

Site: ***ESSO CHEMICAL***
TANK TRUCK (CARGO) TORONTO CITY ON

Database: ***SPL***

Ref No:	21541	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	7/5/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	7/5/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	OVERSTRESS/OVERPRESSURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO CHEMICAL - LID OF TANKER TRUCK BLOWN OFF 40L TOLUENE TO GROUND		
Contaminant Qty:			

Site: ***IMPERIAL OIL***
ESSO SERVICE STATION TORONTO CITY ON

Database: ***SPL***

Ref No:	14737	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/9/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	CONTAINER OVERFLOW	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/13/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	

Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO SERVICE STATION		
Contaminant Qty:			

Site: ***ESSO PETROLEUM CANADA***
SERVICE STATION TORONTO CITY ON

Database: ***SPL***

Ref No:	122134	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	12/30/1995	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	VALVE/FITTING LEAK OR FAILURE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	1106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	12/30/1995	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO:20L GASOLINE LEAKED TO GROUND FROM LEAKING PUMP.CLEANED UP.		
Contaminant Qty:			

Site: ***ONTARIO HYDRO***
LAKESHORE BLVD EAST (SOUTH SIDE) WEST OF COXWELL AVE. HIGH VOLTAGE CABLE TORONTO CITY ON

Database: ***SPL***

Ref No:	58949	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	10/22/1991	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	01106
Nature of Impact:	Soil Contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	10/23/1991	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	GASKET/JOINT	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ONTARIO HYDRO: 340L CABLEINSULATING OIL TO GROUND FROM HIGH VOLTAGE CABLE.		
Contaminant Qty:			

Site: ***ESSO PETROLEUM CANADA***
ISLAND JR/SR PUBLIC SCHOOL, HANLON'S POINT TANK TRUCK (CARGO) TORONTO CITY ON

Database: ***SPL***

Ref No:	110274	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	2/22/1995	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	1106
Nature of Impact:	Soil contamination	***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	FD, MCCR
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	2/22/1995	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: ESSO TANK TRUCK: 200 L FURNACE OIL TO SOIL : OVERFILL: MCCR
Contaminant Qty:

Site: ***ESSO PETROLEUM CANADA***
TANK TRUCK (CARGO) TORONTO CITY ON

Database: ***SPL***

Ref No:	59567	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	11/8/1991	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	11/9/1991	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			

Incident Summary: ESSO PETROLEUM: 4L GASOLINE BACKFLOW WHEN DUMP VALVE MALFUNCTIONED
Contaminant Qty:

Site: ***ESSO PETROLEUM CANADA***
TANK TRUCK (CARGO) TORONTO CITY ON

Database: ***SPL***

Ref No:	48558	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	4/4/1991	***Health/Env Conseq:***	
Year:		***Client Type:***	

Incident Cause:	CONTAINER OVERFLOW	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	4/4/1991	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	ERROR	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO-10 LITRES FURNACE OIL TO GRND,TRUCK OVER FILLED,CLEANED-UP		
Contaminant Qty:			

Site: ***UNKNOWN***
HWY. #2 & ROUGE RIVER TORONTO CITY ON

Database: ***SPL***

Ref No:	19118	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	5/25/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	WASTEWATER DISCHARGE TO WATERCOURSE	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	WORKS DEPT, POLUTION CONTROL & MOE
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	5/25/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	SPILL INITIATED COMPLAINTPETROLEUM PRODUCT TO ROUGE RIVER VIA SEWER.		
Contaminant Qty:			

Site: ***ESSO PETROLEUM CANADA***
SERVICE STATION TORONTO CITY ON

Database: ***SPL***

Ref No:	44046	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	11/17/1990	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	OTHER CONTAINER LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	

Environment Impact:	NOT ANTICIPATED	***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	FIRE DEPT
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	11/17/1990	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO SERVICE STATION-20 LOF GASOLINE TO PAVEMENT.		
Contaminant Qty:			

Site: ***Global Waste Services Inc.***
Lakeshore Blvd., west of Strachan Ave infront of the Automotive Building Toronto ON

Database: ***SPL***

Ref No:	8320-6FZMWK	***Discharger Report:***	0
Site No:		***Material Group:***	Oil
Incident Dt:	9/7/2005	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Other Transport Accident	***Sector Type:***	Transport Truck
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:	DIESEL FUEL	***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	Toronto
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	Possible	***Site Municipality:***	Toronto
Nature of Impact:		***Site Lot:***	
Receiving Medium:	Land	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	9/7/2005	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	Spills to Highways (usually highway accidents)
Incident Reason:	Unknown - Reason not determined	***Source Type:***	
Site Name:	Roadside<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Lakeshore Blvd: 20 L spill of DSL to road		
Contaminant Qty:			

Site: ***ESSO PETROLEUM***
TANK TRUCK (CARGO) TORONTO CITY ON

Database: ***SPL***

Ref No:	28792	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	12/12/1989	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	PIPE/HOSE LEAK	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	01106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	MCCR
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	12/12/1989	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	

Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO PETROLEUM - 50 L OF VARSOL TO CEMENT WHILE OFF-LOADING TANK TRUCK.		
Contaminant Qty:			

Site: ***Database:*** ***SPL***

At Lakeshore Blvd. Toronto ON

Ref No:	3166-976KQD	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	27-APR-13	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	Unknown / N/A	***Sector Type:***	Unknown / N/A
Incident Event:		***Agency Involved:***	
Contaminant Code:	13	***Nearest Watercourse:***	
Contaminant Name:	HYDROCARBON LIGHT	***Site Address:***	At Lakeshore Blvd.
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	Confirmed	***Site Municipality:***	Toronto
Nature of Impact:	Surface Water Pollution	***Site Lot:***	
Receiving Medium:		***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:	No Field Response	***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	27-APR-13	***Site Map Datum:***	
Dt Document Closed:	07-MAY-13	***SAC Action Class:***	Pollution Incident Reports (PIRs) and "Other" calls
Incident Reason:	Unknown / N/A	***Source Type:***	
Site Name:	Mimico Creek<UNOFFICIAL>		
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	Mimico Creek: Rainbow Sheen		
Contaminant Qty:	0 other - see incident description		

Site: ***UNKNOWN*** ***Database:*** ***SPL***

HUMBER RIVER, NOTICED AT LAKESHORE BLVD TORONTO CITY ON

Ref No:	166809	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	//	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	UNKNOWN	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:	CONFIRMED	***Site Municipality:***	1106
Nature of Impact:	Water course or lake	***Site Lot:***	
Receiving Medium:	WATER	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	WORKS
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	4/20/1999	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	UNKNOWN	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	UNKNOWN SOURCE:PETROLEUM SHEEN NOTICED ON HUMBER RIVER.		
Contaminant Qty:			

Site: ***ESSO PETROLEUM***
SERVICE STATION TORONTO CITY ON

Database: ***SPL***

Ref No:	4934	***Discharger Report:***	
Site No:		***Material Group:***	
Incident Dt:	1/16/1988	***Health/Env Conseq:***	
Year:		***Client Type:***	
Incident Cause:	CONTAINER OVERFLOW	***Sector Type:***	
Incident Event:		***Agency Involved:***	
Contaminant Code:		***Nearest Watercourse:***	
Contaminant Name:		***Site Address:***	
Contaminant Limit 1:		***Site District Office:***	
Contam Limit Freq 1:		***Site Postal Code:***	
Contaminant UN No 1:		***Site Region:***	
Environment Impact:		***Site Municipality:***	1106
Nature of Impact:		***Site Lot:***	
Receiving Medium:	LAND	***Site Conc:***	
Receiving Env:		***Northing:***	
MOE Response:		***Easting:***	
Dt MOE Arvl on Scn:		***Site Geo Ref Accu:***	
MOE Reported Dt:	1/16/1988	***Site Map Datum:***	
Dt Document Closed:		***SAC Action Class:***	
Incident Reason:	EQUIPMENT FAILURE	***Source Type:***	
Site Name:			
Site County/District:			
Site Geo Ref Meth:			
Incident Summary:	ESSO SERVICE STATION - 18 L GASOLINE TO GROUND		
Contaminant Qty:			

Site: ***IMPERIAL OIL LIMITED***
TORONTO ON

Database: ***SRDS***

Company Code:		***Sector:***	
Works ID:		***Region:***	
SIC:		***District:***	
SIC1:		***UTM Zone:***	
SIC1 Desc:		***UTM Easting:***	
SIC2:		***UTM Northing:***	
SIC2 Desc:		***UTM Precision:***	
SIC3:		***Minor Basin:***	
SIC3 Desc:		***Major Basin:***	
Body of Water:		***Report Year:***	1990-1994
Terminal Stream:			
SIC Desc:			
Mailing Address:			
Corp Address:			

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ***Note:*** *Databases denoted with " * " indicates that the database will no longer be updated. See the individual database description for more information.*

Abandoned Aggregate Inventory: Provincial AAGR

The MAAP Program maintains a database of abandoned pits and quarries. Please note that the database is only referenced by lot and concession and city/town location. The database provides information regarding the location, type, size, land use, status and general comments.*

Government Publication Date: Sept 2002*

Aggregate Inventory: Provincial AGR

The Ontario Ministry of Natural Resources maintains a database of all active pits and quarries. The database provides information regarding the registered owner/operator, location name, operation type, approval type, and maximum annual tonnage.

Government Publication Date: Up to Sep 2018

Abandoned Mine Information System: Provincial AMIS

The Abandoned Mines Information System contains data on known abandoned and inactive mines located on both Crown and privately held lands. The information was provided by the Ministry of Northern Development and Mines (MNDM), with the following disclaimer: "the database provided has been compiled from various sources, and the Ministry of Northern Development and Mines makes no representation and takes no responsibility that such information is accurate, current or complete". Reported information includes official mine name, status, background information, mine start/end date, primary commodity, mine features, hazards and remediation.

Government Publication Date: 1800-Oct 2018

Anderson's Waste Disposal Sites: Private ANDR

The information provided in this database was collected by examining various historical documents which aimed to characterize the likely position of former waste disposal sites from 1860 to present. The research initiative behind the creation of this database was to identify those sites that are missing from the Ontario MOE Waste Disposal Site Inventory, as well as to provide revisions and corrections to the positions and descriptions of sites currently listed in the MOE inventory. In addition to historic waste disposal facilities, the database also identifies certain auto wreckers and scrap yards that have been extrapolated from documentary sources. Please note that the data is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1860s-Present

Aboveground Storage Tanks: Provincial AST

Historical listing of aboveground storage tanks made available by the Department of Natural Resources and Forestry. Includes tanks used to hold water or petroleum. This dataset has been retired as of September 25, 2014 and will no longer be updated.

Government Publication Date: May 31, 2014

Automobile Wrecking & Supplies: Private AUWR

This database provides an inventory of known locations that are involved in the scrap metal, automobile wrecking/recycling, and automobile parts & supplies industry. Information is provided on the company name, location and business type.

Government Publication Date: 1999-Jul 31, 2019

Borehole: Provincial BORE

A borehole is the generalized term for any narrow shaft drilled in the ground, either vertically or horizontally. The information here includes geotechnical investigations or environmental site assessments, mineral exploration, or as a pilot hole for installing piers or underground utilities. Information is from many sources such as the Ministry of Transportation (MTO) boreholes from engineering reports and projects from the 1950 to 1990's in Southern Ontario. Boreholes from the Ontario Geological Survey (OGS) including The Urban Geology Analysis Information System (UGAIS) and the York Peel Durham Toronto (YPDT) database of the Conservation Authority Moraine Coalition. This database will include fields such as location, stratigraphy, depth, elevation, year drilled, etc. For all water well data or oil and gas well data for Ontario please refer to WWIS and OOGW.

Government Publication Date: 1875-Jul 2018

Certificates of Approval: Provincial CA

This database contains the following types of approvals: Air & Noise, Industrial Sewage, Municipal & Private Sewage, Waste Management Systems and Renewable Energy Approvals. The MOE in Ontario states that any facility that releases emissions to the atmosphere, discharges contaminants to ground or surface water, provides potable water supplies, or stores, transports or disposes of waste, must have a Certificate of Approval before it can operate lawfully. Fields include approval number, business name, address, approval date, approval type and status. This database will no longer be updated, as CofA's have been replaced by either Environmental Activity and Sector Registry (EASR) or Environmental Compliance Approval (ECA). Please refer to those individual databases for any information after Oct.31, 2011.

Government Publication Date: 1985-Oct 30, 2011*

Dry Cleaning Facilities: Federal CDRY

List of dry cleaning facilities made available by Environment and Climate Change Canada. Environment and Climate Change Canada's Tetrachloroethylene (Use in Dry Cleaning and Reporting Requirements) Regulations (SOR/2003-79) are intended to reduce releases of tetrachloroethylene to the environment from dry cleaning facilities.

Government Publication Date: Jan 2004-Dec 2017

Commercial Fuel Oil Tanks: Provincial CFOT

List of commercial underground fuel oil tanks made available by the Fuels Safety Program of the Technical Standards & Safety Authority (TSSA). Ontario Regulation 213/01 of the Technical Standards and Safety Act (2000) requires that all underground tanks be registered with the TSSA. Note: the Fuels Safety Division does not register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of commercial fuel tanks in the province. The TSSA updates information in its system on an ongoing basis; this listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Chemical Register: Private CHEM

This database includes information from both a one time study conducted in 1992 and private source and is a listing of facilities that manufacture or distribute chemicals. The production of these chemical substances may involve one or more chemical reactions and/or chemical separation processes (i.e. fractionation, solvent extraction, crystallization, etc.).

Government Publication Date: 1999-Jul 31, 2019

Compressed Natural Gas Stations: Private CNG

Canada has a network of public access compressed natural gas (CNG) refuelling stations. These stations dispense natural gas in compressed form at 3,000 pounds per square inch (psi), the pressure which is allowed within the current Canadian codes and standards. The majority of natural gas refuelling is located at existing retail gasoline that have a separate refuelling island for natural gas. This list of stations is made available by the Canadian Natural Gas Vehicle Alliance.

Government Publication Date: Dec 2012 - Jun 2019

Inventory of Coal Gasification Plants and Coal Tar Sites: Provincial COAL

This inventory includes both the "Inventory of Coal Gasification Plant Waste Sites in Ontario-April 1987" and the Inventory of Industrial Sites Producing or Using Coal Tar and Related Tars in Ontario-November 1988) collected by the MOE. It identifies industrial sites that produced and continue to produce or use coal tar and other related tars. Detailed information is available and includes: facility type, size, land use, information on adjoining properties, soil condition, site operators/occupants, site description, potential environmental impacts and historic maps available. This was a one-time inventory.*

Government Publication Date: Apr 1987 and Nov 1988*

Compliance and Convictions: Provincial CONV

This database summarizes the fines and convictions handed down by the Ontario courts beginning in 1989. Companies and individuals named here have been found guilty of environmental offenses in Ontario courts of law.

Government Publication Date: 1989-Jul 2019

Certificates of Property Use: Provincial CPU

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all CPU's on the registry such as (EPA s. 168.6) - Certificate of Property Use.

Government Publication Date: 1994-Sep 30, 2019

Drill Hole Database: Provincial DRL

The Ontario Drill Hole Database contains information on more than 113,000 percussion, overburden, sonic and diamond drill holes from assessment files on record with the department of Mines and Minerals. Please note that limited data is available for southern Ontario, as it was the last area to be completed. The database was created when surveys submitted to the Ministry were converted in the Assessment File Research Image Database (AFRI) project. However, the degree of accuracy (coordinates) as to the exact location of drill holes is dependent upon the source document submitted to the MNDM. Levels of accuracy used to locate holes are: centering on the mining claim; a sketch of the mining claim; a 1:50,000 map; a detailed company map; or from submitted a "Report of Work".

Government Publication Date: 1886 - Oct 2018

Environmental Activity and Sector Registry: Provincial EASR

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. The EASR allows businesses to register certain activities with the ministry, rather than apply for an approval. The registry is available for common systems and processes, to which preset rules of operation can be applied. The EASR is currently available for: heating systems, standby power systems and automotive refinishing. Businesses whose activities aren't subject to the EASR may apply for an ECA (Environmental Compliance Approval), Please see our ECA database.

Government Publication Date: Oct 2011-Sep 30, 2019

Environmental Registry: Provincial EBR

The Environmental Registry lists proposals, decisions and exceptions regarding policies, Acts, instruments, or regulations that could significantly affect the environment. Through the Registry, thirteen provincial ministries notify the public of upcoming proposals and invite their comments. For example, if a local business is requesting a permit, license, or certificate of approval to release substances into the air or water; these are notified on the registry. Data includes: Approval for discharge into the natural environment other than water (i.e. Air) - EPA s. 9, Approval for sewage works - OWRA s. 53(1), and EPA s. 27 - Approval for a waste disposal site. For information regarding Permit to Take Water (PTTW), Certificate of Property Use (CPU) and (ORD) Orders please refer to those individual databases.

Government Publication Date: 1994-Sep 30, 2019

Environmental Compliance Approval: Provincial ECA

On October 31, 2011, a smarter, faster environmental approvals system came into effect in Ontario. In the past, a business had to apply for multiple approvals (known as certificates of approval) for individual processes and pieces of equipment. Today, a business either registers itself, or applies for a single approval, depending on the types of activities it conducts. Businesses whose activities aren't subject to the EASR may apply for an ECA. A single ECA addresses all of a business's emissions, discharges and wastes. Separate approvals for air, noise and waste are no longer required. This database will also include Renewable Energy Approvals. For certificates of approval prior to Nov 1st, 2011, please refer to the CA database. For all Waste Disposal Sites please refer to the WDS database.

Government Publication Date: Oct 2011-Sep 30, 2019

Environmental Effects Monitoring: Federal EEM

The Environmental Effects Monitoring program assesses the effects of effluent from industrial or other sources on fish, fish habitat and human usage of fisheries resources. Since 1992, pulp and paper mills have been required to conduct EEM studies under the Pulp and Paper Effluent Regulations. This database provides information on the mill name, geographical location and sub-lethal toxicity data.

Government Publication Date: 1992-2007*

ERIS Historical Searches: Private EHS

ERIS has compiled a database of all environmental risk reports completed since March 1999. Available fields for this database include: site location, date of report, type of report, and search radius. As per all other databases, the ERIS database can be referenced on both the map and "Statistical Profile" page.

Government Publication Date: 1999-Jul 31, 2019

Environmental Issues Inventory System: Federal EIIS

The Environmental Issues Inventory System was developed through the implementation of the Environmental Issues and Remediation Plan. This plan was established to determine the location and severity of contaminated sites on inhabited First Nation reserves, and where necessary, to remediate those that posed a risk to health and safety; and to prevent future environmental problems. The EIIS provides information on the reserve under investigation, inventory number, name of site, environmental issue, site action (Remediation, Site Assessment), and date investigation completed.

Government Publication Date: 1992-2001*

Emergency Management Historical Event: Provincial EMHE

List of locations of historical occurrences of emergency events, including those assigned to the Ministry of Natural Resources by Order-In-Council (OIC) under the Emergency Management and Civil Protection Act, as well as events where MNR provided requested emergency response assistance. Many of these events will have involved community evacuations, significant structural loss, and/or involvement of MNR emergency response staff. These events fall into one of ten (10) type categories: Dam Failure; Drought / Low Water; Erosion; Flood; Forest Fire; Soil and Bedrock Instability; Petroleum Resource Center Event, EMO Requested Assistance, Continuity of Operations Event, Other Requested Assistance. EMHE record details are reproduced by ERIS under License with the Ontario Ministry of Natural Resources © Queen's Printer for Ontario, 2017.

Government Publication Date: Dec 31, 2016

Environmental Penalty Annual Report: Provincial EPAR

This database contains data from Ontario's annual environmental penalty report published by the Ministry of the Environment and Climate Change. These reports provide information on environmental penalties for land or water violations issued to companies in one of the nine industrial sectors covered by the Municipal Industrial Strategy for Abatement (MISA) regulations.

Government Publication Date: Jan 1, 2011 - Dec 31, 2018

List of TSSA Expired Facilities: Provincial EXP

List of facilities and tanks - for which there was once a registration - no longer registered with the Fuels Safety Program of the Technical Standards and Safety Authority (TSSA). Includes private fuel outlets, bulk plants, fuel oil tanks, gasoline stations, marinas, propane filling stations, liquid fuel tanks, piping systems, etc. Tanks which have been removed from the ground are included in the expired facilities inventory held by the TSSA. Notes: the Fuels Safety Division did not register private fuel underground/aboveground storage tanks prior to January of 1990, or furnace oil tanks prior to May 1, 2002; nor does the Division register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of expired tanks/tank facilities in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Federal Convictions: Federal FCON

Environment Canada maintains a database referred to as the "Environmental Registry" that details prosecutions under the Canadian Environmental Protection Act (CEPA) and the Fisheries Act (FA). Information is provided on the company name, location, charge date, offence and penalty.

Government Publication Date: 1988-Jun 2007*

Contaminated Sites on Federal Land: Federal FCS

The Federal Contaminated Sites Inventory includes information on known federal contaminated sites under the custodianship of departments, agencies and consolidated Crown corporations as well as those that are being or have been investigated to determine whether they have contamination arising from past use that could pose a risk to human health or the environment. The inventory also includes non-federal contaminated sites for which the Government of Canada has accepted some or all financial responsibility. It does not include sites where contamination has been caused by, and which are under the control of, enterprise Crown corporations, private individuals, firms or other levels of government.

Government Publication Date: Jun 2000-May 2019

Fisheries & Oceans Fuel Tanks: Federal FOFT

Fisheries & Oceans Canada maintains an inventory of aboveground & underground fuel storage tanks located on Fisheries & Oceans property or controlled by DFO. Our inventory provides information on the site name, location, tank owner, tank operator, facility type, storage tank location, tank contents & capacity, and date of tank installation.

Government Publication Date: 1964-Sep 2018

Fuel Storage Tank: Provincial FST

List of registered private and retail fuel storage tanks made available by the Fuels Safety Program of the Technical Standards & Safety Authority (TSSA). Ontario Regulation 213/01 of the Technical Standards and Safety Act (2000) requires that all underground tanks be registered with the TSSA. Notes: the Fuels Safety Division did not register private fuel underground/aboveground storage tanks prior to January of 1990, or furnace oil tanks prior to May 1, 2002; nor does the Division register waste oil tanks in apartments, office buildings, residences, etc., or aboveground gas or diesel tanks. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of fuel storage tanks/tank facilities in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Fuel Storage Tank - Historic: Provincial FSTH

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks. Public records of private fuel storage tanks are only available since the registration became effective in September 1989. This information is now collected by the Technical Standards and Safety Authority.

Government Publication Date: Pre-Jan 2010*

Ontario Regulation 347 Waste Generators Summary: Provincial GEN

Regulation 347 of the Ontario EPA defines a waste generation site as any site, equipment and/or operation involved in the production, collection, handling and/or storage of regulated wastes. A generator of regulated waste is required to register the waste generation site and each waste produced, collected, handled, or stored at the site. This database contains the registration number, company name and address of registered generators including the types of hazardous wastes generated. It includes data on waste generating facilities such as: drycleaners, waste treatment and disposal facilities, machine shops, electric power distribution etc. This information is a summary of all years from 1986 including the most currently available data. Some records may contain, within the company name, the phrase "See & Use..." followed by a series of letters and numbers. This occurs when one company is amalgamated with or taken over by another registered company. The number listed as "See & Use", refers to the new ownership and the other identification number refers to the original ownership. This phrase serves as a link between the 2 companies until operations have been fully transferred.

Government Publication Date: 1986-Jul 31, 2019

Greenhouse Gas Emissions from Large Facilities: Federal GHG

List of greenhouse gas emissions from large facilities made available by Environment Canada. Greenhouse gas emissions in kilotonnes of carbon dioxide equivalents (kt CO2 eq).

Government Publication Date: 2013-Dec 2017

TSSA Historic Incidents: Provincial HINC

List of historic incidences of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen recorded by the TSSA in their previous incident tracking system. The TSSA's Fuels Safety Program administers the Technical Standards & Safety Act 2000, providing fuel-related safety services associated with the safe transportation, storage, handling and use of fuels such as gasoline, diesel, propane, natural gas and hydrogen. Under this Act, the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of historical fuel spills and leaks in the province. This listing is a copy of the data captured at one moment in time and is hence limited by the record date provided here.

Government Publication Date: 2006-June 2009*

Indian & Northern Affairs Fuel Tanks: Federal IAFT

The Department of Indian & Northern Affairs Canada (INAC) maintains an inventory of aboveground & underground fuel storage tanks located on both federal and crown land. Our inventory provides information on the reserve name, location, facility type, site/facility name, tank type, material & ID number, tank contents & capacity, and date of tank installation.

Government Publication Date: 1950-Aug 2003*

TSSA Incidents: Provincial INC

List of spills and leaks of diesel, fuel oil, gasoline, natural gas, propane, and hydrogen reported to the Spills Action Centre (SAC) and made available by the Technical Standards and Safety Authority (TSSA). Under the Technical Standards & Safety Act (2000), the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors, and equipment or appliances that use fuels. Includes incidents from fuel-related hazards such as spills, fires, and explosions. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of fuel-related leaks, spills, and incidents in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Landfill Inventory Management Ontario: Provincial LIMO

The Landfill Inventory Management Ontario (LIMO) database is updated every year, as the ministry compiles new and updated information. The inventory will include small and large landfills. Additionally, each year the ministry will request operators of the larger landfills complete a landfill data collection form that will be used to update LIMO and will include the following information from the previous operating year. This will include additional information such as estimated amount of total waste received, landfill capacity, estimated total remaining landfill capacity, fill rates, engineering designs, reporting and monitoring details, size of location, service area, approved waste types, leachate of site treatment, contaminant attenuation zone and more. The small landfills will include information such as site owner, site location and certificate of approval # and status.

Government Publication Date: Feb 28, 2019

Canadian Mine Locations: Private MINE

This information is collected from the Canadian & American Mines Handbook. The Mines database is a national database that provides over 290 listings on mines (listed as public companies) dealing primarily with precious metals and hard rocks. Listed are mines that are currently in operation, closed, suspended, or are still being developed (advanced projects). Their locations are provided as geographic coordinates (x, y and/or longitude, latitude). As of 2002, data pertaining to Canadian smelters and refineries has been appended to this database.

Government Publication Date: 1998-2009*

Mineral Occurrences: Provincial MNR

In the early 70's, the Ministry of Northern Development and Mines created an inventory of approximately 19,000 mineral occurrences in Ontario, in regard to metallic and industrial minerals, as well as some information on building stones and aggregate deposits. Please note that the "Horizontal Positional Accuracy" is approximately +/- 200 m. Many reference elements for each record were derived from field sketches using pace or chain/tape measurements against claim posts or topographic features in the area. The primary limiting factor for the level of positional accuracy is the scale of the source material. The testing of horizontal accuracy of the source materials was accomplished by comparing the plan metric (X and Y) coordinates of that point with the coordinates of the same point as defined from a source of higher accuracy.

Government Publication Date: 1846-Jan 2019

National Analysis of Trends in Emergencies System (NATES): Federal NATE

In 1974 Environment Canada established the National Analysis of Trends in Emergencies System (NATES) database, for the voluntary reporting of significant spill incidents. The data was to be used to assist in directing the work of the emergencies program. NATES ran from 1974 to 1994. Extensive information is available within this database including company names, place where the spill occurred, date of spill, cause, reason and source of spill, damage incurred, and amount, concentration, and volume of materials released.

Government Publication Date: 1974-1994*

Non-Compliance Reports: Provincial NCPL

The Ministry of the Environment provides information about non-compliant discharges of contaminants to air and water that exceed legal allowable limits, from regulated industrial and municipal facilities. A reported non-compliance failure may be in regard to a Control Order, Certificate of Approval, Sectoral Regulation or specific regulation/act.

Government Publication Date: Dec 31, 2017

National Defense & Canadian Forces Fuel Tanks: Federal NDFT

The Department of National Defense and the Canadian Forces maintains an inventory of all aboveground & underground fuel storage tanks located on DND lands. Our inventory provides information on the base name, location, tank type & capacity, tank contents, tank class, date of tank installation, date tank last used, and status of tank as of May 2001. This database will no longer be updated due to the new National Security protocols which have prohibited any release of this database.

Government Publication Date: Up to May 2001*

National Defense & Canadian Forces Spills: Federal NDSP

The Department of National Defense and the Canadian Forces maintains an inventory of spills to land and water. All spill sites have been classified under the "Transportation of Dangerous Goods Act - 1992". Our inventory provides information on the facility name, location, spill ID #, spill date, type of spill, as well as the quantity of substance spilled & recovered.

Government Publication Date: Mar 1999-Apr 2018

National Defence & Canadian Forces Waste Disposal Sites: Federal NDWD

The Department of National Defence and the Canadian Forces maintains an inventory of waste disposal sites located on DND lands. Where available, our inventory provides information on the base name, location, type of waste received, area of site, depth of site, year site opened/closed and status.

Government Publication Date: 2001-Apr 2007*

National Energy Board Pipeline Incidents: Federal NEBI

Locations of pipeline incidents from 2008 to present, made available by the Canada Energy Regulator (CER) - previously the National Energy Board (NEB). Includes incidents reported under the Onshore Pipeline Regulations and the Processing Plant Regulations related to pipelines under federal jurisdiction, does not include incident data related to pipelines under provincial or territorial jurisdiction.

Government Publication Date: 2008-Jun 30, 2019

National Energy Board Wells: Federal NEBP

The NEBW database contains information on onshore & offshore oil and gas wells that are outside provincial jurisdiction(s) and are thereby regulated by the National Energy Board. Data is provided regarding the operator, well name, well ID No./UWI, status, classification, well depth, spud and release date.

Government Publication Date: 1920-Feb 2003*

National Environmental Emergencies System (NEES): Federal NEES

In 2000, the Emergencies program implemented NEES, a reporting system for spills of hazardous substances. For the most part, this system only captured data from the Atlantic Provinces, some from Quebec and Ontario and a portion from British Columbia. Data for Alberta, Saskatchewan, Manitoba and the Territories was not captured. However, NEES is also a repository for previous Environment Canada spill datasets. NEES is composed of the historic datasets ' or Trends ' which dates from approximately 1974 to present. NEES Trends is a compilation of historic databases, which were merged and includes data from NATES (National Analysis of Trends in Emergencies System), ARTS (Atlantic Regional Trends System), and NEES. In 2001, the Emergencies Program determined that variations in reporting regimes and requirements between federal and provincial agencies made national spill reporting and trend analysis difficult to achieve. As a consequence, the department has focused efforts on capturing data on spills of substances which fall under its legislative authority only (CEPA and FA). As such, the NEES database will be decommissioned in December 2004.

Government Publication Date: 1974-2003*

National PCB Inventory: Federal NPCB

Environment Canada's National PCB inventory includes information on in-use PCB containing equipment in Canada including federal, provincial and private facilities. Federal out-of-service PCB containing equipment and PCB waste owned by the federal government or by federally regulated industries such as airlines, railway companies, broadcasting companies, telephone and telecommunications companies, pipeline companies, etc. are also listed. Although it is not Environment Canada's mandate to collect data on non-federal PCB waste, the National PCB inventory includes some information on provincial and private PCB waste and storage sites. Some addresses provided may be Head Office addresses and are not necessarily the location of where the waste is being used or stored.

Government Publication Date: 1988-2008*

National Pollutant Release Inventory: Federal NPRI

Environment Canada has defined the National Pollutant Release Inventory ("NPRI") as a federal government initiative designed to collect comprehensive national data regarding releases to air, water, or land, and waste transfers for recycling for more than 300 listed substances.

Government Publication Date: 1993-May 2017

Oil and Gas Wells: Private OGWE

The Nickle's Energy Group (publisher of the Daily Oil Bulletin) collects information on drilling activity including operator and well statistics. The well information database includes name, location, class, status and depth. The main Nickle's database is updated on a daily basis, however, this database is updated on a monthly basis. More information is available at www.nickles.com.

Government Publication Date: 1988-Aug 31, 2019

Ontario Oil and Gas Wells: Provincial OOGW

In 1998, the MNR handed over to the Ontario Oil, Gas and Salt Resources Corporation, the responsibility of maintaining a database of oil and gas wells drilled in Ontario. The OGSR Library has over 20,000+ wells in their database. Information available for all wells in the ERIS database include well owner/operator, location, permit issue date, and well cap date, license No., status, depth and the primary target (rock unit) of the well being drilled. All geology/stratigraphy table information, plus all water table information is also provide for each well record.

Government Publication Date: 1800-Jun 2019

Inventory of PCB Storage Sites: Provincial OPCB

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of PCB storage sites within the province. Ontario Regulation 11/82 (Waste Management - PCB) and Regulation 347 (Generator Waste Management) under the Ontario EPA requires the registration of inactive PCB storage equipment and/or disposal sites of PCB waste with the Ontario Ministry of Environment. This database contains information on: 1) waste quantities; 2) major and minor sites storing liquid or solid waste; and 3) a waste storage inventory.

Government Publication Date: 1987-Oct 2004; 2012-Dec 2013

Orders: Provincial ORD

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all Orders on the registry such as (EPA s. 17) - Order for remedial work, (EPA s. 18) - Order for preventative measures, (EPA s. 43) - Order for removal of waste and restoration of site, (EPA s. 44) - Order for conformity with Act for waste disposal sites, (EPA s. 136) - Order for performance of environmental measures.

Government Publication Date: 1994-Sep 30, 2019

Canadian Pulp and Paper: Private PAP

This information is part of the Pulp and Paper Canada Directory. The Directory provides a comprehensive listing of the locations of pulp and paper mills and the products that they produce.

Government Publication Date: 1999, 2002, 2004, 2005, 2009-2014

Parks Canada Fuel Storage Tanks: Federal PCFT

Canadian Heritage maintains an inventory of known fuel storage tanks operated by Parks Canada, in both National Parks and at National Historic Sites. The database details information on site name, location, tank install/removal date, capacity, fuel type, facility type, tank design and owner/operator.

Government Publication Date: 1920-Jan 2005*

Pesticide Register: Provincial PES

The Ontario Ministry of the Environment and Climate Change maintains a database of licensed operators and vendors of registered pesticides.

Government Publication Date: 1988-Mar 2019

TSSA Pipeline Incidents: Provincial PINC

List of pipeline incidents (strikes, leaks, spills) made available by the Technical Standards and Safety Authority (TSSA). Under the Technical Standards & Safety Act (2000), the TSSA regulates fuel suppliers, storage facilities, transport trucks, pipelines, contractors, and equipment or appliances that use fuels. Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of pipeline incidents in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Private and Retail Fuel Storage Tanks: Provincial PRT

The Fuels Safety Branch of the Ontario Ministry of Consumer and Commercial Relations maintained a database of all registered private fuel storage tanks and licensed retail fuel outlets. This database includes an inventory of locations that have gasoline, oil, waste oil, natural gas and/or propane storage tanks on their property. The MCCR no longer collects this information. This information is now collected by the Technical Standards and Safety Authority (TSSA).

Government Publication Date: 1989-1996*

Permit to Take Water: Provincial PTTW

This is a subset taken from Ontario's Environmental Registry (EBR) database. It will include all PTTW's on the registry such as OWRA s. 34 - Permit to take water.

Government Publication Date: 1994-Sep 30, 2019

Ontario Regulation 347 Waste Receivers Summary: Provincial REC

Part V of the Ontario Environmental Protection Act ("EPA") regulates the disposal of regulated waste through an operating waste management system or a waste disposal site operated or used pursuant to the terms and conditions of a Certificate of Approval or a Provisional Certificate of Approval. Regulation 347 of the Ontario EPA defines a waste receiving site as any site or facility to which waste is transferred by a waste carrier. A receiver of regulated waste is required to register the waste receiving facility. This database represents registered receivers of regulated wastes, identified by registration number, company name and address, and includes receivers of waste such as: landfills, incinerators, transfer stations, PCB storage sites, sludge farms and water pollution control plants. This information is a summary of all years from 1986 including the most currently available data.

Government Publication Date: 1986-2016

Record of Site Condition: Provincial RSC

The Record of Site Condition (RSC) is part of the Ministry of the Environment's Brownfields Environmental Site Registry. Protection from environmental cleanup orders for property owners is contingent upon documentation known as a record of site condition (RSC) being filed in the Environmental Site Registry. In order to file an RSC, the property must have been properly assessed and shown to meet the soil, sediment and groundwater standards appropriate for the use (such as residential) proposed to take place on the property. The Record of Site Condition Regulation (O. Reg. 153/04) details requirements related to site assessment and clean up.
RSCs filed after July 1, 2011 will also be included as part of the new (O.Reg. 511/09).

Government Publication Date: 1997-Sept 2001, Oct 2004-Jul 2019

Retail Fuel Storage Tanks: Private RST

This database includes an inventory of retail fuel outlet locations (including marinas) that have on their property gasoline, oil, waste oil, natural gas and / or propane storage tanks.

Government Publication Date: 1999-Jul 31, 2019

Scott's Manufacturing Directory: Private SCT

Scott's Directories is a data bank containing information on over 200,000 manufacturers across Canada. Even though Scott's listings are voluntary, it is the most comprehensive database of Canadian manufacturers available. Information concerning a company's address, plant size, and main products are included in this database.

Government Publication Date: 1992-Mar 2011*

Ontario Spills: Provincial SPL

This database identifies information such as location (approximate), type and quantity of contaminant, date of spill, environmental impact, cause, nature of impact, etc. Information from 1988-2002 was part of the ORIS (Occurrence Reporting Information System). The SAC (Spills Action Centre) handles all spills reported in Ontario. Regulations for spills in Ontario are part of the MOE's Environmental Protection Act, Part X.

Government Publication Date: 1988-Feb 2019

Wastewater Discharger Registration Database: Provincial SRDS

Information under this heading is combination of the following 2 programs. The Municipal/Industrial Strategy for Abatement (MISA) division of the Ontario Ministry of Environment maintained a database of all direct dischargers of toxic pollutants within nine sectors including: Electric Power Generation; Mining; Petroleum Refining; Organic Chemicals; Inorganic Chemicals; Pulp & Paper; Metal Casting; Iron & Steel; and Quarries. All sampling information is now collected and stored within the Sample Result Data Store (SRDS).

Government Publication Date: 1990-Dec 31, 2017

Anderson's Storage Tanks: Private TANK

The information provided in this database was collected by examining various historical documents, which identified the location of former storage tanks, containing substances such as fuel, water, gas, oil, and other various types of miscellaneous products. Information is available in regard to business operating at tank site, tank location, permit year, permit & installation type, no. of tanks installed & configuration and tank capacity. Data contained within this database pertains only to the city of Toronto and is not warranted to be complete, exhaustive or authoritative. The information was collected for research purposes only.

Government Publication Date: 1915-1953*

Transport Canada Fuel Storage Tanks: Federal TCFT

List of fuel storage tanks currently or previously owned or operated by Transport Canada. This inventory also includes tanks on The Pickering Lands, which refers to 7,530 hectares (18,600 acres) of land in Pickering, Markham, and Uxbridge owned by the Government of Canada since 1972; properties on this land has been leased by the government since 1975, and falls under the Site Management Policy of Transport Canada, but is administered by Public Works and Government Services Canada. This inventory provides information on the site name, location, tank age, capacity and fuel type.

Government Publication Date: 1970-Aug 2018

TSSA Variances for Abandonment of Underground Storage Tanks: Provincial VAR

List of variances granted for abandoned tanks. Under the Technical Standards and Safety Authority (TSSA) Liquid Fuels Handling Code and Fuel Oil Code, all underground storage tanks must be removed within two years of disuse. If removal of a tank is not feasible, an application may be sought for a variance from this code requirement.
Records are not verified for accuracy or completeness. This is not a comprehensive or complete inventory of tank variances in the province. The TSSA updates information in its system on an ongoing basis; this listing is hence limited by the record date provided here.

Government Publication Date: Feb 28, 2017

Waste Disposal Sites - MOE CA Inventory: Provincial WDS

The Ontario Ministry of Environment, Waste Management Branch, maintains an inventory of known open (active or inactive) and closed disposal sites in the Province of Ontario. Active sites maintain a Certificate of Approval, are approved to receive and are receiving waste. Inactive sites maintain Certificate(s) of Approval but are not receiving waste. Closed sites are not receiving waste. The data contained within this database was compiled from the MOE's Certificate of Approval database. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number. All new Environmental Compliance Approvals handed out after Oct 31, 2011 for Waste Disposal Sites will still be found in this database.

Government Publication Date: Oct 2011-Sep 30, 2019

Waste Disposal Sites - MOE 1991 Historical Approval Inventory: Provincial WDSH

In June 1991, the Ontario Ministry of Environment, Waste Management Branch, published the "June 1991 Waste Disposal Site Inventory", of all known active and closed waste disposal sites as of October 30st, 1990. For each "active" site as of October 31st 1990, information is provided on site location, site/CA number, waste type, site status and site classification. For each "closed" site as of October 31st 1990, information is provided on site location, site/CA number, closure date and site classification. Locations of these sites may be cross-referenced to the Anderson database described under ERIS's Private Source Database section, by the CA number.

Government Publication Date: Up to Oct 1990*

Water Well Information System: Provincial WWIS

This database describes locations and characteristics of water wells found within Ontario in accordance with Regulation 903. It includes such information as coordinates, construction date, well depth, primary and secondary use, pump rate, static water level, well status, etc. Also included are detailed stratigraphy information, approximate depth to bedrock and the approximate depth to the water table.

Government Publication Date: Feb 28, 2019

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.